

# NEWMAR CORPORATION

## WARRANTY

### DEPARTMENT

# TECHNICAL SERVICE BULLETIN

DATE ISSUED	MODEL YEAR(S) AFFECTED	TSB #
10/19/2017	2018	497

## MODEL

Bay Star Sport	<input type="checkbox"/>	Ventana	<input checked="" type="checkbox"/>	Essex	<input type="checkbox"/>
Bay Star	<input type="checkbox"/>	Dutch Star	<input checked="" type="checkbox"/>	King Aire	<input type="checkbox"/>
Canyon Star	<input type="checkbox"/>	Mountain Aire	<input type="checkbox"/>	New Aire	<input type="checkbox"/>
Ventana LE	<input type="checkbox"/>	London Aire	<input type="checkbox"/>	Other	<input type="checkbox"/>


## DESCRIPTION

Newmar has determined that certain 2018 Dutch Star and Ventana coaches were shipped without a notice label regarding the ShowerMiser.

Issue: The customer or servicing technician may not place the ShowerMiser valve in the correct position when pumping antifreeze into the water lines during the winterization process. This may allow antifreeze to be pumped into the fresh water tank.

## RECOMMENDED ACTION

Order the notice label (part # 139030) from the Newmar Parts Department. Once you have label, wipe the water works panel clean. Place the label and adhere it above, below, or beside the winterizing text on the water works panel. Below are some examples:



Flat Rate code: TSB 497

Labor Time: .1 (one-tenth) hr.

***Please read this bulletin in its entirety prior to beginning any diagnosis or repairs.***