

1301 STAHLEY DRIVE
BUILDING #42
NAPPANEE, IN 46550

NEWMAR CORPORATION

WARRANTY

DEPARTMENT

Dealer Svc. 866-290-5371
Customer Svc. 800-731-8300

RECALL SERVICE BULLETIN

DATE ISSUED	MODEL YEAR(S) AFFECTED	RSB #
1/12/2018	2017, 2018	503
MODEL		
Bay Star Sport <input type="checkbox"/>	Ventana <input type="checkbox"/>	Essex <input type="checkbox"/>
Bay Star <input type="checkbox"/>	Dutch Star <input type="checkbox"/>	King Aire <input type="checkbox"/>
Canyon Star <input type="checkbox"/>	Mountain Aire <input type="checkbox"/>	New Aire <input type="checkbox"/>
Ventana LE <input type="checkbox"/>	London Aire <input checked="" type="checkbox"/>	Other <input type="checkbox"/>
DESCRIPTION		
<p>Newmar Corporation has decided that a defect relating to motor vehicle safety exists in specific motorhomes built on Freightliner Chassis. On certain motorhomes, if the headlight high beams are activated, only the high beam bulbs illuminate. The intention of the high beam function on the affected coaches is to have both the high beam and low beam bulbs illuminate together.</p> <p>Issue: Driving a motorhome at night without the required illumination of the road may reduce the driver's visibility, increasing the risk of a crash causing injury and/or property damage.</p> <p>Correction: Daimler Trucks North America (DTNA) authorized service facilities will repair as necessary to ensure the low beam bulb and the high beam bulbs illuminate together during activation of the high beams.</p> <p>Affected Units: Refer to the attached population list for specific coach and VIN numbers.</p>		
RECOMMENDED ACTION		
<p>Action: Contact your Service Account Manager at Newmar to assist in scheduling this repair with a DTNA authorized service facility.</p> <p>The work instructions, any necessary parts or software updates, and labor time will be provided to the authorized facility by DTNA.</p> <p>Flat Rate Code: 17V 723 Labor Time: .9 hr.</p> <p><u>Please read this bulletin in its entirety prior to beginning any diagnosis or repairs.</u></p>		

If you have any questions regarding this R.S.B., please contact a Warranty Service Representative at Newmar Corporation.



WHEN YOU KNOW THE DIFFERENCE

NEWMAR CORPORATION

NEWMARCORP.COM

Date: January 10, 2018
Re: Newmar Corporation – Motor Vehicle Recall Notification

Subject: Recall Campaign No.: 17V 723

This notice is sent to you as a Newmar Dealer in accordance with the requirements of the National Traffic and Motor Vehicle Safety Act. Newmar Corporation has decided that a defect which relates to motor vehicle safety exists in specific Newmar recreational vehicles.

The National Traffic and Motor Vehicle Safety Act requires that each vehicle, which is subject to a recall campaign of this type, must be satisfactorily repaired within a reasonable time after the owner has tendered it for repair. A failure to adequately repair within 60 days after tender of a vehicle is prima facie evidence of failure to repair within a reasonable time. To avoid providing these problematic solutions, every effort must be made to promptly schedule an appointment with each owner and to repair their vehicle as soon as possible. Vehicle owners are being notified of this recall. If the condition is not remedied within a reasonable time, they are instructed on how to contact the National Highway Traffic Safety Administration.

REASON FOR THIS RECALL

Newmar Corporation has decided that a defect, which relates to motor vehicle safety exists in specific motorhomes.

On certain motorhomes, built on Freightliner Chassis, if the headlight high beams are activated, only the high beam bulbs illuminate. The intention of the high beam function on the affected coaches is to have both the high beam and low beam bulbs illuminate together. Not having the required illumination of the road could reduce the driver's visibility, which could increase the risk of a crash causing injury and/or damage to property. Correction: Daimler Trucks North America authorized service facilities will repair as necessary to ensure the low beam bulb will turn on along with the high beam bulb.

The motorhomes require immediate service. Continued use poses a potential safety hazard.

DEALER CAMPAIGN RESPONSIBILITY

Dealers are to provide to all customers/owner vehicles the service of completing this campaign at no charge to the customer/owner regardless of vehicle age, vehicle mileage, or ownership at the time of repair.

REPAIR PROCEDURE

Newmar Corporation will provide the work instructions.

If you should have any questions please contact your service account manager direct or the Newmar service department at: 1-866-290-5371.

Thank you for your cooperation.

Sincerely,

Newmar Corporation



WHEN YOU KNOW THE DIFFERENCE

NEWMAR CORPORATION

NEWMARCORP.COM

IMPORTANT SAFETY RECALL

This notice applies to your vehicle VIN. # _____

Name

Address

City, State Zip code

Date: January 10, 2018

Motor Vehicle Recall Notification - Recall Campaign No. 17V 723

Dear Valued Customer:

This notice is sent to you in accordance with the requirements of the National Traffic and Motor Vehicle Safety Act.

REASON FOR THIS RECALL

Newmar Corporation has decided that a defect which relates to motor vehicle safety exists in specific motorhomes.

On certain motorhomes, built on Freightliner Chassis, if the headlight high beams are activated, only the high beam bulbs illuminate. The intention of the high beam function on the affected coaches is to have both the high beam and low beam bulbs illuminate together. Not having the required illumination of the road could reduce the driver's visibility, which could increase the risk of a crash causing injury and/or damage to property. Correction: Daimler Trucks North America authorized service facilities will repair as necessary to ensure the low beam bulb will turn on along with the high beam bulb.

The motorhomes require immediate service. Continued use poses a potential safety hazard.

The Safety Risk

Not having the required illumination of the road could reduce the driver's visibility, which could increase the risk of a crash causing injury and/or damage to property.

WHAT WE WILL DO

Newmar will provide owners of all affected motorhomes a remedy for the potential defect at no charge for parts or labor. A Daimler Trucks North America authorized service facility will repair as necessary to ensure the low beam bulb will turn on along with the high beam bulb. Time for this repair is approximately one hour.

WHAT YOU NEED TO DO

As this defect does affect motor vehicle safety, it is recommended that you contact the Newmar service department immediately at **1-800-731-8300**. An associate will assist you in making an appointment to have this repair done by an authorized service facility.

Federal regulations require that any vehicle lessor receiving this recall notification must forward a copy of this notice to the lessee within ten days.

If you have had the repair performed before receiving this letter, you may be eligible to receive reimbursement for the cost of obtaining a pre-notification remedy. For additional information contact Newmar Corporation at:

Service Department
Newmar Corporation
355 N Delaware St
Nappanee, IN 46550-0030

An authorized service facility, is best equipped to obtain parts and provide service to ensure your vehicle is corrected as promptly as possible. HOWEVER, if you take your vehicle to your dealer or Authorized Service Facility on the scheduled date and this condition is not remedied on that date or within five days; please contact the Newmar Corporation Customer Service Department at 1-800-731-8300. You may also submit a complaint to the Administrator, National Highway Traffic Safety Administration, 1200 New Jersey Ave., SE., Washington DC 20590; or call the toll-free Vehicle Safety Hotline at 1-888-327-4236 (TTY: 1-800-424-9153); or go to <http://www.safercar.gov>.

If you no longer own this vehicle, please furnish us the complete name and address of the person or dealership you sold or traded your vehicle to. Thank you for your cooperation.

Your safety and satisfaction with your Newmar product is important to us and we regret any inconvenience to you.

Sincerely,

Newmar Corporation



WHEN YOU KNOW THE DIFFERENCE

NEWMAR CORPORATION

NEWMARCORP.COM

Date: January 10, 2018
Re: Newmar Corporation – Motor Vehicle Recall Notification

Subject: Recall Campaign No.: # 2017-562

This notice is sent to you as a Newmar Dealer in accordance with the requirements of the Canada Motor Vehicle Safety Act. Newmar Corporation has decided that a defect which relates to motor vehicle safety exists in specific Newmar recreational vehicles.

Each vehicle, which is subject to a recall campaign of this type, must be satisfactorily repaired within a reasonable time after the owner has tendered it for repair. A failure to adequately repair within 60 days after tender of a vehicle is prima facie evidence of failure to repair within a reasonable time. To avoid providing these problematic solutions, every effort must be made to promptly schedule an appointment with each owner and to repair their vehicle as soon as possible. Vehicle owners are being notified of this recall. If the condition is not remedied within a reasonable time, they are instructed to contact Transport Canada.

REASON FOR THIS RECALL

Newmar Corporation has decided that a defect which relates to motor vehicle safety exists in specific motorhomes.

On certain motorhomes, built on Freightliner Chassis, if the headlight high beams are activated, only the high beam bulbs illuminate. The intention of the high beam function on the affected coaches is to have both the high beam and low beam bulbs illuminate together. Not having the required illumination of the road could reduce the driver's visibility, which could increase the risk of a crash causing injury and/or damage to property. Correction: Daimler Trucks North America authorized service facilities will repair as necessary to ensure the low beam bulb will turn on along with the high beam bulb.

These motorhomes require immediate service. Continued use poses a potential safety hazard.

This recall applies to certain 2017-2018 Newmar London Aire motorhomes built between 05/31/2016 and 10/24/2017.

DEALER CAMPAIGN RESPONSIBILITY

Dealers are to provide to all customers/owner vehicles the service of completing this campaign at no charge to the customer/owner regardless of vehicle age, vehicle mileage, or ownership at the time of repair.

REPAIR PROCEDURE

Newmar will provide the work instructions.

If you should have any questions please contact your service account manager direct or the Newmar service department at: 1-866-290-5371.

Thank you for your cooperation.

Sincerely,

Newmar Corporation



WHEN YOU KNOW THE DIFFERENCE

NEWMAR CORPORATION

NEWMARCORP.COM

VIN#
Name
Address
City, State Zip code
Date: January 10, 2018
Motor Vehicle Recall Notification - Recall Campaign No. 2017-562

Dear Valued Customer:

This notice is sent to you in accordance with the requirements of the Canada Motor Vehicle Safety Act.

REASON FOR THIS RECALL

Newmar Corporation has determined that a defect which relates to motor vehicle safety exists in specific motorhomes.

On certain motorhomes, built on Freightliner Chassis, if the headlight high beams are activated, only the high beam bulbs illuminate. The intention of the high beam function on the affected coaches is to have both the high beam and low beam bulbs illuminate together. Not having the required illumination of the road could reduce the driver's visibility, which could increase the risk of a crash causing injury and/or damage to property. Correction: Daimler Trucks North America authorized service facilities will repair as necessary to ensure the low beam bulb will turn on along with the high beam bulb.

The motorhomes require immediate service. Continued use poses a potential safety hazard.

WHAT WE WILL DO

Newmar Corporation will provide owners of all affected motorhomes a remedy for the potential defect at no charge for parts or labor. An authorized service facility will repair as necessary to ensure the low beam bulb will turn on along with the high beam bulb.

WHAT YOU NEED TO DO

As this defect does affect motor vehicle safety, it is recommended that you contact the Newmar service department immediately at **1-800-731-8300**. An associate will assist you in making an appointment to have this repair done by an authorized service center.

Federal regulations require that any vehicle lessor receiving this recall notification must forward a copy of this notice to the lessee within ten days.

If you have had the repair performed before receiving this letter, you may be eligible to receive reimbursement for the cost of obtaining a pre-notification remedy. For additional information contact Newmar Corporation at:

Service Department
Newmar Corporation
355 N Delaware St
Nappanee, IN 46550-0030

An authorized service facility, is best equipped to obtain parts and provide service to ensure your vehicle is corrected as promptly as possible. HOWEVER, if you take your vehicle to your dealer or Authorized Service Facility on the scheduled date and this condition is not remedied on that date or within five days; please contact the Newmar Corporation Customer Service Department at 1-800-731-8300. If you no longer own this vehicle, please furnish us the complete name and address of the person or dealership you sold or traded your vehicle to. Thank you for your cooperation.

Your safety and satisfaction with your Newmar product is important to us and we regret any inconvenience to you.

Sincerely,

Newmar Corporation



WHEN YOU KNOW THE DIFFERENCE

NEWMAR CORPORATION.

NEWMARCORP.COM

NIV

Nom

Adresse

Ville, province, code postal

Date : 10 janvier 2018

Avis de rappel visant un véhicule motorisé – Campagne de rappel n° 2017-562

Madame, Monsieur,

Le présent avis vous est envoyé conformément aux exigences de la *Loi sur la sécurité automobile* du Canada.

MOTIF DU PRÉSENT RAPPEL

Newmar Corporation a déterminé qu'une défaillance relevant de la sécurité automobile existe pour certaines autocaravanes.

Sur certaines autocaravanes, construites par Freightliner Chassis, lorsque les feux de route sont activés, seules les ampoules des feux de route s'allument. Sur les véhicules touchés, les ampoules des feux de route et celles des feux de croisement devraient s'allumer ensemble. Le fait que la route ne soit pas bien éclairée peut réduire la visibilité du conducteur, ce qui pourrait augmenter les risques d'accident pouvant entraîner des blessures ou des dommages matériels (ou les deux). Mesure corrective : Les installations d'entretien autorisées de Daimler Trucks North America devront effectuer les réparations nécessaires pour s'assurer que les ampoules des feux de croisement s'allument en même temps que celles des feux de route.

Il est impératif que la réparation sur ces autocaravanes soit effectuée immédiatement. Leur utilisation prolongée pose un risque d'accident potentiel.

CE QUE NOUS FERONS

Newmar Corporation fournira aux propriétaires de toutes les autocaravanes concernées une solution gratuite (pour les pièces et la main-d'œuvre) à la défaillance potentielle. Un centre de service autorisé devra effectuer les réparations nécessaires pour s'assurer que les ampoules des feux de croisement s'allument en même temps que celles des feux de route.

CE QUE VOUS DEVEZ FAIRE

Puisque cette défaillance touche la sécurité automobile, nous vous recommandons de communiquer immédiatement avec le service technique de Newmar en composant le **1-800-731-8300**. Un associé vous aidera à prendre rendez-vous aux fins d'exécution de cette réparation par un centre de service autorisé.

En vertu de règlements fédéraux, tout donneur à bail d'un véhicule, qui reçoit le présent avis de rappel, est tenu d'en acheminer une copie au preneur à bail dans un délai de dix jours.

Si les réparations ont été effectuées avant réception de la présente lettre, vous pouvez être admissible à un remboursement des frais liés à l'obtention de la solution adoptée avant réception du présent avis. Pour de plus amples renseignements, communiquez avec Newmar Corporation à l'adresse suivante :

Service technique
Newmar Corporation
355 N Delaware St
Nappanee, IN 46550-0030

Un centre de service autorisé est le plus à même de fournir du service et d'obtenir des pièces qui assureront une réparation de votre véhicule dans les plus brefs délais. CELA DIT, si vous apportez votre véhicule à votre concessionnaire ou un centre de service autorisé à la date prévue et que le problème n'est pas résolu à cette date ou dans les cinq jours qui suivent, veuillez communiquer avec le service à la clientèle de Newmar Corporation en composant le 1-800-731-8300. Si l'autocaravane concernée ne vous appartient plus, nous vous prions de bien vouloir nous fournir le nom complet et l'adresse complète de la personne ou du concessionnaire faisant maintenant office de propriétaire. Nous vous remercions de votre coopération.

Votre sécurité et votre satisfaction par rapport à nos produits Newmar sont importantes pour nous, et nous sommes désolés de tout désagrément occasionné.

Cordialement,

Newmar Corporation

March 2018
SF564AB

Subject: Newmar Motorhome Headlights

Models Affected: Specific Newmar Corporation Dutch Star, Essex, London Aire, Ventana, and Ventana LE motorhomes manufactured May 24, 2016, through January 16, 2018, built with certain Freightliner Custom Chassis motorhome chassis manufactured November 24, 2010, through December 4, 2017.

General Information

On behalf of Newmar Corporation, Daimler Trucks North America LLC, is initiating Field Service Campaign SF564 to modify the vehicles mentioned above.

On certain Newmar motorhomes, only the high beam bulbs illuminate when both the high and low beam bulbs should illuminate together.

The software controlling the headlights will be updated.

There are approximately 1,350 vehicles involved.

Additional Repairs

Dealers must complete all outstanding field service campaigns prior to the sale or delivery of a vehicle. A Dealer will be liable for any progressive damage that results from its failure to complete campaigns before sale or delivery of a vehicle.

Owners may be liable for any progressive damage that results from failure to complete campaigns within a reasonable time after receiving notification.

Please contact Warranty Campaigns for consideration of additional charges prior to performing the repair.

Work Instructions

Please refer to the attached work instructions. Prior to performing the campaign, check the vehicle for a completion sticker (Form WAR261).

Replacement Parts

No parts are required for this campaign. Software will be updated.

If our records show your dealership has ordered any vehicle(s) involved in campaign SF564, a list of the customers and vehicle identification numbers will be available on DTNACconnect.

Removed Parts

U. S. and Canadian Dealers, please follow Warranty Failed Parts Tracking shipping instructions for the disposition of all removed parts. Export distributors, please destroy removed parts unless otherwise advised.

Labor Allowance

Table 1 - Labor Allowance

Campaign Number	Procedure	Time Allowed (hours)	SRT Code	Corrective Action
SF564AB	Update RVM parameters	0.5	996-F007A	12-Repair Recall/Campaign

Table 1

March 2018
SF564AB

IMPORTANT: When the campaign has been completed, locate the base completion label in the appropriate location on the vehicle, and attach the gray completion sticker provided in the field service kit (Form WAR261). If the vehicle does not have a base completion label, clean a spot on the appropriate location of the vehicle and first attach the base completion label (Form WAR259). If a field service kit is not required or there is no completion sticker in the kit, write the campaign number on a blank sticker and attach it to the base completion label.

Claims for Credit

You will be reimbursed for your parts, labor, and handling (landed cost for Export Distributors) by submitting your claim through the Warranty system within 30 days of completing this campaign. Please reference the following information in OWL:

- Claim type is **Field Service Campaign**.
- In the Campaign field, enter the campaign number and appropriate group (**SF564-A or SF564-B**).
- In the Primary Failed Part field, enter **25-SF564-000**.
- No parts are required for this campaign.
- In the Labor section, enter the appropriate SRT from the Labor Allowance Table. Administrative time will be included automatically as SRT 39-6010A for 0.4 hours.
- The VMRS Component Code is **003-006-008** and the Cause Code is **A1 - Campaign**.
- This Field Service Campaign will **CONTINUE UNTIL FURTHER NOTICE**. Dealers will be notified of any changes to the termination date via Important Campaign Information Letter posted on DTNACconnect.

IMPORTANT: OWL must be viewed prior to beginning work to ensure the vehicle is involved and the campaign has not previously been completed. Also, check for a completion sticker before beginning work.

All claims must be submitted within 30 days of the repair and within 30 days of the termination date of the campaign. U.S. and Canadian Dealers: All excess inventory to be returned to the PDC following the conclusion of the campaign must be returned in resalable condition to the Memphis PDC within 90 days from the termination date. Please submit a PAR to request return to the Memphis PDC. (Canadian dealers should return the kits to their facing PDC.) Export Distributors: Excess inventory is not returnable.

For questions, U.S. and Canadian dealers, contact the Warranty Campaigns Department via Web inquiry at DTNACconnect.com / WSC, or the Customer Assistance Center at (800) 385-4357, after normal business hours, if you have any questions or need additional information. Export distributors submit a Web inquiry or contact your International Service Manager.

March 2018
SF564AB

Owner Notification

Subject: Newmar Motorhome Headlights

Newmar has notified vehicle owners directly.

March 2018
SF564AB

Work Instructions

Subject: Newmar Motorhome Headlights

Models Affected: Specific Newmar Corporation Dutch Star, Essex, London Aire, Ventana, and Ventana LE motorhomes manufactured May 24, 2016, through January 16, 2018, built with certain Freightliner Custom Chassis motorhome chassis manufactured November 24, 2010, through December 4, 2017.

Recreational Vehicle Module (RVM) Parameter Refresh

1. Inspect the base label (Form WAR259) for a completion sticker for SF564 (Form WAR261). If a sticker is present for campaign SF564, no work is needed. If there is no sticker, continue with the steps below.
2. Park the vehicle on a level surface, shut down the engine, and set the parking brake. Chock the tires.
3. Connect an RP1210B compliant vehicle diagnostic adaptor to the laptop and the vehicle diagnostic port.
4. Turn the ignition switch to the "ON" position.
5. Open ServiceLink®. The vehicle identification number (VIN) will automatically appear. If it does not, select "Retry."

If the VIN still does not appear, check the adaptor connection settings. For instructions, select "Help" in ServiceLink.

Once the settings have been verified, type in the VIN.

6. Select the "Bulkhead Module" icon.
7. Select the "Features" tab. ServiceLink displays a list of installed parameters.
8. Enter the new parameter number.
 - SF564-A — Enter the new parameter number—26-04006-010
(for Newmar Dutch Star, London Aire, Ventana, and Ventana LE models)
 - SF564-B — Enter the new parameter number—26-04006-013
(for Newmar Essex models)
9. Select "Apply Changes."
10. A progress bar will appear on the laptop screen while the parameter information is being updated. Once the progress bar reaches 100%, ServiceLink performs a refresh of the parameters.
11. Verify that the new parameter is in the updated parameter list. If the new parameter is not in the updated parameter list, repeat steps 8 through 11.

If the new parameter appears in the list, go to the next step.
12. Once the update is finished, select "disconnect" in ServiceLink, then disconnect the RP1210B hardware adaptor from the vehicle.
13. Clean a spot on the base label (Form WAR259) and attach a completion sticker for SF564 (Form WAR261) to indicate the work has been completed.

Prod#	VIN Number	Year	Brand	Type	Floor	Chassis	DateIn	DateOff
501441	4UZFBTGB1HCHZ7803	2017	LA	DP	4553	FL	5/24/2016	6/2/2016
501448	4UZFBTGB0HCJA0484	2017	LA	DP	4553	FL	6/13/2016	6/21/2016
501449	4UZFBTGB9HCJA4758	2017	LA	DP	4519	FL	7/13/2016	7/21/2016
501450	4UZFBTGB8HCJC3155	2017	LA	DP	4519	FL	8/15/2016	8/22/2016
501451	4UZFBTGBGXHCJC3156	2017	LA	DP	4533	FL	8/18/2016	8/25/2016
501452	4UZFBTGBGXHCJA2887	2017	LA	DP	4519	FL	6/28/2016	7/14/2016
501453	4UZFBTGB8HCJA2886	2017	LA	DP	4513	FL	6/13/2016	6/22/2016
501456	4UZFBTGB8HCJC3110	2017	LA	DP	4553	FL	8/1/2016	8/8/2016
501457	4UZFBTGB4HCJA6756	2017	LA	DP	4533	FL	7/14/2016	7/22/2016
501459	4UZFBTGB6HCJA6757	2017	LA	DP	4519	FL	7/26/2016	8/3/2016
501460	4UZFBTGB1HCJC3157	2017	LA	DP	4519	FL	8/19/2016	8/29/2016
501464	4UZFBTGB4HCJD1348	2017	LA	DP	4525	FL	8/29/2016	9/7/2016
501468	4UZFBTGBGXHCJC8180	2017	LA	DP	4519	FL	10/14/2016	10/24/2016
501471	4UZFBTGB3HCJC8179	2017	LA	DP	4553	FL	10/10/2016	10/17/2016
501492	4UZFBTGB1HCJG0712	2017	LA	DP	4519	FL	3/20/2017	3/27/2017
501493	4UZFBTGF0JCJD9866	2018	LA	DP	4531	FL	1/13/2017	1/23/2017
501494	4UZFBTGF1JCJN9984	2017	LA	DP	4519	FL	4/4/2017	4/12/2017
501496	4UZFBTGB9HCJF4379	2017	LA	DP	4519	FL	2/22/2017	3/2/2017
501497	4UZFBTGB5HCJF4380	2017	LA	DP	4533	FL	2/24/2017	3/3/2017
501499	4UZFBTGB9HCJF6665	2017	LA	DP	4519	FL	3/10/2017	3/20/2017
501501	4UZFBTGF5JCJP0406	2017	LA	DP	4519	FL	5/4/2017	5/12/2017
501504	4UZFBTGF5JCJR6603	2018	LA	DP	4531	FL	5/22/2017	6/2/2017
501507	4UZFBTGF1JCJR8347	2018	LA	DP	4535	FL	6/23/2017	7/11/2017
501509	4UZFBTGF9JCJT1852	2018	LA	DP	4553	FL	7/21/2017	7/31/2017
501512	4UZFBTGF2JCJZ9698	2018	LA	DP	4534	FL	12/18/2017	
501513	4UZFBTGF6JCJU4946	2018	LA	DP	4534	FL	8/16/2017	8/24/2017
501515	4UZFBTGF7JCJU2249	2018	LA	DP	4531	FL	8/29/2017	9/7/2017
501516	4UZFBTGF1JCJS6791	2018	LA	DP	4534	FL	7/12/2017	7/20/2017
501521	4UZFBTGF8JCJY9452	2018	LA	DP	4531	FL	12/5/2017	12/13/2017
501528	4UZFBTGF8JCJZ5557	2018	LA	DP	4531	FL	12/12/2017	12/19/2017
501529	4UZFBTGF8JCJZ5558	2018	LA	DP	4533	FL	12/20/2017	
501530	4UZFBTGF5JCJV6165	2018	LA	DP	4535	FL	9/22/2017	10/2/2017
501535	4UZFBTGF3JCJT8411	2018	LA	DP	4553	FL	8/7/2017	8/15/2017
501536	4UZFBTGF4JCJY2501	2018	LA	DP	4553	FL	11/21/2017	11/30/2017
501538	4UZFBTGF0JCJW7509	2018	LA	DP	4531	FL	10/4/2017	10/12/2017
501540	4UZFBTGF4JCJX0543	2018	LA	DP	4533	FL	10/11/2017	10/19/2017
501543	4UZFBTGF2JCJY2500	2018	LA	DP	4531	FL	11/7/2017	11/15/2017
501545	4UZFBTGF8JCJX7057	2018	LA	DP	4535	FL	10/26/2017	11/3/2017
501550	4UZFBTGF8JCJY9453	2018	LA	DP	4531	FL		
501551	4UZFBTGF6JCJY9451	2018	LA	DP	4533	FL	12/1/2017	12/8/2017
501557	4UZFBTGF2JCJX9211	2018	LA	DP	4534	FL	11/3/2017	11/13/2017

Canadian Units

501440	4UZFBTGB3HCHZ7804	2017	LA	DP	4553	FL	5/31/2016	6/9/2016
501455	4UZFBTGB7HCJC0649	2017	LA	DP	4553	FL	8/9/2016	8/17/2016
501469	4UZFBTGB6HCJD1349	2017	LA	DP	4553	FL	10/19/2016	10/27/2016
501472	4UZFBTGB5HCJE7011	2017	LA	DP	4519	FL	10/12/2016	10/20/2016
501490	4UZFBTGB7HCJF6664	2017	LA	DP	4553	FL	3/8/2017	3/16/2017
501500	4UZFBTGF3JCJP0405	2017	LA	DP	4553	FL	4/17/2017	4/25/2017
501534	4UZFBTGF6JCJX7056	2018	LA	DP	4531	FL	10/16/2017	10/24/2017