

1301 STAHLEY DRIVE
BUILDING #42
NAPPANEE, IN 46550

NEWMAR CORPORATION

WARRANTY

DEPARTMENT

Dealer Svc. 866-290-5371
Customer Svc. 800-731-8300

PRODUCT INFORMATION BULLETIN

DATE ISSUED	MODEL YEAR(S) AFFECTED	PIB #
1/29/2019	2017, 2018, 2019	539

MODEL

Bay Star Sport	<input type="checkbox"/>	Ventana	<input type="checkbox"/>	Essex	<input checked="" type="checkbox"/>
Bay Star	<input type="checkbox"/>	Dutch Star	<input type="checkbox"/>	King Aire	<input checked="" type="checkbox"/>
Canyon Star	<input type="checkbox"/>	Mountain Aire	<input checked="" type="checkbox"/>	New Aire	<input checked="" type="checkbox"/>
Ventana LE	<input type="checkbox"/>	London Aire	<input checked="" type="checkbox"/>	Other	<input type="checkbox"/>

PRODUCT INFORMATION

The driver console USB port to the Xite G3 system may not function properly when plugged into the USB dongle on the Xite G3 system.

Unplug the USB cord from the dongle, plug it into the front USB port on the G3 core, and test the USB function. It may work properly after changing to the port. USB cords on coaches with an in-production date after 11/28/2018 should already be plugged into the front USB port on the G3 core.

G3 systems have been used in the following coaches:

2017, 2018, 2019 King Aire

2018, 2019 Essex

2018, 2019 New Aire

2019 London Aire

2019 Mountain Aire

Flat Rate Code: PIB 539

Labor Time: .2 hr.

Please read this bulletin in its entirety prior to beginning any diagnosis or repairs.

If you have any questions regarding this P.I.B., please contact a Warranty Service Representative at Newmar Corporation.