800.858.4924 Fax 219.773.2007

NEWMAR CORPORATION WARRANTY DEPARTMENT

TECHNICAL SERVICE BULLETIN								
DATE ISSUED		MODEL YEAR(S) AFFECTED		MODEL(S) AFFECTED		TSB#		
4/19/05		2004-2005		Essex / MADP		251		
		BRAND	BRAND				Түре	
All		American Star		Mountain Aire		All \square	ТТП	
		Dutch Star		Kountry Aire		FW 🗖	САП	
		Kountry Star		Essex		D₽■	DB□	
Sco	ttsdale	Northern Star		London Aire				
☐ Air Conditioning & Heating ☐ Electrical Components								
☐ Appliances & Accessories ☐ Exterior Components								
☐ Cabinets & Furniture ☐ Interior Components					nents			
	Chassis Components □ Plumbing & Bath Components							
	Construction Components Windows, Awnings, Vents, & Doors				8			
DESCRIPTION OF PROBLEM								
Water migrating through the engine compartment may get into the Spartan Electronics package mounted on the rear wall. Water settling into the electronics can damage them.								
RECOMMENDED SOLUTION								
Install a water resistant ABS plastic box with clear cover (p/n 76512P) over the Spartan Electronics Package. This minimizes the risk of moisture damage to the electronics. 1) Locate the Spartan Electronics Package on the right rear wall of the engine compartment (picture 1). 2) Cut wire passage openings in bottom of box, and install foam tape around back of box (picture 2). 3) Position the box over the Spartan Electronics and screw the box to the rear wall (picture 3). 4) Install the clear plastic cover on the front of the box and rotate tabs to secure it in place (picture 4). Total Time Allowed: 1.0 labor Labor Operation Code: 0261 Failure Code: 34 – Part Missing								

NEWMAR CORPORATION WARRANTY DEPARTMENT



Picture 1 Locating the Spartan Electronics Package on the Engine Compartment Rear Wall



Picture 2
Installing foam tape on back of box (p/n 76512P) to provide a seal against the rear wall.

NEWMAR CORPORATION WARRANTY DEPARTMENT



Picture 3 Installing the box over the electronic components.



Picture 4
Clear plastic cover on box (note retaining clips).