		Technical	Serv	ice Bulletin			
Date Issued Model Year(s) Affected		ted	Model(s) Affected		1	TSB #	
	1/3/2007 12/2/2005 - 5/9/2006		2006	All Star		311	
		Brand				Туре	
All	C	American Star		Mountain Aire		All 🗖	ТТП
		Dutch Star		Kountry Aire		FW 🗖	САП
All	Star	Kountry Star		Essex		D P 🗖	DB□
Sco	ttsdale 🛛	Northern Star		London Aire		D1 –	
□ Air Conditioning & Heating			Electrical Components				
	Appliances & Acc	ressories	[Exterior Components			
□ Cabinets & Furniture □			Interior Components				
■ Chassis Components □ I			Plumbing & Bath Components				
Construction Components			[□ Windows, Awnings, Vents, & Doors			
		Descri	iption of I	Problem			
Pote	ential for Driveline	Vibration.					
		Recom	mended	Solution			
-		the rear engine mounts, and nufacturer directly for addit		-		's attached	l repair

If you have any questions regarding this T.S.B., please contact a Warranty Service Representative at Newmar Corporation.



Spartan Chassis, Inc. Customer Service Group

January 2, 2007

Re: Notice of Campaign Service Bulletin: CSB06-170-002

Dear Service Manager,

Attached is a copy of campaign service bulletin **CSB06-170-002** which addresses the condition for potential driveline vibration. This condition applies to certain Spartan units produced as Newmar All-star models, with a VDM (Vehicle Date of Manufacture) of December 2, 2005 through May 9, 2006.

The correction is to inspect the location of the rear engine mounts, and correct if necessary.

.5 hrs is allowed for inspection only. 2 hrs is allowed for inspection / rework.

If you have any questions, call Spartan's Customer Service Dept. @ 800-393-8861 (Option 2).

Although **this is not a recall**, Spartan Chassis is committed to serving you with your best interests in mind.

Best Regards,

Wayne Ridge

Wayne Ridge Product Improvement Administrator Spartan Chassis, Inc.

Should the servicing facility have any billing questions, call Wayne Ridge at 517-543-6400 ext.445



Spartan Chassis, Inc. Customer Service Group



December, 2006 Page 1 of 4

CAMPAIGN SERVICE BULLETIN

<u>SUBJECT</u>: Engine -Mounts

<u>APPLIES TO</u>: Spartan units produced as Newmar All-star Models, with a VDM (Vehicle Date of Manufacture) of December 2, 2005 through May 9, 2006.

- **<u>CONDITION</u>**: Potential for Driveline Vibration.
- **<u>CORRECTION</u>**: Inspect the location of the rear engine mounts, and correct if necessary

PART / SERVICE INFORMATION:

Labor Time:Inspection Only0.5 HoursInspection/Rework2.0 Hours

<u>QTY.</u>	Part Number	Description
As needed	81790	Adhesive- removable threadlocker "blue"
		Or equivalent

PLEASE READ THE ENTIRE BULLETIN BEFORE PROCEEDING WITH ANY WORK. CONTACT SPARTAN CHASSIS IF THERE ARE ANY CONCERNS WITH THE PROCEDURES CONTAINED IN THIS DOCUMENT

STEP-BY-STEP INSTRUCTIONS:

1. Observe all industry safety standards and secure vehicle for rework of the rear engine mounts.

Inspection

2. Refer to FIG. 2-1. Measure the bolt hole location on the vertical surface of each rear upper engine mounting bracket.

Technical Service Bulletins are intended for use by Professional Technicians only. They are written to guide Professional Technicians in performing service to vehicles of product specific nature in conjunction with industry standards. Professional Technicians are appropriately trained on industry standards and have the tools and equipment to perform procedures safely and properly.




December, 2006 Page 2 of 4

CAMPAIGN SERVICE BULLETIN

NOTE: The hole location must be measured for EACH of the rear upper engine mounting brackets.

- 2a) From the rear vertical edge of the bracket, measure to the centerline of the first hole. If the dimension is 1.50" the mount is installed properly and no further work is necessary.
- 2b) If the measurement is not 1.50" proceed to step #3.

NOTE: The measurement should be the same for both brackets. If the measurement is not the same, contact Spartan Chassis, Inc.



FRONT OF COACH

Correction

3. Place jack under center of flywheel housing and raise engine to remove weight from rear engine mounting isolators.


Technical Service Bulletins are intended for use by Professional Technicians only. They are written to guide Professional Technicians in performing service to vehicles of product specific nature in conjunction with industry standards. Professional Technicians are appropriately trained on industry standards and have the tools and equipment to perform procedures safely and properly.



December, 2006 Page 3 of 4

CAMPAIGN SERVICE BULLETIN

- 4. Refer to FIG. 3-1. Remove 3/4 X 4.50" bolts that pass thru the engine mounting brackets and isolators. Save fasteners for reuse.
- 5. Remove 5/8 X 1.50" bolts from support frame brackets. Save fasteners for reuse.
- 6. Remove M12 X 35MM bolts from upper engine mounting bracket and isolator as an assembly from each side of flywheel housing. Save fasteners for reuse.
- 7. Remove all of the threadlocker from the threads of the bolts that were attaching the upper engine mounting brackets to the flywheel housing.



8. Install upper engine mounting bracket and isolator assemblies such that the bolt hole location of the first hole from the rear vertical edge is 1.50" as described in step #2. Apply a liberal amount of thread locker. Reuse existing hardware. Torque to 38 ft. lbs.

Technical Service Bulletins are intended for use by Professional Technicians only. They are written to guide Professional Technicians in performing service to vehicles of product specific nature in conjunction with industry standards. Professional Technicians are appropriately trained on industry standards and have the tools and equipment to perform procedures safely and properly.



December, 2006 Page 4 of 4

CAMPAIGN SERVICE BULLETIN

- 9. Reinstall lower engine mounting brackets to support frame brackets. Reuse existing fasteners. Torque to 180 ft. lbs.
- 10. Reinstall 3/4 x 4.50" bolt and flat washer through upper and lower engine mounting brackets.
- 11. Lower then remove jack from under flywheel housing.
- 12. Reinstall 3/4" nuts onto mounting bracket bolts. Torque to 300 ft. lbs.
- 13. Review entire engine compartment to insure that **no** pipes brackets or braces are contacting any portion of the frame that would cause vibrations.

Technical Service Bulletins are intended for use by Professional Technicians only. They are written to guide Professional Technicians in performing service to vehicles of product specific nature in conjunction with industry standards. Professional Technicians are appropriately trained on industry standards and have the tools and equipment to perform procedures safely and properly.

Vantive First Name	Garry Brent Larry & Lena O	Aaron & Rita Kimber Esther	Kevin & Jennifer Eddy C Craig S Kenneth E Bhoal & Lucianna	Christopher D
Vantive Last Name or Company Name	Tupy Pacheco	Fessler Earl	tani tugh ar	
Vantive Vantive VDM Chassis 12/2/2005 MG (All Star) 12/16/2005 MG (All Star)	1/4/2006 MG (All Star) 1/6/2006 MG (All Star) 1/10/2006 MG (All Star) 1/16/2006 MG (All Star)	MG (AII MG (AII MG (AII MG (AII MG (AII MG (AII MG (AII)	MG (AII) MG	MG AII MG
VDMDTE BDYBLD 12/2005 NEWMAR (CHASSIS ONLY 12/16/2005 NEWMAR (CHASSIS ONLY	1/4/2006 NEWMAR (CHASSIS ONLY 1/6/2006 NEWMAR (CHASSIS ONLY 1/10/2006 NEWMAR (CHASSIS ONLY 1/16/2006 NEWMAR (CHASSIS ONLY	NEWMAR (CHASSIS NEWMAR (CHASSIS NEWMAR (CHASSIS NEWMAR (CHASSIS NEWMAR (CHASSIS NEWMAR (CHASSIS NEWMAR (CHASSIS NEWMAR (CHASSIS NEWMAR (CHASSIS	NEWMAR (CHASSIS NEWMAR (CHASSIS	NEWMAR (CHASSIS NEWMAR (CHASSIS
FPN MG24360-095 MG24360-095	MG24360-095 MG24360-095 MG24360-095 MG24360-095	MG24360-095 MG24360-095 MG24360-095 MG24360-095 MG24360-095 MG24360-095 MG24360-095 MG24360-095 MG24360-095	MG24360-095 MG24360-095 MG24360-095 MG24360-095 MG24360-095 MG24360-095 MG24360-095 MG24360-095 MG24360-095 MG24360-095 MG24360-095 MG24360-095 MG24360-095 MG24360-095 MG24360-095 MG24360-095 MG24360-095	MG24360-095 MG24360-095 MG24360-095 MG24360-095 MG24360-095 MG24360-095 MG24360-095 MG24360-095 MG24360-095 MG24360-095 MG24360-095 MG24360-095
SALES SALES VINNUM ORDER 4VZBN3D967C053846 53846 4VZBN3D947C054199 54199	4VZBN3D937C054601 54601 4VZBN3D977C054200 54200 4VZBN3D967C054723 54723 4VZBN3D987C054724 54724			

3/14/2006 MG (All Star) 3/15/2006 MG (All Star) 3/16/2006 MG (All Star) 3/16/2006 MG (All Star) 3/16/2006 MG (All Star) 3/21/2006 MG (All Star) 3/21/2006 MG (All Star)
3/14/2006 NEWMAR (CHASSIS ONLY 3/15/2006 NEWMAR (CHASSIS ONLY 3/16/2006 NEWMAR (CHASSIS ONLY 3/16/2006 NEWMAR (CHASSIS ONLY 3/16/2006 NEWMAR (CHASSIS ONLY 3/21/2006 NEWMAR (CHASSIS ONLY 3/21/2006 NEWMAR (CHASSIS ONLY
MG24360-095 MG24360-095 MG24360-095 MG24360-095 MG24360-095 MG24360-095 MG24360-095 MG24360-095
55533 55534 55535 55535 55536 55537 55604 55605
4VZBR3D907C055533 4VZBR3D927C055534 4VZBR3D947C055535 4VZBR3D967C055536 4VZBR3D987C055536 4VZBR3D987C055537 4VZBR3D987C055604 4VZBR3D987C055604