72185 COUNTY ROAD 3 NAPPANEE, IN 46550

NEWMAR CORPORATION WARRANTY DEPARTMENT

800.858.4924 Fax 219.773.2007

TECHNICAL SERVICE BULLETIN						
DATE ISSUED	MODEL YEAR(S) AFFECTED		Model(s) Affected		TSB#	
			Certain units			
1/15/2008	2007 - 2008		w/Spartan DP & ME		327	
			Chassis			
BRAND					Түре	
All \square	American Star		Mountain Aire		All \square	ТТП
Cypress	Dutch Star		Kountry Aire		$F W \square$	САП
Northern Star	reducty our		Essex		D₽■	DB■
Scottsdale	Taning Tanie		London Aire		D 1	D D
All Star	Ventana					
☐ Air Conditioning & Heating ☐ Electrical Components						
☐ Appliances & Accessories ☐			☐ Exterior Components			
☐ Cabinets & Furniture □			☐ Interior Components			
■ Chassis Components			☐ Plumbing & Bath Components			
☐ Construction Components ☐			☐ Windows, Awnings, Vents, & Doors			
DESCRIPTION OF PROBLEM						
Potential fracture and failure of fastener hardware on certain Spartan chassis.						
RECOMMENDED SOLUTION						
Inspect fastener hardware per attached Spartan Campaign Service Bulletin CSB07-940-001 . Spartan allows an inspection time of between .5 - 1.5 hours. Read the attached procedure from Spartan before beginning any inspection or repairs. Questions can be directed to Wayne Ridge at Spartan Motors: 1-517-543-6400 ext. 3445.						



Spartan Chassis, Inc. Customer Service Group

January 3, 2008

Re: Notice of Campaign Service Bulletin: CSB07-940-001

Dear Service Manager,

Attached is a copy of campaign service bulletin **CSB06-940-001** which addresses the condition for potential fastener fracture. This condition applies to certain Spartan motorhomes having a VDM (Vehicle Date of Manufacture) of May 3, 2007 through July 18, 2007.

The correction is to inspect and replace if necessary.

Between .5 to 1.5 hrs are allowed for inspection. Inspection times may vary (see bulletin).

IMPORTANT: The inspection report must be filled out and returned to Spartan before payment will be authorized. Labor time must be pre-approved by Spartan Chassis, Inc.

If you have any questions, call Spartan's Customer Service Dept. @ 800-393-8861 (Option 2).

Although **this is not a recall**, Spartan Chassis is committed to serving you with your best interests in mind.

Best Regards,

Wayne Ridge Product Improvement Administrator Spartan Chassis, Inc.

Should the servicing facility have any billing questions, call Wayne Ridge at 517-543-6400 ext.3445

CSB07-940-001 January, 2008 Page 1 of 6

CAMPAIGN SERVICE BULLETIN

SUBJECT:

Fasteners - 5/8" X 1.50" Grade 8 Yellow Flange Head Bolts

APPLIES TO:

Certain Spartan Motorhomes having a VDM (Vehicle Date of

Manufacture) of May 3, 2007 through July 18, 2007.

CONDITION:

Fasteners Fractured

CORRECTION:

Inspect - Replace Fasteners as Needed

PLEASE READ THE ENTIRE BULLETIN BEFORE PROCEEDING WITH ANY WORK. CONTACT SPARTAN CHASSIS IF THERE ARE ANY CONCERNS WITH THE PROCEDURES CONTAINED IN THIS DOCUMENT

PART / SERVICE INFORMATION:

Hendrickson Airtek Front Suspension Inspection/Torque Time: .50 hrs.

Hendrickson Independent Front Suspension Inspection/Torque Time: 1.00 hrs.

Tuthill/Granning Independent Front Suspension &

Steering Gear Mounting Inspection/Torque Time: 1.50 hrs.

Inspection report must be filled out and returned to Spartan Chassis, Inc. before payment will be authorized.

If defective bolts are found and need to be replaced the Labor Time must be preapproved by Spartan Chassis, Inc.

Fastener part numbers are listed below:

Part Number

Description

10110150FH8Y 1011FLN8Y Bolt - 5/8 - 11 x 1.50" Flanged head

Nut - 5/8 - 11 Flanged Lock nut

STEP-BY-STEP INSTRUCTIONS:

 Observe all industry safety standards, disconnect any necessary power source and secure vehicle for inspection and possible replacement of certain 5/8" X 1.50" grade 8 yellow flange head bolts.

CSB07-940-001 January, 2008 Page 2 of 6

CAMPAIGN SERVICE BULLETIN





STEERING GEAR SUPPORT MOUNTING LOCATION FIG. 2-1

If the unit is equipped with a Tuthill/Granning Independent Front Suspension (IFS) perform the following:

STEERING GEAR MOUNTING INSPECTION

- 2. Refer to FIG. 2-1. Visually inspect the six bolts attaching the steering gear support to the frame. If all of the bolts appear to be intact proceed to step 3. If any bolts are missing proceed to step 4.
- 3. Using a torque wrench set at 50 lbs. ft. attempt to rotate each bolt from which ever side is most accessible. If a bolt or nut rotates it must be replaced. If it does not rotate do not replace. Torque the new bolt and nut to 148 lbs. ft. from the nut, or 185 lbs. ft. from the bolt head.
- 4. Replace the missing bolts and nuts and torque them to 148 lbs. ft. from the nut or 185 lbs. ft. from the bolt head. Perform step 3 to the bolts that are not missing.
- 5. Refer to FIG. 3-1 & FIG. 3-2. Visually inspect the bolts attaching the IFS cradle to each frame rail. If all of the bolts appear to be intact proceed to step 6. If any bolts are missing proceed to step 7.
- 6. Using a torque wrench set at 50 lbs. ft. attempt to rotate each bolt from which ever side is most accessible. If a bolt or nut rotates it must be replaced. If it does not rotate do not replace. Torque the new bolt and nut to 148 lbs. ft. from the nut, or 185 lbs. ft. from the bolt head.
- 7. Replace the missing bolts and nuts and torque them to 148 lbs. ft. from the nut or 185 lbs. ft. from the bolt head. Perform step 6 to the bolts that are not missing.




SPARTAN CHASSIS, INC.


CSB07-940-001

January, 2008 Page 3 of 6


CAMPAIGN SERVICE BULLETIN

8. Reconnect any power source previously disconnected.





TUTHIL/GRANNING IFS CRADLE MOUNTING LOCATION (BEHIND AIRSPRING) FIG. 3-1





TUTHIL/GRANNING IFS CRADLE MOUNTING LOCATION FIG. 3-2



SPARTAN CHASSIS, INC.

CSB07-940-001 January, 2008

Page 4 of 6

CAMPAIGN SERVICE BULLETIN

If the unit is equipped with a Hendrickson Independent Front Suspension (IFS) perform the following:

- 1. Refer to FIG. 4-1. Visually inspect the bolts attaching the IFS cradle to each frame rail. If all of the bolts appear to be intact proceed to step 2. If any bolts are missing proceed to step 3.
- 2. Using a torque wrench set at 50 lbs. ft. attempt to rotate each bolt from which ever side is most accessible. If a bolt or nut rotates it must be replaced. If it does not rotate do not replace. Torque the new bolt and nut to 148 lbs. ft. from the nut, or 185 lbs. ft. from the bolt head.
- 3. Replace the missing bolts and nuts and torque them to 148 lbs. ft. from the nut or 185 lbs. ft. from the bolt head. Perform step 2 to the bolts that are not missing.
- 4. Reconnect any power source previously disconnected.




HENDRICKSON IFS CRADLE MOUNTING LOCATION FIG. 4-1

CSB07-940-001 January, 2008 Page 5 of 6

CAMPAIGN SERVICE BULLETIN

If the unit is equipped with a Hendrickson Airtek Front Suspension perform the following:

- 1. Refer to FIG. 5-1. Visually inspect the bolts attaching the front suspension shock absorber upper mounting brackets to each frame rail. If the bolts appear to be intact proceed to step 2. If any bolts are missing proceed to step 3.
- 2. Using a torque wrench set at 50 lbs. ft. attempt to rotate each bolt from which ever side is most accessible. If a bolt or nut rotates it must be replaced. If it does not rotate do not replace. Torque the new bolt and nut to 148 lbs. ft. from the nut, or 185 lbs. ft. from the bolt head.
- 3. Replace the missing bolts and nuts and torque them to 148 lbs. ft. from the nut or 185 lbs. ft. from the bolt head. Perform step 2 to the bolts that are not missing.
- 4. Reconnect any power source previously disconnected.



HENDRICKSON AIRTEK SHOCK MOUNTING LOCATION FIG. 5-1

CSB07-940-001 January, 2008 Page 6 of 6

CAMPAIGN SERVICE BULLETIN

INSPECTION REPORT VIN #_____ Customer Name: __ Date of Inspection: Inspected By: Service Facility: ___ Service Facility Address: The vehicle indicated above was inspected in our service facility according to instructions provided to us in the Spartan Chassis campaign bulletin CSB07-940-001. Please check & complete each area representing fastener inspections & or repairs that were performed by your service facility including the quantity of fasteners replaced in each location: Tuthill / Granning IFS suspension fastener torque inspection: (We replaced the fasteners in this suspension because we found defective fasteners) **Quantity** Tuthill / Granning IFS suspension fastener torque inspection: (We did not find any defective fasteners and did not replace any fasteners) Tuthill / Granning Steering Gear Support fastener torque inspection: (We replaced the fasteners in the steering gear support because we found defective fasteners) Quantity Tuthill / Granning Steering Gear Support fastener torque inspection: (We did not find any defective fasteners and did not replace any fasteners) Hendrickson IFS suspension fastener torque inspection: (We replaced the fasteners in this suspension because we found defective fasteners) Quantity Hendrickson IFS suspension fastener torque inspection (We did not find any defective fasteners and did not replace any fasteners) Hendrickson Airtek front suspension shock absorber inspection: (We replaced the fasteners in this suspension because we found defective fasteners) Quantity Hendrickson Airtek front suspension shock absorber inspection: (We did not find any defective fasteners and did not replace any fasteners)

This form must be completed and returned to Spartan Chassis, Inc. before payment will be authorized.

We have validated and / or repaired all defective materials required as indicated above