NEWMAR CORPORATION WARRANTY DEPARTMENT

TECHNICAL SERVICE BULLETIN			
DATE ISSUED	MODEL YEAR(S) AFFECTED	MODEL(S) AFFECTED	TSB #
1/30/08	2007-2008	All with Oasis Heat	331
	BRAND		Түре
AllICypressINorthern StarIScottsdaleIAll Star MEI	American StarIDutch StarIKountry StarIKing AireIVentanaI	Kountry Aire	All \Box $T T \Box$ $F W \Box$ $C A \Box$ $D P \blacksquare$ $D B \Box$
All Star ME I Ventana I Image: A conditioning & Heating Electrical Components Appliances & Accessories Exterior Components Cabinets & Furniture Interior Components Chassis Components Plumbing & Bath Components Construction Components Windows, Awnings, Vents, & Doors DESCRIPTION OF PROBLEM			
	RECOMMENDED	SOLUTION	
Oasis has issued a Technical Service Bulletin to address concerns of an Oasis heating system that exhibits High Fault Limits. This procedure changes the "cycling auquastat" to and updated version. Any questions regarding this TSB should be directed to Oasis at (604) 278-1272, or Toll Free at 1-800-755-1272. READ THE PROCEDURE THOROUGHLY AND COMPLETELY PRIOR TO BEGINNING DIAGNOSIS OR REPAIRS.			

If you have any questions regarding this T.S.B., please contact a Warranty Service Representative at Newmar Corporation.




TECHNICAL BULLETIN

INTERNATIONAL LTD THERMAL RESEARCH

Heating Systems	November 13, 2007	Bulletin Identification No.: MTB-102-22
Release Type: Public		Standard Repair Time: 45 Minutes
Affected Model(s):	OASIS CH50	
Effective Date:	August 1, 2007	
Effective Serial Number:	CH50X-XXX-1436	
Description:	Aquastat upgrade	
Part No. (Old):	1031 - 160-10F Cycling aquastat (screw type) Or 1121: 160-10F Cycling aquastat (sealed)	
		F Cycling aquastat assembly (sealed)
Part No. (New):	2130-20: A73 Cycling aquastat assembly	

Short description of change:

The cycling aquastat has been changed to a faster responding aquastat. If an Oasis, prior to this change, has had a problem with high limit faults, change the cycling aquastat by following the instructions below:




Canada customer contact info: International Thermal Research Ltd. 2431 Simpson Road, Richmond, BC, Canada, V6X 2R2 Tel: (604) 278-1272, Fax: (604) 278-1274 Toll Free: 1-800-755-1272 Reference to MCR-102-10 Page 1 of 5



TECHNICAL BULLETIN

INTERNATIONAL LTD THERMAL RESEARCH

Heating Systems	November 13, 2007	Bulletin Identification No.: MTB-102-22
Release Type: Public		Standard Repair Time: 45 Minutes




Canada customer contact info: International Thermal Research Ltd. 2431 Simpson Road, Richmond, BC, Canada, V6X 2R2 Tel: (604) 278-1272, Fax: (604) 278-1274 Toll Free: 1-800-755-1272 Reference to MCR-102-10 Page 2 of 5



TECHNICAL BULLETIN

INTERNATIONAL LTD THERMAL RESEARCH

Heating Systems	November 13, 2007	Bulletin Identification No.: MTB-102-22
Release Type: Public		Standard Repair Time: 45 Minutes




Canada customer contact info: International Thermal Research Ltd. 2431 Simpson Road, Richmond, BC, Canada, V6X 2R2 Tel: (604) 278-1272, Fax: (604) 278-1274 Toll Free: 1-800-755-1272 Reference to MCR-102-10 Page 3 of 5



INTERNATIONAL LTD THERMAL RESEARCH

TECHNICAL BULLETIN

Heating Systems	November 13, 2007	Bulletin Identification No.: MTB-102-22
Release Type: Public		Standard Repair Time: 45 Minutes



Canada customer contact info: International Thermal Research Ltd. 2431 Simpson Road, Richmond, BC, Canada, V6X 2R2 Tel: (604) 278-1272, Fax: (604) 278-1274 Toll Free: 1-800-755-1272 Reference to MCR-102-10 Page 4 of 5




INTERNATIONAL LTD THERMAL RESEARCH

TECHNICAL BULLETIN

Heating Systems	November 13, 2007	Bulletin Identification No.: MTB-102-22
Release Type: Public		Standard Repair Time: 45 Minutes

Slide the new aquastat bracket under the bottom square washer in position and tighten the bottom nut. Place a new nut on top and tighten down together with high limit aquastat tab.
Connect the green wires from the aquastat to the OASIS wiring harness. Place the front section back, close the aquastat cover and reconnect the 32-pin connector to the board. Turn on the power and check the operation



of the heater.

Re-mount the front panel.

Canada customer contact info: International Thermal Research Ltd. 2431 Simpson Road, Richmond, BC, Canada, V6X 2R2 Tel: (604) 278-1272, Fax: (604) 278-1274 Toll Free: 1-800-755-1272 Reference to MCR-102-10 Page 5 of 5