1	DATE ISSUED		TECHNICAL S Model Year(s) Aff						TSB #
3/24/08			2006-2007			MODEL(S) AFFECTED All Newmar DP on Spartan MM Chassis		335	
Brand					•		7	Гүре	
All			American Star			Mountain Aire		All 🗖	ТТП
Сург	ess		Dutch Star			Kountry Aire		FW□	САП
Northern Star			Kountry Star		Essex				
Scot	Scottsdale		King Aire			London Aire		D P 🗖	D B □
All S	tar ME		Ventana						
Air Conditioning & Heating Electrical Components									
	0 0				Exterior Components				
	11				Interior Components				
	_				Plumbing & Bath Components				
 Construction Components 				Windows, Awnings, Vents, & Doors					
Description of Problem									
Spartan RSB07-500-002 / NHTSA Recall # 07V-363. Possible chassis electrical failure due to bad jumper connection inside the "Bussman Box" in the chassis electrical system. Electrical failure can mean shut down of engine, transmission, and numerous other chassis electrical components or systems.									
RECOMMENDED SOLUTION									
Inspect and replace the "Bussman" electrical box per the chassis manufacturers attached procedure. PLEASE READ THE ATTACHED PROCEDURE COMPLETELY BEFORE BEGINNING ANY REPAIRS. CONTACT SPARTAN MOTORS IF YOU SHOULD HAVE ANY QUESTIONS REGARDING THIS RECALL.									

Note that this is a NHTSA Recall.

SPARTAN CHASSIS, INC.

Page 1 of 3

NHTSA # 07V-363 RSB07-500-002 January, 2008

RECALL SERVICE BULLETIN

SUBJECT: Power Distribution – Bussmann® (DVEC) Dual Vehicle Electrical Center.

APPLIES TO: Certain Spartan Chassis Models Manufactured from July 5, 2006 to July 19, 2007, produced with a 2598-GG5A-002 Bussmann® DVEC and has less than 4000 miles on the vehicle.

CONDITION: Electrical power may be lost to components of the major chassis operating systems (engine, transmission, starting, cooling) causing the vehicle to shutdown and/or not be capable of powering up. Each vehicle could potentially experience a unique circumstance where one or a combination of the following conditions could occur: loss of electrical power to the engine, transmission, starting and engine cooling systems, in operation of the right chassis stop/turn signal and right trailer stop/turn signal, the anti-lock brake system (ABS), the auxiliary brake system, the heater elements in the air dryer, and the water-in-fuel separator.

CAUSE:Loose jumper connection inside the Bussmann® DVECCORRECTION:Replace Bussmann® DVEC.

PLEASE READ THE ENTIRE BULLETIN BEFORE PROCEEDING WITH ANY WORK AND CONTACT SPARTAN CHASSIS IF THERE ARE ANY CONCERNS WITH THE PROCEDURES CONTAINED IN THIS DOCUMENT

PART / SERVICE INFORMATION:

Labor Time: 1.0 Hr.

OTY.	Part Number	Description
1	S-1923-001	Kit- Bussmann® DVEC Replacement, ISC, ISL with GEN4

Kit #S-1923-001 Contains:

OTY.	Part Number	Description
1	2598-GG5B-002	Bussmann® DVEC, ISC, ISL with GEN4
1	RSB07-500-002	Document Instructions

Technical Service Bulletins are intended for use by Professional Technicians only. They are written to guide Professional Technicians in performing service to vehicles of product specific nature in conjunction with industry standards. Professional Technicians are appropriately trained on industry standards and have the tools and equipment to perform procedures safely and properly.

07025




Page 2 of 3

NHTSA # 07V-363 RSB07-500-002 January, 2008

RECALL SERVICE BULLETIN

STEP-BY-STEP INSTRUCTIONS:

- 1. Observe all industry safety standards, disconnect any necessary power source and secure vehicle to allow for replacement of the Bussmann® DVEC at the rear PDC (Power Distribution Center).
- 2. Locate the rear PDC near the engine, generally on the passenger side between the rear wheels and the rear of the vehicle.
 - 2a. Refer to FIG. 2-1. Identify the DVEC having a part number beginning with 2598-GG5A. The part number is located on the inside cover and on the lower right inside face of the box.
 - 2b. Refer to FIG. 2-1, 2-2 & 3-1. The DVEC having a part number in the top right corner of the box ending in a -1 is defective and must be replaced with a box where this number ends in -2 as shown in FIG. 3-1.






FIG. 2-2

Technical Service Bulletins are intended for use by Professional Technicians only. They are written to guide Professional Technicians in performing service to vehicles of product specific nature in conjunction with industry standards. Professional Technicians are appropriately trained on industry standards and have the tools and equipment to perform procedures safely and properly.



Page 3 of 3


NHTSA # 07V-363 RSB07-500-002 January, 2008

RECALL SERVICE BULLETIN

3. Disconnect the electrical connectors to the DVEC and remove the 4 fasteners attaching the DVEC to the mounting surface. Retain mounting fasteners for reinstallation. Replaced DVEC must be returned to Spartan Chassis Inc.

Note: Follow instructions for returning the defective DVEC to Spartan Chassis Inc.

- 4. Attach the DVEC to the mounting surface using the fasteners removed in step #3.
- 5. Connect electrical connectors to the new DVEC.
- 6. Reconnect any power source previously disconnected.



CORRECT BUSSMANN® DVEC SHOWN FIG. 3-1

Technical Service Bulletins are intended for use by Professional Technicians only. They are written to guide Professional Technicians in performing service to vehicles of product specific nature in conjunction with industry standards. Professional Technicians are appropriately trained on industry standards and have the tools and equipment to perform procedures safely and properly.