# NEWMAR CORPORATION WARRANTY DEPARTMENT

					<u>со +</u>	
DATE ISSUED	MODEL YEAR(S) AFFECTED	D MODEL(S) AFFECTED		1	TSB #	
7/3/08	2009 All DP		)	346		
Brand				Түре		
All 🗖	American Star	Mountain Aire		All 🗖	ТТ 🗖	
Cypress 🛛	Dutch Star	Kountry Aire		FW□	СА□	
Northern Star	Dutch Aire	Essex		D P 📕	DBロ	
Scottsdale	King Aire	London Aire		D1 <b>–</b>		
All Star ME	Ventana	Bay Star				
□ Air Conditioning &	Heating	Electrical Com	oonents			
□ Appliances & Accessories □ Exterior Components						
□ Cabinets & Furniture □ Interior Components						
Chassis Components Plumbing & Bath Components						
Construction Com		□ Windows, Awn	-		s	
		,	0 /	,		
	DESCRIPTION OF	F PROBLEM				
	Irregular flash rate i	n turn signals.				
	Recommended	SOLUTION				
Spartan has released CSI	308-500-03 to replace the Spartan (	Control Module (SCI nd completely prior (				

If you have any questions regarding this T.S.B., please contact a Warranty Service Representative at Newmar Corporation.



### CSB08-500-003

June, 2008 Page 1 of 3

# **CAMPAIGN SERVICE BULLETIN**

**<u>SUBJECT</u>**: Low Voltage Power Distribution – Spartan Control Module (SCM)

<u>APPLIES TO</u>: Certain Spartan Motorhome Chassis produced for Newmar, Fleetwood & Tiffin, equipped with a Spartan control module rev A-D, having a VDM (Vehicle Date of Manufacture) of October 3, 2007 through May 8, 2008.

**<u>CONDITION</u>**: Irregular flash rate in turn signals

**CORRECTION:** Replace SCM with Revision E

### PLEASE READ THE ENTIRE BULLETIN BEFORE PROCEEDING WITH ANY WORK. CONTACT SPARTAN CHASSIS IF THERE ARE ANY CONCERNS WITH THE PROCEDURES CONTAINED IN THIS DOCUMENT

### **PART / SERVICE INFORMATION:**

#### Labor Time: 1.0 Hrs.

OTY.	Part Number	Description
1	S-1963-001A	Kit- Spartan Control Module (Tiffin & Newmar)
1	S-1963-002A	Kit-Spartan Control Module (Fleetwood)
1	CSB08-500-003	Document Instructions
Kit # S-1963-	001A Contains:	
QTY.	Part Number	Description
1	2791-NN2E-001	Kit-Spartan Control Module (Tiffin & Newmar)
1	CSB08-500-003	Document Instructions
Kit # S-1963-	002A Contains:	
OTY.	Part Number	Description
4	AROA NINTAR AGA	

2791-NN2E-002Kit-Spartan Control Module (Fleetwood)CSB08-500-003Document Instructions

Technical Service Bulletins are intended for use by Professional Technicians only. They are written to guide Professional Technicians in performing service to vehicles of product specific nature in conjunction with industry standards. Professional Technicians are appropriately trained on industry standards and have the tools and equipment to perform procedures safely and properly.

08015

1




**CSB08-500-003** June, 2008 Page 2 of 3

# **CAMPAIGN SERVICE BULLETIN**

### **STEP-BY-STEP INSTRUCTIONS:**

- 1. Observe all industry safety standards, disconnect any necessary power source and secure vehicle for replacement of Spartan Control Module (SCM).
- 2. Locate main disconnect switch, normally installed on rear bulkhead in engine compartment, switch to the "off" position.
- 3. Refer to FIG. 2-1. Locate SCM in driver side front compartment or under front hood.



## SPARTAN CONTROL MODULE FIG. 2-1

Technical Service Bulletins are intended for use by Professional Technicians only. They are written to guide Professional Technicians in performing service to vehicles of product specific nature in conjunction with industry standards. Professional Technicians are appropriately trained on industry standards and have the tools and equipment to perform procedures safely and properly.



**CSB08-500-003** June, 2008 Page 3 of 3

## **CAMPAIGN SERVICE BULLETIN**

- 4. Refer to FIG. 2-1. Remove main power lug from 3/8" stud on SCM, retain nut for reuse.
- 5. Refer to FIG. 2-1. Remove two (2) connectors labeled P1 & P2 from SCM.
- 6. Refer to FIG. 2-1. Remove SCM from mounting location, retain mounting hardware for reuse. Properly dispose of control module.
- 7. Install new SCM (Rev.E) from kit, using hardware retained from previous steps. Torque to 10 lbs. ft.
- 8. Refer to FIG. 2-1. Reinstall both connectors (P1 & P2). Torque to 25 lbs. in.
- 9. Refer to FIG. 2-1. Reinstall main power cable to 3/8" power stud. Torque to 5 lbs. ft.
- 10. Reconnect any power source previously disconnected.
- 11. Return main power switch to the "on" position.

Technical Service Bulletins are intended for use by Professional Technicians only. They are written to guide Professional Technicians in performing service to vehicles of product specific nature in conjunction with industry standards. Professional Technicians are appropriately trained on industry standards and have the tools and equipment to perform procedures safely and properly.