# NEWMAR CORPORATION WARRANTY DEPARTMENT

|   | T         | ECHNICAL  | SERV         |   | FTIN |       |      |
|---|-----------|---|--------------|---|------|-------|------|
| DATE ISSUED   |           | Model Year(s) Affected  |              | Model(s) AFFECTED                             |      | TSB # |      |
| 7/28/08   |           | 2007 – 2008   |              | All on Spartan K2 & K<br>chassis w/ Hadley SL |      | 3 349 |      |
| BRAND   |           |   |              | •   | Т    | YPE   |      |
| All   |           | American Star   |              | Mountain Aire                                 |      | All 🗖 | ТТ 🗖 |
| Cypress   |           | Dutch Star  |              | Kountry Aire                                  |      | FW□   | САП  |
| Northern Star   |           | Kountry Star  |              | Essex   |      |       |      |
| Scottsdale  |           | King Aire   |              | London Aire                                   |      | D P 📕 | D B  |
| All Star ME   |           | Ventana   |              | Bay Star                                      |      |       |      |
| <ul> <li>Air Conditioning &amp; Heating</li> <li>Appliances &amp; Accessories</li> <li>Exterior Components</li> <li>Cabinets &amp; Furniture</li> <li>Interior Components</li> <li>Chassis Components</li> <li>Plumbing &amp; Bath Components</li> <li>Construction Components</li> <li>Windows, Awnings, Vents, &amp; Doors</li> </ul> DESCRIPTION OF PROBLEM Potential for chassis not to be at the proper ride height on units equipped with Hadley SLS Air Leveling system. |           |   |              |   |      |       |      |
|   |           | RECON   | IMENDED      | SOLUTION                                      |      |       |      |
| Read the attache  | d manufao | issued CSB08-330-00<br>cturers information b<br>SB should be directed | efore perfor | ming any diagnosis                            |      |       | Any  |

If you have any questions regarding this T.S.B., please contact a Warranty Service Representative at Newmar Corporation.



CSB08-330-002 July, 2008 Page 1 of 3

## **CAMPAIGN SERVICE BULLETIN**

<u>SUBJECT</u>: Air Supply System – Hadley<sup>®</sup> SLS (Self Leveling System) Ride height Control

- <u>APPLIES TO</u>: Certain Spartan K-2 & K-3 Chassis produced for Newmar & Tiffin equipped with a Hadley<sup>®</sup> SLS ride height control system and having a VDM (Vehicle Date of Manufacture) of April 18, 2007 through June 26, 2008.
- **<u>CONDITION</u>**: Potential for chassis not to be at proper ride height.

**CORRECTION:** Incorporate a diode harness

### PLEASE READ THE ENTIRE BULLETIN BEFORE PROCEEDING WITH ANY WORK. CONTACT SPARTAN CHASSIS IF THERE ARE ANY CONCERNS WITH THE PROCEDURES CONTAINED IN THIS DOCUMENT

### **PART / SERVICE INFORMATION:**

Labor Time: .50 Hrs.

 OTY.
 Part Number

 1
 S-1958-001B

#### Kit # S-1958-001B Contains:

| OTY. | Part Number   |  |  |
|------|---------------|--|--|
| 1    | 3164-GG5A     |  |  |
| 3    | T-120RO       |  |  |
| 1    | CSB08-330-002 |  |  |

Description Kit- Hadley®

Description Module Filter Harness Cable Tie Document Instructions

Technical Service Bulletins are intended for use by Professional Technicians only. They are written to guide Professional Technicians in performing service to vehicles of product specific nature in conjunction with industry standards. Professional Technicians are appropriately trained on industry standards and have the tools and equipment to perform procedures safely and properly.




CSB08-330-002

July, 2008 Page 2 of 3

# **CAMPAIGN SERVICE BULLETIN**

### **STEP-BY-STEP INSTRUCTIONS:**

- 1. Observe all industry safety standards, disconnect any necessary power source and secure vehicle for adding an additional harness to the Hadley<sup>®</sup> ride height electrical system.
- 2. Refer to FIG. 2-1. Locate the Hadley<sup>®</sup> Jack Interface Control Module. The module is typically mounted at left front corner of vehicle, either on front bulkhead or in a driver side front compartment.
- 3. Refer to FIG. 2-1 & 3-1. Trace wires from interface control module to the 16-way connector (approximately 12").
  - 3a. Slide grey secondary lock out, to disconnect connector, and re-connect appropriate connector end into each side of new harness from kit.
  - 3b. Slide grey secondary lock in, to secure harness connections.



### HADLEY® JACK INTERFACE CONTROL MODULE FIG. 2-1


Technical Service Bulletins are intended for use by Professional Technicians only. They are written to guide Professional Technicians in performing service to vehicles of product specific nature in conjunction with industry standards. Professional Technicians are appropriately trained on industry standards and have the tools and equipment to perform procedures safely and properly.



**CSB08-330-002** July, 2008 Page 3 of 3

## **CAMPAIGN SERVICE BULLETIN**

- 4. Using cable ties from kit, secure harness to protect from rubbing and chaffing.
- 5. Reconnect any power source previously disconnected.



INTERFACE CONTROL MODULE WITH MODULE FILTER HARNESS FIG. 3-1

Technical Service Bulletins are intended for use by Professional Technicians only. They are written to guide Professional Technicians in performing service to vehicles of product specific nature in conjunction with industry standards. Professional Technicians are appropriately trained on industry standards and have the tools and equipment to perform procedures safely and properly.