TECHNICAL SERVICE BULLETIN										
DATE ISSUED	MODEL YEAR(S) AFFECTED				MODEL(S) AFFECTED			TSB #		
2/25/00	SATELLITE EQUIPPED				1999-2000			201		
BRAND					Түре					
All Americ	can Star 🛛	Kountry Star		Dute	ch Star 🛛	All	Т	Т 🗖	FW 🗖	
NewAire D Mount	ain Aire 🛛	Kountry Aire		Lon	don Aire 🗖	СА 🗆	D	P□	DB 🗖	
□ Air Conditioning & Heating					Electrical Components					
<ul> <li>Appliances &amp; Accessories</li> </ul>				Exterior Components						
□ Cabinets & Furniture					Interior Components					
Chassis Compone				Plumbing &	e Bath Components					
Construction Components					☐ Windows, Awnings, Vents, & Doors					
DESCRIPTION OF PROBLEM Datron satellite information.										
See attached informatio	911.									

If you have any questions regarding this T.S.B., please contact a Warranty Service Representative at Newmar Corporation.

# NEWMAR CORPORATION WARRANTY DEPARTMENT

DATRON/TRANSCO INC.

February 17, 2000

## DBS Technical Bulletin #37

#### Subject:

Improving the performance of your DBS-4000/4500 in rain conditions

#### Purpose:

Explain the procedure for relieving some of the rain interference that may occur due to rain.

### **Detailed Description:**

We have tested a new product <u>Brillianize</u>, which help's eliminate the collection of rain on the DBS-4000/4500 domes. While RAIN X eliminates the collection of rain, Brillianize has proven to be even more effective.

It is our recommendation that you use **Brillianize**.

The Brillianize Company can be contact at **1-800-445-9344** or at any of the numbers below:

The Brillianize Company 4966 Industrial Way Benecia, Ca. 94510 707-751-0656 PH. 707-751-0545 FAX www.brillianize.com

Please feel free to contact our Technical Support Department with any additional questions at 800-287-5052.

DBS-ENG-101-37 02/18/00 10:40 AM

If you have any questions regarding this T.S.B., please contact a Warranty Service Representative at Newmar Corporation.