72185 COUNTY ROAD 3 NAPPANEE, IN 46550

NEWMAR CORPORATION WARRANTY DEPARTMENT

800.858.4924 Fax 219.773.2007

TECHNICAL SERVICE BULLETIN								
DATE ISSUED	MODEL YEAR(S) AFFECTED		D	MODEL(S) AFFECTED		TSB#		
7/6/88	1	987-1988		AI	LL	11		
BRAND				Түре				
All American Star		Kountry Star	Dut	ch Star 🛚	All T	ТП	FW □	
NewAire □ Mountain Aire □		Kountry Aire	Lon	don Aire□	СА 🗆 П	P□	DB 🗆	
■ Air Conditioning & Heating				☐ Electrical Components				
☐ Appliances & Accessories				☐ Exterior Components				
☐ Cabinets & Furniture				☐ Interior Components				
☐ Chassis Components				☐ Plumbing & Bath Components				
☐ Construction Components				☐ Windows, Awnings, Vents, & Doors				
DESCRIPTION OF PROBLEM Air flow in air conditioning installation.								
RECOMMENDED SOLUTION								
See attachment.								

NEWMAR CORPORATION WARRANTY DEPARTMENT



TECHNICAL SERVICES

TO:

ALL RV O.E.M.'S

ALL RV DISTRIBUTORS
ALL RV SERVICE CENTERS

ALL RV SERVICING DEALERS SELECTED COLEMAN RV PERSONNEL


SUBJECT:

DUCT COLLAR INSTALLATION LENGTH

Air conditioning season is here and we are finding many installers who are improperly measuring duct collar length. Trimming the duct collar for a given air conditioner application is a very important exercise. Please refer to the application figure below.

CAUTION

Do not use tape to seal duct collar to prevent possible fire and/or asphyxiation.



Measure the distance between the bottom of the air conditioner base pan and the vehicle interior ceiling line. Take the aluminum duct collar and trim its height to the measured length less 1/4".

Trimming the duct collar too long can create the following problems:

- Restricted discharge air flow due to the inward crushing of the duct collar walls.
- 2. Improper air conditioner base pan gasket compression.

B100 (10-80)

800.858.4924 Fax 219.773.2007

NEWMAR CORPORATION WARRANTY DEPARTMENT

3. Excessive pressure and/or upward bending of the air conditioner base pan. This installation condition on Coleman dash (-) model Super Mach air conditioners may result in operation noise complaints. The blower housing (scroll) for the dash (-) model Super Mach evaporative discharge impellor sits on the base pan. Excessive pressure and/or upward bending of the air conditioner base pan can close the distance between the blower housing (scroll) cutoff and the discharge impellor. This movement (clearance reduction) may create an unacceptable air flow noise.

Trimming the duct collar too short can create the following problems:

- 1. Thermostat short cycling.
- 2. Evaporative coil freezing discharge air quickly mixing with return air which may push coil temperature below 32°.
- 3. Customer complaints poor cooling performance.

R.V. CUSTOMER SERVICES
THE COLEMAN COMPANY, INC.