

NEWMAR CORPORATION WARRANTY DEPARTMENT

TECHNICAL SERVICE BULLETIN			
DATE ISSUED	MODEL YEAR(S) AFFECTED	MODEL(S) AFFECTED	TSB #
9/22/99	1999 & 2000	ALL	181
BRAND		TYPE	
All <input checked="" type="checkbox"/> American Star <input type="checkbox"/> Kountry Star <input type="checkbox"/> Dutch Star <input type="checkbox"/>		All <input checked="" type="checkbox"/> T T <input type="checkbox"/> F W <input type="checkbox"/>	
NewAire <input type="checkbox"/> Mountain Aire <input type="checkbox"/> Kountry Aire <input type="checkbox"/> London Aire <input type="checkbox"/>		C A <input type="checkbox"/> D P <input type="checkbox"/> D B <input type="checkbox"/>	
<input type="checkbox"/> Air Conditioning & Heating			
<input checked="" type="checkbox"/> Appliances & Accessories			
<input type="checkbox"/> Cabinets & Furniture			
<input type="checkbox"/> Chassis Components			
<input type="checkbox"/> Construction Components			
<input type="checkbox"/> Electrical Components			
<input type="checkbox"/> Exterior Components			
<input type="checkbox"/> Interior Components			
<input type="checkbox"/> Plumbing & Bath Components			
<input type="checkbox"/> Windows, Awnings, Vents, & Doors			
DESCRIPTION OF PROBLEM			
All units equipped with a satellite TV – reception problems.			
RECOMMENDED SOLUTION			
See the attached information.			

If you have any questions regarding this T.S.B., please contact a Warranty Service Representative at Newmar Corporation.

72185 COUNTY ROAD 3
NAPPANEE, IN 46550

NEWMAR CORPORATION WARRANTY DEPARTMENT

800.858.4924
FAX 219.773.2007



Dear Winegard Customer,

Recently, additional satellites have been launched by EchoStar (DISH Network™) and DSS®. These new "birds" have given digital satellite customers even more programming than before!

With these additions, the satellites are positioned within only a few degrees of each other. This close proximity may cause some signal acquisition problems for owners of automatic systems — the positioner may lock on the wrong signal.

There are some ways to avoid signal acquisition problems. We have included the page we are inserting in the manual for Winegard's automatic satellite system, RD-9946.

If you have any questions, please contact your Winegard Regional Manager, or telephone us at 319/754-0600, 7:30 a.m. to 4:00 p.m., CDT.

If you have any questions regarding this T.S.B., please contact a Warranty Service Representative at Newmar Corporation.

NEWMAR CORPORATION

WARRANTY DEPARTMENT

LOCATING THE SATELLITE

SUGGESTIONS FOR AVOIDING SATELLITE SIGNAL ACQUISITION ERRORS

With the addition of several new U.S. satellites, your system may encounter some difficulty locating the correct satellite on the first attempt.

To reduce searching errors, it is recommended that you use the “ENTER ELEVATION” Search Method on the Winegard Automatic Positioner. Refer to page 9 in the Operation section of this manual.

Elevation can be acquired by entering your local ZIP code in the Receiver Set-up Menu. Once you find the correct elevation, subtract 3 degrees and enter this number. Example: If you are in an area that requires 41 degrees elevation, enter 38 degrees in the Elevation Search Method.

□