TECHNICAL SERVICE BULLETIN								
DATE ISSUED	MODEL YEAR(S) AFFECTED			MODEL(S) AFFECTED			TSB #	
10/25/99 19		999 & 2000		MOTORIZED			183	
Brand					Түре			
All 🗖 Ameri	can Star 🛛	Kountry Star	Dut	ch Star 🗖	All 🗖	ТТП	FW 🗖	
NewAire 🗖 Mountain Aire 🗖		Kountry Aire	Lon	don Aire	CA	D P	DB	
Air Conditioning		Electrical Components						
□ Appliances & Accessories				Exterior Components				
□ Cabinets & Furniture				Interior Components				
Chassis Compone			Plumbing &	& Bath Components				
Construction Components				Windows, A	indows, Awnings, Vents, & Doors			
DESCRIPTION OF PROBLEM Water value failures.								
RECOMMENDED SOLUTION								
See the attached inform	nation.							

If you have any questions regarding this T.S.B., please contact a Warranty Service Representative at Newmar Corporation.

72185 COUNTY ROAD 3 NAPPANEE, IN 46550



Jamas N. Wood Vice President Sales & Marketing 701 Ann St., N.W. Grand Rapids, MI 49504

Fax 616/361-9646 Telephone 616/361-2681

NEWMAR CORPORATION

WARRANTY DEPARTMENT

October 11, 1999

Mr. Duane Casteel Newmar Corp. P.O. Box 30 Nappanee, IN 46550

Dear Duane,

Attached please find a Service Bulletin Warning of damage to the electronic water valve as a result of excessive debris in some cooling systems. In the last 3 months, Evans has seen several reports of multiple water valve failures that have been traced to this problem. Since these valves were introduced in 1997, and problems seem to be more recent, we suspect a quality problem related to the excessive debris.

Evans is investigating the possibility of offering a filter to protect the water valve, but this may only change the problem to a clogged filter. In all reported cases, the engine manufacturers has handled flushing the system as a warranty item. We believe this is the only way to prevent damage to the water valve and other components of the cooling system.

Please contact me with any questions or concerns.

Sincerely,

James N. Wood V.P. Sales & Marketing

cc: Jeff Roberts Arlan Miller

NEWMAR CORPORATION WARRANTY DEPARTMENT

800.858.4924

FAX 219.773.2007

Service Bulletin Evans Tempcon, Inc. October 1, 1999 WARNING

Excessive casting sand and metal debris in engine cooling system causing water valve damage.

Evans has had several reports recently of multiple failures of Electronic Water Valves on a single vehicle. These failures have been traced to the valve being damaged and/or blocked open by debris. This failure is not the fault of the Evans valve, but instead, is caused by an excessively contaminated cooling system.

So far all known reports have been on pusher chassis with Cummins Engines, but similar problems are possible on any chassis/engine. Symptoms are usually poor cooling, which is traced to electronic water valve not closing. When the valve is replaced, system will operate correctly, but will usually fail again soon. [In many cases less than 100 miles of operation.]

Any Electronic Water Valve that does not close is a suspect for contamination. <u>Do not</u> continue to replace valves without checking the cooling system for contamination. <u>Evans cannot pay warranty claims</u> on valves damaged by a contaminated cooling system.

To correct problem: We suggest you send the vehicle to a service facility for either the chassis or engine manufacturer, and have the entire cooling system back flushed.

Any questions, please contact your normal Evans service contact.