TECHNICAL SERVICE BULLETIN								
DATE ISSUED	MODEL YEAR(S) AFFECTED			MODEL(S) AFFECTED		,	TSB #	
04/25/01	2001			ALL			216	
BRAND					Түре			
All Americ	can Star 🛛	Kountry Star 🛛	Dut	ch Star 🛛	All 🗖	ГТ 🗖	FW 🗖	
NewAire 🗖 Mount	ain Aire 🛛	Kountry Aire	Lon	don Aire 🗖		OP□	DB 🗖	
Air Conditioning & Heating			Electrical Components					
Appliances & Accessories				Exterior Components				
Cabinets & Furniture				Interior Components				
Chassis Components				Plumbing & Bath Components				
Construction Components				Windows, Awnings, Vents, & Doors				
DESCRIPTION OF PROBLEM								
RECOMMENDED SOLUTION								
Please review the attach	ed notices.							

If you have any questions regarding this T.S.B., please contact a Warranty Service Representative at Newmar Corporation.



Technical Notice

13128 State Rt. 226, PO Box 38, Big Prairie, Ohio 44611 U.S.A. Telephone 330/496-3211 800/321-9886 Fax: 330/496-3097



Newmar Corporation TSB 216 Page 1/5

Winterization of a VacuFlush[®] Toilet System

There are two ways to winterize a SeaL and Technology toilet. The first method utilizes antifreeze, and the second requires draining of all water from the water valve.

Method 1	1. Thoroughly flush system with fresh water.		
	2. Empty holding tank.		
	3. Shut off water supply to toilet, and remove inlet waterline.		
	4. Press flush lever until all water is drained from toilet and water valve.		
	5. Drain potable water tank.		
	Add antifreeze to potable water tank. The antifreeze should be pink and contain no alcohol. DO NOT DILUTE antifreeze with water.		
	Reconnect your water inlet to the tollet. Flush the antifreeze through the system into the holding tank.		
	8. Empty holding tank.		
	9. Turn off electrical power to system.		
Method 2	1. Remove brass cap from the bottom of the water valve.		
	2. Depress flush pedal to allow water to drain out of toilet.		
	3. Allow all water to drain out of water valve and water inlet line.		
	Reattach brass cap to bottom of water valve. (Be careful not to strip plastic threads on water valve body.)		
Additional information:	Call SeaLand's Customer Service Department at 1-800-321-9886, 8 a.m. to 5 p.m. Eastern Time if you have questions or need additional information.		

⑦ Registered; ™ Trademark of SeaLand Technology, Inc. ® Taylor★Made is a registered trademark of Nelson A. Taylor Co., Inc. The Taylor Made Group logo is a trademark of Taylor Made Group, Inc. © 2000 SeaLand Technology, Inc. 11/00

If you have any questions regarding this T.S.B., please contact a Warranty Service Representative at Newmar Corporation.



Technical Bulletin

13128 State Rt. 226, P.O. Box 38, Big Prairle, Ohio 44611 U.S.A. Telephone 330/496-3211 800/321-9886 Fax: 330/496-3097

> **Bulletin Number :** Effective Date:

1019 September 2000 800.858.4924

Newmar Corporation TSB 216 Page 2/5

VacuFlush[®] Toilet System: Potential Vacuum Leak at Inlet Seal **Resulting from Improper Hose Support**

Products Affected:

VacuFlush® Vacuum Generators and Vacuum Holding Tanks.

Situation:

Long after the installation and use of a leak-free vacuum sanitation system, a small vacuum leak slowly develops in some instances. The leak may take many months or even years to develop. The leak becomes more noticeable as it eventually causes the vacuum pump to recycle about every hour.


VACUUM HOLDING TANK

Cause:

The hose from the toilet to the Vacuum Generator or Vacuum Holding Tank inlet elbow was installed so that it places a lateral, or sideways, load on the Uniseal sealing ring surrounding the inlet elbow. This load can slowly deform the Uniseal® ring until a very small vacuum leak occurs.

Locations

VACUUM GENERATOR



Corrective Action:

Reposition hose supports so that the hose does not place a sideways force on the Uniseal® sealing ring. Replace the Uniseal® ring with a new one - Part No. 342932. Be sure to lubricate the inside diameter of the seal and the outside of the inlet fitting with liquid dish soap before installing. It is usually not necessary to replace the inlet fitting.

NOTE: For reference, older Uniseal[®] sealing rings are black. New Uniseal[®] rings are white in color. The change from black to white began in March 2000.

Additional Information:

Call SeaLand's Customer Service Department at 1-800-321-9886, 8 a.m. to 5 p.m. Eastern Time if you have questions or need additional information.

> C Uniseal is a registered trademark of injection Plastics, Inc. C VacuFlush is a registered trademark of SeaLand Technology, Inc. Taylor Made is a registered trademark of Nelson A. Taylor Co., Inc. The Taylor Made Group logo is a trademark of Taylor Made Group, Inc. @ 2000 SeaLand Technology, Inc. Form No. 1019 9/00



Technical Bulletin

13128 State Rt. 226, P.O. Box 38, Blg Prairie, Ohio 44611 U.S.A. Telephone 330/496-3211 800/321-9886 Fax: 330/496-3097

Taylor Made

Bulletin Number : Effective Date:

1020 February 2001

Solvent Bonding Holding Tank Diptube to Waste Fittings Page 3/5

Product Affected: Universal Diptube Kit - Part No. 310660

Situation: Difficulty solvent bonding the Universal Diptube white WASTE ONLY fitting and white PVC pipe. The pipe does not bond to the fitting securely.

Cause: SeaLand Technology switched from black ABS pipe to white PVC pipe in the Universal Diptube Kit. If ABS cement is used instead of medium-bodied PVC cement, the joint may not bond properly.

Corrective Action: Only medium-bodied PVC cement should be used to solvent bond the diptube kit together. Always prep both surfaces of the joint with PVC primer before gluing. Apply cement to both surfaces and insert the pipe with a twisting motion. Hold the pipe and fitting together for approximately 30 seconds or until the cement sets up.



Be sure to use <u>PVC</u> primer and cement on both contact surfaces.



Insert PVC pipe into WASTE ONLY fitting with twisting motion and hold for 30 seconds.

Handle all newly assembled joints carefully until the cement has gone through the "cure" period. Recommended cure time is related to temperature as follows:

60° to 100°F (16° to 38°C): 4 hours 40° to 60°F (5° to 18°C): 8 hours 10° to 40°F (-12° to 5°C): 24 hours

Safety Precautions:

Cement and primer contain highly volatile solvents which evaporate rapidly. Avoid breathing the vapors. If necessary, use a fan to keep the work area clear of fumes. Avoid skin or eye contact. Do not use near heat sparks or open flame.

Additional Information:

nation: Call SeaLand's Customer Service Department at 1-800-321-9886, 8 a.m. to 5 p.m. Eastern Time if you have questions or need additional information.

® Taylor★Made is a registered trademark of Nelson A. Taylor Co., Inc. The Taylor Made Group logo is a trademark of Taylor Made Group, Inc. © 2001 SeaLand Technology, Inc. Form No. 1020 2/01



LAYLOR MADE

Technical Bulletin

13128 State Rt. 226, P.O. Box 38, Big Prairie, Ohio 44611 U.S.A. Telephone 330/496-3211 800/321-9886 Fax: 330/496-3097

> Bulletin Number : Effective Date:

1021 March 2001

Newmar Corporation TSB 216

SeaLand Holding Tank Vent Filter and Page 4/5 Waste Treatment Systems

Products Affected: SeaLand Vent Filter Part Nos. 310001 or 310002 (5/8"-16mm), and 310003 or 310004 (1-1/2"-38mm).



```
CAUTIONARY WARNING:
```

The SeaLand Holding Tank Vent Filter is intended for use in the vent of a holding tank that receives untreated human waste and flush water. We do not recommend using the SeaLand Vent Filter In installations where the waste coming into the holding tank has been treated through an onboard water treatment system, such as the Lectra/San[®] Type I Marine Sanitation Device*. The chemicals that are produced in the treatment process may reach a concentration that causes the filter media to smolder.

SeaLand[®] Brand Holding Tank Deodorants and other similar products intended as deodorizers are acceptable.

Additional Information: Call SeaLand's Customer Service Department at 1-800-321-9886, 8 a.m. to 5 p.m. Eastern Time if you have questions or need additional information.

* Lectra/San^e is a trademark of Raritan Engineering Company, Inc.

® Taylor★Made is a registered trademark of Nelson A. Taylor Co., Inc. The Taylor Made Group logo is a trademark of Taylor Made Group, Inc. © 2000 SeaLand Technology, Inc. Form No. 1021 3/01

If you have any questions regarding this T.S.B., please contact a Warranty Service Representative at Newmar Corporation.

NEWMAR CORPORATION WARRANTY DEPARTMENT



13128 State Rt. 226, P.O. Box 38, Blg Prairie, Ohio 44611 U.S.A. Telephone 330/496-3211 800/321-9886 Fax: 330/496-3097

March 2001

Newmar Corporation TSB 216 Page 5/5

Plastic Protective Cover for SeaLand Toilet Bowls

Products Affected: All SeaLand china toilets.

Toilets will not hold water in the bowl soon after the new vehicle/boat is delivered Situation: to the owner.

Cause: The ball seal is fouled by debris left in the bowl during installation and construction of the vehicle's interior. Sawdust, dirt, and foreign objects fall into the toilet during construction, thus fouling the ball seal.


Corrective Action: SeaLand will now cover the toilet bowl with a protective plastic film. The film should remain over the bowl until final delivery to the dealership. This will prevent any foreign objects from entering the bowl that could foul the ball seal.

> The removal of mounting components and all testing of the toilet can still be performed, because the plastic cover can be lifted and easily resealed.



Lift the plastic cover to retrieve the mounting hardware and pedal cover. However, the cover must then be resealed over the bowl.

Additional Information:



This label reminds installers that the plastic should remain in place until the unit arrives at the sales dealership.

Cail SeaLand's Customer Service Department at 1-800-321-9886, 8 a.m. to 5 p.m. Eastern Time if you have questions or need additional information.

> ® Registered; ™ Trademark of SeaLand Technology, Inc. ® Taylor Made is a registered trademark of Nelson A. Taylor Co., Inc. The Taylor Made Group logo is a trademark of Taylor Made Group, Inc. © 2000 SeaLand Technology, Inc. Form No. 1022 3/01