

NEWMAR CORPORATION WARRANTY DEPARTMENT

TECHNICAL SERVICE BULLETIN						
DATE ISSUED	MODEL YEAR(S) AFFECTED	MODEL(S) AFFECTED	TSB #			
11/12/01	2002	NewAire	232			
BRAND		TYPE				
All <input type="checkbox"/>	American Star <input type="checkbox"/>	Kountry Star <input type="checkbox"/>	Dutch Star <input type="checkbox"/>	All <input type="checkbox"/>	T T <input type="checkbox"/>	F W <input type="checkbox"/>
NewAire <input checked="" type="checkbox"/>	Mountain Aire <input type="checkbox"/>	Kountry Aire <input type="checkbox"/>	London Aire <input type="checkbox"/>	C A <input type="checkbox"/>	D P <input checked="" type="checkbox"/>	D B <input type="checkbox"/>
<input type="checkbox"/> Air Conditioning & Heating				<input type="checkbox"/> Electrical Components		
<input type="checkbox"/> Appliances & Accessories				<input type="checkbox"/> Exterior Components		
<input type="checkbox"/> Cabinets & Furniture				<input type="checkbox"/> Interior Components		
<input checked="" type="checkbox"/> Chassis Components				<input type="checkbox"/> Plumbing & Bath Components		
<input type="checkbox"/> Construction Components				<input type="checkbox"/> Windows, Awnings, Vents, & Doors		
DESCRIPTION OF PROBLEM						
Possible low air pressure switch failure. The switch will activate the light without a need when the unit has proper air pressure to operate.						
RECOMMENDED SOLUTION						
Replace the air pressure switch for the low air indicator light, part #45120, with switch, part #51962. Please use flat rate code #15461203, .5 hour.						

□

If you have any questions regarding this T.S.B., please contact a Warranty Service Representative at Newmar Corporation.