72185 COUNTY ROAD 3 NAPPANEE, IN 46550

NEWMAR CORPORATION WARRANTY DEPARTMENT

800.858.4924 Fax 219.773.2007

TECHNICAL SERVICE BULLETIN						
DATE ISSUED	ED MODEL YEAR(S) AFFECTED		Model(s) Affected		TSB#	
1/30/92	1992 A		AI	L	48	
Brand				Түре		
All	can Star Kountry Star	■ Du	tch Star 🛚	All T	T 🗆 F W 🗖	
NewAire □ Mountain Aire ■ Kountry		■ Lo	ndon Aire	C A 🗆 D	PD DBD	
■ Air Conditioning & Heating			☐ Electrical Components			
☐ Appliances & Accessories			☐ Exterior Components			
☐ Cabinets & Furniture			☐ Interior Components			
☐ Chassis Components			☐ Plumbing & Bath Components			
☐ Construction Components			☐ Windows, Awnings, Vents, & Doors			
DESCRIPTION OF PROBLEM						
RECOMMENDED SOLUTION The attached sheet from Hydro Flame should help clear up some questions that you might have on thermostat						
	n Hydro Flame should help onts. Please contact the New					

NEWMAR CORPORATION WARRANTY DEPARTMENT



PRODUCT INFORMATION UPDATE THERMOSTAT

This update is provided to help you better serve our mutual customers by simplifying trouble-shooting and repairs on furnaces.

What is a Thermostat

The thermostat is basically an on-off switch controlled by a bi-metal coil which opens and closes an electrical contact by sensing changes in ambient air temperature. When the thermostat contacts are closed, it supplies power to the blower relay, which in turn closes a connection that sends power to the blower motor. If the blower is running, the thermostat is making contact.

The thermostat Hydro Flame supplies is equipped with a heat anticipator which allows adjustment of the heating cycle. HEAT ANTICIPATOR ADJUSTMENTS ARE NOT COVERED UNDER WARRANTY.

When a heat-cool thermostat is used in conjunction with a roof air conditioner, the warranty, installation instructions and diagnostics are provided by the company that supplies the thermostat, not by Hydro Flame.

How should the thermostat be installed?

The ideal location for a thermostat is on an inside wall 48" to 54" above the floor, away from areas of abnormal heat or cold. If it is installed on an outside wall, a 3/4" minimum spacer must be used, so the thermostat will sense the temperature of the room air and not the temperature of the wall.

The wires used to connect the thermostat to the furnace must be a minimum of 22-ga. stranded wire. We recommend 18-ga. stranded wire whenever possible.

Diagnosing Problems

BLOWER DOES NOT RUN

Thermostat wires broken or disconnected

Heat anticipator burned out - no continuity through thermostat NOT COVERED UNDER OUR WARRANTY

Usually caused by a dead short (NOT COVERED UNDER WARRANTY). Do not replace the thermostat until the cause of the short is found and corrected.

Sometimes caused by a faulty relay pulling more than 1 amp. In this case, the relay and thermostat would be covered under warranty, when both are replaced.





NEWMAR CORPORATION WARRANTY DEPARTMENT

No continuity through thermostat with contacts closed, switch on, and anticipator not broken

Continuity through thermostat to furnace but blower does not run Replace thermostat

Check the following:

- . Power to the furnace
- . Tripped circuit breaker
- . Defective relay
- . Defective motor
- . Poor ground connection
- . Wire disconnected

FURNACE CYCLES TOO QUICKLY

Heat anticipator set too low for amp draw Move anticipator to a higher amp setting to lengthen cycle (ADJUSTMENT NOT COVERED UNDER WARRANTY).


HIGH TEMPERATURE VARIANCE

Heat anticipator set too high

Move anticipator to a lower amp setting to shorten cycle (ADJUSTMENT NOT COVERED UNDER WARRANTY).

NOTE: When the anticipator is properly set and the system has operated for several hours, the furnace should cycle 4 to 6 times per hour.

Calibration of Robertshaw Thermostats



- 1. Set lever to lowest position; wait 10 minutes.
- Set lever to the reading of a thermometer that is accurate and close to the thermostat. Remove cover, do not let heat from hands, breath, etc. affect calibration. Work quickly.
- 3. Hold the lever and with a blade screw driver, turn calibration shaft counter clockwise until contacts break, then slowly turn the shaft clockwise until the contacts just snap closed.
- 4. Replace cover.

NOTE: Thermostat calibration is not covered under warranty

72185 COUNTY ROAD 3 NAPPANEE, IN 46550

NEWMAR CORPORATION
WARRANTY DEPARTMENT

800.858.4924 Fax 219.773.2007

January 20, 1992

All Dealers

Dear Dealer:

In regard to warranty labor claims where you have to do work on appliances such as, refrigerators, air conditioners, furnaces, stoves, and ice makers. Please make sure that you put the serial number and model number of the appliances on the warranty claim! This will help us to process the claim faster and you will get paid faster.

The other problem is that when work is done on a motorized unit, the chassis number is put on the claim. We need the serial number of the unit. For example, if it is a Kountry Star, it would be M34-72000. This number can be found by the driver's door on a manufacturers tag. This will, also, speed up the payment of the claim.

Please let me know if you have any questions on this, or if you have any suggestions on ways that we can better serve you.

Thanks. Sincerely,

David F Garl Warranty Manager

DFG/njh