TECHNICAL SERVICE BULLETIN						
DATE ISSUED	MODEL YEAR(S) AFFECTED		CTED	TSB #		
11/04/2014	2014-2015 Essex			Recall 14V-620 TSB 411		
BRAND						
Bay Star Sport 🛛 🗖	Ventana		Essex	x X		
Bay Star 🛛	Dutch Star		King	Aire 🛛		
Canyon Star	Mountain Aire		Other	r 🗖		
Ventana LE 🛛 🗖	London Aire					
DESCRIPTION						
Newmar Corporation has decided that a defect which relates to motor vehicle safety exists in certain 2014-2015 Essex motorhomes. The affected motorhomes were equipped with a jack mounting bracket that may be attached too close to the rear airbag. These motor homes require immediate service. Continued use poses a potential safety hazard.						
RECOMMENDED ACTION						
On certain Newmar 2014-2015 Essex motorhomes built on Freightliner chassis, the rear axle jack mounting bracket may have been attached too close to the rear suspension airbag. This could damage the suspension airbag over time, potentially resulting in an air leak and suspension collapse. This could affect vehicle handling, increasing the risk of a crash causing injury and/or damage to property. For the correction, dealers will reposition the bracket. Newmar Corporation will provide owners of all affected motor homes a remedy for the potential defect at no charge for parts or labor. This remedy consists of providing clearance between the mounting bracket and airbag.						
As this defect does affect motor vehicle safety, it is recommended that you contact the Newmar service department immediately at 1-866-290-5371. An associate will assist you in making an appointment to have this repair done by an authorized Newmar Dealer or Service Center. <u>US NHTSA #</u> - 14V-620 <u>Flat Rate Code</u> - 14V620 <u>Canadian recall #</u> - 2014-372 <u>Labor time</u> - 1 side = 1.0 hr. or 2 sides = 1.5 hrs.						
<u>RECOMMENDED TOOLS</u> : Plasma cutter, protective sheet metal - 3/16" thick minimum and protective welding blanket to cover air bag. Please read this bulletin in its entirety prior to beginning any diagnosis or repairs .						

Inspection and Repair Instructions

Rear Jack "U" Channel and Airbag Clearance

• Inspect both rear jacks "U" channel clearance to the airbag. There needs to be a minimum of 3/4 inch clearance showing from top to bottom.





If less than 3/4 of inch is showing than the radius portion of the "U" channel will need removed.
 Place a protective blanket covering any exposed material (tires, harness, airlines and airbag).
 Place a metal plate between "U" channel and airbag.





• Starting below the chassis railing, cut the channel radius off down to the bottom edge of bracket.





- Paint the cut bracket edge with black paint to prevent rust. Remove protective blankets.
- Inspect and repeat process of other side of coach if needed.
- Inspect airbag for any damage. Replace airbag if any damage shows.

• The radius piece removed from bracket.





WHEN YOU KNOW THE DIFFERENCE

NEWMAR CORPORATION

Date:August 28, 2014Re:Newmar Corporation – Motor Vehicle Recall Notification

Subject: Recall Campaign No.: 14V620

This notice is sent to you as a Newmar Dealer in accordance with the requirements of the National Traffic and Motor Vehicle Safety Act. Newmar Corporation has decided that a defect which relates to motor vehicle safety exists in specific Newmar recreational vehicles.

The National Traffic and Motor Vehicle Safety Act requires that each vehicle which is subject to a recall campaign of this type must be satisfactorily repaired within a reasonable time after the owner has tendered it for repair. A failure to adequately repair within 60 days after tender of a vehicle is prima facie evidence of failure to repair within a reasonable time. If the condition is not properly repaired within a reasonable time, the owners may be entitled to an identical or reasonably equivalent vehicle at no charge or to a refund of the purchase price less a reasonable allowance for depreciation.

To avoid providing these problematic solutions, every effort must be made to promptly schedule an appointment with each owner and to repair their vehicle as soon as possible. Vehicle owners are being notified of this recall and are instructed to contact Newmar Corporation if you do not remedy the condition within five days of the mutually agreed upon service date. If the condition is not remedied within a reasonable time, they are instructed on how to contact the National Highway Traffic Safety Administration.

REASON FOR THIS RECALL

Newmar Corporation has decided that a defect which relates to motor vehicle safety exists in specific motor homes.

On certain Newmar 2014 and 2015 Essex motorhomes built on Freightliner chassis, the rear axle jack mounting bracket may have been attached to close to the rear airbag. This could cause rubbing/friction and result in damage to the airbag. These motorhomes require immediate service. These motorhomes may have risk of personal injury or a vehicle crash.

These motor homes require immediate service. Continued use poses a potential safety hazard.

This recall applies to certain Newmar Essex motorhomes built between 2/15/2013 and 6/4/2014.

DEALER CAMPAIGN RESPONSIBILITY

Dealers are to provide to all customers/owner vehicles the service of completing this campaign at no charge to the customer/owner regardless of vehicle age, vehicle mileage, or ownership at the time of repair.

REPAIR PROCEDURE

Please reference work instructions enclosed.

If you should have any questions please contact the Newmar service department at: 1-866-290-5371.

Thank you for your cooperation.

Sincerely,

Newmar Corporation



WHEN YOU KNOW THE DIFFERENCE

NEWMAR CORPORATION

Date:September 18, 2014Re:Newmar Corporation – Motor Vehicle Recall Notification

Subject: Recall Campaign No.: # 2014-372

This notice is sent to you as a Newmar Dealer in accordance with the requirements of the Canada Motor Vehicle Safety Act. Newmar Corporation has decided that a defect which relates to motor vehicle safety exists in specific Newmar recreational vehicles.

Each vehicle which is subject to a recall campaign of this type must be satisfactorily repaired within a reasonable time after the owner has tendered it for repair. A failure to adequately repair within 60 days after tender of a vehicle is prima facie evidence of failure to repair within a reasonable time. If the condition is not properly repaired within a reasonable time, the owners may be entitled to an identical or reasonably equivalent vehicle at no charge or to a refund of the purchase price less a reasonable allowance for depreciation.

To avoid providing these problematic solutions, every effort must be made to promptly schedule an appointment with each owner and to repair their vehicle as soon as possible. Vehicle owners are being notified of this recall and are instructed to contact Newmar Corporation if you do not remedy the condition within five days of the mutually agreed upon service date

REASON FOR THIS RECALL

Newmar Corporation has decided that a defect which relates to motor vehicle safety exists in specific motor homes.

On certain Newmar 2014 Essex motorhomes built on Freightliner chassis, the rear axle jack mounting bracket may have been attached too close to the rear suspension airbag. This could damage the suspension airbag over time, potentially resulting in an air leak and suspension collapse. This could affect vehicle handling, increasing the risk of a crash causing injury and/or damage to property. Correction: Dealers will reposition the bracket.

These motor homes require immediate service. Continued use poses a potential safety hazard.

This recall applies to certain Newmar Essex motorhomes built between 7/22/2013 and 4/15/2014.

DEALER CAMPAIGN RESPONSIBILITY

Dealers are to provide to all customers/owner vehicles the service of completing this campaign at no charge to the customer/owner regardless of vehicle age, vehicle mileage, or ownership at the time of repair.

REPAIR PROCEDURE

Please reference work instructions enclosed.

If you should have any questions please contact the Newmar service department at: 1-866-290-5371.

Thank you for your cooperation.

Sincerely,

Newmar Corporation

RECALL CAMPAIGN NO. # 14V620

COACH NUMBER: _____

VIN NUMBER: _____

DATE YOU RECEIVED THIS NOTICE: _____

DATE SET FOR REPAIR OF YOUR RECREATIONAL VEHICLE:

DATE REPAIR COMPLETED:

NAME OF SERVICE CENTER REPAIR
WAS COMPLETED AT: _____

SERVICE CENTER ADDRESS: _____

CUSTOMER SIGNATURE: _____

PLEASE MAIL A COPY OF THIS FORM TO NEWMAR CORPORATION UPON COMPLETION OF THIS REPAIR.

NEWMAR CORPORATION 355 N DELAWARE ST P.O. BOX 30 NAPPANEE, IN 46550-0030

Production Number	VIN Number	Date In Production
801095	4UZFCTDV1FCGJ0309	41794
801094	4UZFCTDV2ECFY1305	41772
801091	4UZFCTDV0ECFY1304	41751
801084	4UZFCTDV5ECFY4943	41718
801083	4UZFCTDV9ECFX1998	41690
801081	4UZFCTDV8ECFV7249	41660
801078	4UZFCTDV4ECFV7250	41648
801069	4UZFCTDV6ECFV7248	41589
801065	4UZFCTDV1ECFS3217	41544
801064	4UZFCTDV3ECFS3218	41551
801063	4UZFCTDVXECFS3216	41533
801058	4UZFCTDV2ECFV7246	41558
801052	4UZFCTDV6ECFS3214	41515
801051	4UZFCTDV8ECFS3215	41526
801047	4UZFCTDV8ECFJ2179	41514
801046	4UZFCTDV4ECFJ2177	41494
801038	4UZFCTDV9ECFJ2174	41414
801025	4UZFCTDV5ECFG6860	41320
801086	4UZFCTBG9FCFZ7054	41730
801085	4UZFCTBG5FCFY1336	41736
801088	4UZFCTBG3FCGF3680	41740
801104	4UZFCTBG5FCGJ5291	41837
801110	4UZFCTBG5FCGK0331	41844
801109	4UZFCTBG8FCGK5202	41848
801114	4UZFCTBG7FCGL4621	41855
Canadian Units		
Production Number	VIN Number	Date In Production
801092	4UZFCTDV9ECFY1303	41744
801048	4UZFCTDV6ECFJ2178	41505
801044	4UZFCTDV2ECFJ2176	41486
801042	4UZFCTDV0ECFJ2175	41477