

1301 STAHLEY DRIVE
BUILDING #42
NAPPANEE, IN 46550

NEWMAR CORPORATION

WARRANTY

DEPARTMENT

Dealer Svc. 866-290-5371
Customer Svc. 800-731-8300

RECALL SERVICE BULLETIN

DATE ISSUED

MODEL YEAR(S) AFFECTED

RSB #

6/21/2018

2017, 2018

461 amended

MODEL

Bay Star Sport	☐	Ventana	☐	Essex	☒
Bay Star	☐	Dutch Star	☒	King Aire	☒
Canyon Star	☐	Mountain Aire	☒	New Aire	☐
Ventana LE	☐	London Aire	☒	Other	☐

DESCRIPTION

Newmar Corporation has decided that a defect which relates to motor vehicle safety exists in specific motorhomes. NHTSA#: 16V 512 TC#: 2016-376

Issue: On certain motorhomes manufactured by Newmar Corporation, the interior front slideout fascia wood trim has the potential to separate from the slideout. If the fascia trim separates from the slideout it could possibly make contact with the occupants causing loss of control of the vehicle resulting in a crash or injury/damage.

This recall applies only to specific 2017 Mountain Aire, London Aire, Essex, King Aire and 2017- 2018 Dutch Star coaches. Please check the attached population list for specific unit numbers.

RECOMMENDED ACTION

Service Procedure: Follow attached work instructions to secure the interior front slideout fascia for recall. Also check and secure rear fascia as needed. Call the Newmar Parts Department at (800) 561-5790 to order parts for this recall. The parts will be sent to the Authorized Service Facility. No prior authorization is needed to complete repair. For technical assistance contact your Service Account Manager.

Flat Rate Code: 16v 512

Labor Time: .2hr

Please read this bulletin in its entirety prior to beginning any diagnosis or repairs.

If you have any questions regarding this R.S.B., please contact a Warranty Service Representative at Newmar Corporation.



WHEN YOU KNOW THE DIFFERENCE

NEWMAR CORPORATION

NEWMARCORP.COM

Date: June 12, 2018
Re: Newmar Corporation – Motor Vehicle Recall Notification

Subject: Recall Campaign No.: 16V 512

This notice is sent to you as a Newmar Dealer in accordance with the requirements of the National Traffic and Motor Vehicle Safety Act. Newmar Corporation has decided that a defect which relates to motor vehicle safety exists in specific Newmar recreational vehicles.

The National Traffic and Motor Vehicle Safety Act requires that each vehicle, which is subject to a recall campaign of this type, must be satisfactorily repaired within a reasonable time after the owner has tendered it for repair. A failure to adequately repair within 60 days after tender of a vehicle is prima facie evidence of failure to repair within a reasonable time. To avoid providing these problematic solutions, every effort must be made to promptly schedule an appointment with each owner and to repair their vehicle as soon as possible. Vehicle owners are being notified of this recall. If the condition is not remedied within a reasonable time, they are instructed on how to contact the National Highway Traffic Safety Administration.

REASON FOR THIS RECALL

Newmar Corporation has decided that a defect, which relates to motor vehicle safety, exists in specific motor homes.

On Certain motorhomes manufactured by Newmar Corporation, the front fascia wood trim has the potential to separate from the slide out. If the fascia trim separates from the slide out it could possibly make contact with the occupants causing loss of control of the vehicle resulting in a crash or injury/damage. Correction: Newmar will secure the fascia trim to the slide out.

The motorhomes require immediate service. Continued use poses a potential safety hazard.

DEALER CAMPAIGN RESPONSIBILITY

Dealers are to provide to all customers/owner vehicles the service of completing this campaign at no charge to the customer/owner regardless of vehicle age, vehicle mileage, or ownership at the time of repair.

REPAIR PROCEDURE

Newmar Corporation will provide the work instructions.

If you should have any questions please contact the Newmar service department at: 1-866-290-5371.

Thank you for your cooperation.

Sincerely,

Newmar Corporation



WHEN YOU KNOW THE DIFFERENCE

NEWMAR CORPORATION

NEWMARCORP.COM

IMPORTANT SAFETY RECALL

This notice applies to your vehicle VIN. # _____

Date: June 12, 2018

Motor Vehicle Recall Notification - Recall Campaign No. 16V 512

Dear Valued Customer:

This notice is sent to you in accordance with the requirements of the National Traffic and Motor Vehicle Safety Act.

REASON FOR THIS RECALL

Newmar Corporation has decided that a defect which relates to motor vehicle safety exists in specific motorhomes.

On Certain motorhomes manufactured by Newmar Corporation, the front fascia wood trim has the potential to separate from the slide out. If the fascia trim separates from the slide out it could possibly make contact with the occupants causing loss of control of the vehicle resulting in a crash or injury/damage. Correction: Newmar will secure the fascia trim to the slide out.

The motorhomes require immediate service. Continued use poses a potential safety hazard.

The Safety Risk

If the fascia trim separates from the slide out it could possibly make contact with the driver or passenger causing loss of control of the vehicle resulting in a crash or injury/damage.

WHAT WE WILL DO

Newmar Corporation will provide owners of all affected motor homes a remedy for the potential defect at no charge for parts or labor. This remedy consists of replacing how the fascia trim is secured to the slide out.

WHAT YOU NEED TO DO

As this defect does affect motor vehicle safety, it is recommended that you contact the Newmar service department immediately at **1-800-731-8300**. An associate will assist you in making an appointment to have this repair done by authorized Newmar Service Facility.

Federal regulations require that any vehicle lessor receiving this recall notification must forward a copy of this notice to the lessee within ten days.

If you have had the repair performed before receiving this letter, you may be eligible to receive reimbursement for the cost of obtaining a pre-notification remedy. For additional information contact Newmar Corporation at:

Service Department
Newmar Corporation
355 N Delaware St
Nappanee, IN 46550-0030

Newmar dealers are best equipped to obtain parts and provide service to ensure your vehicle is corrected as promptly as possible. HOWEVER, if you take your vehicle to your dealer on the scheduled date and this condition is not remedied on that date or within five days; please contact the Newmar Corporation Customer Service Department at 1-800-731-8300. You may also submit a complaint to the Administrator, National Highway Traffic Safety Administration, 1200 New Jersey Ave., SE., Washington DC 20590; or call the toll-free Vehicle Safety Hotline at 1-888-327-4236 (TTY: 1-800-424-9153); or go to <http://www.safercar.gov>.

If you no longer own this vehicle, please furnish us the complete name and address of the person or dealership you sold or traded your vehicle to. Thank you for your cooperation.

Your safety and satisfaction with your Newmar product is important to us and we regret any inconvenience to you.

Sincerely,

Newmar Corporation

HOW TO SECURE FASCIA AT FRONT OF HWH FLAT FLOOR SLIDEOUT

RELEVANT COACHES

Brand: Dutch Star, Mountain Aire, London Aire, Essex, King Aire

Year(s): Early 2017 Models

Floorplan: All floorplans with HWH Flat Floor Slideout

AMENDMENT (6/2018):

Brand: Dutch Star

Year: 2018

Floorplan: 3718, 3736, 4002, 4310, 4311, 4326, 4327, 4362, 4369

ISSUE

Recall: NHTSA# 16V 512, TC# 2016-376 / 2018-314. The front fascia wood trim has the potential to separate from the slideout. If the fascia front trim separates from the slideout, it could possibly make contact with the occupants of the motorhome, causing loss of control of the vehicle and/or resulting in a crash or injury/damage.

ACTION

Follow the service procedure below to correct the condition. The approximate time to complete this repair is two-tenths of an hour (.2 hr).

NECESSARY TOOLS & REPLACEMENT PARTS

Screw Gun
6" x #2 Square Bit
Flashlight

Part Name	Part Quantity	Newmar Part Number
#8 x 1 1/4" Washer Head Screw	.004 (4 Washer Head Screws)	25826



NOTICE

Due to the recall status, dealers are unable to place a Comnet order for the screws. Call the Newmar Parts Department @ (800)561-5790 to order parts. They will be sent at no charge.

SERVICE PROCEDURE

FRONT FASCIA INSTRUCTIONS



STEP 1

Verify the coach has a HWH Flat Floor Slideout and determine which side of the unit it is on (this will vary by model and floorplan). Check the recall population list for the coach number. Early 2017 model year coaches were built with the front slideout fascia being attached with magnets and will need to be secured with screws.

On 2018 Dutch Star coaches, the fascia leg above the end table may be attached with foam tape and/or a couple of pin nails.



IMPORTANT

There is no need to remove the existing magnets or steel plates in order to secure the fascia with screws.

STEP 2

Move the driver and or passenger seat forward, and retract the HWH Flat Floor Slideout.

STEP 3

Install a minimum of three screws on the front vertical slide fascia column. The screws will need to be installed from the back side of the structural fascia close to the steel frame of the HWH system. Screws should be placed within one foot of the bottom, within one foot of the top and near the middle of the column (avoiding the magnet and steel plate). The exact placement of the screws is not as important as securing the decorative fascia's wood backers to the structural fascia.



NOTICE

On London Aire coaches, the decorative fascia does not have a solid back. Pull the fascia off and mark the backer's location, then install screws from the back side of the fascia into the backer areas as explained above.

Be aware of the magnet and steel magnet backer locations. Do NOT run screws in these locations. The front vertical decorative fascia can be pulled off to determine the exact locations of the magnets.



NOTICE

On King Aire coaches, install an additional screw into the top fascia block, as it is separate from the vertical column.



The screw should be installed on the opposite side of the steel HWH frame and near the outer edge of the structural fascia to miss steel magnet plate.

Production #	VIN Number	Model Year	Brand	Type	Floor Plan	Chassis	Date In	Date Off
USA Units								
501327	4VZVU1E90HC081288	2017	LA	DP	4513 S		12/9/2015	12/16/2015
501337	4VZVU1E94HC081133	2017	LA	DP	4553 S		2/10/2016	2/18/2016
501339	4VZVU1E99HC082214	2017	LA	DP	4533 S		5/12/2016	5/20/2016
501441	4UZFACTBG1HCHZ7803	2017	LA	DP	4553 FL		5/24/2016	6/2/2016
501447	4VZVU1E96HC082445	2017	LA	DP	4519 S		6/3/2016	6/13/2016
501448	4UZFACTBG0HCJA0484	2017	LA	DP	4553 FL		6/13/2016	6/21/2016
501453	4UZFACTBG8HCJA2886	2017	LA	DP	4513 FL		6/13/2016	6/22/2016
530361	4VZVU1E92HC081132	2017	KG	DB	4519 S		1/22/2016	2/1/2016
530365	4VZVU1E90HC081131	2017	KG	DB	4584 S		2/9/2016	2/17/2016
530371	4VZVU1E92HC082216	2017	KG	DB	4519 S		5/13/2016	5/25/2016
530373	4VZVU1E90HC082277	2017	KG	DB	4584 S		6/20/2016	6/28/2016
605925	4UZFCHCY9HCHP4113	2017	DS	DP	4054 FL		1/26/2016	2/3/2016
605953	4UZFCHCYXHCHV9345	2017	DS	DP	4369 FL		2/24/2016	3/4/2016
605954	4UZACHCY4HCHP4112	2017	DS	DP	3736 FL		2/16/2016	2/24/2016
606031	4VZAU1D94HC082119	2017	DS	DP	4018 S		5/13/2016	5/23/2016
606032	4VZAU1D90HC082120	2017	DS	DP	4369 S		5/13/2016	5/24/2016
606049	4UZFCHCY8HCHY5412	2017	DS	DP	4369 FL		5/12/2016	5/23/2016
606050	4UZFCHCY7HCHZ7793	2017	DS	DP	4369 FL		5/17/2016	5/26/2016
606051	4UZFCHCY8HCHZ7785	2017	DS	DP	4018 FL		5/16/2016	5/24/2016
606052	4UZFCHCY3HCHZ7791	2017	DS	DP	4369 FL		5/18/2016	5/26/2016
606055	4UZFCHCY3HCJA2878	2017	DS	DP	4369 FL		6/14/2016	6/22/2016
606056	4UZFCHCY0HCHZ7795	2017	DS	DP	4310 FL		5/20/2016	5/31/2016
606057	4UZFCHCY2HCHZ7796	2017	DS	DP	4310 FL		5/20/2016	6/1/2016
606058	4UZFCHCY6HCHZ7798	2017	DS	DP	4369 FL		5/23/2016	6/2/2016
606059	4UZFCHCY4HCHZ7797	2017	DS	DP	4369 FL		5/24/2016	6/2/2016
606060	4UZFCHCY8HCHZ7799	2017	DS	DP	4311 FL		5/18/2016	6/1/2016
606061	4UZFCHCY9HCHZ7794	2017	DS	DP	4369 FL		5/18/2016	5/26/2016
606064	4UZFCHCY3HCHZ7788	2017	DS	DP	4018 FL		5/25/2016	6/3/2016
606065	4UZFCHCY0HCJA0473	2017	DS	DP	4310 FL		5/31/2016	6/8/2016
606066	4UZFCHCY4HCJA0475	2017	DS	DP	4369 FL		6/8/2016	6/17/2016
606068	4UZFCHCYXHCA2876	2017	DS	DP	4369 FL		6/8/2016	6/17/2016
606069	4UZFCHCY5HCJA7967	2017	DS	DP	4369 FL		6/14/2016	6/23/2016
606071	4UZFCHCY2HCJA0474	2017	DS	DP	4369 FL		5/31/2016	6/8/2016
606074	4UZFCHCY8HCJA0477	2017	DS	DP	4369 FL		6/1/2016	6/9/2016
606076	4UZFCHCY6HCJA0476	2017	DS	DP	4369 FL		6/2/2016	6/10/2016
606078	4UZACHCY3GCHW0152	2017	DS	DP	3736 FL		6/15/2016	6/23/2016
606079	4UZFCHCY5HCHZ7792	2017	DS	DP	4369 FL		5/19/2016	5/27/2016
606081	4UZACHCY7GCHW0154	2017	DS	DP	3736 FL		6/9/2016	6/17/2016
606082	4UZFCHCY1HCHZ7787	2017	DS	DP	4018 FL		5/25/2016	6/6/2016
606083	4UZFCHCYXHCHZ7786	2017	DS	DP	4018 FL		5/16/2016	5/25/2016
606084	4UZFCHCY7HCJA0468	2017	DS	DP	4018 FL		6/15/2016	6/24/2016
606086	4UZFCHCY8HCJB5853	2017	DS	DP	4311 FL		6/20/2016	6/28/2016
606094	4UZACHCY0HCJA0466	2017	DS	DP	3736 FL		6/23/2016	7/11/2016
606095	4UZFCHCY1HCJA0479	2017	DS	DP	4369 FL		6/2/2016	6/10/2016
606096	4UZFCHCY9HCJA0469	2017	DS	DP	4054 FL		6/16/2016	6/24/2016
606099	4UZFCHCY5HCJA2879	2017	DS	DP	4369 FL		6/16/2016	6/24/2016
606107	4UZACHCY1GCHW0151	2017	DS	DP	3736 FL		6/3/2016	6/13/2016
606124	4UZFCHCY5HCJA6754	2017	DS	DP	4018 FL		6/20/2016	6/28/2016
606125	4UZFCHCY5HCJA0470	2017	DS	DP	4002 FL		6/21/2016	6/29/2016
606126	4UZFCHCY5HCHZ7789	2017	DS	DP	4018 FL		6/6/2016	6/14/2016
606134	4UZFCHCYXHCA0478	2017	DS	DP	4369 FL		5/27/2016	6/7/2016
606135	4UZACHCY5GCHW0153	2017	DS	DP	3736 FL		6/7/2016	6/15/2016
606141	4UZFCHCY5HCJA0467	2017	DS	DP	4018 FL		6/10/2016	6/20/2016

Production #	VIN Number	Model Year	Brand	Type	Floor Plan	Chassis	Date In	Date Off
606144	4UZACHCY8HCJA2871	2017	DS	DP	3736	FL	6/29/2016	7/15/2016
606145	4UZACHCY3HCHZ7784	2017	DS	DP	3736	FL	6/21/2016	6/30/2016
606146	4UZFCHCY2HCJA2872	2017	DS	DP	4018	FL	6/22/2016	6/30/2016
606153	4UZFCHCY3HCJA2881	2017	DS	DP	4369	FL	6/17/2016	6/27/2016
606161	4UZFCHCY0HCJA4751	2017	DS	DP	4369	FL	6/29/2016	7/15/2016
606181	4UZFCHCY1HCJA2880	2017	DS	DP	4310	FL	6/27/2016	7/13/2016
606182	4UZFCHCY4HCJA2873	2017	DS	DP	4002	FL	6/30/2016	7/18/2016
606185	4UZFCHCY2HCJA4749	2017	DS	DP	4018	FL	6/27/2016	7/14/2016
606756	4VZAU1D92JC085185	2018	DS	DP	4369	S	3/20/2018	3/27/2018
606814	4UZFCHFE7KCKD9170	2018	DS	DP	4369	FL	2/28/2018	3/8/2018
606815	4VZAU1D90JC085377	2018	DS	DP	4369	S	4/10/2018	4/17/2018
606862	4UZFCHFE6JCJZ9697	2018	DS	DP	4311	FL	3/7/2018	3/15/2018
606894	4UZFCHFE8KCKD1269	2018	DS	DP	4369	FL	3/28/2018	4/5/2018
606907	4VZAU1D94JC085401	2018	DS	DP	4369	S	4/13/2018	4/23/2018
606918	4VZAU1D94JC085186	2018	DS	DP	4369	S	3/21/2018	3/29/2018
606925	4UZACHFE9KCKF8622	2018	DS	DP	3736	FL	3/13/2018	3/20/2018
606926	4UZACHFE4KCKH4405	2018	DS	DP	3718	FL	4/11/2018	4/19/2018
606928	4UZFCHFE9KCKF8626	2018	DS	DP	4002	FL	4/18/2018	4/26/2018
606934	4UZFCHFE2KCKJ5752	2018	DS	DP	4369	FL	4/24/2018	5/1/2018
606956	4UZFCHFE9KCKD9171	2018	DS	DP	4369	FL	3/14/2018	3/21/2018
606958	4UZACHFE3KCKD1268	2018	DS	DP	3718	FL	3/23/2018	4/2/2018
606959	4UZFCHFE5KCKE8403	2018	DS	DP	4002	FL	3/29/2018	4/6/2018
606962	4UZFCHFE1KCKM9892	2018	DS	DP	4002	FL	4/24/2018	5/1/2018
606963	4UZFCHFE0KCKF4383	2018	DS	DP	4002	FL	4/3/2018	4/11/2018
606982	4UZFCHFE5KCKF8624	2018	DS	DP	4002	FL	3/22/2018	3/29/2018
606983	4UZFCHFE9KCKD5601	2018	DS	DP	4369	FL	2/23/2018	3/2/2018
606985	4UZFCHFE9KCKD7999	2018	DS	DP	4002	FL	3/14/2018	3/21/2018
607050	4VZAU1D98JC085403	2018	DS	DP	4369	S	4/20/2018	4/27/2018
607055	4UZFCHFE9KCKF4388	2018	DS	DP	4369	FL	4/6/2018	4/13/2018
607069	4VZAU1D92JC085378	2018	DS	DP	4369	S	4/13/2018	4/20/2018
607073	4VZAU1D92JC085445	2018	DS	DP	4369	S	4/20/2018	4/30/2018
607075	4UZFCHFE6KCKL1212	2018	DS	DP	4327	FL	4/26/2018	5/4/2018
607080	4UZFCHFE0KCKM9897	2018	DS	DP	4369	FL	4/27/2018	5/4/2018
607100	4UZFCHFE2KCKD9173	2018	DS	DP	4369	FL	3/15/2018	3/22/2018
607101	4UZFCHFE2KCKE8407	2018	DS	DP	4369	FL	4/4/2018	4/11/2018
607102	4VZAU1D91JC085176	2018	DS	DP	4369	S	3/16/2018	3/23/2018
607103	4UZFCHFE0KCKJ5751	2018	DS	DP	4369	FL	4/17/2018	4/25/2018
607104	4UZFCHFE2KCKH4408	2018	DS	DP	4369	FL	4/5/2018	4/12/2018
607105	4VZAU1D96JC085254	2018	DS	DP	4369	S	3/29/2018	4/6/2018
607114	4VZAU1D9XJC085032	2018	DS	DP	4369	S	3/2/2018	3/9/2018
607116	4VZAU1D90JC085072	2018	DS	DP	4362	S	3/2/2018	3/12/2018
607117	4VZAU1D99JC085085	2018	DS	DP	4002	S	3/8/2018	3/16/2018
607125	4VZAU1D94JC084295	2018	DS	DP	4369	S	4/19/2018	4/26/2018
607128	4VZAU1D96JC085190	2018	DS	DP	4369	S	3/29/2018	4/6/2018
607151	4VZAU1D96JC085402	2018	DS	DP	4369	S	4/20/2018	4/27/2018
607155	4VZAU1D96JC085464	2018	DS	DP	4369	S	4/25/2018	5/3/2018
607156	4VZAU1D96JC085447	2018	DS	DP	4369	S	4/26/2018	5/3/2018
607157	4VZAU1D98JC085465	2018	DS	DP	4369	S	5/1/2018	5/8/2018
607158	4UZFCHFE2KCKL1210	2018	DS	DP	4369	FL	4/26/2018	5/3/2018
607167	4VZAU1D92JC085073	2018	DS	DP	4369	S	3/2/2018	3/12/2018
607172	4VZAU1D90JC085010	2018	DS	DP	4369	S	2/23/2018	3/5/2018
607181	4UZFCHFE0KCKD9172	2018	DS	DP	4327	FL	4/4/2018	4/11/2018
607183	4VZAU1D96JC085075	2018	DS	DP	4362	S	3/6/2018	3/14/2018
607200	4UZACHFE1KCKD5593	2018	DS	DP	3736	FL	3/19/2018	3/26/2018

Production #	VIN Number	Model Year	Brand	Type	Floor Plan	Chassis	Date In	Date Off
607202	4VZAU1D91JC085257	2018	DS	DP	4369	S	4/4/2018	4/11/2018
607209	4UZCFHFE7KCKM9900	2018	DS	DP	4369	FL	5/1/2018	5/8/2018
607217	4VZAU1D98JC085255	2018	DS	DP	4369	S	4/2/2018	4/10/2018
607223	4VZAU1D96JC085089	2018	DS	DP	4326	S	3/15/2018	3/22/2018
607225	4UZCFHFE0KCKD9169	2018	DS	DP	4369	FL	3/7/2018	3/14/2018
607227	4VZAU1D94JC085074	2018	DS	DP	4362	S	3/5/2018	3/12/2018
607228	4VZAU1D94JC085088	2018	DS	DP	4362	S	3/12/2018	3/19/2018
607229	4UZCFHFE8KCKF4387	2018	DS	DP	4326	FL	3/15/2018	3/22/2018
607240	4UZCFHFE0KCKH4407	2018	DS	DP	4369	FL	4/6/2018	4/16/2018
607244	4VZAU1D98JC085188	2018	DS	DP	4362	S	3/26/2018	4/3/2018
607245	4VZAU1D92JC085087	2018	DS	DP	4369	S	3/12/2018	3/20/2018
607246	4VZAU1D9XJC085189	2018	DS	DP	4362	S	3/26/2018	4/3/2018
607247	4VZAU1D94JC085012	2018	DS	DP	4310	S	2/28/2018	3/7/2018
607249	4VZAU1D9XJC085175	2018	DS	DP	4369	S	3/16/2018	3/23/2018
607251	4UZCFHFEXKCKK2674	2018	DS	DP	4369	FL	4/23/2018	5/1/2018
607254	4VZAU1D94JC085253	2018	DS	DP	4369	S	3/28/2018	4/5/2018
607256	4UZCFHFE6KCKL1209	2018	DS	DP	4369	FL	4/9/2018	4/16/2018
607260	4VZAU1D93JC085258	2018	DS	DP	4362	S	4/4/2018	4/12/2018
607263	4VZAU1D94JC085446	2018	DS	DP	4369	S	4/24/2018	5/1/2018
607265	4UZCFHFE1KCKK2675	2018	DS	DP	4369	FL	4/24/2018	5/2/2018
607274	4VZAU1D90JC085251	2018	DS	DP	4002	S	4/2/2018	4/9/2018
607280	4UZCFHFE2KCKM9898	2018	DS	DP	4326	FL	4/30/2018	5/7/2018
607284	4VZAU1D98JC085031	2018	DS	DP	4369	S	3/2/2018	3/9/2018
607293	4UZCFHFE4KCKH4409	2018	DS	DP	4369	FL	4/11/2018	4/19/2018
607302	4VZAU1D9XJC085256	2018	DS	DP	4362	S	4/3/2018	4/10/2018
607304	4UZACHFE5KCKK2673	2018	DS	DP	3736	FL	4/18/2018	4/25/2018
607311	4VZAU1D99JC085376	2018	DS	DP	4327	S	4/9/2018	4/16/2018
607312	4UZACHFE3KCKK2672	2018	DS	DP	3718	FL	4/17/2018	4/24/2018
607313	4VZAU1D9XJC085404	2018	DS	DP	4369	S	4/20/2018	4/30/2018
801196	4VZVU1E99HC081130	2017	EX	DP	4553	S	12/14/2015	1/7/2016
801202	4UZFACTBG1HCHP4120	2017	EX	DP	4533	FL	2/2/2016	2/10/2016
801212	4VZVU1E9XHC082285	2017	EX	DP	4519	S	5/24/2016	6/3/2016
801213	4UZFACTBG1HCJA2888	2017	EX	DP	4519	FL	6/15/2016	6/23/2016
801214	4VZVU1E90HC082313	2017	EX	DP	4519	S	6/6/2016	6/15/2016
801215	4UZFACTBG0HCJA0503	2017	EX	DP	4519	FL	5/26/2016	6/6/2016
904443	4VZAU1E96HC081116	2017	MA	DP	4519	S	12/4/2015	12/11/2015
904458	4UZFACTBG3HCHP4118	2017	MA	DP	4513	FL	2/5/2016	2/15/2016
904467	4UZFACTBG3HCHZ1906	2017	MA	DP	4553	FL	6/9/2016	6/20/2016
904468	4VZVU1E90HC082215	2017	MA	DP	4533	S	6/21/2016	6/29/2016
904469	4VZAU1E97HC080685	2017	MA	DP	4553	S	5/19/2016	5/27/2016
904470	4UZFACTBG6HCHY6232	2017	MA	DP	4553	FL	5/27/2016	6/7/2016
904473	4UZFACTBG4HCHY6231	2017	MA	DP	4553	FL	5/23/2016	6/2/2016
904475	4VZAU1E97GC081396	2017	MA	DP	4519	S	6/14/2016	6/22/2016
904476	4UZFACTBG5HCHZ1907	2017	MA	DP	4525	FL	6/17/2016	6/28/2016
904478	4UZFACTBG1HCHZ1905	2017	MA	DP	4553	FL	6/3/2016	6/14/2016

Canadian units

501440	4UZFACTBG3HCHZ7804	2017	LA	DP	4553	FL	5/31/2016	6/9/2016
501442	4VZVU1E94HC082217	2017	LA	DP	4533	S	5/27/2016	6/8/2016
605895	4UZFCHCYXHCHV8728	2017	DS	DP	4369	FL	2/15/2016	2/23/2016
606053	4UZFCHCY1HCJA2877	2017	DS	DP	4369	FL	6/7/2016	6/16/2016
606120	4UZFCHCY9HCJA0472	2017	DS	DP	4369	FL	5/26/2016	6/6/2016