

1301 STAHLEY DRIVE
BUILDING #42
NAPPANEE, IN 46550

NEWMAR CORPORATION

WARRANTY

DEPARTMENT

Dealer Svc. 866-290-5371
Customer Svc. 800-731-8300

PRODUCT INFORMATION BULLETIN

DATE ISSUED	MODEL YEAR(S) AFFECTED	PIB #
10/12/2017	2018	496

MODEL

Bay Star Sport	<input type="checkbox"/>	Ventana	<input type="checkbox"/>	Essex	<input type="checkbox"/>
Bay Star	<input type="checkbox"/>	Dutch Star	<input type="checkbox"/>	King Aire	<input type="checkbox"/>
Canyon Star	<input type="checkbox"/>	Mountain Aire	<input type="checkbox"/>	New Aire	<input checked="" type="checkbox"/>
Ventana LE	<input type="checkbox"/>	London Aire	<input type="checkbox"/>	Other	<input type="checkbox"/>

PRODUCT INFORMATION

This Product Information Bulletin's purpose is to inform technicians that when working on the 2018 New Aire HVAC system, there is an extra zone thermostat sensor installed in the driver's side slideout. It is often located in the rear overhead cabinet on coaches built prior to 9/15/17.

The extra sensor is not hooked up or operational. Do not spend time diagnosing the extra thermostat sensor. It has been eliminated, and the location of the three active zone sensors has been changed starting with production #710224 beginning on 9/15/2017.

On coaches built after this date, this fourth zone sensor will no longer be installed during production. The remaining zone sensors are located in the front wall of the driver's side slideout on the valance, in the bottom of the medicine cabinet in the bathroom, and on the driver's side of the wardrobe wall.

If you have any questions regarding this P.I.B., please contact a Warranty Service Representative at Newmar Corporation.