

NEWMAR CORPORATION

WARRANTY

DEPARTMENT

PRODUCT INFORMATION BULLETIN

DATE ISSUED	MODEL YEAR(S) AFFECTED	PIB #
4/12/2018	2018	511

MODEL

Bay Star Sport	<input type="checkbox"/>	Ventana	<input type="checkbox"/>	Essex	<input checked="" type="checkbox"/>
Bay Star	<input type="checkbox"/>	Dutch Star	<input type="checkbox"/>	King Aire	<input checked="" type="checkbox"/>
Canyon Star	<input type="checkbox"/>	Mountain Aire	<input checked="" type="checkbox"/>	New Aire	<input checked="" type="checkbox"/>
Ventana LE	<input type="checkbox"/>	London Aire	<input checked="" type="checkbox"/>	Other	<input type="checkbox"/>

PRODUCT INFORMATION

Certain Dash Xite Radio USB Inputs may have been spliced without the shield of the cable properly attached. If affected, the USB ports may not be active as the USB input to the Xite Infotainment center. The affected USB input is normally located on the driver side console

Non-working USB cables may be replaced with unmodified cables (Newmar part# 110664) to fix the issue.



USB Typical Location on Driver Side



Newmar part # 110664