

1301 STAHLEY DRIVE
BUILDING #42
NAPPANEE, IN 46550

NEWMAR CORPORATION

WARRANTY

DEPARTMENT

Dealer Svc. 866-290-5371
Customer Svc. 800-731-8300

RECALL SERVICE BULLETIN

DATE ISSUED

MODEL YEAR(S) AFFECTED

RSB #

4/26/2018

2018

519

MODEL

Bay Star Sport	☒	Ventana	☒	Essex	☒
Bay Star	☒	Dutch Star	☒	King Aire	☒
Canyon Star	☒	Mountain Aire	☒	New Aire	☒
Ventana LE	☒	London Aire	☒	Other	☐

DESCRIPTION

Newmar Corporation has decided that a defect relating to motor vehicle safety exists in specific motorhomes. Recall NHTSA 18V 236, TC 2018-182.

On certain motorhomes, there may be loose electrical connections in the breaker box that were not properly tightened. A loose power connection may cause a buildup of heat at the connection, potentially increasing the risk of overheating or a fire causing injury and/or damage to property.

Correction: Dealers will inspect the electrical connections in the breaker box and repair as necessary.

Affected Units: Refer to the attached population list for specific coach and VIN numbers.

RECOMMENDED ACTION

Inspect the breaker box. Torque the electrical connections to the specified torque listed on the breaker box cover. Submit the claim.

If the breaker box and/or wiring are damaged from heat buildup, submit photos and contact your Newmar Service Account Manager for authorization of additional labor time and/or parts.

Flat Rate Code: 18V 236

Labor time: .3 hr.

Please read this bulletin in its entirety prior to beginning any diagnosis or repairs.

If you have any questions regarding this R.S.B., please contact a Warranty Service Representative at Newmar Corporation.



WHEN YOU KNOW THE DIFFERENCE

NEWMAR CORPORATION

NEWMARCORP.COM

Date: April 25, 2018
Re: Newmar Corporation – Motor Vehicle Recall Notification

Subject: Recall Campaign No.: 18V 236

This notice is sent to you as a Newmar Dealer in accordance with the requirements of the National Traffic and Motor Vehicle Safety Act. Newmar Corporation has decided that a defect that relates to motor vehicle safety exists in specific Newmar recreational vehicles.

The National Traffic and Motor Vehicle Safety Act requires that each vehicle, which is subject to a recall campaign of this type, must be satisfactorily repaired within a reasonable time after the owner has tendered it for repair. A failure to adequately repair within 60 days after tender of a vehicle is prima facie evidence of failure to repair within a reasonable time. To avoid providing these problematic solutions, every effort must be made to promptly schedule an appointment with each owner and to repair their vehicle as soon as possible. Vehicle owners are being notified of this recall. If the condition is not remedied within a reasonable time, they are instructed on how to contact the National Highway Traffic Safety Administration.

REASON FOR THIS RECALL

Newmar Corporation has decided that a defect that relates to motor vehicle safety exists in specific motorhomes.

On certain motorhomes, there may be a loose electrical connection in the breaker box that was not properly tightened. A loose power connection may cause a buildup of heat at the connection, which would increase the risk of overheating or a fire causing injury and/or damage to property. Correction: Dealers will inspect the electrical connections in the breaker box and repair as necessary.

Motorhomes included in this recall include: 2018 Bay Star Sport, Bay Star, Canyon Star, Ventana, Ventana LE, Dutch Star, New Aire, Mountain Aire, London Aire, Essex and King Aire Class A motorhomes built between 06/02/2017 and 10/12/2017.

These motorhomes require immediate service. Continued use poses a potential safety hazard.

DEALER CAMPAIGN RESPONSIBILITY

Dealers are to provide to all customers/owner vehicles the service of completing this campaign at no charge to the customer/owner regardless of vehicle age, vehicle mileage, or ownership at the time of repair.

REPAIR PROCEDURE

Newmar will provide the work instructions

If you should have any questions please contact your service account manager direct or the Newmar service department at: 1-866-290-5371.

Thank you for your cooperation.

Sincerely,

Newmar Corporation



WHEN YOU KNOW THE DIFFERENCE

NEWMAR CORPORATION

NEWMARCORP.COM

IMPORTANT SAFETY RECALL

This notice applies to your vehicle VIN. # _____

Name

Address

City, State Zip code

Date: April 25, 2018

Motor Vehicle Recall Notification - Recall Campaign No. 18V 236

Dear Valued Customer:

This notice is sent to you in accordance with the requirements of the National Traffic and Motor Vehicle Safety Act.

REASON FOR THIS RECALL

Newmar Corporation has decided that a defect that relates to motor vehicle safety exists in specific motorhomes.

On certain motorhomes, there may be a loose electrical connection in the breaker box that was not properly tightened. A loose power connection may cause a buildup of heat at the connection, which would increase the risk of overheating or a fire causing injury and/or damage to property. Correction: Dealers will inspect the electrical connections in the breaker box and repair as necessary.

The motorhomes require immediate service. Continued use poses a potential safety hazard.

The Safety Risk

A loose power connection may cause a buildup of heat at the connection, which would increase the risk of overheating or a fire causing injury and/or damage to property.

WHAT WE WILL DO

Newmar Corporation will provide owners of all affected motorhomes a remedy for the potential defect at no charge for parts or labor. Dealers will inspect the electrical connections in the breaker box; this repair will take approximately 15 minutes.

WHAT YOU NEED TO DO

As this defect does affect motor vehicle safety, it is recommended that you contact the Newmar service department immediately at 1-800-731-8300. An associate will assist you in making an appointment to have this repair done by an authorized Newmar Dealer.

Federal regulations require that any vehicle lessor receiving this recall notification must forward a copy of this notice to the lessee within ten days.

If you have had the repair performed before receiving this letter, you may be eligible to receive reimbursement for the cost of obtaining a pre-notification remedy. For additional information contact Newmar Corporation at:

Service Department
Newmar Corporation
355 N Delaware St
Nappanee, IN 46550-0030

Newmar dealers are best equipped to obtain parts and provide service to ensure your vehicle is corrected as promptly as possible. HOWEVER, if you take your vehicle to your dealer on the scheduled date and this condition is not remedied on that date or within five days; please contact the Newmar Corporation Customer Service Department at 1-800-731-8300. You may also submit a complaint to the Administrator, National Highway Traffic Safety Administration, 1200 New Jersey Ave., SE., Washington DC 20590; or call the toll-free Vehicle Safety Hotline at 1-888-327-4236 (TTY: 1-800-424-9153); or go to <http://www.safercar.gov>.

If you no longer own this vehicle, please furnish us the complete name and address of the person or dealership you sold or traded your vehicle to. Thank you for your cooperation.

Your safety and satisfaction with your Newmar product is important to us and we regret any inconvenience to you.

Sincerely,

Newmar Corporation



WHEN YOU KNOW THE DIFFERENCE

NEWMAR CORPORATION

NEWMARCORP.COM

Date: April 25, 2018

Re: Newmar Corporation – Motor Vehicle Recall Notification

Subject: Recall Campaign No. 2018-182

This notice is sent to you as a Newmar Dealer in accordance with the requirements of the Canada Motor Vehicle Safety Act. Newmar Corporation has decided that a defect which relates to motor vehicle safety exists in specific Newmar recreational vehicles.

Each vehicle, which is subject to a recall campaign of this type, must be satisfactorily repaired within a reasonable time after the owner has tendered it for repair. A failure to adequately repair within 60 days after tender of a vehicle is prima facie evidence of failure to repair within a reasonable time. To avoid providing these problematic solutions, every effort must be made to promptly schedule an appointment with each owner and to repair their vehicle as soon as possible. Vehicle owners are being notified of this recall. If the condition is not remedied within a reasonable time, they are instructed to contact Transport Canada.

REASON FOR THIS RECALL

Newmar Corporation has decided that a defect which relates to motor vehicle safety exists in specific motorhomes.

On certain motorhomes, there may be a loose electrical connection in the breaker box that was not properly tightened. A loose power connection may cause a buildup of heat at the connection, which would increase the risk of overheating or a fire causing injury and/or damage to property. Correction: Dealers will inspect the electrical connections in the breaker box and repair as necessary. Motorhomes included in this recall include: 2018 Bay Star Sport, Bay Star, Canyon Star, Ventana, Ventana LE, Dutch Star, New Aire, Mountain Aire, London Aire, Essex and King Aire Class A motorhomes.

These motorhomes require immediate service. Continued use poses a potential safety hazard.

This recall applies to certain Newmar motorhomes built between 06/05/2017 and 10/09/2017.

DEALER CAMPAIGN RESPONSIBILITY

Dealers are to provide to all customers/owner vehicles the service of completing this campaign at no charge to the customer/owner regardless of vehicle age, vehicle mileage, or ownership at the time of repair.

REPAIR PROCEDURE

Newmar will provide the work instructions.

If you should have any questions please contact your service account manager direct or the Newmar service department at: 1-866-290-5371.

Thank you for your cooperation.

Sincerely,

Newmar Corporation



WHEN YOU KNOW THE DIFFERENCE

NEWMAR CORPORATION

NEWMARCORP.COM

VIN#
Name
Address
City, State Zip code

Date: April 25, 2018
Motor Vehicle Recall Notification - Recall Campaign No. 2018-182

Dear Valued Customer:

This notice is sent to you in accordance with the requirements of the Canada Motor Vehicle Safety Act.

REASON FOR THIS RECALL

Newmar Corporation has determined that a defect that relates to motor vehicle safety exists in specific motorhomes.

On certain motorhomes, there may be a loose electrical connection in the breaker box that was not properly tightened. A loose power connection may cause a buildup of heat at the connection, which would increase the risk of overheating or a fire causing injury and/or damage to property. Correction: Dealers will inspect the electrical connections in the breaker box and repair as necessary.

The motorhomes require immediate service. Continued use poses a potential safety hazard.

WHAT WE WILL DO

Newmar Corporation will provide owners of all affected motorhomes a remedy for the potential defect at no charge for parts or labor.

WHAT YOU NEED TO DO

As this defect does affect motor vehicle safety, it is recommended that you contact the Newmar service department immediately at **1-800-731-8300**. An associate will assist you in making an appointment to have this repair done by an authorized Newmar Dealer.

Federal regulations require that any vehicle lessor receiving this recall notification must forward a copy of this notice to the lessee within ten days.

If you have had the repair performed before receiving this letter, you may be eligible to receive reimbursement for the cost of obtaining a pre-notification remedy. For additional information contact Newmar Corporation at:

Service Department
Newmar Corporation
355 N Delaware St
Nappanee, IN 46550-0030

Newmar dealers are best equipped to obtain parts and provide service to ensure your vehicle is corrected as promptly as possible. HOWEVER, if you take your vehicle to your dealer on the scheduled date and this condition is not remedied on that date or within five days; please contact the Newmar Corporation Customer Service Department at 1-800-731-8300.

If you no longer own this vehicle, please furnish us the complete name and address of the person or dealership you sold or traded your vehicle to. Thank you for your cooperation.

Your safety and satisfaction with your Newmar product is important to us and we regret any inconvenience to you.

Sincerely,

Newmar Corporation



WHEN YOU KNOW THE DIFFERENCE

NEWMAR CORPORATION

NEWMARCORP.COM

NIV

Nom

Adresse

Ville, province, code postal

Date : 25 avril 2018

Avis de rappel visant un véhicule motorisé – Campagne de rappel n° 2018-182

Madame, Monsieur,

Le présent avis vous est envoyé conformément aux exigences de la *Loi sur la sécurité automobile du Canada*.

MOTIF DU PRÉSENT RAPPEL

Newmar Corporation a déterminé qu'une défaillance relevant de la sécurité automobile existe pour certaines autocaravanes.

Sur certaines autocaravanes, il est possible qu'une connexion électrique lâche dans le boîtier de disjoncteur n'ait pas été resserrée adéquatement. Si une connexion d'alimentation est lâche, cela peut engendrer une accumulation de chaleur, ce qui peut augmenter le risque d'incendie pouvant causer des blessures ou des dommages matériels. Mesure corrective : Les concessionnaires inspecteront les connexions électriques dans le boîtier de disjoncteur et effectueront les réparations nécessaires.

Il est impératif que les réparations sur ces autocaravanes soient effectuées immédiatement. Leur utilisation prolongée pose un risque d'accident potentiel.

CE QUE NOUS FERONS

Newmar Corporation fournira aux propriétaires de toutes les autocaravanes concernées une solution gratuite (pour les pièces et la main-d'œuvre) à la défaillance potentielle.

CE QUE VOUS DEVEZ FAIRE

Puisque cette défaillance touche la sécurité automobile, nous vous recommandons de communiquer immédiatement avec le service technique de Newmar en composant le **1-800-731-8300**. Un associé vous aidera à prendre rendez-vous aux fins d'exécution de cette réparation par un concessionnaire Newmar autorisé.

En vertu de règlements fédéraux, tout donneur à bail d'un véhicule, qui reçoit le présent avis de rappel, est tenu d'en acheminer une copie au preneur à bail dans un délai de dix jours.

Si les réparations ont été effectuées avant réception de la présente lettre, vous pouvez être admissible à un remboursement des frais liés à l'obtention de la solution adoptée avant réception du présent avis. Pour de plus amples renseignements, communiquez avec Newmar Corporation à l'adresse suivante :

Service technique
Newmar Corporation
355 N Delaware St
Nappanee, IN 46550-0030

Les concessionnaires Newmar sont les plus à même de fournir du service et d'obtenir des pièces qui assureront une réparation de votre véhicule dans les plus brefs délais. CELA DIT, si vous apportez votre véhicule à votre concessionnaire à la date prévue et que le problème n'est pas résolu à cette date ou dans les cinq jours qui suivent, veuillez communiquer avec le service à la clientèle de Newmar Corporation en composant le 1-800-731-8300.

Si l'autocaravane concernée ne vous appartient plus, nous vous prions de bien vouloir nous fournir le nom complet et l'adresse complète de la personne ou du concessionnaire faisant maintenant office de propriétaire. Nous vous remercions de votre coopération.

Votre sécurité et votre satisfaction par rapport à nos produits Newmar sont importantes pour nous, et nous sommes désolés de tout désagrément occasionné.

Cordialement,

Newmar Corporation

BREAKER BOX ELECTRICAL CONNECTIONS RECALL WORK INSTRUCTIONS

Provides work instructions related to recall NHTSA 18V 236 (TC 2018-182).

RELEVANT COACHES

Model: All
Year(s): 2018
Floorplan: All

ISSUE

Recall 18V 236: On certain motorhomes, there may be loose electrical connections in the breaker box that were not properly tightened. A loose power connection may cause a buildup of heat at the connection, potentially increasing the risk of overheating or a fire causing injury and/or damage to property.

AFFECTED COMPONENTS

- Breaker Boxes
- Sub Panels

ACTION

Follow the service procedure below to correct the condition. The approximate time to complete this repair is three-tenths of an hour (.3 hr).

NECESSARY TOOLS & REPLACEMENT PARTS

Torque Wrench with Sockets/Screwdriver Bits

Phillips Screwdriver or Flathead Screwdriver (if applicable)
--

SERVICE PROCEDURE

1. Disconnect electrical power. Unplug the coach from shore power and make sure the generator and inverter are both turned off.
2. Test voltage at each breaker box or subpanel.
3. Remove the breaker box cover(s), which may be screwed or clipped on..
4. Check all of the electrical connections in the breaker box(s) breaker, including all neutral and ground connections. Some coaches will have both a breaker box and a subpanel.
5. Use an inch-pound torque wrench with the correct size of straight bit to torque the connections to the specified value (shown on the back side of the breaker box cover).



NOTICE

The torque specifications may vary by wire size; however, they are listed on the back of the cover by wire size (if applicable).

4. If the connections are loose and show signs of overheating to the relays or wiring, take pictures.
5. Contact your Service Account Manager to submit the photos and obtain authorization for any further repairs.

Prod#	VIN Number	Year	Brand	Type	Floor	Chassis	Date In	Date Off
USA Units								
112751	1F66F5DYXJ0A00965	2018	BT	CA	2702	F	7/24/2017	8/1/2017
112753	1F66F5DY0J0A00574	2018	BS	CA	3124	F	6/19/2017	6/27/2017
112754	1F66F5DY1J0A00972	2018	BS	CA	3124	F	7/24/2017	7/31/2017
112755	1F65F5DY6H0A13562	2018	BT	CA	2702	F	6/5/2017	6/13/2017
112758	1F66F5DY2H0A08038	2018	BS	CA	3113	F	6/13/2017	6/21/2017
112759	1F66F5DY5H0A15081	2018	BT	CA	2812	F	7/10/2017	7/18/2017
112760	1F66F5DY5H0A15873	2018	BT	CA	2812	F	6/23/2017	7/12/2017
112762	1F66F5DY9J0A01948	2018	BS	CA	3518	F	7/24/2017	8/1/2017
112763	1F66F5DY1H0A14302	2018	BT	CA	2903	F	6/9/2017	6/19/2017
112764	1F66F5DY2H0A15877	2018	BT	CA	2903	F	7/25/2017	8/1/2017
112765	1F65F5DY0H0A16747	2018	BT	CA	2702	F	6/14/2017	6/22/2017
112766	1F65F5DY9H0A14303	2018	BT	CA	2702	F	6/7/2017	6/15/2017
112770	1F66F5DY3J0A00133	2018	BS	CA	3113	F	6/6/2017	6/14/2017
112771	1F66F5DY0H0A08037	2018	BS	CA	3124	F	6/14/2017	6/22/2017
112772	1F66F5DY2J0A00575	2018	BS	CA	3124	F	6/20/2017	6/28/2017
112773	1F66F5DY9J0A01884	2018	BS	CA	3518	F	7/18/2017	7/26/2017
112775	1F66F5DY6H0A17356	2018	BT	CA	3113	F	9/6/2017	9/14/2017
112778	1F66F5DY5J0A03356	2018	BT	CA	3312	F	9/26/2017	10/3/2017
112779	1F66F5DY4H0A17355	2018	BT	CA	2903	F	9/7/2017	9/15/2017
112789	1F66F5DY8J0A00578	2018	BS	CA	3113	F	6/26/2017	7/13/2017
112790	1F66F5DY4J0A01887	2018	BS	CA	3113	F	8/7/2017	8/15/2017
112791	1F66F5DY3J0A02139	2018	BS	CA	3124	F	8/11/2017	8/21/2017
112792	1F66F5DY1J0A03368	2018	BS	CA	3401	F	9/15/2017	9/22/2017
112795	1F66F5DY6J0A01888	2018	BS	CA	3401	F	8/9/2017	8/17/2017
112796	1F66F5DY1J0A02141	2018	BS	CA	3113	F	8/22/2017	8/30/2017
112797	1F66F5DYXJ0A02137	2018	BS	CA	3113	F	8/8/2017	8/16/2017
112798	1F66F5DYXJ0A03367	2018	BS	CA	3124	F	9/13/2017	9/21/2017
112799	1F66F5DY1J0A00132	2018	BT	CA	2903	F	9/11/2017	9/19/2017
112801	1F66F5DY6H0A15882	2018	BT	CA	2903	F	8/14/2017	8/22/2017
112803	1F66F5DY6H0A16756	2018	BT	CA	2812	F	9/1/2017	9/11/2017
112804	1F66F5DY9H0A16458	2018	BT	CA	3113	F	7/28/2017	8/7/2017
112806	1F66F5DY2H0A15880	2018	BT	CA	3113	F	8/9/2017	8/17/2017
112807	1F66F5DY2H0A16754	2018	BT	CA	3312	F	8/28/2017	9/6/2017
112808	1F66F5DY9H0A16749	2018	BT	CA	3312	F	8/23/2017	8/31/2017
112809	1F66F5DY7H0A16748	2018	BT	CA	3307	F	8/25/2017	9/1/2017
112810	1F66F5DY0H0A16753	2018	BT	CA	3307	F	8/25/2017	9/5/2017
112812	1F66F5DYXJ0A02140	2018	BS	CA	3403	F	8/15/2017	8/22/2017
112813	1F66F5DY8J0A02878	2018	BS	CA	3403	F	8/30/2017	9/8/2017
112814	1F66F5DY8J0A02881	2018	BS	CA	3113	F	9/1/2017	9/12/2017
112817	1F66F5DY4J0A02876	2018	BS	CA	3401	F	8/30/2017	9/8/2017
112818	1F66F5DY9J0A02632	2018	BS	CA	3124	F	8/30/2017	9/7/2017
112824	1F66F5DY3H0A15080	2018	BT	CA	2903	F	6/27/2017	7/14/2017
112825	1F66F5DY8H0A15544	2018	BT	CA	3113	F	7/12/2017	7/20/2017
112826	1F66F5DYXJ0A00971	2018	BS	CA	3124	F	7/25/2017	8/2/2017
112827	1F66F5DY5J0A00134	2018	BS	CA	3403	F	6/8/2017	6/16/2017

112828	1F66F5DY7H0A15874	2018	BT	CA	2903	F	6/29/2017	7/17/2017
112829	1F66F5DYXJ0A01358	2018	BS	CA	3009	F	8/9/2017	8/17/2017
112830	1F66F5DY4J0A01355	2018	BS	CA	3403	F	7/31/2017	8/8/2017
112831	1F65F5DY7H0A12632	2018	BT	CA	2702	F	6/8/2017	6/16/2017
112835	1F66F5DY7J0A00135	2018	BS	CA	3401	F	6/2/2017	6/12/2017
112836	1F66F5DY8H0A17357	2018	BT	CA	3307	F	9/5/2017	9/13/2017
112837	1F66F5DY8J0A03724	2018	BS	CA	3113	F	9/21/2017	9/29/2017
112838	1F66F5DY4J0A04997	2018	BS	CA	3401	F	10/2/2017	10/10/2017
112839	1F66F5DY3H0A13944	2018	BT	CA	2903	F	6/14/2017	6/23/2017
112840	1F65F5DY1J0A01180	2018	BT	CA	2702	F	8/16/2017	8/24/2017
112841	1F66F5DY1J0A02138	2018	BS	CA	3009	F	8/15/2017	8/23/2017
112842	1F66F5DY9J0A00573	2018	BS	CA	3113	F	6/20/2017	6/28/2017
112843	1F66F5DY6H0A15543	2018	BT	CA	2903	F	6/20/2017	6/29/2017
112844	1F66F5DY9H0A15519	2018	BT	CA	3113	F	6/15/2017	6/26/2017
112846	1F66F5DY7J0A02628	2018	BS	CA	3124	F	8/21/2017	8/29/2017
112847	1F66F5DY8J0A02136	2018	BS	CA	3406	F	8/10/2017	8/18/2017
112848	1F66F5DY5J0A01185	2018	BS	CA	3518	F	7/21/2017	7/31/2017
112849	1F66F5DY5H0A06364	2018	BS	CA	3124	F	6/15/2017	6/23/2017
112851	1F66F5DY7J0A01950	2018	BS	CA	3532	F	8/16/2017	8/24/2017
112852	1F66F5DY5J0A02630	2018	BS	CA	3403	F	8/24/2017	8/31/2017
112853	1F66F5DYXJ0A03725	2018	BS	CA	3401	F	9/20/2017	9/28/2017
112854	1F66F5DY6J0A02877	2018	BS	CA	3401	F	8/29/2017	9/7/2017
112855	1F66F5DY2J0A04495	2018	BS	CA	3124	F	10/3/2017	10/10/2017
112856	1F66F5DY8H0A15883	2018	BT	CA	3113	F	8/16/2017	8/23/2017
112858	1F66F5DY6J0A03110	2018	BT	CA	3307	F	9/19/2017	9/27/2017
112861	1F66F5DY9H0A16752	2018	BT	CA	3312	F	8/31/2017	9/11/2017
112862	1F66F5DY4H0A15881	2018	BT	CA	2903	F	8/18/2017	8/28/2017
112863	1F66F5DY3J0A02142	2018	BS	CA	3124	F	8/24/2017	9/1/2017
112864	1F66F5DY4J0A00576	2018	BS	CA	3414	F	6/21/2017	6/29/2017
112870	1F66F5DY8J0A03366	2018	BS	CA	3124	F	9/13/2017	9/21/2017
112879	1F66F5DY8J0A03111	2018	BT	CA	3307	F	9/22/2017	10/2/2017
112880	1F66F5DY3J0A02884	2018	BS	CA	3124	F	9/14/2017	9/22/2017
112881	1F66F5DY5J0A03759	2018	BS	CA	3532	F	9/8/2017	9/18/2017
112882	1F66F5DYXJ0A00579	2018	BS	CA	3401	F	6/28/2017	7/14/2017
112883	1F66F5DY6J0A00580	2018	BS	CA	3113	F	7/13/2017	7/21/2017
112884	1F66F5DY0J0A01885	2018	BS	CA	3113	F	8/11/2017	8/21/2017
112885	1F66F5DY9J0A01349	2018	BS	CA	3113	F	8/1/2017	8/9/2017
112886	1F66F5DY9J0A02629	2018	BS	CA	3401	F	8/25/2017	9/5/2017
112887	1F66F5DY7J0A00572	2018	BS	CA	3113	F	6/21/2017	7/10/2017
112888	1F66F5DY5J0A00571	2018	BS	CA	3113	F	6/22/2017	7/10/2017
112889	1F66F5DY8J0A04064	2018	BS	CA	3113	F	9/26/2017	10/4/2017
112895	1F66F5DY3J0A01184	2018	BS	CA	3414	F	7/26/2017	8/3/2017
112896	1F65F5DY0J0A00568	2018	BT	CA	2702	F	7/25/2017	8/2/2017
112898	1F66F5DY7J0A01351	2018	BS	CA	3124	F	8/3/2017	8/10/2017
112899	1F65F5DY3J0A00130	2018	BT	CA	2702	F	7/14/2017	7/24/2017
112900	1F66F5DY7H0A15082	2018	BT	CA	2903	F	7/13/2017	7/21/2017
112901	1F66F5DY8J0A00967	2018	BS	CA	3124	F	7/14/2017	7/24/2017

112902	1F66F5DY8J0A00970	2018	BS	CA	3414	F	7/20/2017	7/28/2017
112903	1F66F5DY7J0A01947	2018	BS	CA	3532	F	7/20/2017	7/28/2017
112904	1F66F5DYXJ0A04065	2018	BS	CA	3401	F	9/27/2017	10/5/2017
112905	1F66F5DY6J0A01356	2018	BS	CA	3414	F	8/2/2017	8/9/2017
112906	1F66F5DY0J0A01949	2018	BS	CA	3532	F	7/27/2017	8/4/2017
112907	1F66F5DY1J0A03371	2018	BS	CA	3113	F	9/20/2017	9/28/2017
112908	1F66F5DY1J0A03113	2018	BT	CA	2903	F	9/27/2017	10/5/2017
112910	1F66F5DY9J0A03358	2018	BT	CA	3307	F	9/29/2017	10/9/2017
112911	1F66F5DYXJ0A01182	2018	BT	CA	3312	F	9/12/2017	9/20/2017
112918	1F66F5DY7J0A03357	2018	BT	CA	2812	F	10/3/2017	10/11/2017
112919	1F65F5DY1J0A02135	2018	BT	CA	2702	F	9/27/2017	10/4/2017
112921	1F66F5DY4H0A15878	2018	BT	CA	3113	F	7/26/2017	8/3/2017
112923	1F66F5DYXJ0A00131	2018	BT	CA	2903	F	9/14/2017	9/21/2017
112924	1F66F5DY2J0A00138	2018	BS	CA	3414	F	6/8/2017	6/19/2017
112925	1F66F5DY3J0A00973	2018	BS	CA	3532	F	6/28/2017	7/17/2017
112926	1F66F5DY6J0A03754	2018	BT	CA	2903	F	9/28/2017	10/6/2017
112927	1F66F5DY8J0A01181	2018	BT	CA	3113	F	9/14/2017	9/22/2017
112928	1F66F5DY1J0A04066	2018	BS	CA	3009	F	10/3/2017	10/11/2017
112930	1F66F5DY1H0A12629	2018	BS	CA	3124	F	7/28/2017	8/7/2017
112931	1F66F5DY8J0A01357	2018	BS	CA	3414	F	8/3/2017	8/11/2017
112932	1F66F5DY5H0A15520	2018	BT	CA	2903	F	7/19/2017	7/27/2017
112934	1F66F5DY0J0A04494	2018	BS	CA	3124	F	10/4/2017	10/12/2017
112937	1F66F5DY4J0A05289	2018	BS	CA	3518	F	9/28/2017	10/6/2017
112938	1F66F5DY7H0A15079	2018	BT	CA	3307	F	6/22/2017	7/11/2017
112939	1F66F5DY6J0A00577	2018	BS	CA	3124	F	6/22/2017	7/11/2017
112942	1F66F5DY5J0A01350	2018	BS	CA	3124	F	8/4/2017	8/11/2017
112943	1F66F5DY8H0A16757	2018	BT	CA	2903	F	9/7/2017	9/15/2017
112944	1F66F5DY7H0A16751	2018	BT	CA	3307	F	8/29/2017	9/6/2017
112945	1F66F5DY1J0A01183	2018	BS	CA	3401	F	7/27/2017	8/3/2017
112947	1F66F5DY3J0A03761	2018	BS	CA	3532	F	9/15/2017	9/25/2017
112948	1F66F5DY6J0A04497	2018	BS	CA	3414	F	10/4/2017	10/12/2017
112953	1F66F5DY3J0A00570	2018	BS	CA	3401	F	6/9/2017	6/19/2017
112954	1F66F5DY2J0A01886	2018	BS	CA	3009	F	8/17/2017	8/25/2017
112960	1F66F5DY4H0A16755	2018	BT	CA	2812	F	9/6/2017	9/13/2017
112961	1F66F5DY0J0A02387	2018	BT	CA	2812	F	9/21/2017	9/29/2017
112964	1F65F5DY5J0A01179	2018	BT	CA	2702	F	8/18/2017	8/28/2017
112972	1F66F5DY6J0A00966	2018	BS	CA	3124	F	7/10/2017	7/19/2017
112973	1F66F5DY6J0A02880	2018	BS	CA	3113	F	9/6/2017	9/14/2017
112974	1F66F5DY3J0A03355	2018	BT	CA	3307	F	9/28/2017	10/6/2017
112977	1F66F5DY5J0A03762	2018	BS	CA	3532	F	9/18/2017	9/26/2017
112979	1F66F5DY9H0A15875	2018	BT	CA	2903	F	7/27/2017	8/4/2017
112992	1F66F5DY0H0A16459	2018	BT	CA	3022	F	8/4/2017	8/14/2017
112994	1F66F5DY1J0A00969	2018	BS	CA	3124	F	7/14/2017	7/24/2017
112996	1F66F5DY0H0A15876	2018	BT	CA	2903	F	7/21/2017	7/31/2017
113010	1F66F5DYXJ0A03112	2018	BT	CA	2812	F	9/22/2017	10/2/2017
113022	1F66F5DY7J0A02631	2018	BS	CA	3113	F	8/28/2017	9/6/2017
113025	1F66F5DY1J0A03757	2018	BS	CA	3124	F	9/25/2017	10/3/2017

113026	1F66F5DYXJ0A02882	2018	BS	CA	3403	F	9/1/2017	9/12/2017
113058	1F66F5DYXJ0A03370	2018	BS	CA	3406	F	9/12/2017	9/19/2017
113090	1F66F5DY5J0A02885	2018	BS	CA	3124	F	9/12/2017	9/20/2017
113092	1F66F5DY7J0A03682	2018	BS	CA	3124	F	9/15/2017	9/25/2017
113103	1F66F5DY7H0A16460	2018	BT	CA	3307	F	8/18/2017	8/28/2017
113185	1F66F5DY3J0A03758	2018	BS	CA	3009	F	9/22/2017	10/2/2017
113186	1F66F5DY3J0A03369	2018	BS	CA	3401	F	9/8/2017	9/18/2017
113192	1F66F5DY1J0A02883	2018	BS	CA	3406	F	9/5/2017	9/13/2017
113193	1F66F5DY1J0A03760	2018	BS	CA	3406	F	9/11/2017	9/19/2017
113194	1F66F5DYXJ0A02879	2018	BS	CA	3009	F	9/1/2017	9/12/2017
113238	1F66F5DY3J0A02626	2018	BT	CA	2903	F	9/18/2017	9/25/2017
162101	1F66F5DY1J0A00583	2018	CS	CA	3710	F	6/16/2017	6/26/2017
162103	1F66F5DY0J0A02633	2018	CS	CA	3911	F	7/31/2017	8/8/2017
162104	1F66F5DYXJ0A00582	2018	CS	CA	3921	F	6/12/2017	6/20/2017
162105	1F66F5DY8J0A00581	2018	CS	CA	3921	F	6/6/2017	6/14/2017
162106	1F66F5DY9J0A01559	2018	CS	CA	3710	F	8/1/2017	8/9/2017
162108	1F66F5DY3J0A01525	2018	CS	CA	3513	F	7/18/2017	7/26/2017
162111	1F66F5DY9J0A01352	2018	CS	CA	3921	F	6/23/2017	7/11/2017
162112	1F66F5DY4J0A03364	2018	CS	CA	3710	F	9/19/2017	9/27/2017
162113	1F66F5DY8J0A00774	2018	CS	CA	3710	F	6/9/2017	6/20/2017
162114	1F66F5DY5J0A03115	2018	CS	CA	3513	F	8/22/2017	8/29/2017
162116	1F66F5DY8J0A01889	2018	CS	CA	3710	F	8/14/2017	8/22/2017
162117	1F66F5DYXJ0A01747	2018	CS	CA	3710	F	8/7/2017	8/15/2017
162120	1F66F5DY4J0A00142	2018	CS	CA	3710	F	6/7/2017	6/15/2017
162121	1F66F5DYXJ0A00775	2018	CS	CA	3710	F	6/12/2017	6/20/2017
162122	1F66F5DY3J0A00777	2018	CS	CA	3924	F	6/13/2017	6/21/2017
162123	1F66F5DY5H0A18451	2018	CS	CA	3513	F	6/2/2017	6/12/2017
162124	1F66F5DY0J0A00140	2018	CS	CA	3710	F	6/2/2017	6/12/2017
162125	1F66F5DY2J0A00141	2018	CS	CA	3921	F	6/5/2017	6/13/2017
162126	1F66F5DY6J0A00143	2018	CS	CA	3924	F	6/5/2017	6/13/2017
162127	1F66F5DY9J0A01187	2018	CS	CA	3710	F	6/23/2017	7/12/2017
162128	1F66F5DY5J0A03339	2018	CS	CA	3953	F	8/21/2017	8/28/2017
162129	1F66F5DY9J0A03117	2018	CS	CA	3953	F	8/29/2017	9/7/2017
162130	1F66F5DY2J0A02634	2018	CS	CA	3710	F	8/15/2017	8/23/2017
162131	1F66F5DYXJ0A01523	2018	CS	CA	3921	F	7/11/2017	7/19/2017
162132	1F66F5DY7J0A00975	2018	CS	CA	3921	F	7/10/2017	7/18/2017
162133	1F66F5DY7J0A02144	2018	CS	CA	3921	F	8/2/2017	8/10/2017
162134	1F66F5DY6J0A02636	2018	CS	CA	3710	F	8/21/2017	8/29/2017
162135	1F66F5DY4J0A02635	2018	CS	CA	3710	F	8/11/2017	8/21/2017
162136	1F66F5DY2J0A03363	2018	CS	CA	3513	F	9/18/2017	9/26/2017
162138	1F66F5DY5J0A04071	2018	CS	CA	3710	F	10/2/2017	10/10/2017
162140	1F66F5DY3J0A03338	2018	CS	CA	3901	F	8/22/2017	8/30/2017
162145	1F66F5DY3J0A03341	2018	CS	CA	3710	F	9/19/2017	9/27/2017
162148	1F66F5DY2J0A01354	2018	CS	CA	3710	F	7/17/2017	7/25/2017
162149	1F66F5DY5J0A01557	2018	CS	CA	3924	F	7/17/2017	7/25/2017
162154	1F66F5DY7J0A01186	2018	CS	CA	3924	F	6/16/2017	6/27/2017
162155	1F66F5DY1J0A01524	2018	CS	CA	3924	F	7/11/2017	7/19/2017

162156	1F66F5DY3J0A01556	2018	CS	CA	3901	F	7/18/2017	7/26/2017
162157	1F66F5DY0J0A01353	2018	CS	CA	3901	F	6/29/2017	7/17/2017
162158	1F66F5DY1J0A00776	2018	CS	CA	3921	F	6/19/2017	6/27/2017
162159	1F66F5DY3J0A03114	2018	CS	CA	3513	F	8/24/2017	9/1/2017
162161	1F66F5DY4J0A01890	2018	CS	CA	3513	F	7/28/2017	8/7/2017
162162	1F66F5DY8J0A01892	2018	CS	CA	3911	F	7/31/2017	8/8/2017
162163	1F66F5DY9J0A02145	2018	CS	CA	3901	F	8/7/2017	8/14/2017
162168	1F66F5DY5J0A04068	2018	CS	CA	3924	F	9/8/2017	9/15/2017
162169	1F66F5DY7J0A04069	2018	CS	CA	3911	F	9/25/2017	10/3/2017
162183	1F66F5DY6J0A03365	2018	CS	CA	3911	F	8/28/2017	9/5/2017
162189	1F66F5DY3J0A04070	2018	CS	CA	3921	F	9/29/2017	10/9/2017
162190	1F66F5DY1J0A03340	2018	CS	CA	3710	F	9/20/2017	9/28/2017
413280	4UZACHFC0JCJU9953	2018	VL	DP	4037	FL	8/14/2017	8/21/2017
413281	4UZAB2FC5JCJU9947	2018	VL	DP	3709	FL	9/22/2017	10/2/2017
413283	4UZFCHFE9JCJT5525	2018	VT	DP	4369	FL	7/10/2017	7/18/2017
413284	4UZAB2FC1JCJS6732	2018	VL	DP	3709	FL	6/9/2017	6/19/2017
413285	4UZAB2FCXJCJS6731	2018	VL	DP	3436	FL	6/16/2017	6/26/2017
413286	4UZACHFC8JCJU4824	2018	VL	DP	4037	FL	9/25/2017	10/3/2017
413287	4UZFCHFE8JCJR8342	2018	VT	DP	4326	FL	6/9/2017	6/20/2017
413288	4UZFCHFE1JCJS6740	2018	VT	DP	4369	FL	6/16/2017	6/27/2017
413291	4UZFCHFE8JCJR6364	2018	VT	DP	4310	FL	6/2/2017	6/12/2017
413292	4UZFCHFE6JCJR6363	2018	VT	DP	4326	FL	6/5/2017	6/13/2017
413293	4UZFCHFE3JCJS2401	2018	VT	DP	4326	FL	6/12/2017	6/20/2017
413294	4UZFCHFE0JCJT1847	2018	VT	DP	4326	FL	6/19/2017	6/27/2017
413298	4UZACHFC1JCJR6358	2018	VT	DP	3715	FL	6/2/2017	6/9/2017
413299	4UZACHFC8JCJR6356	2018	VT	DP	3436	FL	6/5/2017	6/13/2017
413300	4UZFCHFE5JCJS6739	2018	VT	DP	4037	FL	6/6/2017	6/14/2017
413301	4UZFCHFE4JCJR8340	2018	VT	DP	4037	FL	6/12/2017	6/20/2017
413302	4UZAB2FC3JCJS2391	2018	VL	DP	3436	FL	6/19/2017	6/28/2017
413303	4UZAB2FC4JCJR8332	2018	VL	DP	3436	FL	6/13/2017	6/21/2017
413304	4UZACHFC1JCJT8394	2018	VL	DP	4048	FL	8/4/2017	8/14/2017
413305	4UZACHFC2JCJU2230	2018	VL	DP	4002	FL	8/8/2017	8/16/2017
413306	4UZAB2FC7JCJU9951	2018	VL	DP	3709	FL	9/11/2017	9/19/2017
413307	4UZACHFC8JCJV3619	2018	VL	DP	4048	FL	8/18/2017	8/28/2017
413308	4UZAB2FC7JCJU9948	2018	VL	DP	3709	FL	9/12/2017	9/20/2017
413309	4UZACHFC6JCJU4823	2018	VL	DP	4002	FL	8/22/2017	8/30/2017
413310	4UZACHFC2JCJT5519	2018	VT	DP	3407	FL	7/19/2017	7/27/2017
413311	4UZACHFCXJCJU2234	2018	VT	DP	3407	FL	7/31/2017	8/7/2017
413312	4UZACHFC9JCJS8454	2018	VT	DP	3407	FL	6/23/2017	7/11/2017
413313	4UZACHFC2JCJV8718	2018	VT	DP	3436	FL	8/31/2017	9/11/2017
413314	4UZACHFC3JCJV3625	2018	VT	DP	3709	FL	8/24/2017	8/31/2017
413315	4UZFCHFE1JCJS2400	2018	VT	DP	4002	FL	6/19/2017	6/27/2017
413316	4UZFCHFE6JCJU4828	2018	VT	DP	4037	FL	8/7/2017	8/15/2017
413318	4UZFCHFEXJCJV6156	2018	VT	DP	4369	FL	9/20/2017	9/28/2017
413319	4UZACHFC9JCJS6736	2018	VT	DP	3715	FL	6/20/2017	6/28/2017
413320	4UZACHFC5JCJR8338	2018	VT	DP	3715	FL	6/13/2017	6/21/2017
413322	4UZACHFC9JCJS2394	2018	VL	DP	4002	FL	6/14/2017	6/22/2017

413323	4UZACHFC4JCJU9955	2018	VL	DP	4037	FL	8/28/2017	9/6/2017
413325	4UZFCHFE3JCJS6741	2018	VT	DP	4326	FL	6/26/2017	7/12/2017
413326	4UZFCHFE0JCJU6669	2018	VT	DP	4369	FL	8/8/2017	8/15/2017
413327	4UZAB2FC5JCJW0690	2018	VL	DP	3413	FL	8/30/2017	9/8/2017
413328	4UZACHFC4JCJR6354	2018	VL	DP	4048	FL	6/20/2017	6/29/2017
413329	4UZACHFC0JCJS8455	2018	VT	DP	3709	FL	6/26/2017	7/13/2017
413330	4UZFCHFE8JCJV6155	2018	VT	DP	4308	FL	9/5/2017	9/13/2017
413333	4UZFCHFE4JCJR6362	2018	VT	DP	4369	FL	6/2/2017	6/12/2017
413334	4UZACHFC3JCJR8337	2018	VT	DP	3709	FL	6/2/2017	6/12/2017
413335	4UZAB2FC4JCJU4822	2018	VL	DP	3709	FL	10/2/2017	10/10/2017
413336	4UZACHFC0JCJV8717	2018	VL	DP	4037	FL	9/6/2017	9/14/2017
413337	4UZFCHFE4JCJU4830	2018	VT	DP	4046	FL	8/30/2017	9/8/2017
413338	4UZAB2FC1JCJS8450	2018	VL	DP	3436	FL	6/29/2017	7/18/2017
413339	4UZAB2FC3JCJS8451	2018	VL	DP	3709	FL	7/10/2017	7/18/2017
413340	4UZAB2FC6JCJU2229	2018	VL	DP	3709	FL	8/15/2017	8/23/2017
413341	4UZAB2FC1JCJU9945	2018	VL	DP	3412	FL	8/8/2017	8/16/2017
413342	4UZFCHFE0JCJU9961	2018	VT	DP	4369	FL	8/11/2017	8/21/2017
413343	4UZACHFC6JCJU9956	2018	VT	DP	3407	FL	8/21/2017	8/29/2017
413344	4UZACHFC3JCJT8395	2018	VT	DP	3436	FL	7/25/2017	8/2/2017
413345	4UZACHFC9JCJT1841	2018	VT	DP	3436	FL	7/20/2017	7/28/2017
413346	4UZACHFC1JCJU4826	2018	VT	DP	3436	FL	8/9/2017	8/17/2017
413347	4UZACHFC2JCJS2396	2018	VT	DP	3412	FL	6/27/2017	7/13/2017
413348	4UZACHFC0JCJU6664	2018	VT	DP	3709	FL	8/15/2017	8/23/2017
413349	4UZACHFC0JCJS6737	2018	VT	DP	3709	FL	6/20/2017	6/29/2017
413350	4UZFCHFE2JCJU9959	2018	VT	DP	4002	FL	8/16/2017	8/24/2017
413351	4UZFCHFE8JCJU2238	2018	VT	DP	4002	FL	7/31/2017	8/8/2017
413352	4UZFCHFE8JCJU4829	2018	VT	DP	4037	FL	8/23/2017	8/31/2017
413353	4UZFCHFE3JCJS6738	2018	VT	DP	4037	FL	6/27/2017	7/13/2017
413354	4UZACHFC1JCJR8336	2018	VT	DP	3436	FL	6/13/2017	6/21/2017
413355	4UZACHFC5JCJS6734	2018	VL	DP	4002	FL	7/18/2017	7/26/2017
413356	4UZACHFC7JCJV3627	2018	VT	DP	3715	FL	8/28/2017	9/6/2017
413358	4UZACHFC6JCJS2398	2018	VT	DP	3715	FL	6/14/2017	6/22/2017
413359	4UZACHFC0JCJR6352	2018	VL	DP	4048	FL	6/5/2017	6/13/2017
413360	4UZACHFC7JCJS6735	2018	VT	DP	3412	FL	6/21/2017	7/10/2017
413361	4UZFCHFE9JCJS2399	2018	VT	DP	4037	FL	6/15/2017	6/26/2017
413362	4UZFCHFE6JCJV6154	2018	VT	DP	4369	FL	9/12/2017	9/20/2017
413363	4UZACHFC7JCJS2393	2018	VL	DP	4002	FL	6/7/2017	6/15/2017
413364	4UZFCHFE7JCJU6667	2018	VT	DP	4046	FL	10/2/2017	10/10/2017
413365	4UZFCHFE5JCJT5523	2018	VT	DP	4037	FL	7/18/2017	7/26/2017
413366	4UZAB2FC3JCJU6660	2018	VL	DP	3709	FL	8/16/2017	8/24/2017
413367	4UZAB2FC3JCJU9946	2018	VL	DP	3412	FL	8/11/2017	8/18/2017
413369	4UZACHFCXJCJU4825	2018	VT	DP	3407	FL	8/1/2017	8/8/2017
413370	4UZFCHFEXJCJT8398	2018	VT	DP	4037	FL	7/26/2017	8/3/2017
413375	4UZACHFC0JCJT1842	2018	VT	DP	3709	FL	7/12/2017	7/19/2017
413376	4UZFCHFEXJCJW0692	2018	VT	DP	4037	FL	9/21/2017	9/29/2017
413377	4UZFCHFEXJCJU4833	2018	VT	DP	4369	FL	8/2/2017	8/10/2017
413381	4UZAB2FC9JCJW3575	2018	VL	DP	3709	FL	9/15/2017	9/25/2017

413383	4UZACHFC3JCJV6153	2018	VT	DP	3412	FL	9/12/2017	9/19/2017
413386	4UZACHFC8JCJR8334	2018	VL	DP	4037	FL	6/21/2017	6/29/2017
413387	4UZFCHFE8JCJR8339	2018	VT	DP	4037	FL	6/6/2017	6/14/2017
413388	4UZAB2FC7JCJW0691	2018	VL	DP	3436	FL	9/18/2017	9/26/2017
413392	4UZFCHFE6JCJT8401	2018	VT	DP	4369	FL	7/25/2017	8/2/2017
413393	4UZACHFC0JCJT5518	2018	VL	DP	4037	FL	8/1/2017	8/9/2017
413394	4UZAB2FC7JCJT5516	2018	VL	DP	3412	FL	7/19/2017	7/27/2017
413395	4UZFCHFE4JCJU9963	2018	VT	DP	4310	FL	8/24/2017	9/1/2017
413396	4UZFCHFE1JCJV3629	2018	VT	DP	4326	FL	8/29/2017	9/7/2017
413397	4UZFCHFE8JCJU2241	2018	VT	DP	4369	FL	7/20/2017	7/28/2017
413398	4UZFCHFE9JCJU6668	2018	VT	DP	4369	FL	8/2/2017	8/10/2017
413399	4UZFCHFE3JCJT5522	2018	VT	DP	4002	FL	7/28/2017	8/4/2017
413400	4UZAB2FCXJCJV6148	2018	VL	DP	3413	FL	9/20/2017	9/28/2017
413401	4UZACHFC0JCJS2395	2018	VT	DP	3436	FL	6/7/2017	6/15/2017
413402	4UZAB2FC9JCJT1838	2018	VL	DP	3709	FL	7/11/2017	7/19/2017
413403	4UZACHFC3JCJS6733	2018	VL	DP	4037	FL	7/11/2017	7/19/2017
413404	4UZACHFC0JCJT1839	2018	VL	DP	4048	FL	7/12/2017	7/20/2017
413405	4UZAB2FC7JCJT1837	2018	VL	DP	3436	FL	7/12/2017	7/20/2017
413406	4UZFCHFE4JCJT8400	2018	VT	DP	4369	FL	7/13/2017	7/21/2017
413407	4UZFCHFE5JCJT1844	2018	VT	DP	4049	FL	7/17/2017	7/25/2017
413408	4UZAB2FC3JCJU6657	2018	VL	DP	3436	FL	8/3/2017	8/11/2017
413409	4UZAB2FC5JCJV8714	2018	VL	DP	3436	FL	9/7/2017	9/15/2017
413410	4UZAB2FC1JCJV6149	2018	VL	DP	3412	FL	9/13/2017	9/21/2017
413411	4UZAB2FC8JCJW3566	2018	VL	DP	3412	FL	10/3/2017	10/11/2017
413413	4UZACHFC1JCJV6152	2018	VT	DP	3407	FL	9/13/2017	9/20/2017
413414	4UZACHFC6JCJV3621	2018	VT	DP	3412	FL	8/29/2017	9/7/2017
413415	4UZACHFC4JCJV3620	2018	VT	DP	3436	FL	8/25/2017	9/5/2017
413421	4UZFCHFE3JCJW3580	2018	VT	DP	4311	FL	9/19/2017	9/27/2017
413422	4UZFCHFE9JCJT1846	2018	VT	DP	4308	FL	7/13/2017	7/24/2017
413423	4UZAB2FC9JCJW0689	2018	VL	DP	3413	FL	9/1/2017	9/12/2017
413424	4UZACHFCXJCJR8335	2018	VL	DP	4048	FL	6/15/2017	6/23/2017
413425	4UZACHFC4JCJV8719	2018	VT	DP	3407	FL	9/13/2017	9/21/2017
413426	4UZACHFC2JCJT1843	2018	VT	DP	3715	FL	6/29/2017	7/17/2017
413427	4UZFCHFEXJCJU2239	2018	VT	DP	4037	FL	8/4/2017	8/14/2017
413428	4UZAB2FC9JCJR6351	2018	VL	DP	3709	FL	6/22/2017	7/11/2017
413429	4UZFCHFE6JCJU4831	2018	VT	DP	4308	FL	7/20/2017	7/28/2017
413430	4UZAB2FC0JCJR6349	2018	VL	DP	3412	FL	6/8/2017	6/16/2017
413431	4UZAB2FC5JCJS2392	2018	VL	DP	3709	FL	6/7/2017	6/15/2017
413432	4UZFCHFE7JCJT5524	2018	VT	DP	4308	FL	6/29/2017	7/17/2017
413434	4UZFCHFE1JCJW0693	2018	VT	DP	4037	FL	9/26/2017	10/4/2017
413440	4UZFCHFE9JCJU9960	2018	VT	DP	4049	FL	9/20/2017	9/28/2017
413441	4UZFCHFE8JCJU4832	2018	VT	DP	4369	FL	7/21/2017	7/28/2017
413442	4UZAB2FC5JCJU9950	2018	VL	DP	3709	FL	9/5/2017	9/13/2017
413443	4UZACHFC7JCJS8453	2018	VL	DP	4037	FL	7/25/2017	8/1/2017
413445	4UZACHFC7JCJU6662	2018	VL	DP	4048	FL	9/14/2017	9/22/2017
413446	4UZAB2FC7JCJV8715	2018	VL	DP	3436	FL	9/21/2017	9/29/2017
413447	4UZAB2FCXJCJT8393	2018	VL	DP	3709	FL	7/12/2017	7/20/2017

413448	4UZAB2FC7JCJW0688	2018	VL	DP	3436	FL	9/7/2017	9/15/2017
413449	4UZAB2FC9CJU2225	2018	VL	DP	3436	FL	7/26/2017	8/3/2017
413451	4UZAB2FC5JCJU6661	2018	VL	DP	3709	FL	8/18/2017	8/25/2017
413455	4UZACHFC2JCJU9954	2018	VL	DP	4037	FL	8/23/2017	8/31/2017
413456	4UZACHFC7JCJT1840	2018	VL	DP	4048	FL	7/27/2017	8/4/2017
413458	4UZAB2FC6JCJR8333	2018	VL	DP	3709	FL	6/23/2017	7/12/2017
413459	4UZFCHFE5JCJS2402	2018	VT	DP	4310	FL	6/16/2017	6/26/2017
413462	4UZACHFC0JCJT5521	2018	VT	DP	3715	FL	7/14/2017	7/24/2017
413465	4UZACHFC2JCJV8721	2018	VT	DP	3436	FL	9/14/2017	9/22/2017
413466	4UZAB2FC9JCJT5517	2018	VL	DP	3709	FL	7/14/2017	7/24/2017
413467	4UZACHFC9JCJX0526	2018	VL	DP	4037	FL	10/4/2017	10/11/2017
413472	4UZACHFC0JCJW3576	2018	VL	DP	4037	FL	9/29/2017	10/9/2017
413473	4UZACHFCXJCJV6151	2018	VT	DP	3412	FL	8/24/2017	9/1/2017
413476	4UZFCHFE5JCJV8722	2018	VT	DP	4369	FL	10/2/2017	10/10/2017
413482	4UZACHFC1JCJU2235	2018	VT	DP	3412	FL	8/3/2017	8/10/2017
413484	4UZACHFC3JCJU2236	2018	VT	DP	3709	FL	8/10/2017	8/18/2017
413486	4UZAB2FC8JCJT8392	2018	VL	DP	3412	FL	7/14/2017	7/24/2017
413487	4UZFCHFE1JCJW7501	2018	VT	DP	4037	FL	9/28/2017	10/6/2017
413491	4UZFCHFE3JCJS8456	2018	VT	DP	4037	FL	7/21/2017	7/31/2017
413493	4UZACHFC5JCJU2237	2018	VT	DP	3715	FL	8/11/2017	8/21/2017
413502	4UZFCHFE0JCJU9958	2018	VT	DP	4037	FL	9/8/2017	9/18/2017
413504	4UZFCHFE5JCJW3578	2018	VT	DP	4002	FL	9/29/2017	10/9/2017
413521	4UZACHFC9JCJU6663	2018	VT	DP	3412	FL	8/14/2017	8/22/2017
413522	4UZACHFC0JCJX0527	2018	VL	DP	4037	FL	10/4/2017	10/12/2017
413523	4UZFCHFE6JCJU2240	2018	VT	DP	4369	FL	7/17/2017	7/25/2017
413527	4UZFCHFE8JCJV3630	2018	VT	DP	4369	FL	9/6/2017	9/14/2017
413528	4UZACHFC9JCJT5520	2018	VT	DP	3407	FL	7/21/2017	7/31/2017
413548	4UZAB2FC4JCJW3564	2018	VL	DP	3412	FL	9/28/2017	10/5/2017
413553	4UZFCHFE2JCJS6746	2018	VT	DP	4311	FL	9/1/2017	9/12/2017
413576	4UZACHFC8JCJV3622	2018	VT	DP	3407	FL	8/15/2017	8/23/2017
413577	4UZAB2FC2JCJU4821	2018	VL	DP	3412	FL	7/28/2017	8/7/2017
413578	4UZACHFC8JCJU9957	2018	VT	DP	3436	FL	9/11/2017	9/18/2017
413580	4UZACHFC4JCJX0532	2018	VT	DP	3412	FL	10/4/2017	10/12/2017
413581	4UZACHFC2JCJX0531	2018	VT	DP	3412	FL	9/22/2017	10/2/2017
413639	4UZACHFC5JCJV3626	2018	VT	DP	3709	FL	9/25/2017	10/3/2017
413705	4UZACHFCXJCJV3623	2018	VT	DP	3715	FL	8/31/2017	9/11/2017
413706	4UZAB2FC9JCJU9949	2018	VL	DP	3709	FL	9/28/2017	10/6/2017
413712	4UZACHFC9JCJW7500	2018	VT	DP	3412	FL	9/18/2017	9/26/2017
501506	4VZVU1E96JC084086	2018	LA	DP	4531	S	8/18/2017	8/28/2017
501507	4UZFTFG1JCJR8347	2018	LA	DP	4535	FL	6/23/2017	7/11/2017
501508	4VZVU1E9XJC083765	2018	LA	DP	4531	S	6/12/2017	6/20/2017
501509	4UZFTFG9JCJT1852	2018	LA	DP	4553	FL	7/21/2017	7/31/2017
501510	4VZVU1E9XJC084074	2018	LA	DP	4553	S	8/2/2017	8/10/2017
501511	4VZVU1E98JC084395	2018	LA	DP	4531	S	9/28/2017	10/6/2017
501513	4UZFTFG6JCJU4946	2018	LA	DP	4534	FL	8/16/2017	8/24/2017
501515	4UZFTFG7JCJU2249	2018	LA	DP	4531	FL	8/29/2017	9/7/2017
501516	4UZFTFG1JCJS6791	2018	LA	DP	4534	FL	7/12/2017	7/20/2017

501517	4VZVU1E98JC084333	2018 LA	DP	4553 S	9/25/2017	10/3/2017
501518	4VZVU1E91JC083766	2018 LA	DP	4531 S	6/14/2017	6/22/2017
501519	4VZVU1E96JC083777	2018 LA	DP	4531 S	6/27/2017	7/14/2017
501520	4VZVU1E97JC083786	2018 LA	DP	4553 S	6/29/2017	7/18/2017
501523	4VZVU1E93JC084157	2018 LA	DP	4535 S	9/1/2017	9/12/2017
501526	4VZVU1E91JC084304	2018 LA	DP	4553 S	9/11/2017	9/19/2017
501527	4VZVU1E99JC084440	2018 LA	DP	4553 S	10/3/2017	10/11/2017
501530	4UZFCTFG5JCJV6165	2018 LA	DP	4535 FL	9/22/2017	10/2/2017
501531	4VZVU1E94JC084085	2018 LA	DP	4553 S	8/14/2017	8/22/2017
501535	4UZFCTFG3JCJT8411	2018 LA	DP	4553 FL	8/7/2017	8/15/2017
501538	4UZFCTFG0JCJW7509	2018 LA	DP	4531 FL	10/4/2017	10/12/2017
501539	4VZVU1E96JC084394	2018 LA	DP	4531 S	9/26/2017	10/4/2017
530426	4VZVU1E91JC084335	2018 KG	DB	4553 S	9/21/2017	9/29/2017
530427	4VZVU1E91JC083881	2018 KG	DB	4531 S	6/9/2017	6/19/2017
530428	4VZVU1E90JC083788	2018 KG	DB	4531 S	6/2/2017	6/12/2017
530429	4VZVU1E91JC083900	2018 KG	DB	4531 S	6/19/2017	6/28/2017
530430	4VZVU1E90JC083953	2018 KG	DB	4531 S	7/14/2017	7/27/2017
530431	4VZVU1E98JC084011	2018 KG	DB	4534 S	7/24/2017	8/1/2017
530432	4VZVU1E99JC084180	2018 KG	DB	4531 S	8/25/2017	9/1/2017
530433	4VZVU1E91JC084089	2018 KG	DB	4553 S	8/9/2017	8/17/2017
530434	4VZVU1E95JC084306	2018 KG	DB	4531 S	9/15/2017	9/25/2017
530437	4VZVU1E95JC084077	2018 KG	DB	4531 S	7/31/2017	8/8/2017
530438	4VZVU1E93JC084398	2018 KG	DB	4531 S	10/2/2017	10/10/2017
530439	4VZVU1E92JC084179	2018 KG	DB	4534 S	8/22/2017	8/30/2017
530440	4VZVU1E90JC084407	2018 KG	DB	4531 S	10/4/2017	10/12/2017
530442	4VZVU1E93JC083901	2018 KG	DB	4531 S	6/26/2017	7/12/2017
530443	4VZVU1E9XJC084155	2018 KG	DB	4553 S	8/17/2017	8/24/2017
530444	4VZVU1E99JC083966	2018 KG	DB	4531 S	7/17/2017	7/25/2017
530445	4VZVU1E92JC083954	2018 KG	DB	4534 S	7/10/2017	7/18/2017
530446	4VZVU1E9XJC084088	2018 KG	DB	4534 S	8/8/2017	8/15/2017
530447	4VZVU1E93JC084336	2018 KG	DB	4533 S	9/26/2017	10/4/2017
530450	4VZVU1E93JC084188	2018 KG	DB	4553 S	8/30/2017	9/8/2017
530452	4VZVU1E98JC084154	2018 KG	DB	4531 S	8/14/2017	8/21/2017
530453	4VZVU1E90JC084245	2018 KG	DB	4553 S	9/6/2017	9/14/2017
530455	4VZVU1E99JC084244	2018 KG	DB	4531 S	8/31/2017	9/11/2017
530458	4VZVU1E93JC084305	2018 KG	DB	4534 S	9/8/2017	9/18/2017
530464	4VZVU1E91JC084397	2018 KG	DB	4534 S	9/27/2017	10/5/2017
606694	4UZACHFE8JCJW0698	2018 DS	DP	3736 FL	9/8/2017	9/15/2017
606695	4VZAU1D9XJC084253	2018 DS	DP	4369 S	9/11/2017	9/19/2017
606696	4UZACHFE6JCJU6671	2018 DS	DP	3736 FL	8/9/2017	8/17/2017
606697	4UZCFHFE1JCJR8344	2018 DS	DP	4018 FL	6/2/2017	6/12/2017
606699	4UZACHFEXJCJS2406	2018 DS	DP	3736 FL	6/5/2017	6/13/2017
606701	4UZCFHFE4JCJS2410	2018 DS	DP	4369 FL	6/8/2017	6/16/2017
606702	4UZCFHFE8JCJS2409	2018 DS	DP	4369 FL	6/9/2017	6/19/2017
606704	4VZAU1D97JC083772	2018 DS	DP	4369 S	6/7/2017	6/16/2017
606705	4UZCFHFE0JCJS8463	2018 DS	DP	4326 FL	6/19/2017	6/27/2017
606706	4UZCFHFE8JCJS6749	2018 DS	DP	4326 FL	6/19/2017	6/27/2017

606708	4VZAU1D99JC083773	2018 DS	DP	4310 S	6/8/2017	6/16/2017
606710	4UZFCHE7JCJR6372	2018 DS	DP	4311 FL	8/21/2017	8/29/2017
606711	4UZFCHE9JCJR8351	2018 DS	DP	4326 FL	6/6/2017	6/14/2017
606712	4UZFCHE4JCJS2407	2018 DS	DP	4018 FL	6/9/2017	6/19/2017
606713	4UZFCHE3JCJR8345	2018 DS	DP	4018 FL	6/6/2017	6/14/2017
606715	4UZFCHE7JCJR8350	2018 DS	DP	4369 FL	6/7/2017	6/15/2017
606719	4UZFCHEXJCJU6677	2018 DS	DP	4327 FL	8/14/2017	8/22/2017
606720	4VZAU1D92JC084070	2018 DS	DP	4362 S	7/31/2017	8/8/2017
606721	4VZAU1D95JC083768	2018 DS	DP	4052 S	6/20/2017	6/28/2017
606722	4VZAU1D90JC083998	2018 DS	DP	4362 S	7/18/2017	7/26/2017
606723	4UZFCHE5JCJR6371	2018 DS	DP	4362 FL	6/6/2017	6/14/2017
606725	4UZFCHE9JCJV3667	2018 DS	DP	4369 FL	8/15/2017	8/23/2017
606726	4UZACHFE3JCJU9964	2018 DS	DP	3718 FL	8/15/2017	8/23/2017
606727	4UZFCHE7JCJU4885	2018 DS	DP	4002 FL	8/16/2017	8/24/2017
606728	4UZFCHE3JCJV6158	2018 DS	DP	4002 FL	9/7/2017	9/15/2017
606729	4UZFCHE2JCJT1848	2018 DS	DP	4018 FL	7/11/2017	7/19/2017
606730	4UZFCHEXJCJT8403	2018 DS	DP	4018 FL	8/2/2017	8/9/2017
606731	4UZFCHE2JCJT5530	2018 DS	DP	4362 FL	7/11/2017	7/20/2017
606733	4UZFCHE3JCJW7502	2018 DS	DP	4018 FL	10/2/2017	10/10/2017
606734	4UZFCHE5JCJV3665	2018 DS	DP	4018 FL	8/22/2017	8/30/2017
606735	4UZFCHE4JCJT5528	2018 DS	DP	4018 FL	7/26/2017	8/2/2017
606736	4VZAU1D93JC083896	2018 DS	DP	4369 S	6/23/2017	7/12/2017
606737	4VZAU1D91JC083783	2018 DS	DP	4018 S	7/17/2017	7/25/2017
606738	4VZAU1D95JC083785	2018 DS	DP	4369 S	6/12/2017	6/20/2017
606740	4VZAU1D9XJC084401	2018 DS	DP	4327 S	9/26/2017	10/4/2017
606742	4VZAU1D9XJC083782	2018 DS	DP	4018 S	7/12/2017	7/20/2017
606743	4VZAU1D98JC084252	2018 DS	DP	4369 S	9/12/2017	9/20/2017
606744	4UZFCHE2JCJW0704	2018 DS	DP	4369 FL	9/27/2017	10/5/2017
606745	4UZFCHE7JCJV3666	2018 DS	DP	4326 FL	8/2/2017	8/10/2017
606754	4VZAU1D98JC084400	2018 DS	DP	4369 S	10/3/2017	10/11/2017
606757	4UZFCHE4JCJS6747	2018 DS	DP	4018 FL	6/26/2017	7/13/2017
606758	4UZFCHE6JCJS2408	2018 DS	DP	4018 FL	6/13/2017	6/21/2017
606761	4UZFCHE6JCJW0706	2018 DS	DP	4327 FL	9/27/2017	10/5/2017
606765	4UZFCHE5JCJU2245	2018 DS	DP	4369 FL	7/19/2017	7/26/2017
606766	4UZFCHE0JCJV3668	2018 DS	DP	4369 FL	8/17/2017	8/25/2017
606771	4UZFCHE9JCJU4886	2018 DS	DP	4018 FL	8/23/2017	8/31/2017
606772	4UZFCHE5JCJW7503	2018 DS	DP	4018 FL	10/3/2017	10/11/2017
606773	4UZFCHE0JCJU4887	2018 DS	DP	4018 FL	8/24/2017	8/31/2017
606774	4UZFCHE4JCJT1849	2018 DS	DP	4018 FL	7/13/2017	7/21/2017
606775	4UZFCHE5JCJV6159	2018 DS	DP	4018 FL	9/12/2017	9/20/2017
606776	4UZACHFE9JCJV6157	2018 DS	DP	3736 FL	9/7/2017	9/14/2017
606777	4VZAU1D91JC083895	2018 DS	DP	4018 S	8/24/2017	9/1/2017
606778	4VZAU1D99JC084390	2018 DS	DP	4369 S	9/22/2017	10/2/2017
606780	4VZAU1D96JC084072	2018 DS	DP	4369 S	8/3/2017	8/11/2017
606781	4VZAU1D96JC084301	2018 DS	DP	4369 S	9/13/2017	9/21/2017
606782	4VZAU1D92JC084151	2018 DS	DP	4369 S	8/18/2017	8/28/2017
606783	4VZAU1D92JC083999	2018 DS	DP	4018 S	7/26/2017	8/3/2017

606784	4VZAU1D94JC084006	2018 DS	DP	4018 S	8/9/2017	8/17/2017
606786	4VZAU1D92JC084084	2018 DS	DP	4369 S	8/10/2017	8/18/2017
606787	4VZAU1D94JC083759	2018 DS	DP	4018 S	6/14/2017	6/22/2017
606788	4VZAU1D95JC084001	2018 DS	DP	4369 S	7/25/2017	8/2/2017
606789	4UZFCHFE2JCJU4888	2018 DS	DP	4327 FL	7/25/2017	8/2/2017
606790	4UZFCHFE0JCJV3671	2018 DS	DP	4327 FL	8/25/2017	9/1/2017
606791	4UZFCHFE2JCJS8464	2018 DS	DP	4369 FL	6/20/2017	6/28/2017
606792	4UZFCHFE3JCJV6161	2018 DS	DP	4369 FL	8/25/2017	9/5/2017
606793	4UZFCHFE7JCJW3582	2018 DS	DP	4369 FL	9/27/2017	10/5/2017
606794	4VZAU1D9XJC083877	2018 DS	DP	4327 S	6/21/2017	6/29/2017
606795	4UZFCHFE7JCJW0701	2018 DS	DP	4327 FL	9/19/2017	9/27/2017
606796	4UZFCHFE3JCJT8405	2018 DS	DP	4326 FL	7/19/2017	7/27/2017
606797	4UZFCHFE6JCJV8728	2018 DS	DP	4326 FL	9/13/2017	9/21/2017
606798	4UZACHFE9JCJU4834	2018 DS	DP	3736 FL	7/27/2017	8/3/2017
606801	4UZFCHFE4JCJS6750	2018 DS	DP	4310 FL	6/14/2017	6/23/2017
606802	4VZAU1D97JC083996	2018 DS	DP	4362 S	7/10/2017	7/18/2017
606803	4VZAU1D96JC083875	2018 DS	DP	4018 S	7/17/2017	7/25/2017
606804	4VZAU1D99JC083997	2018 DS	DP	4327 S	7/18/2017	7/26/2017
606805	4UZFCHFE3JCJV3664	2018 DS	DP	4018 FL	8/25/2017	9/5/2017
606806	4UZFCHFE0JCJV8725	2018 DS	DP	4018 FL	9/18/2017	9/26/2017
606807	4VZAU1D90JC084309	2018 DS	DP	4018 S	9/8/2017	9/18/2017
606808	4VZAU1D90JC084326	2018 DS	DP	4018 S	9/28/2017	10/6/2017
606810	4UZFCHFE9JCJV6164	2018 DS	DP	4369 FL	9/6/2017	9/14/2017
606812	4VZAU1D96JC084251	2018 DS	DP	4018 S	9/6/2017	9/14/2017
606813	4VZAU1D94JC084328	2018 DS	DP	4362 S	9/19/2017	9/27/2017
606816	4UZACHFE4JCJU6670	2018 DS	DP	3718 FL	8/3/2017	8/14/2017
606817	4UZFCHFE0JCJT1850	2018 DS	DP	4327 FL	6/27/2017	7/13/2017
606818	4UZFCHFE4JCJV8727	2018 DS	DP	4369 FL	9/19/2017	9/27/2017
606819	4UZFCHFE0JCJW0703	2018 DS	DP	4327 FL	9/20/2017	9/28/2017
606820	4VZAU1D90JC083760	2018 DS	DP	4052 S	6/15/2017	6/23/2017
606821	4VZAU1D93JC084241	2018 DS	DP	4362 S	9/1/2017	9/13/2017
606822	4VZAU1D93JC083784	2018 DS	DP	4369 S	6/15/2017	6/23/2017
606823	4VZAU1D91JC083878	2018 DS	DP	4369 S	6/21/2017	7/10/2017
606824	4VZAU1D93JC084000	2018 DS	DP	4362 S	7/20/2017	7/27/2017
606825	4VZAU1D93JC083879	2018 DS	DP	4362 S	6/21/2017	7/10/2017
606826	4VZAU1D92JC084067	2018 DS	DP	4327 S	7/27/2017	8/4/2017
606828	4UZACHFE2JCJS8460	2018 DS	DP	3736 FL	6/15/2017	6/23/2017
606830	4UZACHFE8JCJT5526	2018 DS	DP	3736 FL	6/28/2017	7/14/2017
606831	4UZACHFE8JCJU6672	2018 DS	DP	3736 FL	8/10/2017	8/18/2017
606832	4VZAU1D97JC083769	2018 DS	DP	4018 S	6/22/2017	7/10/2017
606833	4UZFCHFE2JCJT5527	2018 DS	DP	4018 FL	6/28/2017	7/14/2017
606834	4VZAU1D92JC083758	2018 DS	DP	4018 S	6/9/2017	6/19/2017
606835	4UZFCHFE6JCJS6748	2018 DS	DP	4018 FL	6/22/2017	7/10/2017
606836	4VZAU1D98JC084302	2018 DS	DP	4369 S	9/14/2017	9/22/2017
606837	4VZAU1D92JC084330	2018 DS	DP	4369 S	9/21/2017	9/29/2017
606838	4VZAU1D95JC083950	2018 DS	DP	4369 S	7/13/2017	7/21/2017
606839	4UZFCHFE1JCJT8404	2018 DS	DP	4369 FL	7/20/2017	7/28/2017

606840	4VZAU1D97JC084002	2018 DS	DP	4369 S	7/21/2017	7/31/2017
606841	4VZAU1D94JC084068	2018 DS	DP	4369 S	7/27/2017	8/4/2017
606843	4UZFCHFE3JCJU2244	2018 DS	DP	4018 FL	8/11/2017	8/21/2017
606845	4VZAU1D96JC084069	2018 DS	DP	4369 S	7/28/2017	8/7/2017
606851	4VZAU1D96JC084329	2018 DS	DP	4362 S	9/21/2017	9/28/2017
606852	4VZAU1D92JC084389	2018 DS	DP	4327 S	9/22/2017	9/29/2017
606859	4UZFCHFE9JCS8462	2018 DS	DP	4018 FL	6/28/2017	7/17/2017
606860	4VZAU1D93JC083770	2018 DS	DP	4018 S	6/22/2017	7/11/2017
606867	4VZAU1D99JC084003	2018 DS	DP	4369 S	7/21/2017	7/31/2017
606869	4UZFCHFE9JCJW7505	2018 DS	DP	4327 FL	10/4/2017	10/12/2017
606871	4UZFCHFE5JCS6790	2018 DS	DP	4311 FL	6/23/2017	7/11/2017
606872	4UZFCHFE9JCJV3670	2018 DS	DP	4326 FL	8/7/2017	8/14/2017
606876	4VZAU1D97JC084243	2018 DS	DP	4369 S	9/5/2017	9/13/2017
606880	4VZAU1D97JC083951	2018 DS	DP	4369 S	7/10/2017	7/18/2017
606881	4UZFCHFE2JCJU6673	2018 DS	DP	4327 FL	8/4/2017	8/14/2017
606882	4UZFCHFE4JCJU6674	2018 DS	DP	4369 FL	8/11/2017	8/21/2017
606883	4VZAU1D92JC084182	2018 DS	DP	4369 S	8/28/2017	9/5/2017
606885	4UZFCHFE7JCJV6163	2018 DS	DP	4369 FL	9/7/2017	9/15/2017
606887	4UZFCHFE1JCJU2243	2018 DS	DP	4018 FL	8/10/2017	8/17/2017
606893	4UZFCHFE2JCJT1851	2018 DS	DP	4369 FL	6/23/2017	7/12/2017
606895	4UZFCHFE2JCJW0699	2018 DS	DP	4018 FL	10/4/2017	10/12/2017
606897	4VZAU1D95JC084080	2018 DS	DP	4369 S	8/4/2017	8/14/2017
606902	4UZFCHFE0JCJU4890	2018 DS	DP	4362 FL	7/28/2017	8/4/2017
606915	4VZAU1D90JC084391	2018 DS	DP	4369 S	9/25/2017	10/3/2017
606916	4UZFCHFE2JCJV3672	2018 DS	DP	4369 FL	8/18/2017	8/28/2017
606944	4UZFCHFE4JCJU4889	2018 DS	DP	4369 FL	7/31/2017	8/7/2017
606945	4VZAU1D94JC084149	2018 DS	DP	4369 S	8/17/2017	8/24/2017
606946	4VZAU1D90JC084150	2018 DS	DP	4310 S	8/17/2017	8/25/2017
606947	4UZFCHFE2JCJV3669	2018 DS	DP	4369 FL	8/23/2017	8/30/2017
606948	4VZAU1D97JC083948	2018 DS	DP	4018 S	8/30/2017	9/8/2017
606949	4VZAU1D95JC083947	2018 DS	DP	4018 S	8/30/2017	9/7/2017
606951	4UZFCHFE7JCJU2246	2018 DS	DP	4369 FL	7/24/2017	7/31/2017
606952	4VZAU1D94JC084183	2018 DS	DP	4327 S	8/28/2017	9/6/2017
606954	4VZAU1D9XJC084303	2018 DS	DP	4369 S	9/15/2017	9/25/2017
606955	4UZFCHFE8JCJT8402	2018 DS	DP	4018 FL	8/1/2017	8/8/2017
606964	4VZAU1D92JC084148	2018 DS	DP	4369 S	8/16/2017	8/23/2017
606965	4VZAU1D97JC084081	2018 DS	DP	4369 S	8/7/2017	8/15/2017
606966	4VZAU1D99JC084082	2018 DS	DP	4326 S	8/9/2017	8/16/2017
606967	4VZAU1D9XJC083894	2018 DS	DP	4002 S	8/18/2017	8/28/2017
606968	4VZAU1D98JC083876	2018 DS	DP	4018 S	7/24/2017	8/1/2017
606969	4VZAU1D96JC084007	2018 DS	DP	4327 S	8/8/2017	8/16/2017
606971	4VZAU1D90JC084083	2018 DS	DP	4369 S	8/9/2017	8/16/2017
606973	4VZAU1D96JC084184	2018 DS	DP	4369 S	8/29/2017	9/7/2017
606974	4VZAU1D90JC084181	2018 DS	DP	4369 S	8/23/2017	9/5/2017
606981	4VZAU1D94JC084152	2018 DS	DP	4369 S	8/21/2017	8/29/2017
606986	4UZFCHFE6JCJU6675	2018 DS	DP	4369 FL	8/8/2017	8/16/2017
606987	4UZFCHFE2JCJV8726	2018 DS	DP	4326 FL	8/31/2017	9/11/2017

606999	4VZAU1D99JC084325	2018 DS	DP	4018 S	9/15/2017	9/25/2017
607001	4VZAU1D93JC084403	2018 DS	DP	4369 S	9/25/2017	10/3/2017
607040	4UZCFHFE4JCJW0705	2018 DS	DP	4326 FL	9/26/2017	10/4/2017
607058	4VZAU1D91JC084240	2018 DS	DP	4310 S	8/31/2017	9/11/2017
607060	4UZCFHFE9JCJW0702	2018 DS	DP	4369 FL	9/22/2017	10/2/2017
607094	4UZCFHFE1JCJV6160	2018 DS	DP	4018 FL	9/8/2017	9/18/2017
607095	4VZAU1D97JC084386	2018 DS	DP	4018 S	9/29/2017	10/9/2017
607099	4VZAU1D91JC084402	2018 DS	DP	4369 S	10/2/2017	10/9/2017
607112	4VZAU1D92JC084327	2018 DS	DP	4369 S	9/18/2017	9/26/2017
607121	4UZCFHFE8JCJV8729	2018 DS	DP	4369 FL	9/15/2017	9/25/2017
607135	4VZAU1D92JC084392	2018 DS	DP	4362 S	9/26/2017	10/4/2017
710207	4UZACEFCXJCJR8348	2018 NA	DP	3341 FL	7/11/2017	7/19/2017
710208	4UZACEFC7JCJS8466	2018 NA	DP	3341 FL	7/31/2017	8/8/2017
710209	4UZACEFC3JCJT8413	2018 NA	DP	3343 FL	8/22/2017	8/30/2017
710210	4UZACEFC0JCJT1855	2018 NA	DP	3343 FL	8/10/2017	8/18/2017
710211	4UZACEFC9JCJT1854	2018 NA	DP	3343 FL	8/7/2017	8/15/2017
710214	4UZACEFC9JCJT5533	2018 NA	DP	3341 FL	8/16/2017	8/24/2017
710215	4UZACEFC3JCJU5040	2018 NA	DP	3343 FL	8/31/2017	9/11/2017
710219	4UZACEFC5JCJU2253	2018 NA	DP	3343 FL	8/28/2017	9/6/2017
710221	4UZACEFC1JCJR8349	2018 NA	DP	3341 FL	7/13/2017	7/21/2017
710224	4UZACEFC9JCJV3675	2018 NA	DP	3343 FL	9/18/2017	9/26/2017
710226	4UZACEFC2JCJT1856	2018 NA	DP	3343 FL	8/11/2017	8/18/2017
710227	4UZACEFC2JCJU9967	2018 NA	DP	3341 FL	9/11/2017	9/19/2017
710228	4UZACEFC7JCJU5042	2018 NA	DP	3343 FL	9/6/2017	9/13/2017
710229	4UZACEFC1JCJS6793	2018 NA	DP	3341 FL	7/20/2017	7/28/2017
710232	4UZACEFC1JCJW3584	2018 NA	DP	3343 FL	10/3/2017	10/11/2017
710233	4UZACEFC7JCJT8415	2018 NA	DP	3343 FL	8/24/2017	9/1/2017
710234	4UZACEFC0JCJU9966	2018 NA	DP	3343 FL	9/8/2017	9/18/2017
710236	4UZACEFC7JCJV8731	2018 NA	DP	3343 FL	9/27/2017	10/5/2017
710240	4UZACEFC3JCJS6794	2018 NA	DP	3343 FL	7/25/2017	8/2/2017
710243	4UZACEFC9JCJS2426	2018 NA	DP	3341 FL	7/26/2017	8/3/2017
710244	4UZACEFC5JCJR6376	2018 NA	DP	3341 FL	7/17/2017	7/25/2017
710245	4UZACEFC5JCJS6795	2018 NA	DP	3343 FL	7/27/2017	8/4/2017
710247	4UZACEFC2JCJV3677	2018 NA	DP	3343 FL	9/14/2017	9/22/2017
710250	4UZACEFC3JCJR6375	2018 NA	DP	3341 FL	6/29/2017	7/17/2017
710251	4UZACEFC7JCJS2425	2018 NA	DP	3343 FL	8/3/2017	8/11/2017
710252	4UZACEFC5JCJS2424	2018 NA	DP	3343 FL	7/18/2017	7/26/2017
710253	4UZACEFC9JCJV8732	2018 NA	DP	3343 FL	9/28/2017	10/6/2017
710256	4UZACEFC1JCJU2251	2018 NA	DP	3343 FL	9/21/2017	9/29/2017
710261	4UZACEFC7JCJT5532	2018 NA	DP	3343 FL	8/14/2017	8/22/2017
710275	4UZACEFC5JCJT8414	2018 NA	DP	3343 FL	8/21/2017	8/29/2017
710276	4UZACEFC5JCJU5041	2018 NA	DP	3343 FL	9/1/2017	9/11/2017
710279	4UZACEFC5JCJV8730	2018 NA	DP	3343 FL	9/25/2017	10/3/2017
801250	4VZVU1E99JC083787	2018 EX	DP	4531 S	6/21/2017	6/29/2017
801253	4UZFTFG7JCJR3945	2018 EX	DP	4531 FL	6/15/2017	6/23/2017
801254	4VZVU1E98JC083778	2018 EX	DP	4531 S	6/7/2017	6/15/2017
801256	4UZFTFG3JCJS6792	2018 EX	DP	4531 FL	6/28/2017	7/14/2017

801257	4VZVU1E99JC083899	2018 EX	DP	4553 S	7/11/2017	7/19/2017
801258	4VZVU1E93JC084076	2018 EX	DP	4531 S	8/18/2017	8/25/2017
801259	4VZVU1E91JC084075	2018 EX	DP	4531 S	8/4/2017	8/11/2017
801260	4VZVU1E9XJC084396	2018 EX	DP	4553 S	9/20/2017	9/27/2017
801261	4UZFTFG5JCJT8412	2018 EX	DP	4531 FL	8/10/2017	8/18/2017
801263	4VZVU1E99JC083952	2018 EX	DP	4531 S	7/19/2017	7/27/2017
801264	4VZVU1E9XJC084009	2018 EX	DP	4531 S	7/26/2017	8/2/2017
801265	4VZVU1E91JC084254	2018 EX	DP	4531 S	9/5/2017	9/13/2017
801266	4UZFTFG0JCJT1853	2018 EX	DP	4553 FL	8/2/2017	8/10/2017
801268	4UZFTFG3JCJU2250	2018 EX	DP	4531 FL	8/22/2017	8/30/2017
801270	4VZVU1E99JC084406	2018 EX	DP	4531 S	9/29/2017	10/6/2017
801273	4UZFTFG0JCJU5039	2018 EX	DP	4534 FL	9/13/2017	9/20/2017
801274	4VZVU1E9XJC084334	2018 EX	DP	4553 S	9/14/2017	9/22/2017
904536	4VZVU1E92JC083789	2018 MA	DP	4047 S	6/14/2017	6/22/2017
904537	4VZVU1E9XJC084219	2018 MA	DP	4553 S	9/7/2017	9/15/2017
904539	4VZVU1E98JC084185	2018 MA	DP	4553 S	8/29/2017	9/7/2017
904540	4VZVU1E92JC083775	2018 MA	DP	4531 S	6/16/2017	6/26/2017
904541	4VZVU1E96JC083780	2018 MA	DP	4047 S	6/6/2017	6/14/2017
904542	4VZVU1E9XJC083880	2018 MA	DP	4531 S	7/18/2017	7/25/2017
904543	4VZVU1E91JC084013	2018 MA	DP	4047 S	8/1/2017	8/9/2017
904544	4VZVU1E94JC084393	2018 MA	DP	4537 S	10/2/2017	10/10/2017
904546	4VZVU1E94JC083955	2018 MA	DP	4047 S	6/22/2017	7/10/2017
904547	4UZFTBG1JCJS8465	2018 MA	DP	4531 FL	9/20/2017	9/28/2017
904550	4UZFTBG6JCJR6373	2018 MA	DP	4553 FL	8/22/2017	8/29/2017
904551	4VZVU1E95JC084399	2018 MA	DP	4047 S	9/18/2017	9/26/2017
904552	4VZVU1E98JC083781	2018 MA	DP	4047 S	6/8/2017	6/16/2017
904553	4VZVU1E98JC084008	2018 MA	DP	4553 S	7/19/2017	7/27/2017
904554	4VZVU1E97JC084307	2018 MA	DP	4047 S	9/11/2017	9/18/2017
904555	4VZVU1E98JC084073	2018 MA	DP	4047 S	7/26/2017	8/3/2017
904556	4UZFTBG6JCJR3943	2018 MA	DP	4531 FL	8/8/2017	8/16/2017
904559	4VZVU1E9XJC084012	2018 MA	DP	4047 S	7/14/2017	7/24/2017
904562	4VZVU1E92JC084246	2018 MA	DP	4047 S	9/5/2017	9/12/2017
904563	4VZVU1E93JC084014	2018 MA	DP	4047 S	7/20/2017	7/28/2017
904564	4VZVU1E90JC084410	2018 MA	DP	4047 S	10/3/2017	10/11/2017
904565	4VZVU1E98JC083764	2018 MA	DP	4531 S	6/12/2017	6/21/2017
904566	4VZVU1E99JC084308	2018 MA	DP	4047 S	9/14/2017	9/21/2017
904567	4VZVU1E94JC083776	2018 MA	DP	4531 S	6/23/2017	7/12/2017
904569	4VZVU1E97JC084078	2018 MA	DP	4047 S	7/24/2017	8/1/2017
904571	4VZVU1E90JC084178	2018 MA	DP	4553 S	8/23/2017	8/31/2017
904574	4UZFTBG3JCJS2411	2018 MA	DP	4535 FL	9/12/2017	9/20/2017
904576	4VZVU1E9XJC084186	2018 MA	DP	4047 S	8/23/2017	8/31/2017
904577	4VZVU1E94JC084409	2018 MA	DP	4047 S	9/25/2017	10/2/2017
904581	4UZFTBG8JCZZ2509	2018 MA	DP	4553 FL	9/7/2017	9/14/2017
904586	4VZVU1E96JC084332	2018 MA	DP	4553 S	9/26/2017	10/4/2017

Canadian Units

112767	1F66F5DY6H0A17549	2018 BS	CA	3532 F	6/13/2017	6/22/2017
--------	-------------------	---------	----	--------	-----------	-----------

112768	1F66F5DY7H0A18015	2018	BS	CA	3518	F	6/26/2017	7/12/2017
112811	1F65F5DY7J0A00129	2018	BT	CA	2702	F	6/16/2017	6/26/2017
112820	1F66F5DY0J0A00137	2018	BS	CA	3414	F	6/7/2017	6/15/2017
112821	1F66F5DY5J0A02143	2018	BS	CA	3414	F	8/17/2017	8/25/2017
112822	1F66F5DY5J0A00974	2018	BS	CA	3518	F	7/12/2017	7/20/2017
112823	1F66F5DY6J0A00773	2018	BS	CA	3532	F	6/27/2017	7/13/2017
112890	1F66F5DYXJ0A00968	2018	BS	CA	3414	F	7/13/2017	7/21/2017
112941	1F66F5DY5H0A16750	2018	BT	CA	2903	F	8/31/2017	9/8/2017
112965	1F66F5DY6H0A15879	2018	BT	CA	3113	F	8/10/2017	8/18/2017
113013	1F66F5DYXJ0A03109	2018	BT	CA	2903	F	9/19/2017	9/26/2017
162118	1F66F5DY1J0A01555	2018	CS	CA	3901	F	7/19/2017	7/27/2017
162119	1F66F5DY0J0A02146	2018	CS	CA	3953	F	8/8/2017	8/16/2017
162142	1F66F5DY7J0A03116	2018	CS	CA	3716	F	8/23/2017	8/30/2017
162143	1F66F5DY7J0A01558	2018	CS	CA	3710	F	8/2/2017	8/10/2017
162147	1F66F5DY6J0A01891	2018	CS	CA	3901	F	8/3/2017	8/11/2017
162216	1F66F5DY9J0A04994	2018	CS	CA	3923	F	9/29/2017	10/9/2017
413357	4UZFCHFE5JCJS8457	2018	VT	DP	4369	FL	6/28/2017	7/14/2017
413371	4UZAB2FC0CJU2226	2018	VL	DP	3413	FL	7/24/2017	8/1/2017
413372	4UZFCHFE7JCJT1845	2018	VT	DP	4037	FL	7/27/2017	8/4/2017
413373	4UZFCHFE7JCJS8458	2018	VT	DP	4308	FL	6/28/2017	7/14/2017
413374	4UZFCHFE2JCJU9962	2018	VT	DP	4308	FL	8/17/2017	8/25/2017
413437	4UZFCHFE2JCJR6361	2018	VT	DP	4037	FL	6/8/2017	6/16/2017
413438	4UZFCHFE1JCJT8399	2018	VT	DP	4037	FL	7/28/2017	8/7/2017
413463	4UZAB2FC6JCJW3565	2018	VL	DP	3412	FL	9/27/2017	10/5/2017
413464	4UZACHFC9CJU9952	2018	VL	DP	4037	FL	8/10/2017	8/17/2017
413551	4UZACHFC0CJCV8720	2018	VT	DP	3436	FL	9/14/2017	9/22/2017
413562	4UZFCHFE5JCJR6365	2018	VT	DP	4311	FL	8/21/2017	8/29/2017
501525	4VZVU1E97JC083898	2018	LA	DP	4533	S	7/28/2017	8/7/2017
530457	4VZVU1E91JC084187	2018	KG	DB	4598	S	8/25/2017	9/5/2017
606698	4UZACHFE9JCJR6366	2018	DS	DP	3736	FL	6/5/2017	6/13/2017
606717	4VZAU1D94JC084300	2018	DS	DP	4369	S	9/11/2017	9/19/2017
606718	4UZACHFE7JCJR8343	2018	DS	DP	3736	FL	6/16/2017	6/26/2017
606741	4UZFCHFE7JCJS8461	2018	DS	DP	4018	FL	7/12/2017	7/20/2017
606751	4VZAU1D99JC083949	2018	DS	DP	4327	S	7/13/2017	7/21/2017
606752	4VZAU1D95JC083897	2018	DS	DP	4362	S	6/27/2017	7/13/2017
606753	4VZAU1D90JC083774	2018	DS	DP	4362	S	6/13/2017	6/21/2017
606799	4VZAU1D99JC084079	2018	DS	DP	4327	S	8/3/2017	8/11/2017
606800	4VZAU1D95JC084242	2018	DS	DP	4369	S	9/1/2017	9/12/2017
606844	4VZAU1D90JC084147	2018	DS	DP	4326	S	8/14/2017	8/22/2017
606847	4UZFCHFE5JCJV6162	2018	DS	DP	4327	FL	8/31/2017	9/8/2017
606848	4UZACHFE9JCJV3663	2018	DS	DP	3736	FL	9/5/2017	9/12/2017
606858	4UZACHFE7JCJU2242	2018	DS	DP	3736	FL	7/14/2017	7/24/2017
606868	4UZACHFE5JCJU9965	2018	DS	DP	3718	FL	8/17/2017	8/25/2017
606870	4UZFCHFE6JCJT5529	2018	DS	DP	4369	FL	6/29/2017	7/17/2017
606874	4VZAU1D92JC084005	2018	DS	DP	4018	S	8/4/2017	8/11/2017
606892	4UZFCHFE8JCJU6676	2018	DS	DP	4369	FL	8/7/2017	8/15/2017
606911	4UZFCHFE9JCJV8724	2018	DS	DP	4018	FL	9/15/2017	9/25/2017

606912	4UZCFHFE5JCJW0700	2018 DS	DP	4018 FL	9/29/2017	10/9/2017
606950	4VZAU1D90JC084004	2018 DS	DP	4310 S	7/24/2017	8/1/2017
606970	4VZAU1D94JC084071	2018 DS	DP	4369 S	8/1/2017	8/9/2017
710212	4UZACEFC3JCJU2252	2018 NA	DP	3341 FL	8/29/2017	9/6/2017
710213	4UZACEFC9JCJS8467	2018 NA	DP	3343 FL	8/1/2017	8/9/2017
710217	4UZACEFC9JCJW0707	2018 NA	DP	3343 FL	9/29/2017	10/9/2017
710218	4UZACEFC1JCJR6374	2018 NA	DP	3343 FL	6/27/2017	7/13/2017
710237	4UZACEFC4JCJU9968	2018 NA	DP	3343 FL	9/13/2017	9/21/2017
710238	4UZACEFC0JCJV3676	2018 NA	DP	3341 FL	9/19/2017	9/27/2017
710241	4UZACEFC0JCJT5534	2018 NA	DP	3343 FL	8/17/2017	8/25/2017
801255	4VZVU1E96JC084010	2018 EX	DP	4534 S	7/28/2017	8/9/2017
801267	4VZVU1E98JC084087	2018 EX	DP	4553 S	8/28/2017	9/6/2017
904549	4VZVU1E94JC084331	2018 MA	DP	4534 S	9/21/2017	9/29/2017
904557	4VZVU1E91JC084156	2018 MA	DP	4047 S	8/15/2017	8/22/2017
904584	4VZVU1E96JC084153	2018 MA	DP	4553 S	8/4/2017	8/14/2017
904585	4UZFCTBG2JCJR8346	2018 MA	DP	4531 FL	8/30/2017	9/8/2017