

NEWMAR CORPORATION

WARRANTY

DEPARTMENT

RECALL SERVICE BULLETIN

DATE ISSUED

MODEL YEAR(S) AFFECTED

RSB #

9/4/18

2018, 2019

528

MODEL

Bay Star Sport	☐	Ventana	☒	Essex	☒
Bay Star	☐	Dutch Star	☒	King Aire	☒
Canyon Star	☐	Mountain Aire	☒	New Aire	☒
Ventana LE	☒	London Aire	☒	Other	☐

DESCRIPTION

Newmar Corporation has decided that a defect relating to motor vehicle safety exists in specific motorhomes. NHTSA 18V 518, TC# 2018-413

Issue: On certain motorhomes, the latch on the entry door may not engage properly. This may allow the door to open unexpectedly while the vehicle is in transit, increasing the risk of injury.

Correction: Dealers will adjust the entry door to ensure that the latch engages properly.

This recall applies only to specific 2018 and 2019 coaches. Refer to the attached population list for specific production numbers and VINs of the affected coaches.

RECOMMENDED ACTION

Contact your Service Account Manager at Newmar for authorization and parts (if needed), and follow the attached work instructions provided by PTL door to ensure the linkage is adjusted properly.

If the door closes hard, the rubber bumpers between the door and screen door should be checked and replaced with the 13/16" (PTL part # 007-118, Newmar part # 027862) if necessary. This should be done in lieu of adjusting the Mov-A-Bolt assembly to move the striker bolt out.

Flat rate code: 18V 518 Time: .5 hr.

Please read this bulletin in its entirety prior to beginning any diagnosis or repairs.



WHEN YOU KNOW THE DIFFERENCE

NEWMAR CORPORATION

NEWMARCORP.COM

Date: August 17, 2018

Re: Newmar Corporation – Motor Vehicle Recall Notification

Subject: Recall Campaign No.: 18V 518

This notice is sent to you as a Newmar Dealer in accordance with the requirements of the National Traffic and Motor Vehicle Safety Act. Newmar Corporation has decided that a defect, which relates to motor vehicle safety, exists in specific Newmar recreational vehicles.

The National Traffic and Motor Vehicle Safety Act requires that each vehicle, which is subject to a recall campaign of this type, must be satisfactorily repaired within a reasonable time after the owner has tendered it for repair. A failure to adequately repair within 60 days after tender of a vehicle is prima facie evidence of failure to repair within a reasonable time. To avoid providing these problematic solutions, every effort must be made to promptly schedule an appointment with each owner and to repair their vehicle as soon as possible. Vehicle owners are being notified of this recall. If the condition is not remedied within a reasonable time, they are instructed on how to contact the National Highway Traffic Safety Administration.

REASON FOR THIS RECALL

Newmar Corporation has decided that a defect, which relates to motor vehicle safety, exists in specific motorhomes.

On certain motorhomes, the latch on the entry door may not engage properly. This could allow the door to open unexpectedly when the vehicle is in transit, which could increase the risk of injury. Correction: Dealers will adjust the entry door to ensure that the latch engages properly.

The motorhomes require immediate service. Continued use poses a potential safety hazard.

DEALER CAMPAIGN RESPONSIBILITY

Dealers are to provide to all customers/owner vehicles the service of completing this campaign at no charge to the customer/owner regardless of vehicle age, vehicle mileage, or ownership at the time of repair.

REPAIR PROCEDURE

PTL Engineering will provide the work instructions.

If you should have any questions please contact your service account manager direct or the Newmar service department at: 1-866-290-5371.

Thank you for your cooperation.

Sincerely,

Newmar Corporation



WHEN YOU KNOW THE DIFFERENCE

NEWMAR CORPORATION

NEWMARCORP.COM

IMPORTANT SAFETY RECALL

This notice applies to your vehicle VIN. # _____

Name

Address

City, State Zip code

Date: August 17, 2018

Motor Vehicle Recall Notification - Recall Campaign No. 18V 518

Dear Valued Customer:

This notice is sent to you in accordance with the requirements of the National Traffic and Motor Vehicle Safety Act.

REASON FOR THIS RECALL

Newmar Corporation has decided that a defect, which relates to motor vehicle safety, exists in specific motorhomes.

On certain motorhomes, the latch on the entry door may not engage properly. This could allow the door to open unexpectedly when the vehicle is in transit, which could increase the risk of injury. Correction: Dealers will adjust the entry door to ensure that the latch engages properly.

The motorhomes require immediate service. Continued use poses a potential safety hazard.

The Safety Risk

Having a door out of adjustment could allow the door to open unexpectedly when the vehicle is in transit, which could increase the risk of injury.

WHAT WE WILL DO

PTL Engineering will provide owners of all affected motorhomes a remedy for the potential defect at no charge for parts or labor. This remedy consists of adjusting the entry door to ensure the latch engages properly. Approximate time for this repair is 0.5 hrs. depending on adjustment needed.

WHAT YOU NEED TO DO

As this defect does affect motor vehicle safety, it is recommended that you contact the Newmar service department immediately at **1-800-731-8300**. An associate will assist you in making an appointment to have this repair done by authorized Newmar Dealer.

Federal regulations require that any vehicle lessor receiving this recall notification must forward a copy of this notice to the lessee within ten days.

If you have had the repair performed before receiving this letter, you may be eligible to receive reimbursement for the cost of obtaining a pre-notification remedy. For additional information, contact Newmar Corporation at:

Service Department
Newmar Corporation
355 N Delaware St
Nappanee, IN 46550-0030

Newmar dealers are best equipped to obtain parts and provide service to ensure your vehicle is corrected as promptly as possible. HOWEVER, if you take your vehicle to your dealer on the scheduled date and this condition is not remedied on that date or within five days; please contact the Newmar Corporation Customer Service Department at 1-800-731-8300. You may also submit a complaint to the Administrator, National Highway Traffic Safety Administration, 1200 New Jersey Ave., SE., Washington DC 20590; or call the toll-free Vehicle Safety Hotline at 1-888-327-4236 (TTY: 1-800-424-9153); or go to <http://www.safercar.gov>.

If you no longer own this vehicle, please furnish us the complete name and address of the person or dealership you sold or traded your vehicle to. Thank you for your cooperation.

Your safety and satisfaction with your Newmar product is important to us and we regret any inconvenience to you.

Sincerely,

Newmar Corporation



WHEN YOU KNOW THE DIFFERENCE

NEWMAR CORPORATION

NEWMARCORP.COM

Date: August 17, 2018
Re: Newmar Corporation – Motor Vehicle Recall Notification

Subject: Recall Campaign No.: 2018-413

This notice is sent to you as a Newmar Dealer in accordance with the requirements of the Canada Motor Vehicle Safety Act. Newmar Corporation has decided that a defect, which relates to motor vehicle safety, exists in specific Newmar recreational vehicles.

Each vehicle, which is subject to a recall campaign of this type, must be satisfactorily repaired within a reasonable time after the owner has tendered it for repair. A failure to adequately repair within 60 days after tender of a vehicle is prima facie evidence of failure to repair within a reasonable time. To avoid providing these problematic solutions, every effort must be made to promptly schedule an appointment with each owner and to repair their vehicle as soon as possible. Vehicle owners are being notified of this recall. If the condition is not remedied within a reasonable time, they are instructed to contact Transport Canada.

REASON FOR THIS RECALL

Newmar Corporation has decided that a defect, which relates to motor vehicle safety, exists in specific motorhomes.

On certain motorhomes, the latch on the entry door may not engage properly. This could allow the door to open unexpectedly when the vehicle is in transit, which could increase the risk of injury. Correction: Dealers will adjust the entry door to ensure that the latch engages properly.

The motorhomes require immediate service. Continued use poses a potential safety hazard.

DEALER CAMPAIGN RESPONSIBILITY

Dealers are to provide to all customers/owner vehicles the service of completing this campaign at no charge to the customer/owner regardless of vehicle age, vehicle mileage, or ownership at the time of repair.

REPAIR PROCEDURE

PTL Engineering will provide the work instructions.

If you should have any questions please contact your service account manager direct or the Newmar service department at: 1-866-290-5371.

Thank you for your cooperation.

Sincerely,

Newmar Corporation



WHEN YOU KNOW THE DIFFERENCE

NEWMAR CORPORATION

NEWMARCORP.COM

VIN#
Name
Address
City, State Zip code

Date: August 17, 2018
Motor Vehicle Recall Notification - Recall Campaign No. 2018-413

Dear Valued Customer:

This notice is sent to you in accordance with the requirements of the Canada Motor Vehicle Safety Act.

REASON FOR THIS RECALL

Newmar Corporation has decided that a defect, which relates to motor vehicle safety, exists in specific motorhomes.

On certain motorhomes, the latch on the entry door may not engage properly. This could allow the door to open unexpectedly when the vehicle is in transit, which could increase the risk of injury. Correction: Dealers will adjust the entry door to ensure that the latch engages properly.

The motorhomes require immediate service. Continued use poses a potential safety hazard.

WHAT WE WILL DO

PTL Engineering will provide owners of all affected motor homes a remedy for the potential defect at no charge for parts or labor. This remedy consists of adjusting the entry door to ensure the latch engages properly.

WHAT YOU NEED TO DO

As this defect does affect motor vehicle safety, it is recommended that you contact the Newmar service department immediately at **1-800-731-8300**. An associate will assist you in making an appointment to have this repair done by authorized Newmar Dealer.

Federal regulations require that any vehicle lessor receiving this recall notification must forward a copy of this notice to the lessee within ten days.

If you have had the repair performed before receiving this letter, you may be eligible to receive reimbursement for the cost of obtaining a pre-notification remedy. For additional information contact Newmar Corporation at:

Service Department
Newmar Corporation
355 N Delaware St
Nappanee, IN 46550-0030

Newmar dealers are best equipped to obtain parts and provide service to ensure your vehicle is corrected as promptly as possible. HOWEVER, if you take your vehicle to your dealer on the scheduled date and this condition is not remedied on that date or within five days; please contact the Newmar Corporation Customer Service Department at 1-800-731-8300.

If you no longer own this vehicle, please furnish us the complete name and address of the person or dealership you sold or traded your vehicle to. Thank you for your cooperation.

Your safety and satisfaction with your Newmar product is important to us and we regret any inconvenience to you.

Sincerely,

Newmar Corporation



WHEN YOU KNOW THE DIFFERENCE

NEWMAR CORPORATION.

NEWMARCORP.COM

NIV
Nom
Adresse
Ville, province, code postal

Date : 17 août 2018

Avis de rappel visant un véhicule motorisé – Campagne de rappel n° 2018-413

Madame, Monsieur,

Le présent avis vous est envoyé conformément aux exigences de la *Loi sur la sécurité automobile du Canada*.

MOTIF DU PRÉSENT RAPPEL

Newmar Corporation a déterminé qu'une défaillance relevant de la sécurité automobile existe pour certaines autocaravanes.

Le loquet de la porte d'entrée de certaines autocaravanes peut ne pas s'engager correctement. Cela pourrait occasionner l'ouverture inopinée de la porte pendant que le véhicule est en mouvement, accroissant ainsi le risque de blessures. Mesure corrective : Les concessionnaires ajusteront la porte d'entrée pour s'assurer que le loquet s'engage correctement.

Il est impératif que les réparations sur ces autocaravanes soient effectuées immédiatement. Leur utilisation prolongée pose un risque d'accident potentiel.

CE QUE NOUS FERONS

PTL Engineering fournira aux propriétaires de toutes les autocaravanes concernées une solution gratuite (pour les pièces et la main-d'œuvre) à la défaillance potentielle. La mesure corrective vise l'ajustement de la porte d'entrée pour s'assurer que le loquet s'engage correctement.

CE QUE VOUS DEVEZ FAIRE

Puisque cette défaillance touche la sécurité automobile, nous vous recommandons de communiquer immédiatement avec le service technique de Newmar en composant le **1-800-731-8300**. Un associé vous aidera à prendre rendez-vous aux fins d'exécution de cette réparation par un concessionnaire Newmar autorisé.

En vertu de règlements fédéraux, tout donneur à bail d'un véhicule, qui reçoit le présent avis de rappel, est tenu d'en acheminer une copie au preneur à bail dans un délai de dix jours.

Si les réparations ont été effectuées avant réception de la présente lettre, vous pouvez être admissible à un remboursement des frais liés à l'obtention de la solution adoptée avant réception du présent avis. Pour de plus amples renseignements, communiquez avec Newmar Corporation à l'adresse suivante :

Service Department
Newmar Corporation
355 N Delaware St
Nappanee, IN 46550-0030

Les concessionnaires Newmar sont les plus à même de fournir du service et d'obtenir des pièces qui assureront une réparation de votre véhicule dans les plus brefs délais. CELA DIT, si vous apportez votre véhicule à votre concessionnaire à la date prévue et que le problème n'est pas résolu à cette date ou dans les cinq jours qui suivent, veuillez communiquer avec le service à la clientèle de Newmar Corporation en composant le 1-800-731-8300.

Si l'autocaravane concernée ne vous appartient plus, nous vous prions de bien vouloir nous fournir le nom complet et l'adresse complète de la personne ou du concessionnaire faisant maintenant office de propriétaire. Nous vous remercions de votre coopération.

Votre sécurité et votre satisfaction par rapport à nos produits Newmar sont importantes pour nous, et nous sommes désolés de tout désagrément occasionné.

Veuillez agréer, Madame, Monsieur, l'expression de nos sentiments distingués.

Newmar Corporation



3333 John Conley Dr.
Lapeer, MI 48446
810.664.2310

Model “3000” and “7000” Entry Door Latch Rod Adjustment Procedure

* Before beginning the adjustment procedure function the outer handle to determine the travel distance. The travel on the handle before it releases the latch should be at least $\frac{3}{4}$ of the total distance. If the travel is at least $\frac{3}{4}$ of the distance no further adjustment is needed. If it is not, then proceed to step one.

1. Start the procedure by opening the door and removing the black plastic plug with a flat tip screwdriver, located just below the rotary latch on the edge of the door.
2. Using a 7/16” deep socket rotate the lock nut located behind the plug counterclockwise if the rotary releases too easily or clockwise if it doesn’t release easily enough.
3. This procedure should be done with the door in the open position by manually closing the rotary and making the adjustments until the outside handle travels $\frac{3}{4}$ of the distance before the rotary releases.
4. Test the function by closing and releasing the rotary several times with both the outside and inside handle before closing the door.
5. Replace the black plastic plug and the adjustment is complete.

*Please refer to our “How To” page tab located at the top of our home page at www.ptlengineering.com and click on the “Adjust the back to back handle rod” for a video on this procedure. You can also contact PTL Engineering directly at 810.664.2310 for assistance.

Prod#	VIN#	Year	Brand	Type	Floor Plan	Chassis	Date In	Date Off
USA Units								
607288	4VZAU1D94KC084346	2019	DS	DP	4328 S		2/26/2018	3/5/2018
413856	4VZAT1D91KC084341	2019	VT	DP	4054 S		2/14/2018	2/21/2018
607298	4UZFCHFE1KCJY2520	2019	DS	DP	4369 FL		3/21/2018	3/28/2018
413368	4UZACHFC1JCKB2523	2018	VL	DP	4037 FL		1/26/2018	2/5/2018
413416	4UZACHFC1JCJZ9681	2018	VT	DP	3709 FL		1/11/2018	1/19/2018
413418	4UZACHFC5KCKD7992	2018	VL	DP	4037 FL		3/27/2018	4/4/2018
413420	4UZFCHFE1JCKA8964	2018	VT	DP	4037 FL		1/10/2018	1/17/2018
413460	4UZACHFC8JCKC6905	2018	VL	DP	4002 FL		2/16/2018	2/26/2018
413496	4UZFCHFE7JCKA3672	2018	VT	DP	4369 FL		1/17/2018	1/25/2018
413499	4UZAB2FCXJCKA8955	2018	VL	DP	3709 FL		1/19/2018	1/29/2018
413508	4UZAB2FC7JCKB9993	2018	VL	DP	3436 FL		1/30/2018	2/6/2018
413509	4UZACHFC7JCKA8959	2018	VL	DP	4037 FL		1/22/2018	1/29/2018
413513	4UZACHFC7JCKA8962	2018	VT	DP	3407 FL		2/7/2018	2/14/2018
413514	4UZACHFC6JCKA3669	2018	VT	DP	3715 FL		1/23/2018	1/30/2018
413515	4UZACHFC3JCKC1000	2018	VT	DP	3709 FL		1/30/2018	2/7/2018
413517	4UZAB2FC8JCKA8954	2018	VL	DP	3713 FL		1/19/2018	1/26/2018
413529	4UZAB2FC6JCKA8953	2018	VL	DP	3709 FL		1/30/2018	2/7/2018
413531	4UZAB2FC3KCKD5576	2018	VL	DP	3412 FL		2/20/2018	2/27/2018
413532	4UZAB2FC2KCKD9148	2018	VL	DP	3412 FL		3/5/2018	3/13/2018
413534	4UZACHFC8JCKB9999	2018	VL	DP	4037 FL		2/6/2018	2/13/2018
413535	4UZAB2FC4JCKC6903	2018	VL	DP	3436 FL		2/14/2018	2/21/2018
413536	4UZFCHFE2JCKC6910	2018	VT	DP	4002 FL		2/7/2018	2/15/2018
413537	4UZACHFC5JCKB2525	2018	VT	DP	3407 FL		2/8/2018	2/15/2018
413538	4UZACHFC7KCKD1255	2018	VT	DP	3407 FL		2/13/2018	2/20/2018
413540	4UZACHFC5JCKA8961	2018	VT	DP	3436 FL		1/25/2018	2/1/2018
413541	4UZACHFC2JCKC0999	2018	VT	DP	3709 FL		1/23/2018	1/30/2018
413542	4UZACHFC5JCKC1001	2018	VT	DP	3715 FL		2/1/2018	2/8/2018
413544	4UZFCHFE1JCKC1004	2018	VT	DP	4037 FL		1/25/2018	2/1/2018
413545	4UZFCHFE7JCKC1007	2018	VT	DP	4037 FL		2/1/2018	2/9/2018
413546	4UZACHFCXJCKB2522	2018	VL	DP	4037 FL		1/24/2018	1/31/2018
413549	4UZFCHFE9JCKA8968	2018	VT	DP	4311 FL		2/26/2018	3/6/2018
413554	4UZFCHFE4JCKC6911	2018	VT	DP	4037 FL		2/8/2018	2/16/2018
413557	4UZFCHFEXJCKB2530	2018	VT	DP	4369 FL		2/2/2018	2/12/2018
413558	4UZAB2FC1JCKA8956	2018	VL	DP	3709 FL		1/31/2018	2/7/2018
413559	4UZAB2FC4JCKA8952	2018	VL	DP	3412 FL		1/25/2018	2/1/2018
413567	4UZACHFC5JCKA3663	2018	VL	DP	4037 FL		1/18/2018	1/26/2018
413568	4UZFCHFE5JCKA3671	2018	VT	DP	4369 FL		1/17/2018	1/24/2018
413571	4UZAB2FC5KCKD5577	2018	VL	DP	3436 FL		2/21/2018	2/28/2018
413572	4UZAB2FC9KCKD9146	2018	VL	DP	3412 FL		2/27/2018	3/7/2018
413573	4UZACHFC9KCKD1256	2018	VT	DP	3412 FL		2/15/2018	2/22/2018
413574	4UZFCHFE9JCKC1008	2018	VT	DP	4037 FL		2/5/2018	2/13/2018
413575	4UZFCHFE7KCKD1263	2018	VT	DP	4369 FL		2/15/2018	2/22/2018
413634	4UZFCHFE9KCKD5587	2018	VT	DP	4037 FL		2/21/2018	3/1/2018
413640	4UZACHFC2KCKD5584	2018	VT	DP	3436 FL		2/28/2018	3/7/2018
413641	4UZACHFC2KCKD1258	2018	VT	DP	3709 FL		2/27/2018	3/6/2018

413645	4UZACHFC3JCKB2524	2018	VL	DP	4042	FL	1/31/2018	2/8/2018
413646	4UZAB2FCXJCJZ9680	2018	VL	DP	3709	FL	1/18/2018	1/25/2018
413649	4UZFCHFE9KCKD5590	2018	VT	DP	4369	FL	2/23/2018	3/2/2018
413651	4UZAB2FC7KCKD5578	2018	VL	DP	3412	FL	2/22/2018	3/1/2018
413653	4UZFCHFE8KCKD9162	2018	VT	DP	4310	FL	3/13/2018	3/20/2018
413654	4UZFCHFE9KCKD1264	2018	VT	DP	4310	FL	2/15/2018	2/22/2018
413655	4UZACHFC6KCKD5586	2018	VT	DP	3715	FL	3/1/2018	3/8/2018
413659	4UZAB2FC3KCKE8389	2018	VL	DP	3412	FL	3/15/2018	3/22/2018
413661	4UZAB2FC4KCKF8610	2018	VL	DP	3436	FL	3/28/2018	4/5/2018
413699	4UZFCHFE2KCKD1266	2018	VT	DP	4308	FL	2/16/2018	2/23/2018
413701	4UZACHFC4JCKB9997	2018	VL	DP	4037	FL	2/1/2018	2/8/2018
413716	4UZACHFC3KCKF4371	2018	VL	DP	4002	FL	3/29/2018	4/6/2018
413732	4UZFCHFE3JCKC1005	2018	VT	DP	4037	FL	1/29/2018	2/5/2018
413740	4UZACHFC0KCKD1257	2018	VT	DP	3412	FL	2/16/2018	2/23/2018
413741	4UZAB2FC0KCKD9147	2018	VL	DP	3412	FL	3/9/2018	3/16/2018
413743	4UZACHFC7KCKD5581	2018	VT	DP	3407	FL	2/19/2018	2/26/2018
413744	4UZAB2FC2JCKB9996	2018	VL	DP	3713	FL	2/27/2018	3/6/2018
413745	4UZFCHFE3KCKD1261	2018	VT	DP	4049	FL	2/12/2018	2/19/2018
413747	4UZACHFC3JCKA8960	2018	VT	DP	3412	FL	1/15/2018	1/23/2018
413750	4UZFCHFE5JCKA8966	2018	VT	DP	4369	FL	1/26/2018	2/2/2018
413754	4UZAB2FC4KCKD9149	2018	VL	DP	3709	FL	3/5/2018	3/12/2018
413778	4UZACHFC7JCKA3664	2018	VL	DP	4037	FL	1/16/2018	1/24/2018
413781	4UZAB2FC6JCJY9437	2018	VL	DP	3709	FL	1/15/2018	1/23/2018
413786	4UZACHFC7JCKB2526	2018	VT	DP	3407	FL	2/12/2018	2/20/2018
413788	4UZFCHFE6JCKC6912	2018	VT	DP	4037	FL	2/6/2018	2/13/2018
413789	4UZACHFC5JCKC6909	2018	VT	DP	3709	FL	2/12/2018	2/19/2018
413791	4UZACHFC5JCKA8958	2018	VL	DP	4042	FL	1/12/2018	1/22/2018
413793	4UZFCHFE1JCKB2528	2018	VT	DP	4037	FL	1/22/2018	1/29/2018
413796	4UZFCHFE5KCKD1262	2018	VT	DP	4037	FL	2/20/2018	2/28/2018
413802	4UZAB2FC0JCKB2514	2018	VL	DP	3412	FL	1/29/2018	2/5/2018
413803	4UZAB2FC9JCKB9994	2018	VL	DP	3709	FL	2/5/2018	2/12/2018
413805	4UZAB2FC5KCKD7989	2018	VL	DP	3436	FL	2/23/2018	3/2/2018
413807	4UZFCHFE1KCKD1260	2018	VT	DP	4037	FL	3/1/2018	3/9/2018
413809	4UZFCHFE3JCKB2529	2018	VT	DP	4369	FL	1/26/2018	2/2/2018
413810	4UZFCHFE8JCKC6913	2018	VT	DP	4369	FL	2/9/2018	2/16/2018
413825	4UZFCHFE1JCKB2531	2018	VT	DP	4310	FL	2/5/2018	2/13/2018
413826	4UZFCHFE5JCKC1006	2018	VT	DP	4037	FL	1/29/2018	2/6/2018
413827	4UZACHFC9KCKD5582	2018	VT	DP	3412	FL	2/23/2018	3/5/2018
413830	4UZACHFC7KCKF4373	2018	VT	DP	3407	FL	2/26/2018	3/5/2018
413831	4UZFCHFE2JCJY4064	2018	VT	DP	4311	FL	1/24/2018	1/31/2018
413836	4UZFCHFE3JCKA8965	2018	VT	DP	4049	FL	1/12/2018	1/22/2018
413848	4UZACHFCXJCJY2488	2018	VT	DP	3715	FL	2/6/2018	2/14/2018
413851	4UZACHFC6JCKB9998	2018	VL	DP	4037	FL	2/2/2018	2/9/2018
413853	4UZACHFCXJCKC6906	2018	VL	DP	4037	FL	2/28/2018	3/7/2018
413855	4UZACHFC7KCJY2515	2019	VT	DP	3709	FL	2/6/2018	2/14/2018
413858	4UZFCHFE0KCKD5591	2018	VT	DP	4369	FL	2/26/2018	3/5/2018
413859	4UZFCHFE4KCKD1267	2018	VT	DP	4369	FL	2/21/2018	2/28/2018

413868	4UZACHFC4KCJY2519	2019	VT	DP	3426	FL	2/22/2018	3/1/2018
413869	4UZACHFC3KCJY2611	2019	VL	DP	4045	FL	2/20/2018	2/27/2018
501514	4UZFG9JCKA3676	2018	LA	DP	4531	FL	1/31/2018	2/7/2018
501553	4VZVU1E90JC084763	2018	LA	DP	4531	S	1/10/2018	1/18/2018
501556	4VZVU1E98JC085014	2018	LA	DP	4531	S	2/23/2018	3/2/2018
501558	4VZVU1E98JC084932	2018	LA	DP	4534	S	1/11/2018	1/19/2018
501559	4UZFG4KCKD1273	2018	LA	DP	4553	S	2/20/2018	2/27/2018
501563	4VZVU1E9XJC084933	2018	LA	DP	4531	S	1/26/2018	2/5/2018
501564	4VZVU1E9XJC085015	2018	LA	DP	4553	S	2/28/2018	3/7/2018
501566	4UZFGXJCKC1023	2018	LA	DP	4535	FL	2/2/2018	2/12/2018
501571	4UZFG0KCJY2514	2019	LA	DP	4576	FL	1/31/2018	2/7/2018
501574	4VZVU1E97KC084342	2019	LA	DP	4534	S	2/14/2018	2/22/2018
530436	4VZVU1E97JC084873	2018	KG	DB	4553	S	2/1/2018	2/9/2018
530454	4VZVU1E95JC084807	2018	KG	DB	4531	S	1/23/2018	1/31/2018
530468	4VZVU1E96JC084766	2018	KG	DB	4534	S	1/11/2018	1/18/2018
530474	4VZVU1E91JC084819	2018	KG	DB	4531	S	1/29/2018	2/5/2018
530475	4VZVU1E97JC084937	2018	KG	DB	4531	S	2/15/2018	2/22/2018
530488	4VZVU1E99KC084343	2019	KG	DB	4531	S	2/5/2018	2/12/2018
530489	4VZVU1E99JC084938	2018	KG	DB	4531	S	3/2/2018	3/9/2018
606747	4UZCFHE8JCKC1016	2018	DS	DP	4369	FL	1/29/2018	2/6/2018
606755	4VZAU1D96JC085027	2018	DS	DP	4018	S	2/22/2018	3/2/2018
606762	4UZCFHE5JCKB2533	2018	DS	DP	4327	FL	1/22/2018	1/29/2018
606769	4UZCFHE7JCKB2534	2018	DS	DP	4369	FL	1/22/2018	1/30/2018
606811	4UZCFHE9JCKA8971	2018	DS	DP	4018	FL	1/19/2018	1/26/2018
606890	4UZACHFE6JCKA3673	2018	DS	DP	3736	FL	2/8/2018	2/15/2018
606899	4UZCFHE9JCKC1011	2018	DS	DP	4018	FL	1/29/2018	2/6/2018
606900	4UZCFHE3JCKC6916	2018	DS	DP	4018	FL	2/14/2018	2/21/2018
606903	4VZAU1D95JC084757	2018	DS	DP	4018	S	1/10/2018	1/18/2018
606904	4VZAU1D90JC084813	2018	DS	DP	4018	S	1/12/2018	1/19/2018
606906	4UZCFHE0JCKA8972	2018	DS	DP	4018	FL	1/19/2018	1/26/2018
606908	4VZAU1D96JC084864	2018	DS	DP	4369	S	1/23/2018	1/30/2018
606910	4UZCFHEXJCKC1017	2018	DS	DP	4369	FL	1/30/2018	2/6/2018
606914	4VZAU1D99JC084924	2018	DS	DP	4362	S	1/19/2018	1/26/2018
606923	4UZCFHE1JCKC1021	2018	DS	DP	4310	FL	1/30/2018	2/6/2018
606924	4UZCFHE1JCKC1018	2018	DS	DP	4369	FL	1/31/2018	2/7/2018
606929	4UZCFHE2JCKA8973	2018	DS	DP	4018	FL	1/18/2018	1/26/2018
606930	4UZCFHE0JCKC1012	2018	DS	DP	4018	FL	1/31/2018	2/8/2018
606931	4UZCFHE7JCKA8970	2018	DS	DP	4018	FL	1/26/2018	2/2/2018
606932	4UZCFHE3JCKA8979	2018	DS	DP	4362	FL	1/18/2018	1/25/2018
606933	4VZAU1D92JC084926	2018	DS	DP	4369	S	1/24/2018	1/31/2018
606936	4VZAU1D97JC084985	2018	DS	DP	4369	S	2/6/2018	2/13/2018
606937	4UZCFHE1KCKD5602	2018	DS	DP	4369	FL	2/15/2018	2/23/2018
606938	4VZAU1D91JC084867	2018	DS	DP	4052	S	1/17/2018	1/25/2018
606939	4VZAU1D94JC084927	2018	DS	DP	4369	S	2/1/2018	2/8/2018
606940	4VZAU1D95JC084919	2018	DS	DP	4052	S	1/24/2018	2/1/2018
606942	4UZACHFE9JCKC6915	2018	DS	DP	3736	FL	2/9/2018	2/16/2018
606943	4VZAU1D97JC084923	2018	DS	DP	4002	S	2/16/2018	2/23/2018

606953	4VZAU1D90JC084925	2018	DS	DP	4369	S	1/25/2018	2/1/2018
606975	4VZAU1D90JC085007	2018	DS	DP	4018	S	2/16/2018	2/23/2018
606976	4VZAU1D96JC084928	2018	DS	DP	4369	S	2/1/2018	2/9/2018
606983	4UZFCHFEXKCKD5601	2018	DS	DP	4369	FL	2/23/2018	3/2/2018
606984	4UZFCHFEXJCKC1020	2018	DS	DP	4327	FL	2/2/2018	2/9/2018
606991	4UZFCHFE5JCKC6920	2018	DS	DP	4369	FL	2/5/2018	2/12/2018
607042	4VZAU1D96JC084816	2018	DS	DP	4326	S	1/10/2018	1/18/2018
607044	4VZAU1D94JC084815	2018	DS	DP	4311	S	1/10/2018	1/18/2018
607047	4VZAU1D92JC084862	2018	DS	DP	4327	S	1/17/2018	1/24/2018
607059	4UZFCHFE6KCKD5594	2018	DS	DP	4018	FL	2/22/2018	3/2/2018
607067	4VZAU1D90JC085086	2018	DS	DP	4018	S	3/9/2018	3/16/2018
607115	4VZAU1D9XJC084866	2018	DS	DP	4369	S	1/18/2018	1/25/2018
607139	4VZAU1D93JC084868	2018	DS	DP	4018	S	1/23/2018	1/31/2018
607154	4VZAU1D98JC084865	2018	DS	DP	4369	S	1/23/2018	1/31/2018
607164	4UZFCHFE3JCKC1019	2018	DS	DP	4326	FL	2/2/2018	2/9/2018
607167	4VZAU1D92JC085073	2018	DS	DP	4369	S	3/2/2018	3/12/2018
607169	4UZFCHFE8KCKD5600	2018	DS	DP	4327	FL	2/14/2018	2/22/2018
607171	4VZAU1D99JC084860	2018	DS	DP	4327	S	1/16/2018	1/24/2018
607172	4VZAU1D90JC085010	2018	DS	DP	4369	S	2/23/2018	3/5/2018
607177	4VZAU1D91JC084920	2018	DS	DP	4018	S	1/25/2018	2/2/2018
607178	4VZAU1D98JC085028	2018	DS	DP	4018	S	2/27/2018	3/6/2018
607179	4UZFCHFE8JCKA8976	2018	DS	DP	4362	FL	1/11/2018	1/18/2018
607186	4VZAU1D94JC084863	2018	DS	DP	4327	S	1/19/2018	1/29/2018
607187	4UZFCHFE2JCKC6924	2018	DS	DP	4326	FL	2/8/2018	2/16/2018
607190	4VZAU1D99JC084986	2018	DS	DP	4327	S	2/12/2018	2/19/2018
607191	4VZAU1D95JC084984	2018	DS	DP	4369	S	2/2/2018	2/12/2018
607193	4VZAU1D90JC084858	2018	DS	DP	4369	S	1/16/2018	1/23/2018
607194	4UZFCHFE7JCKC1010	2018	DS	DP	4018	FL	1/24/2018	1/31/2018
607195	4VZAU1D90JC084987	2018	DS	DP	4327	S	2/7/2018	2/14/2018
607203	4UZFCHFEXJCKA8977	2018	DS	DP	4327	FL	1/15/2018	1/22/2018
607206	4VZAU1D90JC084861	2018	DS	DP	4369	S	1/17/2018	1/24/2018
607207	4UZFCHFE4JCKC1014	2018	DS	DP	4369	FL	1/25/2018	2/2/2018
607208	4UZFCHFE0JCKC6923	2018	DS	DP	4369	FL	2/9/2018	2/16/2018
607210	4VZAU1D92JC085008	2018	DS	DP	4018	S	2/23/2018	3/2/2018
607219	4UZFCHFE6KCKD1271	2018	DS	DP	4369	FL	2/12/2018	2/20/2018
607220	4UZFCHFE5KCKD5599	2018	DS	DP	4369	FL	2/13/2018	2/20/2018
607221	4VZAU1D92JC084988	2018	DS	DP	4369	S	2/13/2018	2/20/2018
607222	4UZFCHFE5JCKC6917	2018	DS	DP	4018	FL	2/20/2018	2/27/2018
607224	4VZAU1D93JC084921	2018	DS	DP	4052	S	2/13/2018	2/21/2018
607226	4UZFCHFEXKCKD5596	2018	DS	DP	4018	FL	2/27/2018	3/6/2018
607230	4VZAU1D94JC084989	2018	DS	DP	4362	S	2/19/2018	2/26/2018
607231	4VZAU1D96JC085030	2018	DS	DP	4052	S	3/5/2018	3/12/2018
607234	4UZFCHFE7JCKC6921	2018	DS	DP	4369	FL	2/7/2018	2/15/2018
607238	4UZFCHFEXJCJY4068	2018	DS	DP	4311	FL	1/29/2018	2/5/2018
607242	4VZAU1D95JC084922	2018	DS	DP	4018	S	2/15/2018	2/22/2018
607253	4UZFCHFE9JCKC6922	2018	DS	DP	4327	FL	2/8/2018	2/15/2018
607257	4UZFCHFE8KCKD5595	2018	DS	DP	4018	FL	2/20/2018	2/28/2018

607261	4VZAU1D94JC084930	2018	DS	DP	4362	S	2/5/2018	2/13/2018
607262	4UZFCHFE5KCKD8003	2018	DS	DP	4369	FL	2/22/2018	3/1/2018
607266	4UZFCHFE4KCKD1270	2018	DS	DP	4369	FL	2/14/2018	2/21/2018
607268	4UZFCHFE3KCJY2518	2019	DS	DP	4018	FL	2/19/2018	2/27/2018
607269	4UZACHFE0KCJY2521	2019	DS	DP	3717	FL	2/21/2018	2/28/2018
607279	4VZAU1D94JC085009	2018	DS	DP	4362	S	2/21/2018	2/28/2018
710268	4UZACEFCXJCKB2535	2018	NA	DP	3343	FL	2/9/2018	2/16/2018
710274	4UZACEFC1JCKB2536	2018	NA	DP	3343	FL	2/12/2018	2/20/2018
710280	4UZACEFC0JCJZ9699	2018	NA	DP	3343	FL	1/18/2018	1/26/2018
710281	4UZACEFC5JCJZ9701	2018	NA	DP	3343	FL	1/16/2018	1/24/2018
710288	4UZACEFC0JCKC6928	2018	NA	DP	3343	FL	2/22/2018	3/2/2018
710291	4UZACEFC7JCKA3680	2018	NA	DP	3343	FL	1/26/2018	2/5/2018
710296	4UZACEFC1KCKD8006	2018	NA	DP	3343	FL	3/9/2018	3/16/2018
710298	4UZACEFC9JCKC6927	2018	NA	DP	3341	FL	2/21/2018	3/1/2018
710303	4UZACEFC5JCKA0650	2018	NA	DP	3343	FL	1/22/2018	1/30/2018
710304	4UZACEFC3JCJZ9700	2018	NA	DP	3343	FL	1/16/2018	1/23/2018
710307	4UZACEFC2JCKA8981	2018	NA	DP	3341	FL	2/2/2018	2/9/2018
710310	4UZACEFC8JCJZ5559	2018	NA	DP	3343	FL	1/12/2018	1/19/2018
710321	4UZACEFC0JCKA3679	2018	NA	DP	3343	FL	2/6/2018	2/13/2018
710324	4UZACEFC7JCKA0651	2018	NA	DP	3343	FL	1/24/2018	1/31/2018
710325	4UZACEFC4KCKD1275	2018	NA	DP	3343	FL	2/26/2018	3/5/2018
710328	4UZACEFC7JCKC6926	2018	NA	DP	3343	FL	2/19/2018	2/27/2018
710329	4UZACEFC8JCKC1024	2018	NA	DP	3341	FL	2/20/2018	2/28/2018
710330	4UZACEFC3JCKB2537	2018	NA	DP	3341	FL	2/12/2018	2/19/2018
710333	4UZACEFC4JCKA8982	2018	NA	DP	3343	FL	2/5/2018	2/12/2018
710340	4UZACEFC0JCKA8980	2018	NA	DP	3343	FL	2/1/2018	2/8/2018
710343	4UZACEFC0KCJY2676	2019	NA	DP	3343	FL	2/15/2018	2/23/2018
801283	4VZVU1E93JC084871	2018	EX	DP	4553	S	1/17/2018	1/25/2018
801284	4VZVU1E95JC084936	2018	EX	DP	4534	S	2/22/2018	3/1/2018
801286	4VZVU1E93JC084935	2018	EX	DP	4531	S	1/30/2018	2/7/2018
801287	4VZVU1E95JC084872	2018	EX	DP	4531	S	1/22/2018	1/29/2018
801293	4VZVU1E91JC084934	2018	EX	DP	4531	S	1/26/2018	2/2/2018
801295	4VZVU1E95KC084338	2019	EX	DP	4551	S	1/10/2018	1/17/2018
801297	4UZFCTFG7JCKA9346	2018	EX	DP	4531	FL	2/19/2018	2/26/2018
801298	4VZVU1E98JC084994	2018	EX	DP	4534	S	2/26/2018	3/6/2018
801299	4UZFCTFG6KCJY2517	2019	EX	DP	4543	FL	2/12/2018	2/19/2018
904601	4UZFCTBG1JCKC6925	2018	MA	DP	4531	FL	2/5/2018	2/13/2018
904604	4VZVU1E90JC084875	2018	MA	DP	4047	S	1/24/2018	2/1/2018
904608	4VZVU1E98JC084820	2018	MA	DP	4047	S	1/19/2018	1/26/2018
904609	4UZFCTBG7JCJY9450	2018	MA	DP	4531	FL	1/19/2018	1/29/2018
904611	4VZVU1E93JC084742	2018	MA	DP	4047	S	1/11/2018	1/19/2018
904614	4VZVU1E95JC084869	2018	MA	DP	4531	S	2/7/2018	2/14/2018
904615	4VZVU1E92JC084876	2018	MA	DP	4047	S	2/14/2018	2/21/2018
904619	4VZVU1E96JC084931	2018	MA	DP	4553	S	2/21/2018	3/1/2018
904620	4UZFCTBG0JCKC1022	2018	MA	DP	4531	FL	1/30/2018	2/6/2018
904624	4VZVU1E9XJC084818	2018	MA	DP	4531	S	1/17/2018	1/24/2018
904625	4VZVU1E98JC084817	2018	MA	DP	4531	S	1/12/2018	1/22/2018

904626	4VZVU1E91JC084870	2018	MA	DP	4531 S	2/13/2018	2/20/2018
904628	4VZVU1E93JC085034	2018	MA	DP	4553 S	3/19/2018	3/27/2018
904629	4VZVU1A96KC084337	2019	MA	DP	4579 S	1/23/2018	1/30/2018
904630	4VZVU1E92JC084991	2018	MA	DP	4553 S	2/27/2018	3/6/2018
904635	4VZVU1E94KC084556	2019	MA	DP	4018 S	2/7/2018	2/15/2018
904641	4VZVU1E92KC084345	2019	MA	DP	4550 S	2/16/2018	2/26/2018

Canadian Units

413642	4UZAB2FC2JCKC6902	2018	VL	DP	3412 FL	2/9/2018	2/19/2018
413795	4UZFCHFE0KCKD1265	2018	VT	DP	4369 FL	2/19/2018	2/26/2018
501524	4VZVU1E96JC084993	2018	LA	DP	4553 S	1/23/2018	1/30/2018
501537	4VZVU1E96JC085013	2018	LA	DP	4531 S	2/1/2018	2/8/2018
501549	4VZVU1E99JC084762	2018	LA	DP	4534 S	1/9/2018	1/17/2018
501572	4UZFTFG2KCKD1272	2018	LA	DP	4531 FL	2/16/2018	2/23/2018
530484	4VZVU1E93JC085017	2018	KG	DB	4531 S	3/13/2018	3/20/2018
530485	4VZVU1E9XJC084995	2018	KG	DB	4534 S	3/6/2018	3/13/2018
530487	4VZVU1E91JC084996	2018	KG	DB	4534 S	3/9/2018	3/16/2018
606913	4UZFCHFE2JCKC1013	2018	DS	DP	4018 FL	2/7/2018	2/14/2018
607130	4UZFCHFE6JCKC1015	2018	DS	DP	4326 FL	1/26/2018	2/5/2018
607170	4UZFCHFE3KCKD8002	2018	DS	DP	4326 FL	2/19/2018	2/27/2018
607176	4UZFCHFE0KCKE8406	2018	DS	DP	4327 FL	3/6/2018	3/13/2018
607185	4UZFCHFE7KCKD8004	2018	DS	DP	4327 FL	2/16/2018	2/26/2018
607243	4VZAU1D93KC084340	2019	DS	DP	4328 S	1/22/2018	1/30/2018
607292	4VZAU1D92JC085011	2018	DS	DP	4327 S	2/27/2018	3/7/2018
801292	4UZFTFG6JCJY4069	2018	EX	DP	4533 FL	2/9/2018	2/16/2018