

NEWMAR CORPORATION

WARRANTY

DEPARTMENT

PRODUCT INFORMATION BULLETIN

DATE ISSUED	MODEL YEAR(S) AFFECTED	PIB #
8/14/2018	2016-2019	529

MODEL

Bay Star Sport	<input type="checkbox"/>	Ventana	<input checked="" type="checkbox"/>	Essex	<input checked="" type="checkbox"/>
Bay Star	<input type="checkbox"/>	Dutch Star	<input checked="" type="checkbox"/>	King Aire	<input checked="" type="checkbox"/>
Canyon Star	<input type="checkbox"/>	Mountain Aire	<input checked="" type="checkbox"/>	New Aire	<input type="checkbox"/>
Ventana LE	<input type="checkbox"/>	London Aire	<input checked="" type="checkbox"/>	Other	<input type="checkbox"/>

PRODUCT INFORMATION

This bulletin was created to inform dealers and techs that an updated linkage is available that provides a remedy for binding linkages to the power actuator. This issue often creates difficulty when locking or unlocking the compartment door using the key and is only relevant on 2016 to early 2019 model year coaches equipped with power baggage locks.

The new replacement linkage (Newmar part #132391A) will replace the old left or right-handed linkages. Complete the following steps to replace the linkages.

1. Remove the cover to expose the latch and linkage assembly.
2. Release the retainer clip.
3. Remove the old linkage.
4. Install the new linkage.
5. Engage the retainer clip on the new linkage.
6. Reinstall the removed cover(s).

