

NEWMAR CORPORATION

WARRANTY

DEPARTMENT

RECALL SERVICE BULLETIN

DATE ISSUED

MODEL YEAR(S) AFFECTED

RSB #

8/28/18

2017-2019

530

MODEL

Bay Star Sport	☐	Ventana	☒	Essex	☒
Bay Star	☐	Dutch Star	☐	King Aire	☐
Canyon Star	☐	Mountain Aire	☒	New Aire	☐
Ventana LE	☒	London Aire	☒	Other	☐

DESCRIPTION

Daimler Trucks North America, LLC has decided that a defect relating to motor vehicle safety exists in specific motorhomes built on Freightliner Chassis (NHTSA 18V 353). In response, Newmar Corporation is releasing recall NHTSA 18V 505 and TC # 2018-401.

Issue: On certain motorhomes equipped with air disc brakes, the brake caliper mounting bolts may be incorrectly torqued. The caliper bolts may loosen, which may lead to the caliper detaching. Insufficiently torqued fasteners may not provide adequate clamping force between the brake caliper and brake anchor plate, potentially resulting in reduced brake effectiveness. This scenario would result in greater stopping distances, increasing the risk of a crash causing injury and/or damage to property.

Correction: DTNA service facilities will inspect the bolts and repair as necessary.

Units Affected: Refer to the attached population list for specific VIN numbers supplied by DTNA.

RECOMMENDED ACTION

Repair Procedure: Contact the Freightliner Customer Support Center at 1-800-FTL-HELP (1-800-385-4357), and follow the prompts, or visit <https://freightliner.com/dealer-search/>. You may also email DTNA at DTNA.Warranty.Campaigns@Daimler.com, or call them at 1-800-547-0712 to locate an authorized DTNA service center to schedule and perform the recall near you. DTNA will provide the work instructions and necessary parts.

Note: Newmar will not be authorizing this repair. DTNA will authorize and schedule this repair. If you need assistance contacting DTNA, contact your Newmar Service Account Manager.

Please read this bulletin in its entirety prior to beginning any diagnosis or repairs.



WHEN YOU KNOW THE DIFFERENCE

NEWMAR CORPORATION

NEWMARCORP.COM

Date: August 24, 2018
Re: Newmar Corporation – Motor Vehicle Recall Notification

Subject: Recall Campaign No.: 18V 505

This notice is sent to you as a Newmar Dealer in accordance with the requirements of the National Traffic and Motor Vehicle Safety Act. Newmar Corporation has decided that a defect, which relates to motor vehicle safety, exists in specific Newmar recreational vehicles.

The National Traffic and Motor Vehicle Safety Act requires that each vehicle, which is subject to a recall campaign of this type, must be satisfactorily repaired within a reasonable time after the owner has tendered it for repair. A failure to adequately repair within 60 days after tender of a vehicle is prima facie evidence of failure to repair within a reasonable time. To avoid providing these problematic solutions, every effort must be made to promptly schedule an appointment with each owner and to repair their vehicle as soon as possible. Vehicle owners are being notified of this recall. If the condition is not remedied within a reasonable time, they are instructed on how to contact the National Highway Traffic Safety Administration.

REASON FOR THIS RECALL

Newmar Corporation has decided that a defect, which relates to motor vehicle safety, exists in specific motorhomes built on Freightliner Chassis. This recall is the result of information provided to us by Daimler Trucks North America LLC.

On certain motorhomes equipped with air disc brakes, the brake caliper mounting bolts may be incorrectly torqued. This could result in the caliper bolts loosening, which could lead to the caliper detaching. Insufficiently torqued fasteners may not provide adequate clamping force between the brake caliper and brake anchor plate potentially resulting in reduced brake effectiveness, which would result in increased stopping distances, increasing the risk of a crash causing injury and/or damage to property. Correction: Daimler Trucks of North America Service Facilities will inspect the bolts, and repair as necessary.

The motorhomes require immediate service. Continued use poses a potential safety hazard.

DEALER CAMPAIGN RESPONSIBILITY

Dealers are to provide to all customers/owner vehicles the service of completing this campaign at no charge to the customer/owner regardless of vehicle age, vehicle mileage, or ownership at the time of repair.

REPAIR PROCEDURE

Daimler Trucks North America will provide the work instructions.

If you should have any questions please contact your service account manager direct or the Newmar service department at: 1-866-290-5371.

Thank you for your cooperation.

Sincerely,

Newmar Corporation



WHEN YOU KNOW THE DIFFERENCE

NEWMAR CORPORATION

NEWMARCORP.COM

IMPORTANT SAFETY RECALL

This notice applies to your vehicle VIN. # _____

Name

Address

City, State Zip code

Date: August 24, 2018

Motor Vehicle Recall Notification - Recall Campaign No. 18V 505

Dear Valued Customer:

This notice is sent to you in accordance with the requirements of the National Traffic and Motor Vehicle Safety Act.

REASON FOR THIS RECALL

Newmar Corporation has decided that a defect, which relates to motor vehicle safety, exists in specific motorhomes built on Freightliner Chassis. This recall is the result of information provided to us by Daimler Trucks North America LLC.

On certain motorhomes equipped with air disc brakes, the brake caliper mounting bolts may be incorrectly torqued. This could result in the caliper bolts loosening, which could lead to the caliper detaching. Insufficiently torqued fasteners may not provide adequate clamping force between the brake caliper and brake anchor plate potentially resulting in reduced brake effectiveness, which would result in increased stopping distances, increasing the risk of a crash causing injury and/or damage to property. Correction: Daimler Trucks of North America Service Facilities will inspect the bolts, and repair as necessary.

The motorhomes require immediate service. Continued use poses a potential safety hazard.

The Safety Risk

Insufficiently torqued fasteners may not provide adequate clamping force between the brake caliper and brake anchor plate potentially resulting in reduced brake effectiveness, which would result in increased stopping distances, increasing the risk of a crash causing injury and/or damage to property.

WHAT WE WILL DO

Daimler Trucks North America will provide owners of all affected motorhomes a remedy for the potential defect at no charge for parts or labor. Daimler Trucks of North America Service Facilities will inspect the bolts, and repair as necessary.

WHAT YOU NEED TO DO

As this defect does affect motor vehicle safety, it is recommended that you call Daimler Trucks North America @ **800-547-0712** to locate a Qualified Service Center near you. If you need further assistance, contact the Newmar service department immediately at 1-800-731-8300. An associate will assist you in making an appointment to have this repair completed.

Federal regulations require that any vehicle lessor receiving this recall notification must forward a copy of this notice to the lessee within ten days.

If you have had the repair performed before receiving this letter, you may be eligible to receive reimbursement for the cost of obtaining a pre-notification remedy. For additional information, contact Newmar Corporation at:

Service Department
Newmar Corporation
355 N Delaware St
Nappanee, IN 46550-0030

An Authorized Chassis Service Facility is best equipped to obtain parts and provide service to ensure your vehicle is corrected as promptly as possible. HOWEVER, if you take your vehicle to your Authorized Chassis Service Facility on the scheduled date and this condition is not remedied on that date or within five days; please contact the Newmar Corporation Customer Service Department at 1-800-731-8300. You may also submit a complaint to the Administrator, National Highway Traffic Safety Administration, 1200 New Jersey Ave., SE., Washington DC 20590; or call the toll-free Vehicle Safety Hotline at 1-888-327-4236 (TTY: 1-800-424-9153); or go to <http://www.safercar.gov>.

If you no longer own this vehicle, please furnish us the complete name and address of the person or dealership you sold or traded your vehicle to. Thank you for your cooperation.

Your safety and satisfaction with your Newmar product is important to us and we regret any inconvenience to you.

Sincerely,

Newmar Corporation



WHEN YOU KNOW THE DIFFERENCE

NEWMAR CORPORATION

NEWMARCORP.COM

Date: August 24, 2018
Re: Newmar Corporation – Motor Vehicle Recall Notification

Subject: Recall Campaign No.: 2018-401

This notice is sent to you as a Newmar Dealer in accordance with the requirements of the Canada Motor Vehicle Safety Act. Newmar Corporation has decided that a defect, which relates to motor vehicle safety, exists in specific Newmar recreational vehicles.

Each vehicle, which is subject to a recall campaign of this type, must be satisfactorily repaired within a reasonable time after the owner has tendered it for repair. A failure to adequately repair within 60 days after tender of a vehicle is prima facie evidence of failure to repair within a reasonable time. To avoid providing these problematic solutions, every effort must be made to promptly schedule an appointment with each owner and to repair their vehicle as soon as possible. Vehicle owners are being notified of this recall. If the condition is not remedied within a reasonable time, they are instructed to contact Transport Canada.

REASON FOR THIS RECALL

Newmar Corporation has decided that a defect, which relates to motor vehicle safety, exists in specific motorhomes built on Freightliner Chassis. This recall is the result of information provided to us by Daimler Trucks North America LLC.

On certain motorhomes equipped with air disc brakes, the brake caliper mounting bolts may be incorrectly torqued. This could result in the caliper bolts loosening, which could lead to the caliper detaching. Insufficiently torqued fasteners may not provide adequate clamping force between the brake caliper and brake anchor plate potentially resulting in reduced brake effectiveness, which would result in increased stopping distances, increasing the risk of a crash causing injury and/or damage to property. Correction: Daimler Trucks of North America Service Facilities will inspect the bolts, and repair as necessary.

The motorhomes require immediate service. Continued use poses a potential safety hazard.

Motorhomes included in this recall: 2018 Ventana LE, 2017-2018- Ventana and 2018 London Aire.

DEALER CAMPAIGN RESPONSIBILITY

Dealers are to provide to all customers/owner vehicles the service of completing this campaign at no charge to the customer/owner regardless of vehicle age, vehicle mileage, or ownership at the time of repair.

REPAIR PROCEDURE

Daimler Trucks North America will provide the work instructions.

If you should have any questions please contact your service account manager direct or the Newmar service department at: 1-866-290-5371.

Thank you for your cooperation.

Sincerely,

Newmar Corporation



WHEN YOU KNOW THE DIFFERENCE

NEWMAR CORPORATION

NEWMARCORP.COM

VIN#
Name
Address
City, State Zip code

Date: August 24, 2018
Motor Vehicle Recall Notification - Recall Campaign No. 2018-401

Dear Valued Customer:

This notice is sent to you in accordance with the requirements of the Canada Motor Vehicle Safety Act.

REASON FOR THIS RECALL

Newmar Corporation has decided that a defect, which relates to motor vehicle safety, exists in specific motorhomes built on Freightliner Chassis. This recall is the result of information provided to us by Daimler Trucks North America LLC.

On certain motorhomes equipped with air disc brakes, the brake caliper mounting bolts may be incorrectly torqued. This could result in the caliper bolts loosening, which could lead to the caliper detaching. Insufficiently torqued fasteners may not provide adequate clamping force between the brake caliper and brake anchor plate potentially resulting in reduced brake effectiveness, which would result in increased stopping distances, increasing the risk of a crash causing injury and/or damage to property. Correction: Daimler Trucks of North America Service Facilities will inspect the bolts, and repair as necessary.

The motorhomes require immediate service. Continued use poses a potential safety hazard.

WHAT WE WILL DO

Daimler Trucks North America will provide owners of all affected motorhomes a remedy for the potential defect at no charge for parts or labor. Daimler Trucks of North America Service Facilities will inspect the bolts, and repair as necessary.

WHAT YOU NEED TO DO

As this defect does affect motor vehicle safety, it is recommended that you call Daimler Trucks North America @ **800-547-0712** to locate a Qualified Service Center near you. If you need further assistance, contact the Newmar service department immediately at 1-800-731-8300. An associate will assist you in making an appointment to have this repair completed.

Federal regulations require that any vehicle lessor receiving this recall notification must forward a copy of this notice to the lessee within ten days.

If you have had the repair performed before receiving this letter, you may be eligible to receive reimbursement for the cost of obtaining a pre-notification remedy. For additional information contact Newmar Corporation at:

Service Department
Newmar Corporation
355 N Delaware St
Nappanee, IN 46550-0030

An Authorized Chassis Service Facility is best equipped to obtain parts and provide service to ensure your vehicle is corrected as promptly as possible. HOWEVER, if you take your vehicle to your Authorized Chassis Service Facility on the scheduled date and this condition is not remedied on that date or within five days; please contact the Newmar Corporation Customer Service Department at 1-800-731-8300.

If you no longer own this vehicle, please furnish us the complete name and address of the person or dealership you sold or traded your vehicle to. Thank you for your cooperation.

Your safety and satisfaction with your Newmar product is important to us and we regret any inconvenience to you.

Sincerely,

Newmar Corporation



WHEN YOU KNOW THE DIFFERENCE

NEWMAR CORPORATION

NEWMARCORP.COM

NIV
Nom
Adresse
Ville, province, code postal

Date : 24 août 2018
Avis de rappel visant un véhicule motorisé – Campagne de rappel n° 2018-401

Madame, Monsieur,

Le présent avis vous est envoyé conformément aux exigences de la *Loi sur la sécurité automobile du Canada*.

MOTIF DU PRÉSENT RAPPEL

Newmar Corporation a déterminé qu'il existe une défaillance relevant de la sécurité automobile dans certaines autocaravanes montées sur châssis Freightliner. Nous procédons à ce rappel en raison de renseignements que Daimler Trucks North America LLC nous a fournis.

Sur certaines autocaravanes équipées de freins à disque pneumatiques, les boulons de fixation de l'étrier de frein peuvent avoir été mal serrés au couple. Les boulons de l'étrier peuvent alors se desserrer, ce qui pourrait entraîner le détachement de l'étrier. Des dispositifs de fixation insuffisamment serrés peuvent ne pas offrir une force de serrage adéquate entre l'étrier de frein et le support de frein, ce qui peut occasionner une réduction de l'efficacité du système de freinage. Une telle situation accroît les distances de freinage et les risques de collisions causant des blessures ou des dommages à la propriété. Mesure corrective : Les installations d'entretien de Daimler Trucks North America inspecteront les boulons et se chargeront d'effectuer une réparation au besoin.

Il est impératif que les réparations sur ces autocaravanes soient effectuées immédiatement. Leur utilisation prolongée pose un risque d'accident potentiel.

CE QUE NOUS FERONS

Daimler Trucks North America fournira aux propriétaires de toutes les autocaravanes concernées une solution gratuite (pour les pièces et la main-d'œuvre) à la défaillance potentielle. Les installations d'entretien de Daimler Trucks North America inspecteront les boulons et se chargeront d'effectuer une réparation au besoin.

CE QUE VOUS DEVEZ FAIRE

Puisque cette défaillance touche la sécurité automobile, nous vous recommandons de communiquer immédiatement avec Daimler Trucks North America au **1-800-547-0712** pour obtenir les coordonnées d'un centre de service autorisé près de chez vous. Si vous avez besoin d'aide, veuillez communiquer immédiatement avec le service technique de Newmar au 1-800-731-8300. Un associé vous aidera à prendre rendez-vous aux fins d'exécution de cette réparation.

En vertu de règlements fédéraux, tout donneur à bail d'un véhicule, qui reçoit le présent avis de rappel, est tenu d'en acheminer une copie au preneur à bail dans un délai de dix jours.

Si les réparations ont été effectuées avant réception de la présente lettre, vous pouvez être admissible à un remboursement des frais liés à l'obtention de la solution adoptée avant réception du présent avis. Pour de plus amples renseignements, communiquez avec Newmar Corporation à l'adresse suivante :

Service Department
Newmar Corporation
355 N Delaware St
Nappanee, IN 46550-0030

Les centres de service autorisés sont les plus à même de fournir du service et d'obtenir des pièces qui assureront une réparation de votre véhicule dans les plus brefs délais. CELA DIT, si vous apportez votre véhicule à un centre de service autorisé à la date prévue et que le problème n'est pas résolu à cette date ou dans les cinq jours qui suivent, veuillez communiquer avec le service à la clientèle de Newmar Corporation en composant le 1-800-731-8300.

Si l'autocaravane concernée ne vous appartient plus, nous vous prions de bien vouloir nous fournir le nom complet et l'adresse complète de la personne ou du concessionnaire faisant maintenant office de propriétaire. Nous vous remercions de votre coopération.

Votre sécurité et votre satisfaction par rapport à nos produits Newmar sont importantes pour nous, et nous sommes désolés de tout désagrément occasionné.

Veuillez agréer, Madame, Monsieur, l'expression de nos sentiments distingués.

Newmar Corporation

Prod#	VIN Number	Year	Brand	Type	Floor Plan	Chassis	Date In	Date Off
USA Units								
413143	4UZAB2DT8HCJM5338	2017	VL	DP	3436	FL	4/21/2017	5/1/2017
413145	4UZACHFC4JCJP1857	2017	VT	DP	3436	FL	5/10/2017	5/18/2017
413185	4UZACHDT9JCJM8089	2018	VT	DP	3715	FL	3/10/2017	3/20/2017
413240	4UZAB2DTXHCJM5339	2017	VL	DP	3412	FL	4/21/2017	4/28/2017
413255	4UZFCHCY9HCJM5352	2017	VT	DP	4037	FL	5/8/2017	5/16/2017
413265	4UZACHDT3HCJM8082	2017	VL	DP	4002	FL	4/28/2017	5/5/2017
413281	4UZAB2FC5JCJU9947	2018	VL	DP	3709	FL	9/22/2017	10/2/2017
413285	4UZAB2FCXJCS6731	2018	VL	DP	3436	FL	6/16/2017	6/26/2017
413287	4UZFCHFE8JCJR8342	2018	VT	DP	4326	FL	6/9/2017	6/20/2017
413294	4UZFCHFE0JCJT1847	2018	VT	DP	4326	FL	6/19/2017	6/27/2017
413299	4UZACHFC8JCJR6356	2018	VT	DP	3436	FL	6/5/2017	6/13/2017
413302	4UZAB2FC3JCJS2391	2018	VL	DP	3436	FL	6/19/2017	6/28/2017
413303	4UZAB2FC4JCJR8332	2018	VL	DP	3436	FL	6/13/2017	6/21/2017
413304	4UZACHFC1JCJT8394	2018	VL	DP	4048	FL	8/4/2017	8/14/2017
413305	4UZACHFC2JCJU2230	2018	VL	DP	4002	FL	8/8/2017	8/16/2017
413307	4UZACHFC8JCJV3619	2018	VL	DP	4048	FL	8/18/2017	8/28/2017
413308	4UZAB2FC7JCJU9948	2018	VL	DP	3709	FL	9/12/2017	9/20/2017
413309	4UZACHFC6JCJU4823	2018	VL	DP	4002	FL	8/22/2017	8/30/2017
413314	4UZACHFC3JCJV3625	2018	VT	DP	3709	FL	8/24/2017	8/31/2017
413315	4UZFCHFE1JCJS2400	2018	VT	DP	4002	FL	6/19/2017	6/27/2017
413317	4UZFCHFE7JCJW0696	2018	VT	DP	4369	FL	10/10/2017	10/18/2017
413328	4UZACHFC4JCJR6354	2018	VL	DP	4048	FL	6/20/2017	6/29/2017
413330	4UZFCHFE8JCJV6155	2018	VT	DP	4308	FL	9/5/2017	9/13/2017
413333	4UZFCHFE4JCJR6362	2018	VT	DP	4369	FL	6/2/2017	6/12/2017
413337	4UZFCHFE4JCJU4830	2018	VT	DP	4046	FL	8/30/2017	9/8/2017
413340	4UZAB2FC6JCJU2229	2018	VL	DP	3709	FL	8/15/2017	8/23/2017
413344	4UZACHFC3JCJT8395	2018	VT	DP	3436	FL	7/25/2017	8/2/2017
413350	4UZFCHFE2JCJU9959	2018	VT	DP	4002	FL	8/16/2017	8/24/2017
413351	4UZFCHFE8JCJU2238	2018	VT	DP	4002	FL	7/31/2017	8/8/2017
413353	4UZFCHFE3JCJS6738	2018	VT	DP	4037	FL	6/27/2017	7/13/2017
413354	4UZACHFC1JCJR8336	2018	VT	DP	3436	FL	6/13/2017	6/21/2017
413356	4UZACHFC7JCJV3627	2018	VT	DP	3715	FL	8/28/2017	9/6/2017
413360	4UZACHFC7JCJS6735	2018	VT	DP	3412	FL	6/21/2017	7/10/2017
413370	4UZFCHFEXJCJT8398	2018	VT	DP	4037	FL	7/26/2017	8/3/2017
413381	4UZAB2FC9JCJW3575	2018	VL	DP	3709	FL	9/15/2017	9/25/2017
413383	4UZACHFC3JCJV6153	2018	VT	DP	3412	FL	9/12/2017	9/19/2017
413385	4UZFCHFE2JCJY9443	2018	VT	DP	4037	FL	12/19/2017	1/11/2018
413389	4UZAB2FC2JCJW7497	2018	VL	DP	3709	FL	11/29/2017	12/7/2017
413391	4UZACHFC8JCJY9438	2018	VL	DP	4048	FL	12/11/2017	12/19/2017
413393	4UZACHFC0JCJT5518	2018	VL	DP	4037	FL	8/1/2017	8/9/2017
413394	4UZAB2FC7JCJT5516	2018	VL	DP	3412	FL	7/19/2017	7/27/2017
413398	4UZFCHFE9JCJU6668	2018	VT	DP	4369	FL	8/2/2017	8/10/2017
413399	4UZFCHFE3JCJT5522	2018	VT	DP	4002	FL	7/28/2017	8/4/2017
413404	4UZACHFC0JCJT1839	2018	VL	DP	4048	FL	7/12/2017	7/20/2017
413407	4UZFCHFE5JCJT1844	2018	VT	DP	4049	FL	7/17/2017	7/25/2017

413409	4UZAB2FC5JCJV8714	2018	VL	DP	3436	FL	9/7/2017	9/15/2017
413417	4UZAB2FC9JCJX7041	2018	VL	DP	3709	FL	12/6/2017	12/13/2017
413421	4UZFCHFE3JCJW3580	2018	VT	DP	4311	FL	9/19/2017	9/27/2017
413422	4UZFCHFE9JCJT1846	2018	VT	DP	4308	FL	7/13/2017	7/24/2017
413423	4UZAB2FC9JCJW0689	2018	VL	DP	3413	FL	9/1/2017	9/12/2017
413424	4UZACHFCXJCJR8335	2018	VL	DP	4048	FL	6/15/2017	6/23/2017
413426	4UZACHFC2JCJT1843	2018	VT	DP	3715	FL	6/29/2017	7/17/2017
413431	4UZAB2FC5CJS2392	2018	VL	DP	3709	FL	6/7/2017	6/15/2017
413433	4UZACHFC6JCJX0533	2018	VT	DP	3436	FL	10/10/2017	10/18/2017
413434	4UZFCHFE1JCJW0693	2018	VT	DP	4037	FL	9/26/2017	10/4/2017
413435	4UZACHFC9JCJV3628	2018	VT	DP	3709	FL	10/11/2017	10/19/2017
413445	4UZACHFC7JCJU6662	2018	VL	DP	4048	FL	9/14/2017	9/22/2017
413446	4UZAB2FC7JCJV8715	2018	VL	DP	3436	FL	9/21/2017	9/29/2017
413449	4UZAB2FC9JCJU2225	2018	VL	DP	3436	FL	7/26/2017	8/3/2017
413451	4UZAB2FC5JCJU6661	2018	VL	DP	3709	FL	8/18/2017	8/25/2017
413456	4UZACHFC7JCJT1840	2018	VL	DP	4048	FL	7/27/2017	8/4/2017
413466	4UZAB2FC9JCJT5517	2018	VL	DP	3709	FL	7/14/2017	7/24/2017
413467	4UZACHFC9JCJX0526	2018	VL	DP	4037	FL	10/4/2017	10/11/2017
413468	4UZACHFC2JCJW3577	2018	VL	DP	4037	FL	10/12/2017	10/20/2017
413485	4UZACHFC1JCJV3624	2018	VT	DP	3715	FL	10/12/2017	10/20/2017
413487	4UZFCHFE1JCJW7501	2018	VT	DP	4037	FL	9/28/2017	10/6/2017
413489	4UZFCHFE7JCJY4061	2018	VT	DP	4037	FL	11/20/2017	11/30/2017
413495	4UZFCHFE5JCJY7203	2018	VT	DP	4369	FL	12/6/2017	12/14/2017
413498	4UZFCHFE3JCJY7202	2018	VT	DP	4369	FL	12/13/2017	12/21/2017
413500	4UZACHFC4JCJY7198	2018	VL	DP	4037	FL	12/13/2017	12/21/2017
413504	4UZFCHFE5JCJW3578	2018	VT	DP	4002	FL	9/29/2017	10/9/2017
413526	4UZACHFC2JCJY7197	2018	VL	DP	4037	FL	11/20/2017	11/30/2017
413548	4UZAB2FC4JCJW3564	2018	VL	DP	3412	FL	9/28/2017	10/5/2017
413555	4UZACHFCXJCJY9439	2018	VL	DP	4002	FL	12/14/2017	1/8/2018
413580	4UZACHFC4JCJX0532	2018	VT	DP	3412	FL	10/4/2017	10/12/2017
413584	4UZACHFC5JCJX3634	2018	VT	DP	3407	FL	10/18/2017	10/26/2017
413585	4UZACHFC7JCJX3635	2018	VT	DP	3436	FL	10/19/2017	10/27/2017
413586	4UZACHFC9JCJX3636	2018	VT	DP	3436	FL	10/26/2017	11/3/2017
413589	4UZACHFC1JCJY2489	2018	VT	DP	3715	FL	11/9/2017	11/17/2017
413597	4UZFCHFE5JCJX9201	2018	VT	DP	4037	FL	11/8/2017	11/16/2017
413598	4UZFCHFE2JCJY2492	2018	VT	DP	4002	FL	11/14/2017	11/21/2017
413599	4UZFCHFE9JCJY4059	2018	VT	DP	4046	FL	11/14/2017	11/22/2017
413600	4UZFCHFE4JCJY9444	2018	VT	DP	4046	FL	11/22/2017	12/4/2017
413602	4UZFCHFE0JCJX9199	2018	VT	DP	4049	FL	11/1/2017	11/9/2017
413606	4UZFCHFE1JCJY7201	2018	VT	DP	4310	FL	11/3/2017	11/10/2017
413607	4UZFCHFE0JCJY4063	2018	VT	DP	4308	FL	11/15/2017	11/27/2017
413608	4UZFCHFE6JCJY2494	2018	VT	DP	4308	FL	11/6/2017	11/14/2017
413609	4UZFCHFE4JCJY2493	2018	VT	DP	4369	FL	11/3/2017	11/13/2017
413611	4UZFCHFE8JCJY2495	2018	VT	DP	4369	FL	11/22/2017	12/4/2017
413612	4UZFCHFE9JCJY4062	2018	VT	DP	4369	FL	11/15/2017	11/27/2017
413617	4UZACHFC4JCJX0529	2018	VL	DP	4042	FL	10/5/2017	10/13/2017
413620	4UZACHFC6JCJW7499	2018	VL	DP	4002	FL	10/20/2017	10/27/2017

413622	4UZACHFC4JCJW7498	2018	VL	DP	4002	FL	10/30/2017	11/7/2017
413627	4UZAB2FC0JCJX7039	2018	VL	DP	3709	FL	11/27/2017	12/5/2017
413644	4UZACHFC8JCJY9441	2018	VL	DP	4037	FL	12/14/2017	12/21/2017
413764	4UZAB2FC0JCJW7496	2018	VL	DP	3709	FL	10/23/2017	10/31/2017
413781	4UZAB2FC6JCJY9437	2018	VL	DP	3709	FL	1/15/2018	1/23/2018
413799	4UZACHFC8JCJV6150	2018	VL	DP	4037	FL	11/6/2017	11/14/2017
413821	4UZFCHFE0KCJY2511	2019	VT	DP	4348	FL	11/20/2017	11/30/2017
413828	4UZACHFC3KCJY2513	2019	VL	DP	3717	FL	12/13/2017	12/21/2017
413831	4UZFCHFE2JCJY4064	2018	VT	DP	4311	FL	1/24/2018	1/31/2018
501501	4UZFCFTFG5JCJP0406	2017	LA	DP	4519	FL	5/4/2017	5/12/2017
501509	4UZFCFTFG9JCJT1852	2018	LA	DP	4553	FL	7/21/2017	7/31/2017
501515	4UZFCFTFG7JCJU2249	2018	LA	DP	4531	FL	8/29/2017	9/7/2017
501521	4UZFCFTFG8JCJY9452	2018	LA	DP	4531	FL	12/5/2017	12/13/2017
501535	4UZFCFTFG3JCJT8411	2018	LA	DP	4553	FL	8/7/2017	8/15/2017
501536	4UZFCFTFG4JCJY2501	2018	LA	DP	4553	FL	11/21/2017	11/30/2017
501540	4UZFCFTFG4JCJX0543	2018	LA	DP	4533	FL	10/11/2017	10/19/2017
501543	4UZFCFTFG2JCJY2500	2018	LA	DP	4531	FL	11/7/2017	11/15/2017
501550	4UZFCFTFGXJCJY9453	2018	LA	DP	4531	FL	1/8/2018	1/15/2018
801248	4UZFCFTFG7JCJR6604	2018	EX	DP	4553	FL	5/19/2017	6/1/2017
801253	4UZFCFTFG7JCJR3945	2018	EX	DP	4531	FL	6/15/2017	6/23/2017
801256	4UZFCFTFG3JCJS6792	2018	EX	DP	4531	FL	6/28/2017	7/14/2017
801261	4UZFCFTFG5JCJT8412	2018	EX	DP	4531	FL	8/10/2017	8/18/2017
801262	4UZFCFTFG0JCJX3648	2018	EX	DP	4531	FL	10/18/2017	10/26/2017
904547	4UZFCFTBG1JCJS8465	2018	MA	DP	4531	FL	9/20/2017	9/28/2017
904556	4UZFCFTBG6JCJR3943	2018	MA	DP	4531	FL	8/8/2017	8/16/2017
904591	4UZFCFTBG5JCJX7054	2018	MA	DP	4537	FL	11/9/2017	11/17/2017
904593	4UZFCFTBG7JCJX7055	2018	MA	DP	4534	FL	11/15/2017	11/27/2017

Canadian Units

413254	4UZFCHCY1HCJK2860	2017	VT	DP	4037	FL	5/2/2017	5/10/2017
413357	4UZFCHFE5JCJS8457	2018	VT	DP	4369	FL	6/28/2017	7/14/2017
413371	4UZAB2FC0JCJU2226	2018	VL	DP	3413	FL	7/24/2017	8/1/2017
413372	4UZFCHFE7JCJT1845	2018	VT	DP	4037	FL	7/27/2017	8/4/2017
413373	4UZFCHFE7JCJS8458	2018	VT	DP	4308	FL	6/28/2017	7/14/2017
413374	4UZFCHFE2JCJU9962	2018	VT	DP	4308	FL	8/17/2017	8/25/2017
413437	4UZFCHFE2JCJR6361	2018	VT	DP	4037	FL	6/8/2017	6/16/2017
413438	4UZFCHFE1JCJT8399	2018	VT	DP	4037	FL	7/28/2017	8/7/2017
413463	4UZAB2FC6JCJW3565	2018	VL	DP	3412	FL	9/27/2017	10/5/2017
413464	4UZACHFC9JCJU9952	2018	VL	DP	4037	FL	8/10/2017	8/17/2017
413520	4UZACHFC0JCJX3637	2018	VT	DP	3412	FL	10/16/2017	10/24/2017
413551	4UZACHFC0JCJV8720	2018	VT	DP	3436	FL	9/14/2017	9/22/2017
501534	4UZFCFTFG6JCJX7056	2018	LA	DP	4531	FL	10/16/2017	10/24/2017