

NEWMAR CORPORATION

WARRANTY

DEPARTMENT

RECALL SERVICE BULLETIN

DATE ISSUED

MODEL YEAR(S) AFFECTED

RSB #

1/8/2019

2018, 2019

537

MODEL

Bay Star Sport	☐	Ventana	☒	Essex	☒
Bay Star	☐	Dutch Star	☐	King Aire	☐
Canyon Star	☐	Mountain Aire	☒	New Aire	☐
Ventana LE	☒	London Aire	☒	Other	☐

DESCRIPTION

Daimler Trucks North America, LLC has decided that a defect relating to motor vehicle safety exists in specific motorhomes built on Freightliner Chassis (NHTSA 18V 703). In response, Newmar Corporation is releasing recall NHTSA 18V 859 and TC # 2018-669.

Issue: On certain motorhomes, the brake caliper mounting bolts may be incorrectly torqued. Insufficiently torqued bolts may not provide adequate clamping force between the brake caliper and brake anchor plate potentially resulting in reduced brake effectiveness. Reduced brake effectiveness could lead to a vehicle crash and/or property damage.

Correction: Daimler Trucks North America LLC service facilities will inspect and repair as necessary.

Units Affected: Refer to the attached population list for specific VIN numbers supplied by DTNA.

RECOMMENDED ACTION

Repair Procedure: Contact the Freightliner Customer Support Center at 1-800-FTL-HELP (1-800-385-4357), and follow the prompts, or visit <https://freightliner.com/dealer-search/>. You may also email DTNA at DTNA.Warranty.Campaigns@Daimler.com, or call them at 1-800-547-0712 to locate an authorized DTNA service center to schedule and perform the recall near you. DTNA will provide the work instructions and any necessary parts.

Note: Newmar will not be authorizing this repair. DTNA will authorize and schedule this repair. If you need assistance contacting DTNA, contact your Newmar Service Account Manager.

Please read this bulletin in its entirety prior to beginning any diagnosis or repairs.



WHEN YOU KNOW THE DIFFERENCE

NEWMAR CORPORATION

NEWMARCORP.COM

Date: January 3, 2019

Re: Newmar Corporation – Motor Vehicle Recall Notification

Subject: Recall Campaign No. 18V 859

This notice is sent to you as a Newmar Dealer in accordance with the requirements of the National Traffic and Motor Vehicle Safety Act. Newmar Corporation has decided that a defect, which relates to motor vehicle safety, exists in specific Newmar recreational vehicles.

The National Traffic and Motor Vehicle Safety Act requires that each vehicle, which is subject to a recall campaign of this type, must be satisfactorily repaired within a reasonable time after the owner has tendered it for repair. A failure to adequately repair within 60 days after tender of a vehicle is prima facie evidence of failure to repair within a reasonable time. To avoid providing these problematic solutions, every effort must be made to promptly schedule an appointment with each owner and to repair their vehicle as soon as possible. Vehicle owners are being notified of this recall. If the condition is not remedied within a reasonable time, they are instructed on how to contact the National Highway Traffic Safety Administration.

REASON FOR THIS RECALL

In response to notification from Daimler Trucks North America LLC, Newmar Corporation has decided that a defect which relates to motor vehicle safety exists in specific motorhomes built on Freightliner chassis.

On certain motorhomes, the brake caliper mounting bolts may be incorrectly torqued. Insufficiently torqued bolts may not provide adequate clamping force between the brake caliper and brake anchor plate potentially resulting in reduced brake effectiveness. Reduced brake effectiveness could lead to a vehicle crash and/or property damage. Correction: Daimler Trucks North America LLC service facilities will inspect and repair as necessary.

The motorhomes require immediate service. Continued use poses a potential safety hazard.

DEALER CAMPAIGN RESPONSIBILITY

Dealers are to provide to all customers/owner vehicles the service of completing this campaign at no charge to the customer/owner regardless of vehicle age, vehicle mileage, or ownership at the time of repair.

REPAIR PROCEDURE

Please reference Daimler Trucks North America LLC work instructions.

If you should have any questions please contact your service account manager direct or the Newmar service department at: 1-866-290-5371.

Thank you for your cooperation.

Sincerely,

Newmar Corporation



WHEN YOU KNOW THE DIFFERENCE

NEWMAR CORPORATION

NEWMARCORP.COM

IMPORTANT SAFETY RECALL

This notice applies to your vehicle VIN. # _____

Name

Address

City, State Zip code

Date: January 3, 2019

Motor Vehicle Recall Notification - Recall Campaign No. 18V 859

Dear Valued Customer:

This notice is sent to you in accordance with the requirements of the National Traffic and Motor Vehicle Safety Act.

REASON FOR THIS RECALL

Newmar Corporation has decided that a defect, which relates to motor vehicle safety, exists in specific motorhomes built on Freightliner chassis. This recall is the result of information provided to us by Daimler Trucks North America LLC.

On certain motorhomes, the brake caliper mounting bolts may be incorrectly torqued. Insufficiently torqued bolts may not provide adequate clamping force between the brake caliper and brake anchor plate potentially resulting in reduced brake effectiveness. Reduced brake effectiveness could lead to a vehicle crash and/or property damage. Correction: Daimler Trucks North America LLC service facilities will inspect and repair as necessary.

The motorhomes require immediate service. Continued use poses a potential safety hazard.

The Safety Risk

Insufficiently torqued bolts may not provide adequate clamping force between the brake caliper and brake anchor plate potentially resulting in reduced brake effectiveness. Reduced brake effectiveness could lead to a vehicle crash and/or property damage.

WHAT WE WILL DO

Daimler Trucks North America LLC will inspect and tighten the brake caliper mounting bolts at no charge for parts or labor. Daimler Trucks North America LLC service facilities will inspect and repair as necessary. Estimated time for repair is 4.8 hours.

WHAT YOU NEED TO DO

As this defect does affect motor vehicle safety, it is recommended that you call Daimler Trucks North America LLC @ **800-547-0712** to locate a Qualified Service Center near you. If you need further assistance, contact the Newmar service department immediately at **1-800-731-8300**. An associate will assist you in making an appointment to have this repair completed.

Federal regulations require that any vehicle lessor receiving this recall notification must forward a copy of this notice to the lessee within ten days.

If you have had the repair performed before receiving this letter, you may be eligible to receive reimbursement for the cost of obtaining a pre-notification remedy. For additional information, contact Newmar Corporation at:

Service Department
Newmar Corporation
355 N Delaware St
Nappanee, IN 46550-0030

Authorized Chassis Service Facility, are best equipped to obtain parts and provide service to ensure your vehicle is corrected as promptly as possible. HOWEVER, if you take your vehicle to your Authorized Chassis Service Facility on the scheduled date and this condition is not remedied on that date or within five days; please contact the Newmar Corporation Customer Service Department at 1-800-731-8300. You may also submit a complaint to the Administrator, National Highway Traffic Safety Administration, 1200 New Jersey Ave., SE., Washington DC 20590; or call the toll-free Vehicle Safety Hotline at 1-888-327-4236 (TTY: 1-800-424-9153); or go to <http://www.safercar.gov>.

If you no longer own this vehicle, please furnish us the complete name and address of the person or dealership you sold or traded your vehicle to. Thank you for your cooperation.

Your safety and satisfaction with your Newmar product is important to us and we regret any inconvenience to you.

Sincerely,

Newmar Corporation



WHEN YOU KNOW THE DIFFERENCE

NEWMAR CORPORATION

NEWMARCORP.COM

Date: January 3, 2019

Re: Newmar Corporation – Motor Vehicle Recall Notification

Subject: Recall Campaign No.: 2018-669

This notice is sent to you as a Newmar Dealer in accordance with the requirements of the Canada Motor Vehicle Safety Act. Newmar Corporation has decided that a defect, which relates to motor vehicle safety, exists in specific Newmar recreational vehicles.

Each vehicle, which is subject to a recall campaign of this type, must be satisfactorily repaired within a reasonable time after the owner has tendered it for repair. A failure to adequately repair within 60 days after tender of a vehicle is prima facie evidence of failure to repair within a reasonable time. To avoid providing these problematic solutions, every effort must be made to promptly schedule an appointment with each owner and to repair their vehicle as soon as possible. Vehicle owners are being notified of this recall. If the condition is not remedied within a reasonable time, they are instructed to contact Transport Canada.

REASON FOR THIS RECALL

In response to notification from Daimler Trucks North America, Newmar Corporation has decided that a defect, which relates to motor vehicle safety, exists in specific motorhomes built on Freightliner chassis.

On certain vehicles equipped with air disc brakes, the brake caliper mounting bolts may be incorrectly torqued. This could result in the caliper bolts loosening, which could lead to the caliper detaching. Insufficiently torqued fasteners may not provide adequate clamping force between the brake caliper and brake anchor plate potentially resulting in reduced brake effectiveness, which would result in increased stopping distances, increasing the risk of a crash causing injury and/or damage to property. Correction: Daimler Trucks of North America Service Facilities will inspect the bolts, and repair as necessary.

The motorhomes require immediate service. Continued use poses a potential safety hazard.

Motorhomes included in this recall: 2018 London Aire; 2018 Ventana LE and 2018-2019 Ventana built between 12/15/2017 and 10/03/2018.

DEALER CAMPAIGN RESPONSIBILITY

Dealers are to provide to all customers/owner vehicles the service of completing this campaign at no charge to the customer/owner regardless of vehicle age, vehicle mileage, or ownership at the time of repair.

REPAIR PROCEDURE

Daimler Trucks North America LLC will provide the work instructions.

If you should have any questions please contact your service account manager direct or the Newmar service department at: 1-866-290-5371.

Thank you for your cooperation.

Sincerely,

Newmar Corporation



WHEN YOU KNOW THE DIFFERENCE

NEWMAR CORPORATION

NEWMARCORP.COM

VIN#
Name
Address
City, State Zip code

Date: January 3, 2019
Motor Vehicle Recall Notification - Recall Campaign No. 2018-669

Dear Valued Customer:

This notice is sent to you in accordance with the requirements of the Canada Motor Vehicle Safety Act.

REASON FOR THIS RECALL

Newmar Corporation has decided that a defect, which relates to motor vehicle safety, exists in specific motorhomes built on Freightliner chassis. This recall is the result of information provided to us by Daimler Trucks North America LLC.

On certain vehicles equipped with air disc brakes, the brake caliper mounting bolts may be incorrectly torqued. This could result in the caliper bolts loosening, which could lead to the caliper detaching. Insufficiently torqued fasteners may not provide adequate clamping force between the brake caliper and brake anchor plate potentially resulting in reduced brake effectiveness, which would result in increased stopping distances, increasing the risk of a crash causing injury and/or damage to property. Correction: Daimler Trucks of North America Service Facilities will inspect the bolts, and repair as necessary.

The motorhomes require immediate service. Continued use poses a potential safety hazard.

WHAT WE WILL DO

Daimler Trucks North America will provide owners of all affected motorhomes a remedy for the potential defect at no charge for parts or labor. Daimler Trucks of North America Service Facilities will inspect the bolts, and repair as necessary.

WHAT YOU NEED TO DO

As this defect does affect motor vehicle safety, it is recommended that you call Daimler Trucks North America @ **800-547-0712** to locate a Qualified Service Center near you. If you need further assistance contact the Newmar service department immediately at 1-800-731-8300. An associate will assist you in making an appointment to have this repair completed.

Federal regulations require that any vehicle lessor receiving this recall notification must forward a copy of this notice to the lessee within ten days.

If you have had the repair performed before receiving this letter, you may be eligible to receive reimbursement for the cost of obtaining a pre-notification remedy. For additional information contact Newmar Corporation at:

Service Department
Newmar Corporation
355 N Delaware St
Nappanee, IN 46550-0030

Authorized Chassis Service Facility, are best equipped to obtain parts and provide service to ensure your vehicle is corrected as promptly as possible. HOWEVER, if you take your vehicle to your Authorized Chassis Service Facility on

the scheduled date and this condition is not remedied on that date or within five days; please contact the Newmar Corporation Customer Service Department at 1-800-731-8300.

If you no longer own this vehicle, please furnish us the complete name and address of the person or dealership you sold or traded your vehicle to. Thank you for your cooperation.

Your safety and satisfaction with your Newmar product is important to us and we regret any inconvenience to you.

Sincerely,

Newmar Corporation



WHEN YOU KNOW THE DIFFERENCE

NEWMAR CORPORATION.

NEWMARCORP.COM

NIV
Nom
Adresse
Ville, province, code postal

Date : 3 janvier 2019
Avis de rappel visant un véhicule motorisé – Campagne de rappel n° 2018-669

Madame, Monsieur,

Le présent avis vous est envoyé conformément aux exigences de la *Loi sur la sécurité automobile du Canada*.

MOTIF DU PRÉSENT RAPPEL

Newmar Corporation a déterminé qu'il existe une défaillance relevant de la sécurité automobile dans certaines autocaravanes montées sur châssis Freightliner. Nous procédons à ce rappel en raison de renseignements que Daimler Trucks North America LLC nous a fournis.

Sur certains véhicules équipés de freins à disque pneumatiques, les boulons de fixation de l'étrier de frein peuvent avoir été mal serrés au couple. Les boulons de l'étrier peuvent alors se desserrer, ce qui pourrait entraîner le détachement de l'étrier. Des dispositifs de fixation insuffisamment serrés peuvent ne pas offrir une force de serrage adéquate entre l'étrier de frein et le support de frein, ce qui peut occasionner une réduction de l'efficacité du système de freinage. Une telle situation accroît les distances de freinage et les risques de collisions causant des blessures ou des dommages à la propriété. Mesure corrective : Les installations d'entretien de Daimler Trucks North America inspecteront les boulons et se chargeront d'effectuer une réparation au besoin.

Il est impératif que les réparations sur ces autocaravanes soient effectuées immédiatement. Leur utilisation prolongée pose un risque d'accident potentiel.

CE QUE NOUS FERONS

Daimler Trucks North America fournira aux propriétaires de toutes les autocaravanes concernées une solution gratuite (pour les pièces et la main-d'œuvre) à la défaillance potentielle. Les installations d'entretien de Daimler Trucks North America inspecteront les boulons et se chargeront d'effectuer une réparation au besoin.

CE QUE VOUS DEVEZ FAIRE

Puisque cette défaillance touche la sécurité automobile, nous vous recommandons de communiquer immédiatement avec Daimler Trucks North America au **1-800-547-0712** pour obtenir les coordonnées d'un centre de service autorisé près de chez vous. Si vous avez besoin d'aide, veuillez communiquer immédiatement avec le service technique de Newmar au 1-800-731-8300. Un associé vous aidera à prendre rendez-vous aux fins d'exécution de cette réparation.

En vertu de règlements fédéraux, tout donneur à bail d'un véhicule, qui reçoit le présent avis de rappel, est tenu d'en acheminer une copie au preneur à bail dans un délai de dix jours.

Si les réparations ont été effectuées avant réception de la présente lettre, vous pouvez être admissible à un remboursement des frais liés à l'obtention de la solution adoptée avant réception du présent avis. Pour de plus amples renseignements, communiquez avec Newmar Corporation à l'adresse suivante :

Service Department
Newmar Corporation
355 N Delaware St
Nappanee, IN 46550-0030

Les centres de service autorisés sont les plus à même de fournir du service et d'obtenir des pièces qui assureront une réparation de votre véhicule dans les plus brefs délais. CELA DIT, si vous apportez votre véhicule à un centre de service autorisé à la date prévue et que le problème n'est pas résolu à cette date ou dans les cinq jours qui suivent, veuillez communiquer avec le service à la clientèle de Newmar Corporation en composant le 1-800-731-8300.

Si l'autocaravane concernée ne vous appartient plus, nous vous prions de bien vouloir nous fournir le nom complet et l'adresse complète de la personne ou du concessionnaire faisant maintenant office de propriétaire. Nous vous remercions de votre coopération.

Votre sécurité et votre satisfaction par rapport à nos produits Newmar sont importantes pour nous, et nous sommes désolés de tout désagrément occasionné.

Veuillez agréer, Madame, Monsieur, l'expression de nos sentiments distingués.

Newmar Corporation

Prod	VIN Number	Model	Brand	Type	Floor	Chassis	Date In	Date Off
USA Units								
413368	4UZACHFC1JCKB2523	2018	VL	DP	4037	FL	1/26/2018	2/5/2018
413378	4UZAB2FC2JCJZ5543	2018	VL	DP	3412	FL	12/8/2017	12/18/2017
413380	4UZAB2FC0JCJZ5542	2018	VL	DP	3412	FL	12/5/2017	12/13/2017
413384	4UZFCHFE4KCKM3293	2018	VT	DP	4037	FL	5/21/2018	5/29/2018
413390	4UZACHFCXJCJZ5547	2018	VL	DP	4037	FL	12/13/2017	12/21/2017
413416	4UZACHFC1JCJZ9681	2018	VT	DP	3709	FL	1/11/2018	1/19/2018
413418	4UZACHFC5KCKD7992	2018	VL	DP	4037	FL	3/27/2018	4/4/2018
413419	4UZAB2FC4JCJZ5544	2018	VL	DP	3412	FL	12/11/2017	12/19/2017
413420	4UZFCHFE1JCKA8964	2018	VT	DP	4037	FL	1/10/2018	1/17/2018
413436	4UZACHFC9KCKF4374	2018	VT	DP	3407	FL	3/20/2018	3/27/2018
413460	4UZACHFC8JCKC6905	2018	VL	DP	4002	FL	2/16/2018	2/26/2018
413469	4UZAB2FC8JCJZ3487	2018	VL	DP	3412	FL	11/29/2017	12/7/2017
413471	4UZAB2FC1JCJZ3489	2018	VL	DP	3709	FL	12/7/2017	12/15/2017
413479	4UZAB2FC6JCJZ3486	2018	VL	DP	3412	FL	11/30/2017	12/8/2017
413481	4UZACHFC3JCJZ5549	2018	VL	DP	4037	FL	11/30/2017	12/8/2017
413483	4UZFCHFE0KCKJ5748	2018	VT	DP	4326	FL	5/7/2018	5/15/2018
413496	4UZFCHFE7JCKA3672	2018	VT	DP	4369	FL	1/17/2018	1/25/2018
413497	4UZFCHFE8JCJZ5554	2018	VT	DP	4369	FL	12/12/2017	12/19/2017
413499	4UZAB2FCXJCKA8955	2018	VL	DP	3709	FL	1/19/2018	1/29/2018
413503	4UZACHFCXJCJZ5550	2018	VL	DP	4037	FL	12/20/2017	1/12/2018
413505	4UZFCHFE2JCJZ3492	2018	VT	DP	4369	FL	12/21/2017	1/12/2018
413506	4UZFCHFE3JCJZ9687	2018	VT	DP	4308	FL	12/21/2017	1/15/2018
413507	4UZAB2FC3JCJZ9679	2018	VL	DP	3412	FL	12/21/2017	1/15/2018
413508	4UZAB2FC7JCKB9993	2018	VL	DP	3436	FL	1/30/2018	2/6/2018
413509	4UZACHFC7JCKA8959	2018	VL	DP	4037	FL	1/22/2018	1/29/2018
413510	4UZACHFC3JCKA3662	2018	VL	DP	4002	FL	12/19/2017	1/10/2018
413511	4UZFCHFE3JCKA3670	2018	VT	DP	4037	FL	12/20/2017	1/11/2018
413512	4UZFCHFEXJCKA8963	2018	VT	DP	4037	FL	1/9/2018	1/17/2018
413513	4UZACHFC7JCKA8962	2018	VT	DP	3407	FL	2/7/2018	2/14/2018
413514	4UZACHFC6JCKA3669	2018	VT	DP	3715	FL	1/23/2018	1/30/2018
413515	4UZACHFC3JCKC1000	2018	VT	DP	3709	FL	1/30/2018	2/7/2018
413516	4UZACHFC8JCJZ5546	2018	VL	DP	4037	FL	12/19/2017	1/11/2018
413517	4UZAB2FC8JCKA8954	2018	VL	DP	3713	FL	1/19/2018	1/26/2018
413518	4UZACHFCXJCJZ3491	2018	VT	DP	3412	FL	12/14/2017	1/8/2018
413519	4UZACHFC2JCKA3667	2018	VT	DP	3407	FL	1/8/2018	1/16/2018
413525	4UZAB2FC1JCKA3661	2018	VL	DP	3412	FL	1/10/2018	1/17/2018
413529	4UZAB2FC6JCKA8953	2018	VL	DP	3709	FL	1/30/2018	2/7/2018
413531	4UZAB2FC3KCKD5576	2018	VL	DP	3412	FL	2/20/2018	2/27/2018
413532	4UZAB2FC2KCKD9148	2018	VL	DP	3412	FL	3/5/2018	3/13/2018
413533	4UZACHFC5KCKE8393	2018	VL	DP	4048	FL	3/14/2018	3/21/2018
413534	4UZACHFC8JCKB9999	2018	VL	DP	4037	FL	2/6/2018	2/13/2018
413535	4UZAB2FC4JCKC6903	2018	VL	DP	3436	FL	2/14/2018	2/21/2018
413536	4UZFCHFE2JCKC6910	2018	VT	DP	4002	FL	2/7/2018	2/15/2018
413537	4UZACHFC5JCKB2525	2018	VT	DP	3407	FL	2/8/2018	2/15/2018
413538	4UZACHFC7KCKD1255	2018	VT	DP	3407	FL	2/13/2018	2/20/2018
413540	4UZACHFC5JCKA8961	2018	VT	DP	3436	FL	1/25/2018	2/1/2018
413541	4UZACHFC2JCKC0999	2018	VT	DP	3709	FL	1/23/2018	1/30/2018

Prod	VIN Number	Model	Brand	Type	Floor	Chassis	Date In	Date Off
413542	4UZACHFC5JCKC1001	2018	VT	DP	3715	FL	2/1/2018	2/8/2018
413543	4UZFCHFE5KCKD1259	2018	VT	DP	4002	FL	2/8/2018	2/15/2018
413544	4UZFCHFE1JCKC1004	2018	VT	DP	4037	FL	1/25/2018	2/1/2018
413545	4UZFCHFE7JCKC1007	2018	VT	DP	4037	FL	2/1/2018	2/9/2018
413546	4UZACHFCXJCKB2522	2018	VL	DP	4037	FL	1/24/2018	1/31/2018
413549	4UZFCHFE9JCKA8968	2018	VT	DP	4311	FL	2/26/2018	3/6/2018
413554	4UZFCHFE4JCKC6911	2018	VT	DP	4037	FL	2/8/2018	2/16/2018
413557	4UZFCHFEXJCKB2530	2018	VT	DP	4369	FL	2/2/2018	2/12/2018
413558	4UZAB2FC1JCKA8956	2018	VL	DP	3709	FL	1/31/2018	2/7/2018
413559	4UZAB2FC4JCKA8952	2018	VL	DP	3412	FL	1/25/2018	2/1/2018
413560	4UZACHFC6JCKC6904	2018	VL	DP	4037	FL	2/7/2018	2/14/2018
413561	4UZFCHFEXJCKC6914	2018	VT	DP	4326	FL	2/14/2018	2/21/2018
413567	4UZACHFC5JCKA3663	2018	VL	DP	4037	FL	1/18/2018	1/26/2018
413568	4UZFCHFE5JCKA3671	2018	VT	DP	4369	FL	1/17/2018	1/24/2018
413571	4UZAB2FC5KCKD5577	2018	VL	DP	3436	FL	2/21/2018	2/28/2018
413572	4UZAB2FC9KCKD9146	2018	VL	DP	3412	FL	2/27/2018	3/7/2018
413573	4UZACHFC9KCKD1256	2018	VT	DP	3412	FL	2/15/2018	2/22/2018
413574	4UZFCHFE9JCKC1008	2018	VT	DP	4037	FL	2/5/2018	2/13/2018
413575	4UZFCHFE7KCKD1263	2018	VT	DP	4369	FL	2/15/2018	2/22/2018
413625	4UZACHFC8JCJZ3490	2018	VL	DP	4037	FL	11/22/2017	12/4/2017
413629	4UZAB2FC4JCJZ3485	2018	VL	DP	3412	FL	11/16/2017	11/28/2017
413634	4UZFCHFE9KCKD5587	2018	VT	DP	4037	FL	2/21/2018	3/1/2018
413640	4UZACHFC2KCKD5584	2018	VT	DP	3436	FL	2/28/2018	3/7/2018
413641	4UZACHFC2KCKD1258	2018	VT	DP	3709	FL	2/27/2018	3/6/2018
413645	4UZACHFC3JCKB2524	2018	VL	DP	4042	FL	1/31/2018	2/8/2018
413646	4UZAB2FCXJCJZ9680	2018	VL	DP	3709	FL	1/18/2018	1/25/2018
413647	4UZAB2FC0JCKB9995	2018	VL	DP	3709	FL	3/1/2018	3/9/2018
413649	4UZFCHFE9KCKD5590	2018	VT	DP	4369	FL	2/23/2018	3/2/2018
413651	4UZAB2FC7KCKD5578	2018	VL	DP	3412	FL	2/22/2018	3/1/2018
413652	4UZACHFC7KCKE8394	2018	VL	DP	4037	FL	3/22/2018	3/29/2018
413653	4UZFCHFE8KCKD9162	2018	VT	DP	4310	FL	3/13/2018	3/20/2018
413654	4UZFCHFE9KCKD1264	2018	VT	DP	4310	FL	2/15/2018	2/22/2018
413655	4UZACHFC6KCKD5586	2018	VT	DP	3715	FL	3/1/2018	3/8/2018
413656	4UZACHFC1JCKC6907	2018	VL	DP	4037	FL	3/2/2018	3/9/2018
413657	4UZACHFC0KCKD7995	2018	VT	DP	3715	FL	3/6/2018	3/13/2018
413659	4UZAB2FC3KCKE8389	2018	VL	DP	3412	FL	3/15/2018	3/22/2018
413662	4UZAB2FC2KCKK3892	2018	VL	DP	3436	FL	4/17/2018	4/24/2018
413663	4UZAB2FC6KCKF8611	2018	VL	DP	3436	FL	4/9/2018	4/16/2018
413664	4UZAB2FC3KCKD7991	2018	VL	DP	3709	FL	4/18/2018	4/25/2018
413671	4UZACHFC4KCKN3282	2018	VT	DP	3407	FL	5/1/2018	5/8/2018
413673	4UZACHFC0KCKN3280	2018	VT	DP	3412	FL	5/14/2018	5/22/2018
413674	4UZACHFC0KCKD5583	2018	VT	DP	3412	FL	3/13/2018	3/21/2018
413684	4UZACHFC9KCKE8400	2018	VT	DP	3715	FL	3/14/2018	3/21/2018
413685	4UZFCHFE5KCKF4377	2018	VT	DP	4369	FL	3/20/2018	3/27/2018
413686	4UZFCHFE9KCKF4379	2018	VT	DP	4369	FL	3/27/2018	4/5/2018
413688	4UZFCHFE1KCKH4402	2018	VT	DP	4369	FL	4/26/2018	5/3/2018
413689	4UZFCHFE2KCKM9884	2018	VT	DP	4369	FL	5/3/2018	5/11/2018
413690	4UZFCHFE6KCKN3291	2018	VT	DP	4369	FL	5/25/2018	6/4/2018

Prod	VIN Number	Model	Brand	Type	Floor	Chassis	Date In	Date Off
413694	4UZFCHFEXKCKD9163	2018	VT	DP	4369	FL	3/7/2018	3/15/2018
413695	4UZFCHFEXKCKM3296	2018	VT	DP	4369	FL	5/11/2018	5/18/2018
413696	4UZFCHF7KCKD7998	2018	VT	DP	4369	FL	3/14/2018	3/22/2018
413699	4UZFCHF2KCKD1266	2018	VT	DP	4308	FL	2/16/2018	2/23/2018
413700	4UZFCHF5JCJZ9688	2018	VT	DP	4326	FL	1/9/2018	1/16/2018
413701	4UZACHFC4JCKB9997	2018	VL	DP	4037	FL	2/1/2018	2/8/2018
413704	4UZAB2FC6JCJZ5545	2018	VL	DP	3709	FL	12/15/2017	1/9/2018
413707	4UZACHFC1KCKE8391	2018	VL	DP	4037	FL	3/8/2018	3/16/2018
413708	4UZFCHF4KCKD9160	2018	VT	DP	4369	FL	3/21/2018	3/28/2018
413713	4UZACHFC5KCKD5580	2018	VL	DP	4037	FL	3/7/2018	3/14/2018
413714	4UZFCHF2KCKD5592	2018	VT	DP	4311	FL	3/21/2018	3/28/2018
413715	4UZFCHF4KCKD9157	2018	VT	DP	4002	FL	3/29/2018	4/6/2018
413716	4UZACHFC3KCKF4371	2018	VL	DP	4002	FL	3/29/2018	4/6/2018
413719	4UZFCHF7KCKF4381	2018	VT	DP	4326	FL	3/29/2018	4/9/2018
413720	4UZFCHFEXJCKB2527	2018	VT	DP	4037	FL	1/16/2018	1/23/2018
413722	4UZACHFC0KCKD9150	2018	VT	DP	3412	FL	3/9/2018	3/16/2018
413727	4UZACHFC5KCKF4372	2018	VL	DP	4002	FL	4/5/2018	4/12/2018
413731	4UZACHFC9KCKE8395	2018	VL	DP	4037	FL	4/20/2018	4/27/2018
413732	4UZFCHF3JCKC1005	2018	VT	DP	4037	FL	1/29/2018	2/5/2018
413733	4UZACHFC6KCKE8399	2018	VT	DP	3715	FL	4/5/2018	4/12/2018
413735	4UZFCHF4KCKK2671	2018	VT	DP	4037	FL	4/17/2018	4/24/2018
413738	4UZACHFC0JCKA3666	2018	VT	DP	3436	FL	12/15/2017	1/9/2018
413739	4UZAB2FCXJCKA3660	2018	VL	DP	3436	FL	12/18/2017	1/10/2018
413740	4UZACHFC0KCKD1257	2018	VT	DP	3412	FL	2/16/2018	2/23/2018
413741	4UZAB2FC0KCKD9147	2018	VL	DP	3412	FL	3/9/2018	3/16/2018
413742	4UZACHFC3JCJZ5552	2018	VT	DP	3709	FL	11/30/2017	12/8/2017
413743	4UZACHFC7KCKD5581	2018	VT	DP	3407	FL	2/19/2018	2/26/2018
413744	4UZAB2FC2JCKB9996	2018	VL	DP	3713	FL	2/27/2018	3/6/2018
413745	4UZFCHF3KCKD1261	2018	VT	DP	4049	FL	2/12/2018	2/19/2018
413746	4UZAB2FC1KCKD7990	2018	VL	DP	3709	FL	4/11/2018	4/18/2018
413747	4UZACHFC3JCKA8960	2018	VT	DP	3412	FL	1/15/2018	1/23/2018
413750	4UZFCHF5JCKA8966	2018	VT	DP	4369	FL	1/26/2018	2/2/2018
413754	4UZAB2FC4KCKD9149	2018	VL	DP	3709	FL	3/5/2018	3/12/2018
413757	4UZFCHF5KCKH4399	2018	VT	DP	4369	FL	4/5/2018	4/12/2018
413760	4UZFCHF7KCKL1204	2018	VT	DP	4049	FL	4/18/2018	4/26/2018
413761	4UZFCHFEXKCKF8618	2018	VT	DP	4037	FL	4/2/2018	4/9/2018
413762	4UZFCHF5KCKD7997	2018	VT	DP	4369	FL	3/8/2018	3/15/2018
413763	4UZFCHF1KCKE8401	2018	VT	DP	4369	FL	3/21/2018	3/29/2018
413770	4UZACHFC9KCKD7994	2018	VT	DP	3412	FL	3/12/2018	3/19/2018
413771	4UZFCHF7JCJZ9689	2018	VT	DP	4369	FL	1/15/2018	1/22/2018
413772	4UZFCHF9KCKL1205	2018	VT	DP	4002	FL	4/19/2018	4/26/2018
413775	4UZFCHF4KCKN3290	2018	VT	DP	4037	FL	5/14/2018	5/21/2018
413777	4UZFCHF6KCKD9158	2018	VT	DP	4369	FL	3/8/2018	3/15/2018
413778	4UZACHFC7JCKA3664	2018	VL	DP	4037	FL	1/16/2018	1/24/2018
413780	4UZAB2FC8KCKL9370	2018	VL	DP	3709	FL	5/3/2018	5/11/2018
413782	4UZACHFC2KCKN3278	2018	VL	DP	4037	FL	5/23/2018	5/31/2018
413786	4UZACHFC7JCKB2526	2018	VT	DP	3407	FL	2/12/2018	2/20/2018
413787	4UZAB2FC1KCKF4370	2018	VL	DP	3412	FL	3/26/2018	4/3/2018

Prod	VIN Number	Model	Brand	Type	Floor	Chassis	Date In	Date Off
413788	4UZFCHFE6JCKC6912	2018	VT	DP	4037	FL	2/6/2018	2/13/2018
413789	4UZACHFC5JCKC6909	2018	VT	DP	3709	FL	2/12/2018	2/19/2018
413790	4UZACHFC5KCKD9175	2018	VT	DP	3715	FL	3/26/2018	4/3/2018
413791	4UZACHFC5JCKA8958	2018	VL	DP	4042	FL	1/12/2018	1/22/2018
413793	4UZFCHFE1JCKB2528	2018	VT	DP	4037	FL	1/22/2018	1/29/2018
413794	4UZACHFC1JCJZ5551	2018	VT	DP	3407	FL	12/4/2017	12/12/2017
413796	4UZFCHFE5KCKD1262	2018	VT	DP	4037	FL	2/20/2018	2/28/2018
413797	4UZFCHFE1JCJZ9686	2018	VT	DP	4037	FL	12/20/2017	1/12/2018
413798	4UZAB2FCXJCJZ3488	2018	VL	DP	3412	FL	12/4/2017	12/12/2017
413800	4UZACHFC1JCJZ5548	2018	VL	DP	4037	FL	12/1/2017	12/11/2017
413802	4UZAB2FC0JCKB2514	2018	VL	DP	3412	FL	1/29/2018	2/5/2018
413803	4UZAB2FC9JCKB9994	2018	VL	DP	3709	FL	2/5/2018	2/12/2018
413804	4UZFCHFE3KCKD7996	2018	VT	DP	4002	FL	3/26/2018	4/4/2018
413805	4UZAB2FC5KCKD7989	2018	VL	DP	3436	FL	2/23/2018	3/2/2018
413806	4UZACHFC7KCKD7993	2018	VL	DP	4037	FL	4/13/2018	4/20/2018
413807	4UZFCHFE1KCKD1260	2018	VT	DP	4037	FL	3/1/2018	3/9/2018
413808	4UZFCHFEXJCJZ5555	2018	VT	DP	4369	FL	1/8/2018	1/16/2018
413809	4UZFCHFE3JCKB2529	2018	VT	DP	4369	FL	1/26/2018	2/2/2018
413810	4UZFCHFE8JCKC6913	2018	VT	DP	4369	FL	2/9/2018	2/16/2018
413811	4UZFCHFE3KCKH4403	2018	VT	DP	4369	FL	5/18/2018	5/25/2018
413812	4UZFCHFE6KCKD9161	2018	VT	DP	4369	FL	3/16/2018	3/23/2018
413813	4UZFCHFE7KCKF4378	2018	VT	DP	4369	FL	3/23/2018	4/2/2018
413814	4UZFCHFE2KCKD9156	2018	VT	DP	4037	FL	4/6/2018	4/13/2018
413815	4UZFCHFE5KCKL1203	2018	VT	DP	4037	FL	4/19/2018	4/27/2018
413816	4UZFCHFE3KCKL9381	2018	VT	DP	4037	FL	5/4/2018	5/14/2018
413817	4UZFCHFE0KCKM3291	2018	VT	DP	4037	FL	5/14/2018	5/21/2018
413818	4UZFCHFE2KCKM3292	2018	VT	DP	4037	FL	5/18/2018	5/25/2018
413819	4UZACHFC3JCKC6908	2018	VL	DP	4002	FL	3/1/2018	3/8/2018
413822	4UZFCHFE4KCKK2668	2018	VT	DP	4037	FL	4/12/2018	4/19/2018
413823	4UZACHFC4KCKE8398	2018	VT	DP	3436	FL	3/16/2018	3/26/2018
413824	4UZACHFC2KCKE8397	2018	VT	DP	3436	FL	3/27/2018	4/4/2018
413825	4UZFCHFE1JCKB2531	2018	VT	DP	4310	FL	2/5/2018	2/13/2018
413826	4UZFCHFE5JCKC1006	2018	VT	DP	4037	FL	1/29/2018	2/6/2018
413827	4UZACHFC9KCKD5582	2018	VT	DP	3412	FL	2/23/2018	3/5/2018
413829	4UZACHFC3KCKE8392	2018	VL	DP	4037	FL	3/12/2018	3/19/2018
413830	4UZACHFC7KCKF4373	2018	VT	DP	3407	FL	2/26/2018	3/5/2018
413835	4UZACHFC0KCKE8396	2018	VT	DP	3407	FL	3/19/2018	3/26/2018
413836	4UZFCHFE3JCKA8965	2018	VT	DP	4049	FL	1/12/2018	1/22/2018
413840	4UZFCHFE3KCKF4376	2018	VT	DP	4002	FL	3/7/2018	3/14/2018
413843	4UZFCHFE0KCKL1206	2018	VT	DP	4037	FL	4/23/2018	4/30/2018
413845	4UZFCHFE3KCKL9378	2018	VT	DP	4002	FL	4/23/2018	4/30/2018
413846	4UZACHFC4KCKD5585	2018	VT	DP	3436	FL	3/6/2018	3/14/2018
413847	4UZFCHFEXKCKF8621	2018	VT	DP	4311	FL	5/24/2018	6/1/2018
413849	4UZFCHFE5KCKF4380	2018	VT	DP	4369	FL	3/28/2018	4/5/2018
413850	4UZFCHFE8KCKM3295	2018	VT	DP	4369	FL	5/7/2018	5/15/2018
413851	4UZACHFC6JCKB9998	2018	VL	DP	4037	FL	2/2/2018	2/9/2018
413853	4UZACHFCXJCKC6906	2018	VL	DP	4037	FL	2/28/2018	3/7/2018
413854	4UZAB2FC9KCKD5579	2018	VL	DP	3709	FL	3/13/2018	3/20/2018

Prod	VIN Number	Model	Brand	Type	Floor	Chassis	Date In	Date Off
413855	4UZACHFC7KCJY2515	2019	VT	DP	3709	FL	2/6/2018	2/14/2018
413858	4UZFCHFE0KCKD5591	2018	VT	DP	4369	FL	2/26/2018	3/5/2018
413859	4UZFCHFE4KCKD1267	2018	VT	DP	4369	FL	2/21/2018	2/28/2018
413860	4UZFCHFE8KCKN3292	2018	VT	DP	4369	FL	5/14/2018	5/21/2018
413861	4UZACHFC4KCKN3279	2018	VT	DP	3407	FL	5/22/2018	5/30/2018
413865	4UZFCHFEXKCKH4401	2018	VT	DP	4369	FL	4/17/2018	4/25/2018
413866	4UZFCHFE5KCKL9379	2018	VT	DP	4037	FL	5/25/2018	6/5/2018
413868	4UZACHFC4KCJY2519	2019	VT	DP	3426	FL	2/22/2018	3/1/2018
413869	4UZACHFC3KCJY2611	2019	VL	DP	4045	FL	2/20/2018	2/27/2018
413870	4UZFCHFE1KCKF8619	2018	VT	DP	4311	FL	4/12/2018	4/19/2018
413872	4UZFCHFE8KCKF8620	2018	VT	DP	4311	FL	5/8/2018	5/16/2018
413873	4UZFCHFE0KCKP0958	2018	VT	DP	4037	FL	5/22/2018	5/31/2018
413874	4UZAB2FCXKCKE8390	2018	VL	DP	3412	FL	3/20/2018	3/28/2018
413876	4UZFCHFE2KCKD5589	2018	VT	DP	4037	FL	3/19/2018	3/27/2018
413879	4UZFCHFE8KCKH4400	2018	VT	DP	4308	FL	4/16/2018	4/23/2018
413882	4UZACHFC0KCKF4375	2018	VT	DP	3407	FL	3/22/2018	3/29/2018
413890	4UZFCHFE1KCKL9380	2018	VT	DP	4037	FL	5/3/2018	5/11/2018
413891	4UZFCHFE4KCKM9885	2018	VT	DP	4369	FL	5/16/2018	5/23/2018
413893	4UZFCHFEXKCKH5497	2019	VT	DP	4369	FL	5/15/2018	5/23/2018
413894	4UZFCHFE6KCKM3294	2018	VT	DP	4369	FL	4/30/2018	5/7/2018
413896	4UZACHFC0KCKL1201	2018	VT	DP	3407	FL	5/31/2018	6/8/2018
413898	4UZFCHFE8KCKS5458	2019	VT	DP	4054	FL	7/23/2018	7/31/2018
413899	4UZACHFC3KCKV7310	2019	VL	DP	3709	FL	7/16/2018	7/23/2018
413909	4UZACHFC5KCKS5457	2019	VT	DP	3717	FL	6/20/2018	7/9/2018
413912	4UZFCHFE2KCKP0993	2019	VT	DP	4037	FL	6/8/2018	6/18/2018
413913	4UZFCHFE5KCKP8408	2019	VT	DP	4037	FL	6/4/2018	6/11/2018
413914	4UZFCHFE7KCKP8409	2019	VT	DP	4369	FL	6/4/2018	6/12/2018
413915	4UZFCHFE7KCKR5257	2019	VT	DP	4369	FL	6/5/2018	6/12/2018
413917	4UZACHFC1KCKS5455	2019	VL	DP	4037	FL	6/18/2018	6/25/2018
413925	4UZAB2FC5KCKX9034	2019	VL	DP	3412	FL	9/6/2018	9/12/2018
413941	4UZFCHFE4KCKP0994	2019	VT	DP	4037	FL	5/29/2018	6/6/2018
413942	4UZFCHFE8KCKP0996	2019	VT	DP	4369	FL	5/31/2018	6/8/2018
413959	4UZACHFC3KCKR5250	2019	VL	DP	4002	FL	6/25/2018	7/10/2018
413961	4UZFCHFE8KCKT8078	2019	VT	DP	4369	FL	7/11/2018	7/18/2018
413964	4UZACHFC6KCKN3283	2019	VT	DP	3412	FL	8/8/2018	8/15/2018
413965	4UZACHFC3KCKS5456	2019	VL	DP	4045	FL	6/18/2018	6/26/2018
413966	4UZFCHFE5KCKP8411	2019	VT	DP	4369	FL	6/12/2018	6/19/2018
413973	4UZACHFC8KCKS5453	2019	VT	DP	3407	FL	7/20/2018	7/27/2018
413979	4UZFCHFE3KCKU4824	2019	VT	DP	4037	FL	8/24/2018	9/4/2018
413981	4UZFCHFE3KCKP8407	2019	VT	DP	4002	FL	8/28/2018	9/5/2018
413992	4UZFCHFE6KCKT8077	2019	VT	DP	4369	FL	8/9/2018	8/16/2018
414001	4UZACHFCXKCKS5454	2019	VT	DP	3426	FL	8/23/2018	8/31/2018
414013	4UZFCHFEXKCKP8405	2019	VT	DP	4002	FL	6/13/2018	6/21/2018
414015	4UZFCHFE0KCKR5259	2019	VT	DP	4369	FL	6/22/2018	7/9/2018
414019	4UZACHFC4KCKT8071	2019	VT	DP	3407	FL	9/24/2018	10/1/2018
414026	4UZFCHFE9KCKU9204	2019	VT	DP	4326	FL	10/9/2018	10/16/2018
414044	4UZFCHFE2KCKT8075	2019	VT	DP	4037	FL	8/10/2018	8/17/2018
414049	4UZFCHFE6KCKT1484	2019	VT	DP	4369	FL	9/24/2018	10/1/2018

Prod	VIN Number	Model	Brand	Type	Floor	Chassis	Date In	Date Off
414052	4UZFHFE2KCKY2108	2019	VT	DP	4037	FL	9/26/2018	10/2/2018
414053	4UZFHFEKCKLE9937	2019	VT	DP	4369	FL	10/3/2018	10/10/2018
414054	4UZACHFC6KCKX4599	2019	VL	DP	4037	FL	9/17/2018	9/21/2018
414060	4UZFHFE4KCKT8076	2019	VT	DP	4369	FL	7/13/2018	7/20/2018
414150	4UZFHFE4KCKW8579	2019	VT	DP	4037	FL	9/6/2018	9/13/2018
414221	4UZAB2FC4KCKS5451	2019	VL	DP	3412	FL	9/4/2018	9/11/2018
414247	4UZFHFE3KCKR5255	2019	VT	DP	4037	FL	6/13/2018	6/20/2018
414248	4UZFHFE3KCKX9041	2019	VT	DP	4037	FL	9/21/2018	9/28/2018
414269	4UZFHFE6KCKP0995	2019	VT	DP	4369	FL	6/6/2018	6/14/2018
414272	4UZFHFE9KCKU4827	2019	VT	DP	4326	FL	8/21/2018	8/29/2018
414273	4UZFHFE1KCKP8406	2019	VT	DP	4037	FL	6/22/2018	7/10/2018
414278	4UZFHFE1KCLE9938	2019	VT	DP	4369	FL	9/26/2018	10/3/2018
414280	4UZFHFE8KCLE9936	2019	VT	DP	4310	FL	10/9/2018	10/16/2018
414283	4UZFHFE1KCLC9947	2019	VT	DP	4310	FL	10/10/2018	10/17/2018
414288	4UZFHFE7KCKY4629	2019	VT	DP	4002	FL	10/10/2018	10/17/2018
414293	4UZFHFE3KCKY4630	2019	VT	DP	4002	FL	10/10/2018	10/17/2018
414339	4UZFHFE0KCKP8414	2019	VT	DP	4311	FL	9/27/2018	10/4/2018
414340	4UZAB2FC6KCKP7857	2019	VL	DP	3426	FL	6/25/2018	7/10/2018
414342	4UZFHFE3KCKP8410	2019	VT	DP	4348	FL	6/14/2018	6/22/2018
414370	4UZFHFE6KCKS5460	2019	VT	DP	4369	FL	8/8/2018	8/16/2018
414372	4UZFHFEKCKS5462	2019	VT	DP	4369	FL	6/26/2018	7/11/2018
414373	4UZFHFE7KCKP8412	2019	VT	DP	4348	FL	6/15/2018	6/22/2018
414375	4UZACHFC4KCKU9202	2019	VT	DP	3709	FL	8/2/2018	8/9/2018
414376	4UZFHFE9KCKP8413	2019	VT	DP	4348	FL	6/7/2018	6/14/2018
414378	4UZFHFE2KCKT1482	2019	VT	DP	4369	FL	7/26/2018	8/3/2018
414462	4UZFHFE9KCKR5258	2019	VT	DP	4369	FL	6/20/2018	6/27/2018
414463	4UZAB2FCXKCLE9932	2019	VL	DP	3426	FL	10/3/2018	10/10/2018
414464	4UZFHFE8KCKS5461	2019	VT	DP	4348	FL	6/28/2018	7/13/2018
414465	4UZACHFC6KCKS5452	2019	VL	DP	3717	FL	6/14/2018	6/21/2018
414468	4UZFHFE9KCKY2106	2019	VT	DP	4037	FL	9/10/2018	9/17/2018
414482	4UZFHFE2KCKT4270	2019	VT	DP	4348	FL	9/13/2018	9/20/2018
414488	4UZFHFE0KCKY2107	2019	VT	DP	4037	FL	9/4/2018	9/11/2018
414494	4UZFHFE4KCKT1483	2019	VT	DP	4369	FL	7/17/2018	7/25/2018
414517	4UZACHFC9KCKY4625	2019	VL	DP	4002	FL	9/21/2018	9/28/2018
414522	4UZAB2FC2KCKT4262	2019	VL	DP	3426	FL	8/9/2018	8/16/2018
414532	4UZAB2FC5KCKU9192	2019	VL	DP	3412	FL	8/15/2018	8/23/2018
414559	4UZFHFE5KCKR5256	2019	VT	DP	4002	FL	7/9/2018	7/17/2018
414560	4UZFHFE5KCKY4628	2019	VT	DP	4002	FL	10/5/2018	10/12/2018
414576	4UZFHFE0KCKT8074	2019	VT	DP	4037	FL	8/3/2018	8/10/2018
414577	4UZFHFE7KCKU9198	2019	VT	DP	4037	FL	8/7/2018	8/15/2018
414583	4UZFHFE5KCKU4825	2019	VT	DP	4037	FL	8/30/2018	9/7/2018
414585	4UZFHFE2KCKU4829	2019	VT	DP	4369	FL	8/21/2018	8/29/2018
414586	4UZFHFE6KCKT4269	2019	VT	DP	4002	FL	8/29/2018	9/6/2018
414587	4UZFHFEKCKS5459	2019	VT	DP	4037	FL	8/28/2018	9/5/2018
414588	4UZFHFE0KCKU4828	2019	VT	DP	4326	FL	10/1/2018	10/8/2018
414589	4UZFHFE4KCKT4271	2019	VT	DP	4369	FL	8/30/2018	9/7/2018
414592	4UZFHFE0KCKU9205	2019	VT	DP	4369	FL	9/18/2018	9/25/2018
414593	4UZFHFE8KCKT1485	2019	VT	DP	4311	FL	10/22/2018	10/29/2018

Prod	VIN Number	Model	Brand	Type	Floor	Chassis	Date In	Date Off
414595	4UZFHFE7KCKU9203	2019	VT	DP	4369	FL	10/8/2018	10/15/2018
501514	4UZFG9JCKA3676	2018	LA	DP	4531	FL	1/31/2018	2/7/2018
501528	4UZFG8JCJZ5557	2018	LA	DP	4531	FL	12/12/2017	12/19/2017
501529	4UZFGXJCJZ5558	2018	LA	DP	4533	FL	12/20/2017	1/12/2018
501559	4UZFG4KCKD1273	2018	LA	DP	4553	FL	2/20/2018	2/27/2018
501566	4UZFGXJCKC1023	2018	LA	DP	4535	FL	2/2/2018	2/12/2018
501567	4UZFG2KCKF4390	2018	LA	DP	4531	FL	4/23/2018	5/1/2018
501571	4UZFG0KCKJY2514	2019	LA	DP	4576	FL	1/31/2018	2/7/2018
501602	4UZFG7KCKY2111	2019	LA	DP	4579	FL	10/16/2018	10/23/2018
801276	4UZFG4JCJX9212	2018	EX	DP	4531	FL	11/10/2017	11/20/2017
801297	4UZFG7JCKA9346	2018	EX	DP	4531	FL	2/19/2018	2/26/2018
801299	4UZFG6KCKJY2517	2019	EX	DP	4543	FL	2/12/2018	2/19/2018
801300	4UZFG9JCKA9347	2018	EX	DP	4531	FL	4/9/2018	4/16/2018
801304	4UZFG9KCKH5494	2019	EX	DP	4551	FL	5/3/2018	5/14/2018
801305	4UZFG6KCKD1274	2018	EX	DP	4531	FL	5/7/2018	5/16/2018
801315	4UZFG3KCKV2409	2019	EX	DP	4579	FL	10/16/2018	10/23/2018
801344	4UZFGXKCLG5222	2019	EX	DP	4533	FL	10/24/2018	10/31/2018
904601	4UZFBG1JCKC6925	2018	MA	DP	4531	FL	2/5/2018	2/13/2018
904620	4UZFBG0JCKC1022	2018	MA	DP	4531	FL	1/30/2018	2/6/2018
904689	4UZFBG3KCKN3307	2019	MA	DP	4543	FL	7/11/2018	7/19/2018
904732	4UZFBG0KCLG5221	2019	MA	DP	4543	FL	10/23/2018	10/30/2018

Canadian Units

413579	4UZFHFE6JCJZ5553	2018	VT	DP	4037	FL	12/15/2017	1/8/2018
413642	4UZAB2FC2JCKC6902	2018	VL	DP	3412	FL	2/9/2018	2/19/2018
413709	4UZFHFE6KCKK2669	2018	VT	DP	4037	FL	4/5/2018	4/12/2018
413710	4UZFHFE3KCKE8402	2018	VT	DP	4369	FL	3/21/2018	3/28/2018
413737	4UZFHFE0KCKM9883	2018	VT	DP	4037	FL	4/27/2018	5/4/2018
413768	4UZFHFE8KCKD9159	2018	VT	DP	4369	FL	3/15/2018	3/22/2018
413769	4UZFHFE0KCKD5588	2018	VT	DP	4037	FL	3/16/2018	3/23/2018
413795	4UZFHFE0KCKD1265	2018	VT	DP	4369	FL	2/19/2018	2/26/2018
413863	4UZACHFC0KCKJ5743	2018	VT	DP	3436	FL	4/6/2018	4/13/2018
413877	4UZFHFE2KCKK2670	2018	VT	DP	4037	FL	4/13/2018	4/20/2018
413880	4UZFCHFEXKCKN3293	2018	VT	DP	4311	FL	5/24/2018	6/4/2018
414036	4UZFHFE0KCKT1481	2019	VT	DP	4002	FL	7/26/2018	8/3/2018
414065	4UZFHFE9KCKU9199	2019	VT	DP	4002	FL	9/11/2018	9/18/2018
414066	4UZFHFE3KCKY4627	2019	VT	DP	4054	FL	9/26/2018	10/3/2018
501512	4UZFG2JCJZ9698	2018	LA	DP	4534	FL	12/18/2017	1/10/2018
501561	4UZFG0JCKA3677	2018	LA	DP	4534	FL	4/2/2018	4/9/2018
501572	4UZFG2KCKD1272	2018	LA	DP	4531	FL	2/16/2018	2/23/2018