

Newmar Corporation

PO Box 30
Nappanee, IN 46550



WHEN YOU KNOW THE DIFFERENCE.

RSB 562
April 16, 2021

NHTSA #21V 088
TC #2021-073

RECALL SERVICE BULLETIN

AFFECTED MODELS

2020 – 2022 :: Dutch Star, Mountain Aire, London Aire, Essex, King Aire

DESCRIPTION

The Shyft Group Inc. (Spartan Chassis) has decided that a defect relating to motor vehicle safety exists in specific motorhomes built on Spartan chassis (NHTSA #21V 041). In response, Newmar Corporation is issuing recall NHTSA # 21V 088 and TC # 2021-073.

ISSUE

On certain motorhomes built on a Spartan chassis, the steering gear mounting fasteners may come loose and fall out or interfere with other steering components. If the steering gear mounting fasteners interfere with other steering components, such as a pitman arm, it may cause difficulty in steering or pin the steering wheel to one direction, which could increase the risk of a crash.

UNITS AFFECTED

Refer to the attached population list for specific VIN numbers supplied by Spartan for the coaches that may be affected.

CORRECTIVE ACTION

Repairs will be performed by Spartan authorized service facilities. The Shyft Group (Spartan) has provided the attached instructions and will provide necessary parts to complete the recall procedure.

CUSTOMER ACTION

Contact Spartan Chassis at 1-800-543-4277 (Opt. 0) to locate a Qualified Service Center near you. If you need further assistance, contact the Newmar service department at 1-800-731-8300. A brand specialist will assist you in scheduling an appointment to have this repair completed.

DEALER ACTION

Contact Spartan. If you need assistance connecting with Spartan, contact your Newmar Service Account Manager.

NOTE

Newmar will not be authorizing this repair. The Shyft Group (Spartan) will authorize and schedule this repair.

IMPORTANT: Please read this bulletin in its entirety prior to beginning any diagnosis or repairs.

NOTICE: Any technical information published in this bulletin is intended for use only by a qualified, Newmar-authorized service technician. Newmar is not responsible for the misuse of this information.



WHEN YOU KNOW THE DIFFERENCE

NEWMAR CORPORATION

NEWMARCORP.COM

Date: April 13, 2021
Re: Newmar Corporation – Motor Vehicle Recall Notification

Subject: Recall Campaign No.: 21V 088

This notice is sent to you as a Newmar Dealer in accordance with the requirements of the National Traffic and Motor Vehicle Safety Act. Newmar Corporation has decided that a defect, which relates to motor vehicle safety, exists in specific Newmar recreational vehicles.

The National Traffic and Motor Vehicle Safety Act requires that each vehicle, which is subject to a recall campaign of this type, must be satisfactorily repaired within a reasonable time after the owner has tendered it for repair. A failure to adequately repair within 60 days after tender of a vehicle is prima facie evidence of failure to repair within a reasonable time. To avoid providing these problematic solutions, every effort must be made to promptly schedule an appointment with each owner and to repair their vehicle as soon as possible. Vehicle owners are being notified of this recall. If the condition is not remedied within a reasonable time, they are instructed on how to contact the National Highway Traffic Safety Administration.

REASON FOR THIS RECALL

In response to notification from The Shyft Group Inc., Newmar Corporation has decided that a defect, which relates to motor vehicle safety, exists in specific motorhomes built on Spartan chassis.

On certain motorhomes built on a Spartan chassis, the steering gear mounting fasteners may come loose and fall out or interfere with other steering components. If the steering gear mounting fasteners interfere with other steering components, such as a pitman arm, it may cause difficulty in steering or pin the steering wheel to one direction, which could increase the risk of a crash.

The motorhomes require immediate service. Continued use poses a potential safety hazard.

DEALER CAMPAIGN RESPONSIBILITY

Dealers are to provide to all customers/owner vehicles the service of completing this campaign at no charge to the customer/owner regardless of vehicle age, vehicle mileage, or ownership at the time of repair.

REPAIR PROCEDURE

The Shyft Group, Inc. will provide the work instructions.

If you should have any questions please contact your service account manager direct or the Newmar service department at: 1-866-290-5371.

Thank you for your cooperation.

Sincerely,

Newmar Corporation



WHEN YOU KNOW THE DIFFERENCE

NEWMAR CORPORATION

NEWMARCORP.COM

IMPORTANT SAFETY RECALL

This notice applies to your vehicle VIN. # _____

Name

Address

City, State Zip code

Date: April 13, 2021

Motor Vehicle Recall Notification - Recall Campaign No. 21V 088

Dear Valued Customer:

This notice is sent to you in accordance with the requirements of the National Traffic and Motor Vehicle Safety Act.

REASON FOR THIS RECALL

Newmar Corporation has decided that a defect, which relates to motor vehicle safety, exists in specific motorhomes built on Spartan chassis. This recall is the result of information provided to us by The Shyft Group Inc.

On certain motorhomes built on a Spartan chassis, the steering gear mounting fasteners may come loose and fall out or interfere with other steering components. If the steering gear mounting fasteners interfere with other steering components, such as a pitman arm, it may cause difficulty in steering or pin the steering wheel to one direction, which could increase the risk of a crash. The Shyft Group recall number is 21V 041

The motorhomes require immediate service. Continued use poses a potential safety hazard.

The Safety Risk

If the steering gear mounting fasteners interfere with other steering components, such as a pitman arm, it may cause difficulty in steering or pin the steering wheel to one direction, which could increase the risk of a crash.

WHAT WE WILL DO

The Shyft Group Inc. will provide owners of all affected motorhomes a remedy for the potential defect at no charge for parts or labor. The steering gear mounting fasteners will be removed and replaced. New fasteners will be installed using Loctite and a washer then tightened to specification. Estimated time for repair is 1 hr.

WHAT YOU NEED TO DO

As this defect does affect motor vehicle safety, it is recommended that you call Spartan Chassis at 1-800-543-4277 opt. 0 to locate a Qualified Service Center near you. If you need further assistance contact the Newmar service department immediately at 1-800-731-8300. An associate will assist you in making an appointment to have this repair completed.

Federal regulations require that any vehicle lessor receiving this recall notification must forward a copy of this notice to the lessee within ten days.

If you have had the repair performed before receiving this letter, you may be eligible to receive reimbursement for the cost of obtaining a pre-notification remedy. For additional information, contact Newmar Corporation at:

Service Department
Newmar Corporation
355 N Delaware St
Nappanee, IN 46550-0030

Authorized Chassis Service Facility, are best equipped to obtain parts and provide service to ensure your vehicle is corrected as promptly as possible. HOWEVER, if you take your vehicle to your Authorized Chassis Service Facility on the scheduled date and this condition is not remedied on that date or within five days; please contact the Newmar Corporation Customer Service Department at 1-800-731-8300. You may also submit a complaint to the Administrator, National Highway Traffic Safety Administration, 1200 New Jersey Ave., SE., Washington DC 20590; or call the toll-free Vehicle Safety Hotline at 1-888-327-4236 (TTY: 1-800-424-9153); or go to <http://www.safercar.gov>.

If you no longer own this vehicle, please furnish us the complete name and address of the person or dealership you sold or traded your vehicle to. Thank you for your cooperation.

Your safety and satisfaction with your Newmar product is important to us and we regret any inconvenience to you.

Sincerely,

Newmar Corporation



WHEN YOU KNOW THE DIFFERENCE

NEWMAR CORPORATION

NEWMARCORP.COM

Date: April 13, 2021

Re: Newmar Corporation – Motor Vehicle Recall Notification

Subject: Recall Campaign No.: 2021-073

This notice is sent to you as a Newmar Dealer in accordance with the requirements of the *Canada Motor Vehicle Safety Act*. Newmar Corporation has decided that a defect, which relates to motor vehicle safety, exists in specific Newmar recreational vehicles.

Each vehicle, which is subject to a recall campaign of this type, must be satisfactorily repaired within a reasonable time after the owner has tendered it for repair. A failure to adequately repair within 60 days after tender of a vehicle is prima facie evidence of failure to repair within a reasonable time. To avoid providing these problematic solutions, every effort must be made to promptly schedule an appointment with each owner and to repair their vehicle as soon as possible. Vehicle owners are being notified of this recall. If the condition is not remedied within a reasonable time, they are instructed to contact Transport Canada.

REASON FOR THIS RECALL

In response to notification from The Shyft Group Inc. Newmar Corporation has decided that a defect, which relates to motor vehicle safety, exists in specific motorhomes built on Spartan chassis.

Issue:

On certain motorhomes, the mounting bolts for the steering gear may loosen and fall out or interfere with steering components. If this happens, you may have difficulty steering or there could be a loss of steering control.

Safety Risk:

A loss of steering control could create a risk of a crash.

Corrective Actions:

Newmar will notify owners by mail and instruct you to take your motorhome to an authorized Shyft Group Inc. repair facility to replace the steering gear mounting fasteners.

The motorhomes require immediate service. Continued use poses a potential safety hazard.

DEALER CAMPAIGN RESPONSIBILITY

Dealers are to provide to all customers/owner vehicles the service of completing this campaign at no charge to the customer/owner regardless of vehicle age, vehicle mileage, or ownership at the time of repair.

REPAIR PROCEDURE

The Shyft Group Inc. will provide the work instructions. The steering gear mounting fasteners will be removed and replaced. New fasteners will be installed using Loctite and a washer then tightened to specification. This will be done at no charge.

If you should have any questions please contact your service account manager direct or the Newmar service department at: 1-866-290-5371.

Thank you for your cooperation.

Sincerely,

Newmar Corporation



WHEN YOU KNOW THE DIFFERENCE

NEWMAR CORPORATION

NEWMARCORP.COM

VIN#
make, model, model year
Name
Address
City, State Zip code

Date: April 13, 2021
Motor Vehicle Recall Notification - Recall Campaign No. 2021-073

Dear Valued Customer:

This notice is sent to you in accordance with the requirements of the *Canada Motor Vehicle Safety Act*.

This is to inform you that your vehicle may contain a defect that could affect the safety of a person.

REASON FOR THIS RECALL

Newmar Corporation has decided that a defect, which relates to motor vehicle safety, exists in specific motorhomes built on a Spartan chassis. This recall is the result of information provided to us by The Shyft Group Inc. The Shyft Group recall number is 21V-041

Issue:

On certain motorhomes, the mounting bolts for the steering gear may loosen and fall out or interfere with steering components. If this happens, you may have difficulty steering or there could be a loss of steering control.

Safety Risk:

A loss of steering control could create a risk of a crash.

Corrective Actions:

Newmar will notify owners by mail and instruct you to take your motorhome to an authorized Shyft Group Inc. repair facility to replace the steering gear mounting fasteners.

The motorhomes require immediate service. Continued use poses a potential safety hazard.

WHAT WE WILL DO

The Shyft Group Inc. will provide owners of all affected motorhomes a remedy for the potential defect at no charge for parts or labor. The steering gear mounting fasteners will be removed and replaced. New fasteners will be installed using loctite and a washer then tightened to specification. Estimated time for repair is 1 hr.

WHAT YOU NEED TO DO

As this defect does affect motor vehicle safety, it is recommended that you call Spartan Chassis at 1-800-543-4277 opt. 0 to locate a Qualified Service Center near you. If you need further assistance contact the Newmar Service department immediately at 1-800-731-8300. An associate will assist you in making an appointment to have this repair completed.

Federal regulations require that any vehicle lessor receiving this recall notification must forward a copy of this notice to the lessee within ten days.

If you have had the repair performed before receiving this letter, you may be eligible to receive reimbursement for the cost of obtaining a pre-notification remedy. For additional information contact Newmar Corporation at:

Service Department
Newmar Corporation
355 N Delaware St
Nappanee, IN 46550-0030

Authorized Chassis Service Facility, are best equipped to obtain parts and provide service to ensure your vehicle is corrected as promptly as possible. HOWEVER, if you take your vehicle to your Authorized Chassis Service Facility on the scheduled date and this condition is not remedied on that date or within five days; please contact the Newmar Corporation Customer Service Department at 1-800-731-8300.

If you no longer own this vehicle, please furnish us the complete name and address of the person or dealership you sold or traded your vehicle to. Thank you for your cooperation.

Your safety and satisfaction with your Newmar product is important to us and we regret any inconvenience to you.

Sincerely,

Newmar Corporation



WHEN YOU KNOW THE DIFFERENCE

NEWMAR CORPORATION

NEWMARCORP.COM

N° VIN
marque, modèle et année du modèle
Name (Nom)
Adresse
Ville, province et code postal

Date : 12 avril 2021

Avis de rappel de véhicule automobile : campagne de rappel n° 2021-073

Cher client :

Le présent avis vous est envoyé conformément aux exigences de la *Loi sur la sécurité automobile du Canada*.

Le présent avis vous est envoyé conformément aux exigences de la [Loi sur la sécurité automobile](#)

La présente a pour but de vous informer que votre véhicule est susceptible d'avoir un défaut qui pourrait porter atteinte à la sécurité humaine.

RAISON DE CE RAPPEL

Newmar Corporation a déterminé que certaines autocaravanes construites sur un châssis Spartan présentaient un défaut lié à la sécurité. Ce rappel fait suite à des informations fournies par The Shyft Group Inc.

Problème :

sur certaines autocaravanes, les boulons de fixation du boîtier de direction peuvent se desserrer, tomber ou interférer avec les composants de la direction. Si cela se produit, vous risquez de rencontrer des problèmes de direction pouvant aller jusqu'à une perte totale de contrôle du véhicule.

Risque pour la sécurité :

une perte de contrôle de la direction peut représenter un risque d'accident.

Mesures correctives :

Newmar informera les propriétaires par la poste et leur demandera d'apporter leur autocaravane à un centre de réparation agréé de Shyft Group Inc., qui se chargera de remplacer les fixations du boîtier de direction.

Les autocaravanes nécessitent une inspection immédiate. Continuer à utiliser ces véhicules sans les faire contrôler constitue un risque potentiel pour la sécurité.

CE QUE NOUS FERONS

The Shyft Group Inc. fournira aux propriétaires de toutes les autocaravanes concernées un remède pour le défaut potentiel, sans frais de pièces ou de main-d'œuvre. Les fixations du boîtier de direction seront déposées et remplacées. Les nouvelles fixations seront installées avec de la colle cyanoacrylate et une rondelle, puis serrées conformément aux spécifications. Le temps estimé pour la réparation est de une heure.

CE QUE VOUS DEVEZ FAIRE

Étant donné que ce défaut est lié à la sécurité automobile, il est recommandé d'appeler Spartan Chassis en composant le **1-800-543-4277 (opt. 0)** pour trouver un centre de réparations certifié dans votre région. Pour toute aide supplémentaire, communiquez avec le service technique de Newmar en composant le 1 800 731-8300. Un représentant vous aidera à fixer un rendez-vous afin de faire effectuer cette réparation.

Les réglementations fédérales exigent que tout loueur de véhicule recevant cet avis de rappel en transmette une copie au locataire dans un délai de dix jours.

Si la réparation a été effectuée avant la réception de cette lettre, vous pourriez avoir droit à un remboursement du coût d'un remède avant la notification. Pour de plus amples renseignements, veuillez communiquer avec Newmar Corporation :

Service technique
Newmar Corporation
355 N Delaware St
Nappanee, IN 46550-0030

Les centres certifiés d'entretien de châssis sont les mieux équipés pour obtenir des pièces et effectuer la réparation afin que votre véhicule soit réparé le plus rapidement possible. TOUTEFOIS, si vous apportez votre véhicule à votre centre certifié d'entretien de châssis à la date prévue et que la réparation n'est pas effectuée à cette date ou dans un délai de cinq jours, veuillez communiquer avec le service à la clientèle de Newmar Corporation en composant le 1 800 731-8300.

Si vous n'êtes plus propriétaire de ce véhicule, veuillez nous fournir le nom et l'adresse de la personne ou du concessionnaire à qui vous avez vendu ou échangé le véhicule. Nous vous remercions de votre coopération.

Votre sécurité et votre satisfaction à l'égard des produits Newmar sont importantes pour nous. Nous vous prions de nous excuser pour tous désagréments que cette situation a pu vous causer.

Cordialement,

Newmar Corporation



Spartan RV Chassis

Recall Service Bulletin RSB21-260-001

DATE: March 8, 2021

APPLIES TO: This service bulletin applies to certain 2020 thru 2022 model year K2, K3 and K4 model Spartan RV motor home chassis with Vehicle Date of Manufacture (VDM) between December 12, 2019 and December 05, 2020 that are equipped with an Independent Front Suspension supplied by Reyco Granning, LLC.

CONDITION: The steering gear mounting fasteners may loosen, leading to reduced clamp load between the steering gear and mounting cradle. Loss of control of vehicle may occur if fasteners become loose.

CORRECTION: Replace steering gear mounting fasteners.

LABOR ALLOCATION: Up to 1 hour

CLASSIFICATION: V3

TOOLS NEEDED: 1-5/16" socket
1-1/8" shallow socket
1-1/8" open end wrench
Torque wrench capable of 300 LB-FT
Torque wrench capable of 500 LB-FT

PARTS NEEDED:

<u>Suspension model</u>	<u>Repair Kit PN</u>	<u>QTY</u>
IFS1700S3	S-2757-001	1 EA
IFS2000S3	S-2757-002	1 EA

Service Bulletins are intended for use by Professional Technicians only. They are written to guide Professional Technicians in performing service to vehicles of specific nature in conjunction with industry standards. Professional Technicians should be appropriately trained on industry standards and have the tools and equipment to perform procedures safely and properly.



Spartan RV Chassis

Recall Service Bulletin
RSB21-260-001

Please read the entire bulletin before proceeding with any work. Follow industry standards regarding safety equipment and procedures.



WARNING: Use jack stands or other safety devices to properly support vehicle. Failure to safely support the vehicle and follow the procedures in this bulletin can lead to property damage and/or personal injury.

Conduct service per below instructions one fastener at a time for each of the 11 suspect fasteners on IFS1700S3, and each of the 22 suspect fasteners on IFS2000S3.

Steering gear and steering gear clamp area to be cleaned with brake cleaner or similar solvent to remove oil, grease, and contaminants prior to fastener replacement.

Threaded holes on steering gear to be cleaned with wire bottle brush or similar to remove contaminants such as, but not limited to, thread locker and oil.

While performing the work, inspect steering gear (threads and body), fittings, hydraulic lines connected to the gear, and pitman arm for damage or leaks. Service and replace as necessary.

Refer to Reyco Granning Owner's Manual D710551 for additional detail.

Service Bulletins are intended for use by Professional Technicians only. They are written to guide Professional Technicians in performing service to vehicles of specific nature in conjunction with industry standards. Professional Technicians should be appropriately trained on industry standards and have the tools and equipment to perform procedures safely and properly.

Step By Step Instructions:

1. Raise the vehicle high enough to get the tires off the ground and safely support per industry standards.
2. Begin with the driver side steering gear and reference Figure 1. Remove the 7/8" bolt and flat washer attached to bottom of steering gear. Discard bolt and washer.
3. Clean the threaded hole in the steering gear.
4. Install new 7/8-14 x 2.00" bolt with 7/8" Nord-Lock® washer. Torque to 500 LB-FT +/- 25 LB-FT. Mark fastener to indicate it has been torqued.




Figure 1

5. Remove one of the two 3/4" bolts closest to the 7/8" bolt attached to bottom of steering gear mounting plate. Discard bolt and flat washer.
6. Clean the threaded hole.
7. Install new 3/4-16 x 1.50" bolt with 3/4" Nord-Lock® washer. Torque to 300 LB-FT +/- 10 LB-FT. Mark fastener to indicate it has been torqued.
8. Repeat steps 5 thru 7 for other 3/4" bolt nearest the 7/8" bolt.

Service Bulletins are intended for use by Professional Technicians only. They are written to guide Professional Technicians in performing service to vehicles of specific nature in conjunction with industry standards. Professional Technicians should be appropriately trained on industry standards and have the tools and equipment to perform procedures safely and properly.

Spartan RV Chassis

Recall Service Bulletin RSB21-260-001

9. Referencing Figure 2, remove one of the two $\frac{3}{4}$ " bolts attached to side of steering gear mounting plate. Discard bolt and flat washer.
10. Clean the threaded hole.
11. Install new $\frac{3}{4}$ -16 x 1.50" bolt with $\frac{3}{4}$ " Nord-Lock® washer. Torque to 300 LB-FT +/- 10 LB-FT. Mark fastener to indicate it has been torqued.
12. Repeat steps 9 thru 11 for other $\frac{3}{4}$ " bolt attached to side of steering gear mounting plate.




Figure 2

Note: Shallow socket and open end wrench required to remove bolt behind shock absorber.

13. Turn steering wheel or steering gear input shaft incrementally to rotate the pitman arm for access to the six bolts surrounding the steering gear output shaft. Reference Figure 3.

Service Bulletins are intended for use by Professional Technicians only. They are written to guide Professional Technicians in performing service to vehicles of specific nature in conjunction with industry standards. Professional Technicians should be appropriately trained on industry standards and have the tools and equipment to perform procedures safely and properly.

Spartan RV Chassis

Recall Service Bulletin
RSB21-260-001



Figure 3

14. Referencing Figure 4, remove one of the six $\frac{3}{4}$ " bolts surrounding the output shaft. Discard bolt and flat washer.




Figure 4

15. Clean the threaded hole in the steering gear.
16. Install new $\frac{3}{4}$ -16 x 2.00" bolt with $\frac{3}{4}$ " Nord-Lock® washer. Torque to 300 LB-FT +/- 10 LB-FT. Mark fastener to indicate it has been torqued.
17. Repeat steps 13 thru 16 for each of the remaining five $\frac{3}{4}$ " bolts surrounding the output shaft.

Service Bulletins are intended for use by Professional Technicians only. They are written to guide Professional Technicians in performing service to vehicles of specific nature in conjunction with industry standards. Professional Technicians should be appropriately trained on industry standards and have the tools and equipment to perform procedures safely and properly.

Spartan RV Chassis

Recall Service Bulletin RSB21-260-001

18. If suspension model is an IFS2000S3, repeat steps 3 thru 17 on the passenger side for the slave gear.
19. Document IFS serial number.
 - a. Serial number is listed on data tag located on front face of driver side air spring tower. Reference Figure 5 & Figure 6 for serial number location.



Figure 5




Figure 6

20. Check steering fluid level. Fill as necessary with AW-46 hydraulic oil.

Service Bulletins are intended for use by Professional Technicians only. They are written to guide Professional Technicians in performing service to vehicles of specific nature in conjunction with industry standards. Professional Technicians should be appropriately trained on industry standards and have the tools and equipment to perform procedures safely and properly.

Prod#	VIN Number	Year	Brand	Type	Floor	Chassis	Date In	Date Off
USA Units								
501694	4VZVU1E98LC088465	2020	LA	DP	4551	S	1/13/2020	1/20/2020
501705	4VZVU1E9XLC089018	2020	LA	DP	4569	S	3/16/2020	3/23/2020
501718	4VZVU1E98LC089017	2020	LA	DP	4551	S	3/12/2020	3/20/2020
501743	4VZVU1E96LC089016	2020	LA	DP	4579	S	3/3/2020	3/12/2020
501748	4VZVU1E98LC088482	2020	LA	DP	4533	S	1/22/2020	1/30/2020
501749	4VZVU1E91LC089019	2020	LA	DP	4551	S	3/20/2020	5/7/2020
501752	4VZVU1E9XLC088483	2020	LA	DP	4569	S	2/10/2020	2/17/2020
501753	4VZVU1E98LC088515	2020	LA	DP	4551	S	2/17/2020	2/25/2020
501755	4VZVU1E96LC088514	2020	LA	DP	4551	S	2/13/2020	2/24/2020
501756	4VZVU1E92LC089014	2020	LA	DP	4551	S	2/20/2020	2/28/2020
501757	4VZVU1E94LC089015	2020	LA	DP	4551	S	2/25/2020	3/3/2020
501759	4VZVU1E98LC089020	2020	LA	DP	4551	S	5/13/2020	5/20/2020
501761	4VZVU1E9XLC089021	2020	LA	DP	4535	S	5/15/2020	5/27/2020
501765	4VZVU1E98MC089259	2021	LA	DP	4579	S	8/3/2020	8/11/2020
501766	4VZVU1E99MC089321	2021	LA	DP	4551	S	8/26/2020	9/3/2020
501767	4VZVU1E9XMC089022	2021	LA	DP	4551	S	6/8/2020	6/17/2020
501768	4VZVU1E99MC089111	2021	LA	DP	4551	S	6/19/2020	7/15/2020
501769	4VZVU1E97MC089110	2021	LA	DP	4551	S	6/15/2020	6/24/2020
501770	4VZVU1E96MC089762	2021	LA	DP	4551	S	10/21/2020	10/29/2020
501771	4VZVU1E90MC089210	2021	LA	DP	4543	S	7/21/2020	7/29/2020
501772	4VZVU1E92MC089211	2021	LA	DP	4551	S	7/28/2020	8/5/2020
501773	4VZVU1E94MC089212	2021	LA	DP	4551	S	7/23/2020	7/31/2020
501774	4VZVU1E9XMC089280	2021	LA	DP	4551	S	8/17/2020	8/25/2020
501776	4VZVU1E90MC089319	2021	LA	DP	4551	S	8/19/2020	8/27/2020
501777	4VZVU1E93MC089783	2021	LA	DP	4551	S	11/30/2020	12/10/2020
501778	4VZVU1E93MC089279	2021	LA	DP	4543	S	8/12/2020	8/21/2020
501780	4VZVU1E91MC089782	2021	LA	DP	4551	S	11/5/2020	11/18/2020
501781	4VZVU1E9XMC089490	2021	LA	DP	4579	S	9/18/2020	9/29/2020
501783	4VZVU1E94MC089761	2021	LA	DP	4533	S	10/20/2020	10/28/2020
501785	4VZVU1E92MC089340	2021	LA	DP	4551	S	9/2/2020	9/11/2020
501786	4VZVU1E97MC089320	2021	LA	DP	4551	S	8/20/2020	8/28/2020
501787	4VZVU1E92MC089760	2021	LA	DP	4535	S	10/14/2020	10/22/2020
501788	4VZVU1E94MC089341	2021	LA	DP	4551	S	9/3/2020	9/14/2020
501789	4VZVU1E93MC089489	2021	LA	DP	4579	S	10/5/2020	10/13/2020
501790	4VZVU1E93MC089380	2021	LA	DP	4533	S	9/15/2020	9/24/2020
501791	4VZVU1E92MC089712	2021	LA	DP	4551	S	9/21/2020	9/30/2020
501799	4VZVU1E95MC089381	2021	LA	DP	4533	S	9/11/2020	9/21/2020
501803	4VZVU1E98MC089763	2021	LA	DP	4551	S	10/28/2020	11/9/2020
501813	4VZVU1E90NC089631	2022	LA	DP	4551	S	11/6/2020	11/19/2020
530620	4VZVU1E92LC088218	2020	KG	DB	4531	S	2/4/2020	2/12/2020
530624	4VZVU1E96LC088254	2020	KG	DB	4533	S	2/24/2020	3/2/2020
530626	4VZVU1E90LC089027	2020	KG	DB	4569	S	3/10/2020	3/18/2020
530630	4VZVU1E94LC089029	2020	KG	DB	4531	S	5/11/2020	5/18/2020
530631	4VZVU1E90LC089030	2020	KG	DB	4531	S	6/2/2020	6/10/2020
530632	4VZVU1E94MC089260	2021	KG	DB	4553	S	7/15/2020	7/23/2020
530634	4VZVU1E90MC089384	2021	KG	DB	4531	S	8/25/2020	9/2/2020
530637	4VZVU1E92MC089323	2021	KG	DB	4531	S	7/29/2020	8/6/2020
530638	4VZVU1E93MC089492	2021	KG	DB	4531	S	10/5/2020	10/13/2020
530639	4VZVU1E93MC089668	2021	KG	DB	4531	S	10/15/2020	10/23/2020
530641	4VZVU1E98MC089715	2021	KG	DB	4531	S	11/10/2020	12/1/2020

Prod#	VIN Number	Year	Brand	Type	Floor	Chassis	Date In	Date Off
530642	4VZVU1E9XMC089716	2021	KG	DB	4553	S	12/1/2020	12/10/2020
530643	4VZVU1E91MC089491	2021	KG	DB	4531	S	9/10/2020	9/18/2020
530645	4VZVU1E93MC089766	2021	KG	DB	4531	S	12/7/2020	12/15/2020
530646	4VZVU1E91MC089670	2021	KG	DB	4531	S	10/29/2020	11/9/2020
530655	4VZVU1E98NC089635	2022	KG	DB	4531	S	12/17/2020	1/12/2021
530658	4VZVU1E9XNC089636	2022	KG	DB	4533	S	1/28/2021	2/5/2021
608408	4VZAU1D97LC088408	2020	DS	DP	4081	S	1/20/2020	1/29/2020
608409	4VZAU1D9XLC088371	2020	DS	DP	4081	S	1/15/2020	1/22/2020
608410	4VZAU1D96LC088965	2020	DS	DP	4081	S	3/12/2020	3/19/2020
608425	4VZAU1D98LC088434	2020	DS	DP	4369	S	1/21/2020	1/29/2020
608428	4VZAU1D97LC088988	2020	DS	DP	4369	S	5/18/2020	5/28/2020
608431	4VZAU1D90LC088511	2020	DS	DP	4369	S	2/20/2020	3/2/2020
608432	4VZAU1D92LC088977	2020	DS	DP	4369	S	3/5/2020	3/16/2020
608435	4VZAU1D95LC088410	2020	DS	DP	4369	S	1/15/2020	1/23/2020
608436	4VZAU1D94LC088432	2020	DS	DP	4369	S	1/16/2020	1/23/2020
608458	4VZAU1D99LC088409	2020	DS	DP	4369	S	1/7/2020	1/15/2020
608462	4VZAU1D95LC088987	2020	DS	DP	4328	S	5/15/2020	5/28/2020
608469	4VZAU1D91LC088372	2020	DS	DP	4081	S	1/17/2020	1/27/2020
608671	4VZAU1D92LC088509	2020	DS	DP	4369	S	2/18/2020	2/27/2020
608788	4VZAU1D99LC088460	2020	DS	DP	4326	S	2/4/2020	2/12/2020
608791	4VZAU1D93LC088535	2020	DS	DP	4081	S	2/24/2020	3/3/2020
608792	4VZAU1D91LC088355	2020	DS	DP	4081	S	1/13/2020	1/20/2020
608805	4VZAU1D90LC088508	2020	DS	DP	4369	S	2/13/2020	2/20/2020
608811	4VZAU1D95LC088990	2020	DS	DP	4369	S	6/1/2020	6/9/2020
608814	4VZAU1D96LC088433	2020	DS	DP	4369	S	1/17/2020	1/28/2020
608820	4VZAU1D92LC088431	2020	DS	DP	4081	S	1/22/2020	1/31/2020
608821	4VZAU1D94LC088978	2020	DS	DP	4369	S	3/18/2020	5/4/2020
608825	4VZAU1D97LC088991	2020	DS	DP	4362	S	6/2/2020	6/10/2020
608827	4VZAU1D9XLC088435	2020	DS	DP	4369	S	1/23/2020	1/31/2020
608828	4VZAU1D91LC088503	2020	DS	DP	4081	S	2/19/2020	2/27/2020
608833	4VZAU1D90LC088461	2020	DS	DP	4326	S	2/4/2020	2/13/2020
608838	4VZAU1D99LC088510	2020	DS	DP	4369	S	2/19/2020	2/28/2020
608843	4VZAU1D94LC088480	2020	DS	DP	4081	S	2/5/2020	2/14/2020
608845	4VZAU1D92LC088459	2020	DS	DP	4081	S	1/31/2020	2/10/2020
608846	4VZAU1D90LC088458	2020	DS	DP	4054	S	2/3/2020	2/11/2020
608848	4VZAU1D95LC088438	2020	DS	DP	4369	S	2/3/2020	2/11/2020
608851	4VZAU1D91LC088436	2020	DS	DP	4369	S	1/23/2020	2/3/2020
608856	4VZAU1D99LC088975	2020	DS	DP	4369	S	3/2/2020	3/11/2020
608859	4VZAU1D9XLC088502	2020	DS	DP	4081	S	2/6/2020	2/14/2020
608861	4VZAU1D93LC088504	2020	DS	DP	4369	S	2/10/2020	2/18/2020
608862	4VZAU1D97LC088506	2020	DS	DP	4363	S	2/11/2020	2/19/2020
608863	4VZAU1D99LC088507	2020	DS	DP	4369	S	2/12/2020	2/19/2020
608881	4VZAU1D99LC088538	2020	DS	DP	4369	S	2/26/2020	3/5/2020
608886	4VZAU1D90LC088976	2020	DS	DP	4369	S	3/3/2020	3/12/2020
608887	4VZAU1D94LC088964	2020	DS	DP	4081	S	3/9/2020	3/17/2020
608898	4VZAU1D93LC088986	2020	DS	DP	4369	S	5/14/2020	5/27/2020
608899	4VZAU1D98LC088983	2020	DS	DP	4369	S	5/5/2020	5/12/2020
608900	4VZAU1D96LC088979	2020	DS	DP	4369	S	3/19/2020	5/6/2020
608901	4VZAU1D98LC088966	2020	DS	DP	4081	S	3/19/2020	5/5/2020
608907	4VZAU1D94LC088981	2020	DS	DP	4369	S	3/20/2020	5/7/2020
608908	4VZAU1D92LC088980	2020	DS	DP	4369	S	3/20/2020	5/6/2020

Prod#	VIN Number	Year	Brand	Type	Floor	Chassis	Date In	Date Off
608909	4VZAU1D99LC088989	2020	DS	DP	4369	S	5/26/2020	6/3/2020
608911	4VZAU1D9XLC088984	2020	DS	DP	4310	S	5/8/2020	5/18/2020
608913	4VZAU1D96LC088982	2020	DS	DP	4328	S	3/24/2020	5/11/2020
608923	4VZAU1D91LC088971	2020	DS	DP	4081	S	5/20/2020	6/2/2020
608924	4VZAU1D91LC088985	2020	DS	DP	4369	S	5/13/2020	5/26/2020
608925	4VZAU1D9XLC088970	2020	DS	DP	4081	S	5/12/2020	5/20/2020
608930	4VZAU1D93LC088969	2020	DS	DP	4081	S	5/12/2020	5/20/2020
608933	4VZAU1D91LC088968	2020	DS	DP	4054	S	5/6/2020	5/14/2020
608939	4VZAU1D91MC089622	2021	DS	DP	4363	S	9/23/2020	10/5/2020
608946	4VZAU1D95MC088974	2021	DS	DP	4081	S	6/9/2020	6/18/2020
608949	4VZAU1D92MC088995	2021	DS	DP	4369	S	6/8/2020	6/17/2020
608950	4VZAU1D90MC088994	2021	DS	DP	4369	S	6/8/2020	6/17/2020
608952	4VZAU1D93MC088973	2021	DS	DP	4020	S	6/5/2020	6/16/2020
608958	4VZAU1D95MC089199	2021	DS	DP	4369	S	7/30/2020	8/7/2020
608968	4VZAU1D9XMC088999	2021	DS	DP	4369	S	6/22/2020	7/16/2020
608970	4VZAU1D91MC088972	2021	DS	DP	4081	S	6/4/2020	6/15/2020
608971	4VZAU1D94MC089565	2021	DS	DP	4369	S	9/10/2020	9/18/2020
608980	4VZAU1D98MC088998	2021	DS	DP	4328	S	6/15/2020	6/24/2020
608981	4VZAU1D93MC089850	2021	DS	DP	4369	S	10/26/2020	11/4/2020
608982	4VZAU1D99MC088993	2021	DS	DP	4369	S	6/4/2020	6/15/2020
608985	4VZAU1D96MC088997	2021	DS	DP	4369	S	6/12/2020	6/23/2020
608987	4VZAU1D94MC088996	2021	DS	DP	4369	S	6/12/2020	6/23/2020
608992	4VZAU1D93MC089332	2021	DS	DP	4369	S	8/19/2020	8/27/2020
608997	4VZAU1D94MC089372	2021	DS	DP	4369	S	8/27/2020	9/4/2020
608998	4VZAU1D96MC089485	2021	DS	DP	4369	S	9/10/2020	9/18/2020
609001	4VZAU1D9XMC089103	2021	DS	DP	4369	S	7/20/2020	7/28/2020
609004	4VZAU1D90MC089000	2021	DS	DP	4369	S	6/24/2020	7/17/2020
609005	4VZAU1D92MC089001	2021	DS	DP	4328	S	6/25/2020	7/20/2020
609011	4VZAU1D98MC089102	2021	DS	DP	4328	S	7/17/2020	7/27/2020
609012	4VZAU1D91MC089104	2021	DS	DP	4369	S	7/22/2020	7/30/2020
609016	4VZAU1D93MC089198	2021	DS	DP	4362	S	7/30/2020	8/7/2020
609018	4VZAU1D91MC089197	2021	DS	DP	4328	S	7/29/2020	8/6/2020
609021	4VZAU1D90MC089272	2021	DS	DP	4326	S	8/5/2020	8/13/2020
609023	4VZAU1D96MC089311	2021	DS	DP	4369	S	8/10/2020	8/20/2020
609025	4VZAU1D9XMC089196	2021	DS	DP	4369	S	7/29/2020	8/6/2020
609027	4VZAU1D98MC089312	2021	DS	DP	4369	S	8/12/2020	8/24/2020
609028	4VZAU1D96MC089373	2021	DS	DP	4369	S	8/31/2020	9/9/2020
609038	4VZAU1D92MC089256	2021	DS	DP	4326	S	8/4/2020	8/12/2020
609042	4VZAU1D9XMC089201	2021	DS	DP	4369	S	8/5/2020	8/12/2020
609045	4VZAU1D91MC089202	2021	DS	DP	4369	S	8/3/2020	8/12/2020
609046	4VZAU1D94MC089274	2021	DS	DP	4362	S	8/10/2020	8/19/2020
609047	4VZAU1D98MC089200	2021	DS	DP	4328	S	8/3/2020	8/11/2020
609051	4VZAU1D98MC089620	2021	DS	DP	4369	S	9/16/2020	9/28/2020
609075	4VZAU1D99MC089853	2021	DS	DP	4369	S	10/29/2020	11/9/2020
609077	4VZAU1D91MC089331	2021	DS	DP	4369	S	8/11/2020	8/20/2020
609079	4VZAU1D95MC089834	2021	DS	DP	4369	S	10/26/2020	11/4/2020
609083	4VZAU1D98MC089911	2021	DS	DP	4369	S	11/17/2020	12/7/2020
609091	4VZAU1D91MC089832	2021	DS	DP	4369	S	10/23/2020	11/3/2020
609101	4VZAU1D94MC089484	2021	DS	DP	4310	S	9/9/2020	9/17/2020
609104	4VZAU1D95MC089333	2021	DS	DP	4310	S	8/20/2020	8/28/2020
609105	4VZAU1D9XMC089621	2021	DS	DP	4369	S	9/23/2020	10/5/2020

Prod#	VIN Number	Year	Brand	Type	Floor	Chassis	Date In	Date Off
609106	4VZAU1D94MC089663	2021	DS	DP	4369	S	10/1/2020	10/12/2020
609109	4VZAU1D9XMC089912	2021	DS	DP	4369	S	12/10/2020	1/4/2021
609115	4VZAU1D92MC089371	2021	DS	DP	4369	S	8/26/2020	9/3/2020
609116	4VZAU1D90MC089854	2021	DS	DP	4369	S	11/3/2020	11/12/2020
609117	4VZAU1D97MC089852	2021	DS	DP	4369	S	11/2/2020	11/10/2020
609118	4VZAU1D96MC089907	2021	DS	DP	4369	S	11/9/2020	11/30/2020
609120	4VZAU1D94MC089906	2021	DS	DP	4369	S	11/9/2020	11/30/2020
609121	4VZAU1D97MC089933	2021	DS	DP	4369	S	11/30/2020	12/9/2020
609144	4VZAU1D92MC089483	2021	DS	DP	4310	S	9/8/2020	9/16/2020
609151	4VZAU1D98MC089374	2021	DS	DP	4369	S	9/4/2020	9/16/2020
609225	4VZAU1D93MC089914	2021	DS	DP	4369	S	12/7/2020	12/15/2020
609232	4VZAU1D93MC089623	2021	DS	DP	4326	S	9/29/2020	10/8/2020
609233	4VZAU1D92MC089662	2021	DS	DP	4310	S	9/29/2020	10/8/2020
609239	4VZAU1D92MC089774	2021	DS	DP	4369	S	10/16/2020	10/26/2020
609240	4VZAU1D99MC089772	2021	DS	DP	4369	S	10/7/2020	10/15/2020
609241	4VZAU1D96MC089910	2021	DS	DP	4369	S	11/16/2020	12/3/2020
609242	4VZAU1D98MC089830	2021	DS	DP	4369	S	10/23/2020	11/3/2020
609243	4VZAU1D9XMC089831	2021	DS	DP	4369	S	10/22/2020	11/2/2020
609244	4VZAU1D9XMC089909	2021	DS	DP	4369	S	11/12/2020	12/2/2020
609245	4VZAU1D92MC089905	2021	DS	DP	4369	S	11/6/2020	11/18/2020
609246	4VZAU1D91MC089829	2021	DS	DP	4369	S	10/22/2020	11/2/2020
609247	4VZAU1D97MC089849	2021	DS	DP	4369	S	10/29/2020	11/9/2020
609248	4VZAU1D93MC089833	2021	DS	DP	4369	S	10/28/2020	11/6/2020
609253	4VZAU1D99MC089934	2021	DS	DP	4369	S	12/1/2020	12/10/2020
609254	4VZAU1D9XMC089828	2021	DS	DP	4369	S	10/22/2020	11/2/2020
609256	4VZAU1D96MC089566	2021	DS	DP	4369	S	9/11/2020	9/22/2020
609259	4VZAU1D90MC089773	2021	DS	DP	4369	S	10/14/2020	10/22/2020
609263	4VZAU1D94MC089775	2021	DS	DP	4369	S	10/13/2020	10/21/2020
609264	4VZAU1D98MC089908	2021	DS	DP	4310	S	11/12/2020	12/2/2020
609268	4VZAU1D90MC089708	2021	DS	DP	4369	S	10/7/2020	10/15/2020
609269	4VZAU1D98MC089827	2021	DS	DP	4369	S	10/21/2020	10/29/2020
609280	4VZAU1D99MC089707	2021	DS	DP	4369	S	10/6/2020	10/14/2020
609285	4VZAU1D90MC089661	2021	DS	DP	4369	S	9/24/2020	10/6/2020
609286	4VZAU1D97MC089706	2021	DS	DP	4369	S	10/6/2020	10/14/2020
609289	4VZAU1D98MC089486	2021	DS	DP	4310	S	9/18/2020	9/29/2020
609297	4VZAU1D96MC089826	2021	DS	DP	4369	S	10/21/2020	10/29/2020
609309	4VZAU1D92MC089855	2021	DS	DP	4326	S	11/5/2020	11/17/2020
609310	4VZAU1D91MC089913	2021	DS	DP	4369	S	12/1/2020	12/10/2020
609312	4VZAU1D94MC089825	2021	DS	DP	4363	S	10/20/2020	10/28/2020
609319	4VZAU1D96MC089776	2021	DS	DP	4369	S	10/19/2020	10/27/2020
609328	4VZAU1D92MC089709	2021	DS	DP	4311	S	11/5/2020	11/16/2020
609358	4VZAU1D92MC089936	2021	DS	DP	4369	S	12/11/2020	1/5/2021
609429	4VZAU1D90MC089935	2021	DS	DP	4369	S	12/9/2020	12/16/2020
609465	4VZAU1D92NC089646	2022	DS	DP	4369	S	11/12/2020	12/1/2020
801396	4VZVU1E93LC089023	2020	EX	DP	4551	S	3/4/2020	3/13/2020
801398	4VZVU1E95LC089024	2020	EX	DP	4543	S	3/17/2020	3/24/2020
801400	4VZVU1E97LC089025	2020	EX	DP	4543	S	5/26/2020	6/3/2020
801401	4VZVU1E96MC089213	2021	EX	DP	4551	S	6/17/2020	7/13/2020
801402	4VZVU1E97MC089026	2021	EX	DP	4551	S	6/12/2020	6/23/2020
801403	4VZVU1E91MC089281	2021	EX	DP	4551	S	7/16/2020	7/24/2020
801406	4VZVU1E98MC089567	2021	EX	DP	4569	S	8/20/2020	8/31/2020

Prod#	VIN Number	Year	Brand	Type	Floor	Chassis	Date In	Date Off
801408	4VZVU1E90MC089322	2021	EX	DP	4551	S	7/24/2020	8/3/2020
801409	4VZVU1E97MC089382	2021	EX	DP	4551	S	8/13/2020	8/24/2020
801411	4VZVU1E96MC089342	2021	EX	DP	4551	S	8/4/2020	8/12/2020
801413	4VZVU1E99MC089383	2021	EX	DP	4551	S	8/7/2020	8/19/2020
801414	4VZVU1E91MC089667	2021	EX	DP	4551	S	9/17/2020	9/28/2020
801415	4VZVU1E98MC089665	2021	EX	DP	4551	S	8/31/2020	9/9/2020
801416	4VZVU1E94MC089713	2021	EX	DP	4551	S	9/30/2020	10/9/2020
801417	4VZVU1E96MC089714	2021	EX	DP	4551	S	10/8/2020	10/16/2020
801423	4VZVU1E9XMC089764	2021	EX	DP	4533	S	10/13/2020	10/21/2020
801424	4VZVU1E91MC089765	2021	EX	DP	4551	S	10/23/2020	11/3/2020
801425	4VZVU1E90MC089837	2021	EX	DP	4551	S	10/27/2020	11/5/2020
801441	4VZVU1E94NC089633	2022	EX	DP	4551	S	2/1/2021	2/9/2021
904778	4VZVU1E95LC088164	2020	MA	DP	4551	S	1/31/2020	2/10/2020
904779	4VZVU1E91LC089005	2020	MA	DP	4551	S	2/28/2020	3/9/2020
904794	4VZVU1E91LC088579	2020	MA	DP	4551	S	2/19/2020	2/27/2020
904817	4VZVU1E96LC088481	2020	MA	DP	4579	S	2/11/2020	2/18/2020
904818	4VZVU1E96LC089002	2020	MA	DP	4018	S	2/26/2020	3/4/2020
904822	4VZVU1E95LC088374	2020	MA	DP	4551	S	2/5/2020	2/13/2020
904823	4VZVU1E99LC089009	2020	MA	DP	4551	S	5/6/2020	5/13/2020
904824	4VZVU1E95LC089010	2020	MA	DP	4533	S	5/7/2020	5/15/2020
904827	4VZVU1E97LC089008	2020	MA	DP	4535	S	3/13/2020	3/20/2020
904828	4VZVU1E99LC089012	2020	MA	DP	4551	S	6/3/2020	6/10/2020
904829	4VZVU1E95LC089007	2020	MA	DP	4569	S	3/11/2020	3/19/2020
904830	4VZVU1E93LC089006	2020	MA	DP	4551	S	3/9/2020	3/17/2020
904833	4VZVU1E97LC089011	2020	MA	DP	4543	S	5/18/2020	5/29/2020
904834	4VZVU1E90MC089207	2021	MA	DP	4551	S	7/30/2020	8/10/2020
904835	4VZVU1E95MC089316	2021	MA	DP	4118	S	6/10/2020	6/19/2020
904836	4VZVU1E96MC089258	2021	MA	DP	4102	S	6/4/2020	6/15/2020
904837	4VZVU1E90LC089013	2021	MA	DP	4551	S	6/16/2020	6/25/2020
904840	4VZVU1E99MC089108	2021	MA	DP	4551	S	6/23/2020	7/17/2020
904841	4VZVU1E92MC089208	2021	MA	DP	4551	S	8/6/2020	8/17/2020
904842	4VZVU1E90MC089109	2021	MA	DP	4551	S	8/6/2020	8/18/2020
904843	4VZVU1E92MC089337	2021	MA	DP	4551	S	10/9/2020	10/19/2020
904845	4VZVU1E92MC089757	2021	MA	DP	4118	S	9/23/2020	10/5/2020
904846	4VZVU1E94MC089338	2021	MA	DP	4543	S	10/26/2020	11/4/2020
904847	4VZVU1E97MC089379	2021	MA	DP	4551	S	12/3/2020	12/14/2020
904848	4VZVU1E96MC089664	2021	MA	DP	4118	S	9/2/2020	9/11/2020
904850	4VZVU1E97MC089317	2021	MA	DP	4118	S	8/24/2020	9/1/2020
904851	4VZVU1E91MC089488	2021	MA	DP	4118	S	8/28/2020	9/8/2020
904852	4VZVU1E98MC089861	2021	MA	DP	4551	S	2/24/2021	3/8/2021
904853	4VZVU1E9XMC089277	2021	MA	DP	4533	S	9/28/2020	10/7/2020
904854	4VZVU1E96MC089549	2021	MA	DP	4118	S	9/4/2020	9/15/2020
904858	4VZVU1E94MC089209	2021	MA	DP	4535	S	9/9/2020	9/17/2020
904859	4VZVU1E94MC089758	2021	MA	DP	4118	S	10/15/2020	10/23/2020
904861	4VZVU1E95MC089378	2021	MA	DP	4551	S	11/16/2020	12/3/2020
904863	4VZVU1E96MC089759	2021	MA	DP	4118	S	10/28/2020	11/6/2020
904865	4VZVU1E99MC089318	2021	MA	DP	4551	S	10/7/2020	10/14/2020
904866	4VZVU1E98MC089777	2021	MA	DP	4118	S	11/4/2020	11/13/2020
904867	4VZVU1E96MC089339	2021	MA	DP	4533	S	11/3/2020	11/12/2020
904887	4VZVU1E94NC089650	2022	MA	DP	4543	S	12/11/2020	1/5/2021

Prod#	VIN Number	Year	Brand	Type	Floor	Chassis	Date In	Date Off
-------	------------	------	-------	------	-------	---------	---------	----------

Canadian Units

530622	4VZVU1E92LC089028	2020	KG	DB	4553	S	5/4/2020	5/12/2020
530625	4VZVU1E94LC088253	2020	KG	DB	4553	S	2/12/2020	2/19/2020
530636	4VZVU1E95MC089669	2021	KG	DB	4531	S	10/16/2020	10/26/2020
609052	4VZAU1D9XMC089313	2021	DS	DP	4369	S	8/12/2020	8/24/2020
609251	4VZAU1D95MC089851	2021	DS	DP	4369	S	10/27/2020	11/5/2020
801397	4VZVU1E90LC088377	2020	EX	DP	4533	S	2/18/2020	2/26/2020
801404	4VZVU1E9XMC089666	2021	EX	DP	4569	S	9/8/2020	9/16/2020
904838	4VZVU1E90MC089515	2021	MA	DP	4118	S	8/27/2020	9/4/2020
904839	4VZVU1E91MC089278	2021	MA	DP	4551	S	9/30/2020	10/9/2020