

Newmar Corporation

PO Box 30
Nappanee, IN 46550



WHEN YOU KNOW THE DIFFERENCE.

RSB 565
May 7, 2021

NHTSA #21V 182
TC #2021-159

RECALL SERVICE BULLETIN

AFFECTED MODELS

2021 :: Ventana, Dutch Star, New Aire

DESCRIPTION

Daimler Trucks North America has decided that a defect relating to motor vehicle safety exists in specific motorhomes built on Freightliner chassis (NHTSA #21V 108). In response, Newmar Corporation is issuing recall NHTSA # 21V 182 and TC # 2021-159.

ISSUE

On certain motorhomes, chassis are equipped with an adjustable brake pedal assembly that may not be equipped with a return spring. In some situations, the brake pedal may not return properly. This may leave the brake signal activated and brake lights illuminated. Additionally, in certain towed vehicles, the service brakes may also remain engaged. If the brake lights remain illuminated after the brake pedal is released, an additional service brake application will not cause the brake lights to illuminate and would not signal to other motorists the intent of the driver to slow the vehicle, potentially leading to an increased risk of a crash. In addition, if the brake activation signal to a towed device remains active when the motorhome chassis service brakes are released, the brakes on a towed device may potentially remain engaged depending on brake configuration of what is being towed. A towed device with incorrectly operating brakes could increase the risk of a crash.

UNITS AFFECTED

Refer to the attached population list for specific VIN numbers supplied by DTNA for the coaches that may be affected.

CORRECTIVE ACTION

Repairs will be performed by Daimler Trucks North America authorized service facilities. DTNA will provide work instructions and any necessary parts to complete the recall procedure.

CUSTOMER ACTION

Contact Daimler Trucks North America at 1-800-547-0712 to locate a Qualified Service Center near you. If you need further assistance, contact the Newmar service department at 1-800-731- 8300. A brand specialist will assist you in scheduling an appointment to have this repair completed.

DEALER ACTION

Contact the Freightliner Customer Support Center at 1-800-FTL-HELP (1-800-385-4357), and follow the prompts, or visit <https://freightliner.com/dealer-search/> to locate an authorized DTNA service center to schedule and perform the recall near you. If you need assistance contacting DTNA, contact your Newmar Service Account Manager.

NOTE

Newmar will not be authorizing this repair. DTNA will authorize and schedule this repair.

IMPORTANT: Please read this bulletin in its entirety prior to beginning any diagnosis or repairs.

NOTICE: Any technical information published in this bulletin is intended for use only by a qualified, Newmar-authorized service technician. Newmar is not responsible for the misuse of this information.



WHEN YOU KNOW THE DIFFERENCE

NEWMAR CORPORATION

NEWMARCORP.COM

Date: May 4, 2021
Re: Newmar Corporation – Motor Vehicle Recall Notification

Subject: Recall Campaign No.: 21V-182

This notice is sent to you as a Newmar Dealer in accordance with the requirements of the National Traffic and Motor Vehicle Safety Act. Newmar Corporation has decided that a defect, which relates to motor vehicle safety, exists in specific Newmar recreational vehicles.

The National Traffic and Motor Vehicle Safety Act requires that each vehicle, which is subject to a recall campaign of this type, must be satisfactorily repaired within a reasonable time after the owner has tendered it for repair. A failure to adequately repair within 60 days after tender of a vehicle is prima facie evidence of failure to repair within a reasonable time. To avoid providing these problematic solutions, every effort must be made to promptly schedule an appointment with each owner and to repair their vehicle as soon as possible. Vehicle owners are being notified of this recall. If the condition is not remedied within a reasonable time, they are instructed on how to contact the National Highway Traffic Safety Administration.

REASON FOR THIS RECALL

Newmar Corporation has decided that a defect, which relates to motor vehicle safety, exists in specific motorhomes built on Freightliner chassis. This recall is the result of information provided to us by Daimler Trucks North America LLC. DTNA recall number is #21V-108.

On certain motorhomes, chassis are equipped with an adjustable brake pedal assembly that may not be equipped with a return spring. In some situations, the brake pedal may not promptly return to the return position leaving the brake signal activated and brake lights to stay illuminated. Additionally, in certain towed vehicles, the service brakes may also stay engaged. If the brakes lights stay illuminated after the brake pedal is released, an additional service brake application will not cause the brake lights to illuminate and would not signal to other motorists the intent of the driver to slow the vehicle, potentially leading to an increased risk of a crash. In addition, if the brake activation signal to a towed device remains active when the motorhome chassis service brakes are released, the brakes on a towed device may potentially remain engaged depending on brake configuration of the trailer. A towed device with incorrectly operating brakes could increase the risk of a crash.

The motorhomes require immediate service. Continued use poses a potential safety hazard.

DEALER CAMPAIGN RESPONSIBILITY

Dealers are to provide to all customers/owner vehicles the service of completing this campaign at no charge to the customer/owner regardless of vehicle age, vehicle mileage, or ownership at the time of repair.

REPAIR PROCEDURE

DTNA will provide the work instructions.

If you should have any questions please contact your service account manager direct or the Newmar service department at: 1-866-290-5371.

Thank you for your cooperation.

Sincerely,

Newmar Corporation



WHEN YOU KNOW THE DIFFERENCE

NEWMAR CORPORATION

NEWMARCORP.COM

IMPORTANT SAFETY RECALL

This notice applies to your vehicle VIN. # _____

Name

Address

City, State Zip code

Date: May 4, 2021

Motor Vehicle Recall Notification - Recall Campaign No. 21V-182

Dear Valued Customer:

This notice is sent to you in accordance with the requirements of the National Traffic and Motor Vehicle Safety Act.

REASON FOR THIS RECALL

Newmar Corporation has decided that a defect, which relates to motor vehicle safety, exists in specific motorhomes built on Freightliner chassis. This recall is the result of information provided to us by Daimler Trucks North America LLC. DTNA recall number is #21V-108.

On certain motorhomes, chassis are equipped with an adjustable brake pedal assembly that may not be equipped with a return spring. In some situations, the brake pedal may not promptly return to the return position leaving the brake signal activated and brake lights to stay illuminated. Additionally, in certain towed vehicles, the service brakes may also stay engaged. If the brakes lights stay illuminated after the brake pedal is released, an additional service brake application will not cause the brake lights to illuminate and would not signal to other motorists the intent of the driver to slow the vehicle, potentially leading to an increased risk of a crash. In addition, if the brake activation signal to a towed device remains active when the motorhome chassis service brakes are released, the brakes on a towed device may potentially remain engaged depending on brake configuration of the trailer. A towed device with incorrectly operating brakes could increase the risk of a crash.

The motorhomes require immediate service. Continued use poses a potential safety hazard.

The Safety Risk

The brake pedal may not promptly return to the return position leaving the brake signal activated and brake lights to stay illuminated. If the brakes lights stay illuminated after the brake pedal is released, an additional service brake application will not cause the brake lights to illuminate and would not signal to other motorists the intent of the driver to slow the vehicle, potentially leading to an increased risk of a crash. In addition, if the brake activation signal to a towed device remains active when the motorhome chassis service brakes are released, the brakes on a towed device may potentially remain engaged depending on brake configuration of the trailer. A towed device with incorrectly operating brakes could increase the risk of a crash.

WHAT WE WILL DO

DTNA will provide owners of all affected motorhomes a remedy for the potential defect at no charge for parts or labor. DTNA will inspect the affected assemblies and install a return spring as needed. Estimated time for repair is 0.1-1.1 hrs.

WHAT YOU NEED TO DO

As this defect does affect motor vehicle safety, it is recommended that you call Daimler Trucks North America @ **800-547-0712** to locate a Qualified Service Center near you. If you need further assistance contact the Newmar service department immediately at 1-800-731-8300. An associate will assist you in making an appointment to have this repair completed.

Federal regulations require that any vehicle lessor receiving this recall notification must forward a copy of this notice to the lessee within ten days.

If you have had the repair performed before receiving this letter, you may be eligible to receive reimbursement for the cost of obtaining a pre-notification remedy. For additional information contact Newmar Corporation at:

Service Department
Newmar Corporation
355 N Delaware St
Nappanee, IN 46550-0030

An Authorized Chassis Service Facility, are best equipped to obtain parts and provide service to ensure your vehicle is corrected as promptly as possible. HOWEVER, if you take your vehicle to your Authorized Chassis Service Facility on the scheduled date and this condition is not remedied on that date or within five days; please contact the Newmar Corporation Customer Service Department at 1-800-731-8300. You may also submit a complaint to the Administrator, National Highway Traffic Safety Administration, 1200 New Jersey Ave., SE., Washington DC 20590; or call the toll-free Vehicle Safety Hotline at 1-888-327-4236 (TTY: 1-800-424-9153); or go to <http://www.safercar.gov>.

If you no longer own this vehicle, please furnish us the complete name and address of the person or dealership you sold or traded your vehicle to. Thank you for your cooperation.

Your safety and satisfaction with your Newmar product is important to us and we regret any inconvenience to you.

Sincerely,

Newmar Corporation



WHEN YOU KNOW THE DIFFERENCE

NEWMAR CORPORATION

NEWMARCORP.COM

Date: May 4, 2021
Re: Newmar Corporation – Motor Vehicle Recall Notification

Subject: Recall Campaign No.: 2021-159

This notice is sent to you as a Newmar Dealer in accordance with the requirements of the *Canada Motor Vehicle Safety Act*. Newmar Corporation has decided that a defect, which relates to motor vehicle safety, exists in specific Newmar recreational vehicles.

Each vehicle, which is subject to a recall campaign of this type, must be satisfactorily repaired within a reasonable time after the owner has tendered it for repair. A failure to adequately repair within 60 days after tender of a vehicle is prima facie evidence of failure to repair within a reasonable time. To avoid providing these problematic solutions, every effort must be made to promptly schedule an appointment with each owner and to repair their vehicle as soon as possible. Vehicle owners are being notified of this recall. If the condition is not remedied within a reasonable time, they are instructed to contact Transport Canada.

REASON FOR THIS RECALL

Newmar Corporation has decided that a defect, which relates to motor vehicle safety, exists in specific motorhomes built on Freightliner chassis. This recall is the result of information provided to us by Daimler Trucks North America LLC.

Issue:

On certain motorhomes, the brake pedal may not be equipped with a return spring. As a result, the pedal may not fully return when it is released. If this happens, the brake lights may stay on. If a trailer is connected to the motorhome, this could also cause the trailer brakes to remain on.

Safety Risk:

Brake lights that stay on could cause other road users not to recognize when the vehicle is braking. This could increase the risk of a crash. Trailers brakes that do not release could also increase the risk of a crash.

Corrective Actions:

Newmar will notify owners by mail and instruct you to take your motorhome to a Daimler Trucks North America (DTNA) authorized service facility to inspect the adjustable brake pedal assembly and install the missing return spring, if necessary.

The motorhomes require immediate service. Continued use poses a potential safety hazard.

DEALER CAMPAIGN RESPONSIBILITY

Dealers are to provide to all customers/owner vehicles the service of completing this campaign at no charge to the customer/owner regardless of vehicle age, vehicle mileage, or ownership at the time of repair.

REPAIR PROCEDURE

DTNA will provide the work instructions. DTNA will provide owners of all affected motorhomes a remedy for the potential defect at no charge for parts or labor. DTNA will inspect the affected assemblies and install a return spring as needed. Estimated time for repair is 0.1-1.1 hrs.

If you should have any questions please contact your service account manager direct or the Newmar service department at: 1-866-290-5371.

Thank you for your cooperation.

Sincerely,

Newmar Corporation



WHEN YOU KNOW THE DIFFERENCE

NEWMAR CORPORATION

NEWMARCORP.COM

Nº VIN
marque, modèle et année du modèle
Nom
Adresse
Ville, province et code postal

Date : 4 mai 2021

Avis de rappel de véhicule automobile : campagne de rappel nº 2021-159

Cher client :

Le présent avis vous est envoyé conformément aux exigences de la *Loi sur la sécurité automobile*.

Le présent avis vous est envoyé conformément aux exigences de la *Loi sur la sécurité automobile*.

La présente a pour but de vous informer que votre véhicule est susceptible d'avoir un défaut qui pourrait porter atteinte à la sécurité humaine.

RAISON DE CE RAPPEL

Newmar Corporation a déterminé que certaines autocaravanes construites sur un châssis Freightliner présentaient un défaut lié à la sécurité. Ce rappel fait suite à des informations fournies par Daimler Trucks North America LLC. Numéro de rappel DTNA : #21V-108.

Problème :

Sur certaines autocaravanes, la pédale de frein peut ne pas être munie d'un ressort de retour. Par conséquent, il se peut que la pédale ne revienne pas complètement à sa position initiale lorsqu'elle est relâchée. Si cela se produit, il se peut que les feux de freinage restent allumés. Si une remorque est fixée à l'autocaravane, cela peut également entraîner le maintien des freins de la remorque.

Risque pour la sécurité :

Des feux de freinage qui restent allumés peuvent empêcher les autres usagers de la route de reconnaître que le véhicule devant eux freine. Cela peut augmenter le risque d'accident. Les freins de la remorque qui ne se relâchent pas peuvent également augmenter le risque d'accident.

Mesures correctives :

Newmar avisera les propriétaires par la poste et les invitera à présenter leur autocaravane dans un centre de service agréé de Daimler Trucks North America (DTNA) afin que l'assemblage de la pédale de frein ajustable soit inspecté et que le ressort de retour manquant soit installé, au besoin.

Les autocaravanes nécessitent une inspection immédiate. Continuer à utiliser ces véhicules sans les faire contrôler constitue un risque potentiel pour la sécurité.

CE QUE NOUS FERONS

DTNA fournira aux propriétaires de toutes les autocaravanes concernées une solution pour le défaut potentiel, sans frais de pièces ou de main-d'œuvre. DTNA inspectera les assemblages concernés et installera, au besoin, un ressort de retour. Le temps estimé pour la réparation se situe entre 10 minutes et 1 h 10.

CE QUE VOUS DEVEZ FAIRE

Étant donné que ce défaut est lié à la sécurité automobile, il est recommandé d'appeler Daimler Trucks North America en composant le **1 800 547-0712** pour trouver un centre de réparations certifié dans votre région. Pour toute aide supplémentaire, communiquez immédiatement avec le service technique de Newmar en composant le 1 800 731-8300. Un représentant vous aidera à fixer un rendez-vous afin de faire effectuer cette réparation.

Les réglementations fédérales exigent que tout loueur de véhicule recevant cet avis de rappel en transmette une copie au locataire dans un délai de dix jours.

Si la réparation a été effectuée avant la réception de cette lettre, vous pourriez avoir droit à un remboursement du coût d'un remède avant la notification. Pour de plus amples renseignements, veuillez communiquer avec Newmar Corporation :

Service technique
Newmar Corporation
355 N Delaware St
Nappanee, IN 46550-0030

Un centre certifié d'entretien de châssis est le mieux équipé pour obtenir des pièces et effectuer la réparation afin que votre véhicule soit réparé le plus rapidement possible. TOUTEFOIS, si vous apportez votre véhicule à votre centre certifié d'entretien de châssis à la date prévue et que la réparation n'est pas effectuée à cette date ou dans un délai de cinq jours, veuillez communiquer avec le service à la clientèle de Newmar Corporation en composant le 1 800 731-8300.

Si vous n'êtes plus propriétaire de ce véhicule, veuillez nous fournir le nom et l'adresse de la personne ou du concessionnaire à qui vous avez vendu ou échangé le véhicule. Nous vous remercions de votre coopération.

Votre sécurité et votre satisfaction à l'égard des produits Newmar sont importantes pour nous. Nous vous prions de nous excuser pour tous désagréments que cette situation a pu vous causer.

Cordialement,

Newmar Corporation



WHEN YOU KNOW THE DIFFERENCE

NEWMAR CORPORATION

NEWMARCORP.COM

VIN#
make, model, model year
Name
Address
City, State Zip code

Date: May 4, 2021
Motor Vehicle Recall Notification - Recall Campaign No. 2021-159

Dear Valued Customer:

This notice is sent to you in accordance with the requirements of the *Canada Motor Vehicle Safety Act*.

This is to inform you that your vehicle may contain a defect that could affect the safety of a person.

REASON FOR THIS RECALL

Newmar Corporation has decided that a defect, which relates to motor vehicle safety, exists in specific motorhomes built on Freightliner chassis. This recall is the result of information provided to us by Daimler Trucks North America LLC. DTNA recall number is #21V-108.

Issue:

On certain motorhomes, the brake pedal may not be equipped with a return spring. As a result, the pedal may not fully return when it is released. If this happens, the brake lights may stay on. If a trailer is connected to the motorhome, this could also cause the trailer brakes to remain on.

Safety Risk:

Brake lights that stay on could cause other road users not to recognize when the vehicle is braking. This could increase the risk of a crash. Trailers brakes that do not release could also increase the risk of a crash.

Corrective Actions:

Newmar will notify owners by mail and instruct you to take your motorhome to a Daimler Trucks North America (DTNA) authorized service facility to inspect the adjustable brake pedal assembly and install the missing return spring, if necessary.

The motorhomes require immediate service. Continued use poses a potential safety hazard.

WHAT WE WILL DO

DTNA will provide owners of all affected motorhomes a remedy for the potential defect at no charge for parts or labor. DTNA will inspect the affected assemblies and install a return spring as needed. Estimated time for repair is 0.1-1.1 hrs.

WHAT YOU NEED TO DO

As this defect does affect motor vehicle safety, it is recommended that you call Daimler Trucks North America @ **800-547-0712** to locate a Qualified Service Center near you. If you need further assistance contact the Newmar Service Department immediately at 1-800-731-8300. An associate will assist you in making an appointment to have this repair completed.

Federal regulations require that any vehicle lessor receiving this recall notification must forward a copy of this notice to the lessee within ten days.

If you have had the repair performed before receiving this letter, you may be eligible to receive reimbursement for the cost of obtaining a pre-notification remedy. For additional information contact Newmar Corporation at:

Service Department
Newmar Corporation
355 N Delaware St
Nappanee, IN 46550-0030

An Authorized Chassis Service Facility, are best equipped to obtain parts and provide service to ensure your vehicle is corrected as promptly as possible. HOWEVER, if you take your vehicle to your Authorized Chassis Service Facility on the scheduled date and this condition is not remedied on that date or within five days; please contact the Newmar Corporation Customer Service Department at 1-800-731-8300.

If you no longer own this vehicle, please furnish us the complete name and address of the person or dealership you sold or traded your vehicle to. Thank you for your cooperation.

Your safety and satisfaction with your Newmar product is important to us and we regret any inconvenience to you.

Sincerely,

Newmar Corporation

Production # VIN Number	Model	Brand	Type	Floor	Chassis	Date In	Date Off
USA Units							
415087	4UZACHFC1MCMR4462	2021	VT	DP	3426 FL	10/19/2020	10/27/2020
415089	4UZACHFC1MCMP4812	2021	VT	DP	3717 FL	8/24/2020	9/1/2020
415093	4UZFCHFE5MCMP2312	2021	VT	DP	4002 FL	8/31/2020	9/10/2020
415100	4UZACHFCXMCMP0693	2021	VT	DP	3407 FL	7/30/2020	8/7/2020
415105	4UZFCHFE3MCMR4471	2021	VT	DP	4369 FL	10/1/2020	10/12/2020
415119	4UZFCHFE8MCMP4815	2021	VT	DP	4037 FL	9/1/2020	9/10/2020
415120	4UZACHFC1MCMR7698	2021	VT	DP	3709 FL	9/24/2020	10/6/2020
415122	4UZFCHFE7MCMP2313	2021	VT	DP	4369 FL	9/15/2020	9/23/2020
415125	4UZFCHFE0MCMR7702	2021	VT	DP	4326 FL	10/1/2020	10/12/2020
415131	4UZACHFC8MCMP4810	2021	VT	DP	3717 FL	8/17/2020	8/26/2020
415133	4UZACHFC0MCMR4467	2021	VT	DP	3709 FL	9/23/2020	10/5/2020
415145	4UZACHFC1MCMR0928	2021	VT	DP	3407 FL	7/31/2020	8/10/2020
415150	4UZFCHFE8MCMR3204	2021	VT	DP	4326 FL	9/30/2020	10/9/2020
415154	4UZACHFC0MCMP2310	2021	VT	DP	3407 FL	7/27/2020	8/4/2020
415155	4UZACHFC1MCMP0694	2021	VT	DP	3709 FL	8/7/2020	8/18/2020
415158	4UZFCHFE2MCMN6858	2021	VT	DP	4369 FL	8/12/2020	8/21/2020
415159	4UZFCHFE3MCMP2311	2021	VT	DP	4037 FL	8/11/2020	8/21/2020
415160	4UZFCHFE2MCMN1000	2021	VT	DP	4369 FL	8/11/2020	8/20/2020
415162	4UZFCHFE5MCMS4499	2021	VT	DP	4037 FL	12/8/2020	12/16/2020
415163	4UZACHFC3MCMR4463	2021	VT	DP	3412 FL	9/23/2020	10/5/2020
415166	4UZACHFCXMCMP4811	2021	VT	DP	3709 FL	8/19/2020	8/27/2020
415169	4UZACHFC3MCMR0929	2021	VT	DP	3407 FL	8/13/2020	8/24/2020
415177	4UZACHFC1MCMT2415	2021	VT	DP	3426 FL	11/9/2020	11/30/2020
415196	4UZFCHFE9MCMP2314	2021	VT	DP	4369 FL	9/10/2020	9/18/2020
415197	4UZFCHFE4MCMN1001	2021	VT	DP	4369 FL	9/15/2020	9/23/2020
415202	4UZFCHFE8MCMT2497	2021	VT	DP	4369 FL	10/29/2020	11/9/2020
415210	4UZACHFC4MCMR3189	2021	VT	DP	3407 FL	9/10/2020	9/18/2020
415213	4UZFCHFE6MCMP4814	2021	VT	DP	4037 FL	8/13/2020	8/24/2020
415214	4UZFCHFE4MCMP0695	2021	VT	DP	4329 FL	9/8/2020	9/16/2020
415216	4UZACHFC7MCMR4465	2021	VT	DP	3709 FL	9/21/2020	9/30/2020
415217	4UZFCHFE6MCMT2496	2021	VT	DP	4369 FL	10/16/2020	10/26/2020
415221	4UZACHFC3MCMT2416	2021	VT	DP	3412 FL	12/3/2020	12/14/2020
415226	4UZFCHFE4MCMN6859	2021	VT	DP	4326 FL	9/4/2020	9/15/2020
415230	4UZFCHFE0MCMN6857	2021	VT	DP	4369 FL	9/3/2020	9/14/2020
415235	4UZFCHFE2MCMT2494	2021	VT	DP	4037 FL	1/7/2021	1/15/2021
415241	4UZFCHFE0MCMT2493	2021	VT	DP	4037 FL	12/16/2020	1/11/2021
415252	4UZFCHFE4MCMT2495	2021	VT	DP	4037 FL	12/2/2020	12/11/2020
415256	4UZACHFC2MCMR4468	2021	VT	DP	3709 FL	10/27/2020	11/5/2020
415257	4UZACHFC3MCMR0932	2021	VT	DP	3407 FL	9/18/2020	9/29/2020
415258	4UZACHFC9MCMR4466	2021	VT	DP	3709 FL	9/15/2020	9/23/2020
415262	4UZFCHFE1MCMR4470	2021	VT	DP	4037 FL	9/28/2020	10/7/2020
415263	4UZFCHFEXMCMR2958	2021	VT	DP	4369 FL	9/18/2020	9/29/2020
415266	4UZFCHFEXMCMT2498	2021	VT	DP	4369 FL	10/27/2020	11/5/2020
415267	4UZFCHFE5MCMR4469	2021	VT	DP	4037 FL	9/28/2020	10/7/2020
415272	4UZACHFC5MCMR4464	2021	VT	DP	3407 FL	9/24/2020	10/6/2020
415281	4UZACHFCXMCMP0930	2021	VT	DP	3412 FL	9/3/2020	9/14/2020
415285	4UZFCHFE4MCMR7699	2021	VT	DP	4037 FL	10/6/2020	10/14/2020
415286	4UZACHFC1MCMS2211	2021	VT	DP	3709 FL	11/16/2020	12/2/2020
415287	4UZACHFC1MCMR0931	2021	VT	DP	3412 FL	9/14/2020	9/22/2020
415288	4UZACHFC7MCMT2418	2021	VT	DP	3709 FL	2/10/2021	2/18/2021

Production # VIN Number	Model	Brand	Type	Floor	Chassis	Date In	Date Off
415308 4UZFCHE9MCMR7701	2021	VT	DP		4369 FL	10/5/2020	10/13/2020
415313 4UZACHFC5MCMT2417	2021	VT	DP		3709 FL	2/9/2021	2/17/2021
415345 4UZFCHE7MCMR7700	2021	VT	DP		4037 FL	11/12/2020	12/1/2020
415367 4UZACHFC2MCMS4498	2021	VT	DP		3717 FL	1/26/2021	2/3/2021
415386 4UZACHFCXMCMS2210	2021	VT	DP		3709 FL	11/5/2020	11/17/2020
415395 4UZFCHE9MCMT2492	2021	VT	DP		4037 FL	1/20/2021	1/28/2021
415420 4UZACHFC0MCMS4497	2021	VT	DP		3717 FL	1/18/2021	1/26/2021
608951 4UZACHFE8MCMP2315	2021	DS	DP		3717 FL	8/27/2020	9/4/2020
608954 4UZFCHE1MCMR7739	2021	DS	DP		4363 FL	9/17/2020	9/28/2020
608961 4UZFCHE3MCMP0705	2021	DS	DP		4369 FL	7/23/2020	7/31/2020
608975 4UZFCHE6MCMR4478	2021	DS	DP		4369 FL	9/1/2020	9/10/2020
609000 4UZFCHE1MCMS2216	2021	DS	DP		4369 FL	10/7/2020	10/15/2020
609020 4UZFCHE5MCMP4822	2021	DS	DP		4326 FL	8/17/2020	8/26/2020
609024 4UZFCHE1MCMP4820	2021	DS	DP		4369 FL	8/18/2020	8/26/2020
609026 4UZFCHE7MCMP4823	2021	DS	DP		4369 FL	9/1/2020	9/10/2020
609033 4UZFCHE4MCMP0700	2021	DS	DP		4081 FL	8/5/2020	8/13/2020
609035 4UZACHFE9MCMP4817	2021	DS	DP		3717 FL	8/17/2020	8/25/2020
609039 4UZFCHE7MCMP0707	2021	DS	DP		4369 FL	7/27/2020	8/4/2020
609041 4UZACHFE9MCMT2499	2021	DS	DP		3736 FL	10/19/2020	10/27/2020
609049 4UZFCHE4MCMP2320	2021	DS	DP		4369 FL	8/20/2020	8/28/2020
609050 4UZFCHE6MCMP0701	2021	DS	DP		4081 FL	8/12/2020	8/21/2020
609055 4UZACHFE0MCMR3207	2021	DS	DP		3736 FL	8/31/2020	9/9/2020
609056 4UZFCHE5MCMR4472	2021	DS	DP		4081 FL	9/16/2020	9/24/2020
609058 4UZFCHE6MCMP2321	2021	DS	DP		4369 FL	8/12/2020	8/21/2020
609060 4UZFCHE5MCMS2221	2021	DS	DP		4369 FL	10/5/2020	10/13/2020
609064 4UZFCHE4MCMR4480	2021	DS	DP		4369 FL	9/8/2020	9/17/2020
609065 4UZFCHE5MCMS2218	2021	DS	DP		4369 FL	10/1/2020	10/12/2020
609072 4UZFCHE8MCMP2319	2021	DS	DP		4369 FL	8/7/2020	8/19/2020
609073 4UZFCHE4MCMR7735	2021	DS	DP		4081 FL	10/9/2020	10/16/2020
609078 4UZFCHE5MCMP0706	2021	DS	DP		4369 FL	8/11/2020	8/21/2020
609084 4UZFCHE2MCMP2316	2021	DS	DP		4020 FL	8/7/2020	8/18/2020
609092 4UZFCHE4MCMS2226	2021	DS	DP		4369 FL	10/16/2020	10/26/2020
609099 4UZFCHE3MCMP4821	2021	DS	DP		4369 FL	8/31/2020	9/9/2020
609100 4UZFCHE6MCMR4481	2021	DS	DP		4369 FL	9/10/2020	9/21/2020
609112 4UZACHFE3MCMS2213	2021	DS	DP		3717 FL	10/14/2020	10/22/2020
609113 4UZACHFE1MCMR7704	2021	DS	DP		3717 FL	9/2/2020	9/11/2020
609127 4UZFCHE7MCMS4505	2021	DS	DP		4369 FL	11/9/2020	11/19/2020
609128 4UZFCHE4MCMP2317	2021	DS	DP		4081 FL	8/18/2020	8/27/2020
609129 4UZACHFE3MCMR7705	2021	DS	DP		3736 FL	9/9/2020	9/17/2020
609140 4UZFCHEXMCMR7741	2021	DS	DP		4369 FL	9/14/2020	9/22/2020
609142 4UZFCHE6MCMR7736	2021	DS	DP		4081 FL	10/9/2020	10/19/2020
609146 4UZACHFE9MCMR3206	2021	DS	DP		3709 FL	8/27/2020	9/8/2020
609148 4UZACHFE7MCMP0698	2021	DS	DP		3717 FL	8/24/2020	9/1/2020
609149 4UZFCHE9MCMP4824	2021	DS	DP		4362 FL	9/2/2020	9/11/2020
609150 4UZFCHE8MCMS4500	2021	DS	DP		4369 FL	10/9/2020	10/19/2020
609156 4UZFCHE3MCMS4503	2021	DS	DP		4369 FL	10/12/2020	10/20/2020
609157 4UZFCHE8MCMS2214	2021	DS	DP		4081 FL	10/8/2020	10/15/2020
609183 4UZFCHE5MCMP4819	2021	DS	DP		4081 FL	9/1/2020	9/11/2020
609184 4UZFCHE0MCMR4475	2021	DS	DP		4081 FL	9/17/2020	9/28/2020
609185 4UZFCHE2MCMR4476	2021	DS	DP		4081 FL	9/30/2020	10/9/2020
609201 4UZFCHEXMCMS2215	2021	DS	DP		4369 FL	9/29/2020	10/8/2020

Production #	VIN Number	Model	Brand	Type	Floor	Chassis	Date In	Date Off
609207	4UZFCHE3MCMP4818	2021	DS	DP	4081	FL	9/3/2020	9/14/2020
609208	4UZACHFE1MCMS2212	2021	DS	DP	3717	FL	9/29/2020	10/8/2020
609213	4UZFCHE8MCMR4482	2021	DS	DP	4369	FL	9/11/2020	9/21/2020
609235	4UZFCHE7MCMS2219	2021	DS	DP	4310	FL	10/8/2020	10/16/2020
609237	4UZFCHE9MCMS2223	2021	DS	DP	4369	FL	10/8/2020	10/16/2020
609238	4UZFCHE2MCMS2225	2021	DS	DP	4369	FL	10/15/2020	10/23/2020
609249	4UZFCHE7MCMS2222	2021	DS	DP	4369	FL	10/9/2020	10/19/2020
609255	4UZFCHE7MCMR4473	2021	DS	DP	4081	FL	9/14/2020	9/22/2020
609257	4UZFCHEXMCMP4483	2021	DS	DP	4369	FL	9/11/2020	9/21/2020
609260	4UZFCHE9MCMR4474	2021	DS	DP	4081	FL	9/21/2020	9/30/2020
609262	4UZFCHE8MCMR4479	2021	DS	DP	4326	FL	9/2/2020	9/14/2020
609274	4UZFCHE5MCMS4504	2021	DS	DP	4362	FL	11/6/2020	11/18/2020
609278	4UZFCHE3MCMS2217	2021	DS	DP	4310	FL	9/28/2020	10/7/2020
609283	4UZFCHE8MCMR7740	2021	DS	DP	4369	FL	9/18/2020	9/29/2020
609284	4UZFCHEXMCMS4501	2021	DS	DP	4369	FL	10/12/2020	10/20/2020
609296	4UZFCHE3MCMS2220	2021	DS	DP	4310	FL	10/5/2020	10/13/2020
609326	4UZFCHE0MCMS2224	2021	DS	DP	4369	FL	11/5/2020	11/17/2020
609350	4UZFCHE0MCMS4507	2021	DS	DP	4369	FL	11/4/2020	11/16/2020
609454	4UZFCHE9MCMS4506	2021	DS	DP	4328	FL	11/12/2020	12/1/2020
710869	4UZACEFE2MCMP2325	2021	NA	DP	3543	FL	9/1/2020	9/10/2020
710892	4UZACEFE5MCMP0715	2021	NA	DP	3545	FL	9/10/2020	9/18/2020
710904	4UZACEFE3MCMP4827	2021	NA	DP	3545	FL	9/23/2020	10/5/2020
710906	4UZACEFE9MCMP2323	2021	NA	DP	3543	FL	8/24/2020	9/1/2020
710912	4UZACEFE0MCMR4484	2021	NA	DP	3543	FL	10/12/2020	10/20/2020
710913	4UZACEFE7MCMP0716	2021	NA	DP	3543	FL	8/13/2020	8/25/2020
710917	4UZACEFE4MCMS5913	2021	NA	DP	3543	FL	10/22/2020	11/2/2020
710927	4UZACEFEXMCMP4825	2021	NA	DP	3543	FL	9/9/2020	9/18/2020
710929	4UZACEFE6MCMR3209	2021	NA	DP	3543	FL	10/5/2020	10/13/2020
710933	4UZACEFE0MCMP2324	2021	NA	DP	3545	FL	9/9/2020	9/17/2020
710940	4UZACEFE4MCMT2506	2021	NA	DP	3545	FL	11/6/2020	11/18/2020
710948	4UZACEFE2MCMR4485	2021	NA	DP	3545	FL	10/27/2020	11/6/2020
710967	4UZACEFE9MCMP0717	2021	NA	DP	3543	FL	9/3/2020	9/15/2020
710969	4UZACEFE4MCMP2326	2021	NA	DP	3543	FL	9/16/2020	9/24/2020
710974	4UZACEFE1MCMP4826	2021	NA	DP	3545	FL	9/15/2020	9/23/2020
710975	4UZACEFE4MCMR3208	2021	NA	DP	3541	FL	9/21/2020	9/30/2020
710979	4UZACEFE5MCMP4828	2021	NA	DP	3543	FL	9/28/2020	10/7/2020
710990	4UZACEFE2MCMR3210	2021	NA	DP	3543	FL	10/13/2020	10/21/2020
710991	4UZACEFE0MCMS5911	2021	NA	DP	3541	FL	10/20/2020	10/28/2020
711012	4UZACEFC5MCMP0714	2021	NA	DP	3343	FL	3/9/2021	3/17/2021
711073	4UZACEFC7MCMS2227	2021	NA	DP	3341	FL	3/29/2021	4/8/2021

Canadian Units

415110	4UZACHFC3MCMP4813	2021	VT	DP	3717	FL	8/27/2020	9/4/2020
415194	4UZACHFC5MCMR3203	2021	VT	DP	3717	FL	9/8/2020	9/16/2020
415195	4UZFCHEXMCMP4816	2021	VT	DP	4037	FL	9/17/2020	9/28/2020
608966	4UZFCHE6MCMP2318	2021	DS	DP	4081	FL	8/28/2020	9/8/2020
608967	4UZFCHE1MCMS4502	2021	DS	DP	4363	FL	11/10/2020	11/30/2020
609178	4UZFCHE4MCMR4477	2021	DS	DP	4081	FL	10/1/2020	10/12/2020
609279	4UZFCHE1MCMR7742	2021	DS	DP	4369	FL	9/18/2020	9/29/2020
710921	4UZACEFE2MCMS5912	2021	NA	DP	3543	FL	10/19/2020	10/27/2020