

Newmar Corporation

PO Box 30
Nappanee, IN 46550



WHEN YOU KNOW THE DIFFERENCE.

RSB 578
June 17, 2022

TC #2022-078

RECALL SERVICE BULLETIN

AFFECTED MODELS

2020 – 2022 :: Mountain Aire

DESCRIPTION

Due to notification from Spartan (NHTSA# 21V 969); Newmar Corporation has decided that a defect, which relates to motor vehicle safety, exists in specific motorhomes built on Spartan Chassis.

ISSUE

On certain motorhomes, the fuel tubes between the fuel rail and the injectors may crack and create a fuel leak. Please note this recall only affects motorhomes equipped with a Cummins X12 diesel engine.

UNITS AFFECTED

Please refer to the attached population which contains numbers and VINS supplied by Spartan for affected units. The attached list contains both USA and Canadian unit numbers.

CORRECTIVE ACTION

Please contact your local Cummins Distributor or authorized warranty dealer. You may also contact Cummins Care at 1-800- CUMMINS (1-800-286-6467) or visit their website at care.cummins.com. For additional assistance, you may call Spartan RV Chassis Customer Product and Support at 1-800-543-5277.

FLAT RATE CODE: 2022-078 (No time to be authorized, for Newmar tracking only)

DEALER ACTION

If you need assistance, contact your Newmar Service Account Manager.

NOTE

Newmar will not authorize this repair it will be handled through Spartan/Cummins at an authorized facility.

IMPORTANT: Please read this bulletin in its entirety prior to beginning any diagnosis or repairs.

NOTICE: Any technical information published in this bulletin is intended for use only by a qualified, Newmar-authorized service technician. Newmar is not responsible for the misuse of this information.



WHEN YOU KNOW THE DIFFERENCE

NEWMAR CORPORATION

NEWMARCORP.COM

Date: 6/14/2022

Re: Newmar Corporation – Motor Vehicle Recall Notification

Subject: Recall Campaign No.: #2022-078

This notice is sent to you as a Newmar Dealer in accordance with the requirements of the *Canada Motor Vehicle Safety Act*. Newmar Corporation has decided that a defect, which relates to motor vehicle safety, exists in specific Newmar recreational vehicles.

Each vehicle, which is subject to a recall campaign of this type, must be satisfactorily repaired within a reasonable time after the owner has tendered it for repair. A failure to adequately repair within 60 days after tender of a vehicle is prima facie evidence of failure to repair within a reasonable time. To avoid providing these problematic solutions, every effort must be made to promptly schedule an appointment with each owner and to repair their vehicle as soon as possible. Vehicle owners are being notified of this recall. If the condition is not remedied within a reasonable time, they are instructed to contact Transport Canada.

REASON FOR THIS RECALL

Newmar Corporation has decided that a defect, which relates to motor vehicle safety, exists in specific motorhomes built on Spartan Chassis.

Issue:

On certain motorhomes, the fuel tubes between the fuel rail and the injectors may crack and create a fuel leak. Please note this recall only affects motorhomes equipped with a Cummins X12 diesel engine.

Safety Risk:

A fuel leak can create the risk of a fire.

Corrective Actions:

Cummins will notify owners by mail and instruct you to take your motorhome to a Cummins authorized service center. On vehicles with 120km or less, Cummins will add vibrations isolators to fuel tubes. On vehicles with more than 120km, Cummins will also replace the fuel tubes for cylinders 4,5 and 6(the rear half of the engine)

This recall applies to certain Newmar 2020, 2021, 2022 Mountain Aire Class A Motorhomes.

The motorhomes require immediate service. Continued use poses a potential safety hazard.

DEALER CAMPAIGN RESPONSIBILITY

Dealers are to provide to all customers/owner vehicles the service of completing this campaign at no charge to the customer/owner regardless of vehicle age, vehicle mileage, or ownership at the time of repair.

REPAIR PROCEDURE

Cummins will provide the work instructions.

If you should have any questions please contact your service account manager direct or the Newmar service department at: 1-866-290-5371.

Thank you for your cooperation.

Sincerely,

Newmar Corporation



WHEN YOU KNOW THE DIFFERENCE

NEWMAR CORPORATION

NEWMARCORP.COM

VIN#
make, model, model year
Name
Address
City, State Zip code

Date: 6/14/2022
Motor Vehicle Recall Notification - Recall Campaign No. 2022-078

Dear Valued Customer:

This notice is sent to you in accordance with the requirements of the *Canada Motor Vehicle Safety Act*.

This is to inform you that your vehicle may contain a defect that could affect the safety of a person.

REASON FOR THIS RECALL

Newmar Corporation has decided that a defect, which relates to motor vehicle safety, exists in specific motorhome built on Spartan Chassis.

Issue:

On certain motorhomes, the fuel tubes between the fuel rail and the injectors may crack and create a fuel leak. Please note this recall only affects motorhomes equipped with a Cummins X12 diesel engine.

Safety Risk:

A fuel leak can create the risk of a fire.

Corrective Actions:

Cummins will notify owners by mail and instruct you to take your motorhome to a Cummins authorized service center. On vehicles with 120km or less, Cummins will add vibrations isolators to fuel tubes. On vehicles with more than 120km, Cummins will also replace the fuel tubes for cylinders 4,5 and 6(the rear half of the engine)

The motorhomes require immediate service. Continued use poses a potential safety hazard.

WHAT WE WILL DO

Cummins will provide owners of all affected motorhomes a remedy for the potential defect at no charge for parts or labor. For Engines having 75 miles or less, Cummins will add vibration isolators to the fuel tubes, fuel tubes will not have to be replaced. For Engines with more than 75 miles, the subject fuel tubes for cylinders 4,5 and 6 (the rear half of the engine) will be replaced with new fuel tubes and vibration isolators will be added to fuel tubes to engines. Cummins will notify owner at time of contact for service an estimated time for repairs. However, due to scheduling times the service provider may need the vehicle longer.

WHAT YOU NEED TO DO

As this defect does affect motor vehicle safety, it is recommended that you call Cummins Care at 1-800-286-6467 to locate a Qualified Service Center near you. If you need further assistance, contact the Newmar service department immediately at 1-800-731-8300. An associate will assist you in making an appointment to have this repair completed.

Federal regulations require that any vehicle lessor receiving this recall notification must forward a copy of this notice to the lessee within ten days.

If you have had the repair performed before receiving this letter, you may be eligible to receive reimbursement for the cost of obtaining a pre-notification remedy. For additional information, contact Newmar Corporation at:

Service Department
Newmar Corporation
355 N Delaware St
Nappanee, IN 46550-0030

Authorized Service Facilities, are best equipped to obtain parts and provide service to ensure your vehicle is corrected as promptly as possible. HOWEVER, if you take your vehicle to your Authorized Service Facility on the scheduled date and this condition is not remedied on that date or within five days; please contact the Newmar Corporation Customer Service Department at 1-800-731-8300.

If you no longer own this vehicle, please furnish us the complete name and address of the person or dealership you sold or traded your vehicle to. Thank you for your cooperation.

Your safety and satisfaction with your Newmar product is important to us and we regret any inconvenience to you.

Sincerely,

Newmar Corporation



WHEN YOU KNOW THE DIFFERENCE

NEWMAR CORPORATION

NEWMARCORP.COM

NIV
marque, modèle, année du modèle
Nom
Adresse
Ville, État Code postal

Date : 2022-06-14

Avis de rappel de véhicules motorisés – Campagne de rappel no 2022-078

Cher client,

Le présent avis vous est envoyé conformément aux exigences de la Loi sur la sécurité automobile du Canada.

La présente a pour but de vous informer que votre véhicule est susceptible de présenter un défaut qui pourrait porter atteinte à la sécurité des personnes.

RAISON DE CE RAPPEL

Newmar Corporation a déterminé qu'un défaut lié à la sécurité des véhicules à moteur existe pour certains véhicules récréatifs construits avec des châssis Spartan.

Problème :

Sur certains véhicules récréatifs, les tubes de carburant entre la rampe d'injection et les injecteurs pourraient se fissurer et créer une fuite de carburant. Veuillez noter que ce rappel ne concerne que les véhicules récréatifs équipés d'un moteur diesel Cummins X12.

Risque pour la sécurité :

Une fuite de carburant peut créer un risque d'incendie.

Mesures correctives :

Cummins informera les propriétaires par courrier et vous demandera d'apporter votre véhicule dans un centre de service agréé Cummins. Sur les véhicules de 120 km ou moins, Cummins ajoutera des isolateurs de vibrations aux tubes de carburant. Sur les véhicules de plus de 120 km, Cummins remplacera également les tubes de carburant des cylindres 4, 5 et 6 (la moitié arrière du moteur)

Les véhicules récréatifs doivent être réparés immédiatement. Une utilisation continue présente un risque potentiel pour la sécurité.

CE QUE NOUS FERONS

Cummins offrira aux propriétaires de tous les véhicules récréatifs concernés une correction du défaut potentiel, sans frais pour les pièces ou la main-d'œuvre. Pour les moteurs ayant 75 miles ou moins, Cummins ajoutera des isolateurs de vibrations aux tubes de carburant, les tubes de carburant n'auront pas à être remplacés. Pour les moteurs de plus de 75 miles, les tubes de carburant concernés pour les cylindres 4, 5 et 6 (la moitié arrière du moteur) seront remplacés par de nouveaux tubes de carburant et des isolateurs de vibrations seront ajoutés aux tubes de carburant des moteurs. Cummins informera le propriétaire au moment de la rencontre des réparations et du temps estimé. Toutefois, en raison des horaires, le fournisseur de services peut avoir besoin du véhicule plus longtemps.

CE QUE VOUS DEVEZ FAIRE

Comme ce défaut affecte la sécurité des véhicules à moteur, il est recommandé d'appeler Cummins Care au 1 800 286-6467 pour localiser un centre de service qualifié près de chez vous. Si vous avez besoin d'une assistance supplémentaire, contactez immédiatement le service après-vente Newmar au 1 800 731-8300. Un agent vous aidera à prendre rendez-vous afin de procéder à cette réparation.

Les réglementations fédérales exigent que tout propriétaire de véhicule recevant cette notification de rappel doit transmettre une copie de cette notification au locataire dans les dix jours.

Si vous avez fait effectuer la réparation avant de recevoir cette lettre, vous pourriez être admissible au remboursement des frais de réparation. Pour plus d'informations, communiquez avec Newmar Corporation à l'adresse suivante :

Service à la clientèle
Newmar Corporation
355 N Delaware St
Nappanee, IN 46550-0030

Les centres de service agréés sont les mieux équipés pour obtenir des pièces et fournir des services pour que votre véhicule soit réparé le plus rapidement possible. CEPENDANT, si vous apportez votre véhicule à votre centre de service agréé à la date prévue et que le problème n'est pas corrigé à cette date ou dans les cinq jours; contactez le service après-vente de Newmar Corporation au 1-800-731-8300.

Si vous ne possédez plus ce véhicule, fournissez le nom complet et l'adresse de la personne ou du concessionnaire à qui vous avez vendu ou avec qui vous avez échangé votre véhicule. Nous vous remercions de votre collaboration.

Votre sécurité et votre satisfaction sont importantes pour nous et nous sommes désolés de tout inconfort auquel vous pourriez être confronté.

Cordialement,

Newmar Corporation

Prod#	VIN Number	Year	Brand	Type	Floor	Chassis	Date In	Date Off
USA Units								
904749	4VZVU1E98LC085534	2020	MA	DP	4551	S	1/25/2019	2/5/2019
904752	4VZVU1E98LC086330	2020	MA	DP	4002	S	2/7/2019	2/15/2019
904763	4VZVU1E96LC087170	2020	MA	DP	4551	S	5/20/2019	5/29/2019
904765	4VZVU1E9XLC087544	2020	MA	DP	4543	S	5/31/2019	6/7/2019
904767	4VZVU1E97LC087873	2020	MA	DP	4018	S	9/5/2019	9/12/2019
904771	4VZVU1E94LC088463	2020	MA	DP	4018	S	1/21/2020	1/29/2020
904774	4VZVU1E92LC087814	2020	MA	DP	4543	S	8/21/2019	8/28/2019
904775	4VZVU1E90LC087813	2020	MA	DP	4018	S	8/26/2019	9/4/2019
904778	4VZVU1E95LC088164	2020	MA	DP	4551	S	1/31/2020	2/10/2020
904779	4VZVU1E91LC089005	2020	MA	DP	4551	S	2/28/2020	3/9/2020
904780	4VZVU1E90LC087584	2020	MA	DP	4018	S	7/12/2019	7/19/2019
904786	4VZVU1E97LC087727	2020	MA	DP	4551	S	8/29/2019	9/9/2019
904788	4VZVU1E97LC087811	2020	MA	DP	4018	S	8/9/2019	8/16/2019
904790	4VZVU1E96LC088111	2020	MA	DP	4018	S	10/3/2019	10/10/2019
904791	4VZVU1E99LC087874	2020	MA	DP	4018	S	10/1/2019	10/8/2019
904793	4VZVU1E98LC087686	2020	MA	DP	4543	S	7/19/2019	7/26/2019
904794	4VZVU1E91LC088579	2020	MA	DP	4551	S	2/19/2020	2/27/2020
904795	4VZVU1E9XLC087642	2020	MA	DP	4551	S	6/20/2019	6/27/2019
904796	4VZVU1E91LC088162	2020	MA	DP	4543	S	11/27/2019	12/9/2019
904797	4VZVU1E97LC087923	2020	MA	DP	4551	S	9/9/2019	9/17/2019
904799	4VZVU1E94LC087653	2020	MA	DP	4002	S	8/2/2019	8/9/2019
904801	4VZVU1E95LC087726	2020	MA	DP	4543	S	7/24/2019	7/31/2019
904806	4VZVU1E96LC088013	2020	MA	DP	4535	S	10/17/2019	10/24/2019
904808	4VZVU1E9XLC087995	2020	MA	DP	4535	S	10/15/2019	10/22/2019
904809	4VZVU1E99LC087812	2020	MA	DP	4018	S	9/24/2019	10/3/2019
904812	4VZVU1E9XLC088144	2020	MA	DP	4551	S	11/15/2019	11/25/2019
904813	4VZVU1E93LC088163	2020	MA	DP	4543	S	1/15/2020	1/22/2020
904815	4VZVU1E90MC088123	2021	MA	DP	4543	S	12/18/2019	1/10/2020
904816	4VZVU1E99LC088216	2020	MA	DP	4002	S	1/8/2020	1/16/2020
904817	4VZVU1E96LC088481	2020	MA	DP	4579	S	2/11/2020	2/18/2020
904818	4VZVU1E96LC089002	2020	MA	DP	4018	S	2/26/2020	3/4/2020
904820	4VZVU1E98MC088130	2021	MA	DP	4118	S	1/28/2020	2/4/2020
904822	4VZVU1E95LC088374	2020	MA	DP	4551	S	2/5/2020	2/13/2020
904823	4VZVU1E99LC089009	2020	MA	DP	4551	S	5/6/2020	5/13/2020
904824	4VZVU1E95LC089010	2020	MA	DP	4533	S	5/7/2020	5/15/2020
904827	4VZVU1E97LC089008	2020	MA	DP	4535	S	3/13/2020	3/20/2020
904828	4VZVU1E99LC089012	2020	MA	DP	4551	S	6/3/2020	6/10/2020
904829	4VZVU1E95LC089007	2020	MA	DP	4569	S	3/11/2020	3/19/2020
904830	4VZVU1E93LC089006	2020	MA	DP	4551	S	3/9/2020	3/17/2020
904833	4VZVU1E97LC089011	2020	MA	DP	4543	S	5/18/2020	5/29/2020
904834	4VZVU1E90MC089207	2021	MA	DP	4551	S	7/30/2020	8/10/2020
904835	4VZVU1E95MC089316	2021	MA	DP	4118	S	6/10/2020	6/19/2020
904836	4VZVU1E96MC089258	2021	MA	DP	4102	S	6/4/2020	6/15/2020
904837	4VZVU1E90LC089013	2021	MA	DP	4551	S	6/16/2020	6/25/2020
904840	4VZVU1E99MC089108	2021	MA	DP	4551	S	6/23/2020	7/17/2020
904841	4VZVU1E92MC089208	2021	MA	DP	4551	S	8/6/2020	8/17/2020
904842	4VZVU1E90MC089109	2021	MA	DP	4551	S	8/6/2020	8/18/2020

Prod#	VIN Number	Year	Brand	Type	Floor	Chassis	Date In	Date Off
904843	4VZVU1E92MC089337	2021	MA	DP	4551	S	10/9/2020	10/19/2020
904845	4VZVU1E92MC089757	2021	MA	DP	4118	S	9/23/2020	10/5/2020
904846	4VZVU1E94MC089338	2021	MA	DP	4543	S	10/26/2020	11/4/2020
904847	4VZVU1E97MC089379	2021	MA	DP	4551	S	12/3/2020	12/14/2020
904848	4VZVU1E96MC089664	2021	MA	DP	4118	S	9/2/2020	9/11/2020
904850	4VZVU1E97MC089317	2021	MA	DP	4118	S	8/24/2020	9/1/2020
904851	4VZVU1E91MC089488	2021	MA	DP	4118	S	8/28/2020	9/8/2020
904853	4VZVU1E9XMC089277	2021	MA	DP	4533	S	9/28/2020	10/7/2020
904854	4VZVU1E96MC089549	2021	MA	DP	4118	S	9/4/2020	9/15/2020
904855	4VZVU1E90MC089921	2021	MA	DP	4551	S	1/12/2021	1/19/2021
904856	4VZVU1E9XMC089862	2021	MA	DP	4551	S	11/19/2020	12/8/2020
904858	4VZVU1E94MC089209	2021	MA	DP	4535	S	9/9/2020	9/17/2020
904859	4VZVU1E94MC089758	2021	MA	DP	4118	S	10/15/2020	10/23/2020
904860	4VZVU1E99MC089920	2021	MA	DP	4118	S	1/11/2021	1/19/2021
904861	4VZVU1E95MC089378	2021	MA	DP	4551	S	11/16/2020	12/3/2020
904863	4VZVU1E96MC089759	2021	MA	DP	4118	S	10/28/2020	11/6/2020
904865	4VZVU1E99MC089318	2021	MA	DP	4551	S	10/7/2020	10/14/2020
904866	4VZVU1E98MC089777	2021	MA	DP	4118	S	11/4/2020	11/13/2020
904867	4VZVU1E96MC089339	2021	MA	DP	4533	S	11/3/2020	11/12/2020
904868	4VZVU1E9XMC089778	2021	MA	DP	4118	S	12/8/2020	12/16/2020
904869	4VZVU1E92MC089922	2021	MA	DP	4551	S	2/4/2021	2/12/2021
904870	4VZVU1E96MC089986	2021	MA	DP	4535	S	2/10/2021	2/18/2021
904871	4VZVU1E92MC089919	2021	MA	DP	4118	S	12/16/2020	1/11/2021
904872	4VZVU1E92MC090004	2021	MA	DP	4551	S	3/10/2021	3/18/2021
904873	4VZVU1E94MC089940	2021	MA	DP	4583	S	2/15/2021	2/23/2021
904875	4VZVU1E98MC090623	2021	MA	DP	4551	S	5/7/2021	5/18/2021
904876	4VZVU1E94MC090831	2021	MA	DP	4551	S	6/4/2021	6/14/2021
904877	4VZVU1E92MC090763	2021	MA	DP	4551	S	5/20/2021	5/28/2021
904878	4VZVU1E94MC090778	2021	MA	DP	4551	S	6/2/2021	6/10/2021
904881	4VZ1U1E97NC090886	2021	MA	DP	4118	S	6/11/2021	6/21/2021
904884	4VZVU1E99MC090825	2021	MA	DP	4118	S	5/28/2021	6/8/2021
904885	4VZVU1E98MC090136	2021	MA	DP	4102	S	2/5/2021	2/15/2021
904886	4VZVU1E91MC090107	2021	MA	DP	4118	S	1/19/2021	1/27/2021
904887	4VZVU1E94NC089650	2022	MA	DP	4543	S	12/11/2020	1/5/2021
904888	4VZVU1E98MC089939	2021	MA	DP	4551	S	2/1/2021	2/9/2021
904890	4VZVU1E98MC090587	2021	MA	DP	4551	S	4/29/2021	5/10/2021
904892	4VZVU1E92MC090049	2021	MA	DP	4535	S	3/31/2021	4/12/2021
904893	4VZVU1E94MC090005	2021	MA	DP	4551	S	3/26/2021	4/7/2021
904894	4VZVU1E92MC090181	2021	MA	DP	4118	S	3/22/2021	3/30/2021
904895	4VZVU1E96MC090586	2021	MA	DP	4118	S	5/5/2021	5/14/2021
904896	4VZVU1E90MC090762	2021	MA	DP	4533	S	5/18/2021	5/26/2021
904897	4VZVU1E98NC089649	2022	MA	DP	4118	S	3/2/2021	3/10/2021
904898	4VZVU1E94MC090182	2021	MA	DP	4118	S	4/14/2021	4/22/2021
904899	4VZVU1E99MC090680	2021	MA	DP	4551	S	5/12/2021	5/21/2021
904900	4VZVU1E98MC089987	2021	MA	DP	4551	S	3/17/2021	3/26/2021
904901	4VZVU1E95MC090093	2021	MA	DP	4551	S	4/12/2021	4/19/2021
904902	4VZVU1E94MC090764	2021	MA	DP	4551	S	5/25/2021	6/3/2021
904905	4VZVU1E94MC090876	2021	MA	DP	4535	S	6/9/2021	6/17/2021

Prod#	VIN Number	Year	Brand	Type	Floor	Chassis	Date In	Date Off
904906	4VZVU1E92MC090875	2021	MA	DP	4551	S	6/8/2021	6/15/2021
904909	4VZVU1E98NC091353	2022	MA	DP	4118	S	8/16/2021	8/26/2021
904911	4VZVU1E99NC091197	2022	MA	DP	4118	S	7/29/2021	8/6/2021
904912	4VZVU1E90NC091198	2022	MA	DP	4535	S	9/17/2021	9/27/2021
904913	4VZVU1E95NC090919	2022	MA	DP	4551	S	6/29/2021	7/15/2021
904914	4VZVU1E91NC091694	2022	MA	DP	4551	S	11/3/2021	11/11/2021
904915	4VZVU1E91NC091243	2022	MA	DP	4535	S	9/23/2021	9/30/2021
904916	4VZVU1E93NC090918	2022	MA	DP	4118	S	6/18/2021	6/29/2021
904918	4VZVU1E91NC090982	2022	MA	DP	4589	S	7/1/2021	7/16/2021
904921	4VZVU1E98NC091093	2022	MA	DP	4551	S	8/11/2021	8/25/2021
904922	4VZVU1E96NC091092	2022	MA	DP	4551	S	8/5/2021	8/17/2021
904924	4VZVU1E93NC091325	2022	MA	DP	4118	S	8/3/2021	8/11/2021
904925	4VZVU1E99NC091121	2022	MA	DP	4543	S	9/14/2021	9/22/2021
904926	4VZVU1E94NC091690	2022	MA	DP	4118	S	10/19/2021	10/28/2021
904937	4VZVU1E93NC091020	2022	MA	DP	4118	S	7/28/2021	8/5/2021
904940	4VZVU1E9XNC091421	2022	MA	DP	4118	S	8/25/2021	9/2/2021
904941	4VZVU1E91NC090920	2022	MA	DP	4533	S	6/29/2021	7/14/2021
904942	4VZVU1E97NC091120	2022	MA	DP	4551	S	9/1/2021	9/10/2021
904943	4VZVU1E9XNC091354	2022	MA	DP	4118	S	8/19/2021	8/31/2021
904945	4VZVU1E96NC091691	2022	MA	DP	4118	S	10/27/2021	11/5/2021
904946	4VZVU1E9XNC090981	2022	MA	DP	4118	S	7/27/2021	8/3/2021
904959	4VZVU1E95NC091021	2022	MA	DP	4551	S	7/20/2021	7/28/2021
904991	4VZVU1E92NC091767	2022	MA	DP	4118	S	12/7/2021	12/16/2021
904992	4VZVU1E91NC091422	2022	MA	DP	4118	S	9/8/2021	9/16/2021
904993	4VZVU1E9XNC091094	2022	MA	DP	4535	S	8/27/2021	9/7/2021
904994	4VZVU1E9XNC091693	2022	MA	DP	4543	S	10/28/2021	11/9/2021
904995	4VZVU1E95NC091830	2022	MA	DP	4551	S	1/7/2022	1/18/2022
904996	4VZVU1E92NC091199	2022	MA	DP	4589	S	9/24/2021	10/4/2021
904998	4VZVU1E9XNC091242	2022	MA	DP	4543	S	9/28/2021	10/7/2021
904999	4VZVU1E92NC091610	2022	MA	DP	4118	S	10/14/2021	10/26/2021
905001	4VZVU1E91NC091629	2022	MA	DP	4551	S	10/12/2021	10/22/2021
905003	4VZVU1E98NC091692	2022	MA	DP	4118	S	11/15/2021	11/24/2021
905006	4VZVU1E92NC092031	2022	MA	DP	4118	S	1/4/2022	1/14/2022
905008	4VZVU1E99NC091829	2022	MA	DP	4551	S	12/16/2021	1/11/2022
905011	4VZVU1E90NC091766	2022	MA	DP	4118	S	2/8/2022	2/16/2022
905012	4VZVU1E92PC091254	2023	MA	DP	4591	S	11/22/2021	12/6/2021

Canadian Units

904766	4VZVU1E96LC087623	2020	MA	DP	4018	S	7/30/2019	8/6/2019
904782	4VZVU1E98LC088112	2020	MA	DP	4551	S	10/21/2019	10/30/2019
904800	4VZVU1E98LC087543	2020	MA	DP	4002	S	6/13/2019	6/20/2019
904807	4VZVU1E98LC087994	2020	MA	DP	4569	S	9/16/2019	9/23/2019
904814	4VZVU1E97LC088201	2020	MA	DP	4018	S	12/9/2019	12/16/2019
904838	4VZVU1E90MC089515	2021	MA	DP	4118	S	8/27/2020	9/4/2020
904839	4VZVU1E91MC089278	2021	MA	DP	4551	S	9/30/2020	10/9/2020
904852	4VZVU1E98MC089861	2021	MA	DP	4551	S	2/24/2021	3/8/2021
904874	4VZVU1E9XMC090137	2021	MA	DP	4118	S	3/15/2021	3/24/2021
904907	4VZVU1E91NC090917	2022	MA	DP	4118	S	6/17/2021	6/28/2021
904953	4VZVU1E92NC091512	2022	MA	DP	4118	S	10/7/2021	10/19/2021