

# Newmar Corporation

PO Box 30  
Nappanee, IN 46550



WHEN YOU KNOW THE DIFFERENCE.

RSB 608  
JAN 23, 2024

NHTSA #24V 019  
TC #2024-016

## RECALL SERVICE BULLETIN

### AFFECTED MODELS

2022 – 2023 :: Dutch Star, Mountain Aire, London Aire, Essex

### DESCRIPTION

Newmar Corporation Service Department was made aware of a Captain Chair Pedestal manufactured by Villa International that had the welds break at the pedestal-to-base plate connection. The weld breaking would cause the seat to no longer comply with FMVSS 207 and 210. Villa filed NHTSA recall # 23E098. In response, Newmar has filed NHTSA # 24V 019 and TC# 2024-016.

### ISSUE

The improper weld from the seat pedestal-to-base plate could fail in an accident, which could increase the risk of injury.

### UNITS AFFECTED

Please refer to the attached population list for unit and VIN numbers possibly affected.

### CUSTOMER ACTION

Have the seat pedestal inspected for proper welds at a Newmar authorized service center, and if found to have improper welds, a new seat pedestal will be installed to meet the compliance FMVSS 207/210 requirements.

### DEALER ACTION

Inspection of the seats in the vehicles included in the recall is necessary to identify if a replacement pedestal is required on the Villa driver and/or passenger seats. A drawing provided by Villa International is attached to help identify the potentially defective weld. If the vehicle inspection reveals that the pedestal(s) do not have the proper weld, then the pedestal(s) are required to be replaced for the affected seat(s). Inspection includes taking and submitting photo(s) of the inspected seat pedestals and their welds. If the pedestal(s) fail inspection and require replacement, the seat pedestal(s) must be returned. If you need assistance, contact your Newmar Service Account Manager.

### PARTS NEEDED (IF NEEDED)

| Item Description | Newmar Part # |
|------------------|---------------|
| Seat pedestal    | 033715        |

FLAT RATE CODE: 24V 019 LABOR TIME: .1 hr. for inspection only; 1.0 hr. for inspection and replacement.

**IMPORTANT:** Please read this bulletin in its entirety prior to beginning any diagnosis or repairs.

NOTICE: Any technical information published in this bulletin is intended for use only by a qualified, Newmar-authorized service technician. Newmar is not responsible for the misuse of this information.



WHEN YOU KNOW THE DIFFERENCE

# NEWMAR CORPORATION

NEWMARCORP.COM

## IMPORTANT SAFETY RECALL NOTICE

**Date:** January 19, 2024

**Subject:** Recall Campaign NHSTA #24V-019: Incorrect Seat Pedestal Weld

---

Newmar Campaign No.: 608 RSB

This notice is sent to you as a Newmar Dealer in accordance with the requirements of the National Traffic and Motor Vehicle Safety Act. Newmar Corporation has decided that a non-compliance, which relates to motor vehicle safety, exists in specific Newmar recreational vehicles.

### **REASON FOR THIS RECALL**

Newmar Corporation Service Department was made aware of 2022 Dutch Star Captain Chair Pedestal manufactured by Villa International that had the welds break at the pedestal to base plate connection. The weld breaking would bring the seat out of compliance with FMVSS 207 and 210.

The improper weld from the seat pedestal to base plate not meeting FMVSS 207/210 requirements could fail in an accident which could increase the risk of an injury.

Motorhomes included in this recall include:

- 2022-2023 Dutch Star Class A motorhomes.
- 2022-2023 Mountain Aire Class A motorhomes.
- 2022-2023 London Aire Class A motorhomes.
- 2022-2023 Essex Class A motorhomes.
- 2016 London Aire Class A motorhome (New seat installed in service included in population list)

### **OWNER NOTIFICATION**

Villa International will be conducting this recall in its entirety. Newmar will notify the owner by mail and instruct them to take their motorhome to an authorized service facility to have the seat pedestal inspected for proper welds and if found to have improper welds a new seat pedestal will be installed to bring the seat into compliance with FMVSS 207/210 requirements.

### **DEALER CAMPAIGN RESPONSIBILITY**

***Dealers are to provide to all customers/owner vehicles the service of completing this campaign at no charge to the customer/owner regardless of vehicle age, vehicle mileage, or ownership at the time of repair.***

**PLEASE NOTE:** Federal law requires dealers to complete this recall service before a new vehicle is delivered to the buyer or lessee. Violation of this requirement by a dealer could result in a civil penalty. Correct all vehicles in your new vehicle inventory before delivery.

## **REPAIR PROCEDURE**

Inspection of the seats in the vehicles included in the recall is necessary in order to identify if a repair is required on the Villa driver and passenger seats. A drawing provided by Villa International will be provided to help identify the defective weld. If the vehicle inspection reveals that the pedestal does have the improper weld, then the pedestal is required to be replaced for that seat.

The National Traffic and Motor Vehicle Safety Act requires that each vehicle, which is subject to a recall campaign of this type, must be satisfactorily repaired within a reasonable time after the owner has tendered it for repair. Every effort must be made to promptly schedule an appointment with each owner and to repair their vehicle as soon as possible. Vehicle owners are being notified of this recall and have been instructed to contact Newmar and/or the National Highway Traffic Safety Administration if the condition is not remedied within a reasonable time.

**If you should have any questions, please contact your service account manager direct or the Newmar service department at: 1-866-290-5371.**

Thank you for your cooperation.

Sincerely,

Newmar Corporation



WHEN YOU KNOW THE DIFFERENCE

# NEWMAR CORPORATION

NEWMARCORP.COM

## IMPORTANT SAFETY RECALL

This notice applies to your vehicle VIN. # \_\_\_\_\_

Name

Address

City, State Zip code

Date: January 26, 2024

Motor Vehicle Recall Notification – NHSTA Recall Campaign No. 24V-019, Newmar Campaign No. 608 RSB

Dear Valued Customer:

This notice is sent to you in accordance with the requirements of the National Traffic and Motor Vehicle Safety Act.

### **REASON FOR THIS RECALL**

Newmar Corporation has decided that certain 2022-2023 Dutch Star Class A Motorhomes, 2022-2023 Mountain Aire Class A Motorhomes, 2022-2023 London Aire Class A Motorhomes, 2022-2023 Essex Class A Motorhomes and a single 206 London Aire Class A Motorhome that fail to conform to Federal Motor Vehicle Safety Standard No. 207, "Seating Systems," and 210 "Seat Belt Assembly Anchorages." The pedestal mounting plate may be improperly welded, causing the plate to separate and the seat assembly to loosen or detach on the driver side or passenger side chairs.

**These motorhomes require immediate service. Continued use poses a potential safety hazard.**

### **The Safety Risk**

A loose or detached seat assembly increases the risk of injury.

### **WHAT WE WILL DO**

Newmar will notify the owner by mail and instruct them to take their motorhome to an authorized service facility to have the seat pedestal inspected for proper welds and if found to have improper welds a new seat pedestal will be installed to bring the seat into compliance with FMVSS 207/210 requirements. This repair is expected to take approximately .10 hour for inspection and 1 hour for installing new pedestal if necessary. However, due to some service scheduling times, the service center may need your vehicle for a longer period. All repairs will be done free of charge to the customer.

### **WHAT YOU NEED TO DO**

As this defect does affect motor vehicle safety, it is recommended that you call Newmar service department immediately at **1-800-731-8300**. An associate will assist you in making an appointment to have this repair completed.

**Federal regulations require that any vehicle lessor receiving this recall notification must forward a copy of this notice to the lessee within ten days.**

*If you have had the repair performed before receiving this letter, you may be eligible to receive reimbursement for the cost of obtaining a pre-notification remedy. For additional information, contact Newmar Corporation at:*

**Service Department**  
Newmar Corporation  
355 N Delaware St  
Nappanee, IN 46550-0030

Newmar dealers are best equipped to obtain parts and provide service to ensure your vehicle is corrected as promptly as possible. HOWEVER, if you take your vehicle to your dealer on the scheduled date and this condition is not remedied on that date or within five days; please contact the Newmar Corporation Customer Service Department at 1-800-731-8300. You may also submit a complaint to the Administrator, National Highway Traffic Safety Administration, 1200 New Jersey Ave., SE., Washington DC 20590; or call the toll-free Vehicle Safety Hotline at 1-888-327-4236 (TTY: 1-800-424-9153); or go to <http://www.safercar.gov>.

If you no longer own this vehicle, please furnish us the complete name, phone number, e-mail and physical address of the person or dealership you sold or traded your vehicle to. Thank you for your cooperation.

Your safety and satisfaction with your Newmar product is important to us and we regret any inconvenience to you.

Sincerely,

Newmar Corporation



WHEN YOU KNOW THE DIFFERENCE

# NEWMAR CORPORATION

NEWMARCORP.COM

## IMPORTANT SAFETY RECALL NOTICE

**Date:** January 26, 2024

**Subject:** Transport Canada Recall Campaign No. 2024-016, Newmar Campaign No. 608 RSB

---

This notice is sent to you as a Newmar Dealer in accordance with the requirements of the *Canada Motor Vehicle Safety Act*. Newmar Corporation has decided that a non-compliance, which relates to motor vehicle safety, exists in specific Newmar recreational vehicles.

### **REASON FOR THIS RECALL**

Issue:

*On a small number of motorhomes, the driver or passenger side seat base may not have been properly welded. As a result, the seat could move or detach in a crash.*

Safety Risk:

*A seat belt that detaches in a crash could create an increased risk of injury.*

Corrective Actions:

*Newmar will notify owners by mail and advise you to take your motorhome to an authorized service facility to inspect and, if necessary, replace the driver or passenger side seat base as needed.*

The vehicle models involved in this recall are:

2022 Dutch Star Class A motorhomes.

2022 London Aire Class A motorhomes.

### **DEALER CAMPAIGN RESPONSIBILITY**

***Dealers are to provide to all customers/owner vehicles the service of completing this campaign at no charge to the customer/owner regardless of vehicle age, vehicle mileage, or ownership at the time of repair.***

**PLEASE NOTE:** Dealers are required to complete this recall service before a new vehicle is delivered to the buyer or lessee. Violation of this requirement by a dealer could result in a civil penalty. Correct all vehicles in your new vehicle inventory before delivery.

### **REPAIR PROCEDURE**

Inspection of the seats in the vehicles included in the recall is necessary in order to identify if a repair is required on the Villa driver and passenger seats. A drawing provided by Villa International will be provided to help identify the defective weld. If the vehicle inspection reveals that the pedestal does have the improper weld, then the pedestal is required to be replaced for that seat.

Each vehicle, which is subject to a recall campaign of this type, must be satisfactorily repaired within a reasonable time after the owner has tendered it for repair. Every effort must be made to promptly schedule an appointment with each owner and to repair their vehicle as soon as possible. Vehicle owners are being notified of this recall and have been instructed to contact Newmar and/or Transport Canada if the condition is not remedied within a reasonable time.

**If you should have any questions please contact your service account manager direct or the Newmar service department at: 1-866-290-5371.**

Thank you for your cooperation.

Sincerely,

Newmar Corporation



WHEN YOU KNOW THE DIFFERENCE

# NEWMAR CORPORATION

NEWMARCORP.COM

## IMPORTANT SAFETY RECALL

VIN#  
make, model, model year  
Name  
Address  
City, State Zip code

Date: January 26, 2024

Motor Vehicle Recall Notification -Transport Canada Recall Campaign No. 2024-016 Newmar Campaign No.608 RSB

Dear Valued Customer:

This notice is sent to you in accordance with the requirements of the *Motor Vehicle Safety Act*.

This is to inform you that your vehicle may be non-compliant with the requirements of the *Motor Vehicle Safety Regulations* and that the non-compliance could affect the safety of a person.

### **REASON FOR THIS RECALL**

Newmar Corporation is recalling certain 2022 Dutch Star and London Aire Class A Motorhomes. The pedestal mounting plate may be improperly welded, causing the plate to separate and the seat assembly to loosen or detach. As such, these seat assemblies fail to comply with the requirements of Canadian Motor Vehicle Safety Standard (CMVSS) number 207, "Seating Systems", and number 210, "Seat belt assembly anchorages."

Issue:

*On a small number of motorhomes, the driver or passenger side seat base may not have been properly welded. As a result, the seat could move or detach in a crash.*

Safety Risk:

*A seat that moves or detaches could increase the risk of injury in a crash.*

Corrective Actions:

*Newmar will notify owners by mail and advise you to take your motorhome to an authorized service facility to inspect and, if necessary, replace the driver or passenger side seat base as needed.*

**The motorhomes require immediate service. Continued use poses a potential safety hazard.**

### **WHAT WE WILL DO**

Newmar will notify the owner by mail and instruct them to take their motorhome to an authorized service facility to have the seat pedestal inspected for proper welds and if found to have improper welds a new seat pedestal will be installed to bring the seat into compliance with CMVSS 207/210 requirements. This repair is expected to take approximately .10 hour for inspection and 1 hour for installing new pedestal if necessary. However, due to some service scheduling times, the service center may need your vehicle for a longer period. All repairs will be done free of charge to the customer.



**WHAT YOU NEED TO DO**

As this defect does affect motor vehicle safety, it is recommended that you call Newmar service department immediately at **1-800-731-8300**. An associate will assist you in making an appointment to have this repair completed.

**Federal regulations require that any vehicle lessor receiving this recall notification must forward a copy of this notice to the lessee within ten days.**

Newmar dealers are best equipped to obtain parts and provide service to ensure your vehicle is corrected as promptly as possible. HOWEVER, if you take your vehicle to your dealer on the scheduled date and this condition is not remedied on that date or within five days; please contact the Newmar Corporation Customer Service Department at 1-800-731-8300.

If you have had the repair performed before receiving this letter, you may be eligible to receive reimbursement for the cost of obtaining a pre-notification remedy. For additional information, contact Newmar Corporation at:

**Service Department**  
Newmar Corporation  
355 N Delaware St  
Nappanee, IN 46550-0030

If you no longer own this vehicle, please furnish us the complete name, phone number, e-mail and physical address of the person or dealership you sold or traded your vehicle to. Thank you for your cooperation.

Your safety and satisfaction with your Newmar product is important to us and we regret any inconvenience to you.

Sincerely,

Newmar Corporation



WHEN YOU KNOW THE DIFFERENCE

# NEWMAR CORPORATION

NEWMARCORP.COM

## RAPPEL D'INNOCUITÉ IMPORTANT

NIV#

la fabrique, le modèle, l'année de modèle

Nom

Adresse

Ville, code postal de l'État

Date : 26 janvier 2024

Avis de rappel de véhicules automobiles - Campagne de rappel de Transports Canada no 2024-016 Campagne Newmar no 608 RSB

Cher client apprécié :

Le présent avis vous est envoyé conformément aux exigences de la *Loi sur la sécurité automobile*.

La présente a pour but de vous informer que votre véhicule est susceptible d'être non conforme aux exigences du *Règlement sur la sécurité des véhicules automobiles* et que la non-conformité pourrait porter atteinte à la sécurité humaine.

### RAISON DE CE RAPPEL

Newmar Corporation rappelle certains camping-cars Dutch Star et Aire de Londres de classe A 2022. La plaque de montage du piédestal peut être mal soudée, ce qui provoque la séparation de la plaque et le desserre ou le détachement de l'ensemble du siège. Par conséquent, ces ensembles de sièges ne sont pas conformes aux exigences de la Norme de sécurité des véhicules automobiles du Canada (NSVAC) numéro 207, « Systèmes de sièges », et numéro 210, « Ancrages de ceintures de sécurité ».

Question en litige :

*Sur un petit nombre de camping-cars, l'assise du côté conducteur ou du côté passager n'a peut-être pas été correctement soudée. En conséquence, le siège pourrait bouger ou se détacher en cas d'accident.*

Risque pour la sécurité :

*Un siège qui bouge ou se détache peut augmenter le risque de blessures en cas d'accident.*

Mesures correctives :

*Newmar avisera les propriétaires par la poste et vous conseillera d'apporter votre camping-car à une installation de service autorisée pour inspecter et, si nécessaire, remplacer l'assise du côté conducteur ou passager au besoin.*

**Les camping-cars nécessitent un service immédiat. L'utilisation continue présente un danger potentiel pour la sécurité.**

### CE QUE NOUS ALLONS FAIRE

Newmar avisera le propriétaire par la poste et lui demandera d'apporter son camping-car à une installation de service autorisée pour faire inspecter le piédestal du siège pour les soudures appropriées et s'il s'avère qu'il y a des soudures inappropriées, un nouveau piédestal de siège sera installé pour rendre le siège conforme aux exigences de la norme 207/210 du CMVSS. Cette réparation devrait prendre environ 10 heures pour l'inspection et 1 heure pour l'installation d'un nouveau piédestal si nécessaire. Cependant, en raison de certains temps de planification de service, le centre de service peut avoir besoin de votre véhicule pour une période plus longue. Toutes les réparations seront effectuées gratuitement pour le client.

### **CE QUE VOUS DEVEZ FAIRE**

Comme ce défaut affecte la sécurité des véhicules automobiles, il est recommandé d'appeler immédiatement le service de Newmar au **1-800-731-8300**. Un associé vous aidera à prendre rendez-vous pour que cette réparation soit terminée.

**La réglementation fédérale exige que tout locateur de véhicule recevant cet avis de rappel transmette une copie de cet avis au locataire dans les dix jours.**

Les concessionnaires Newmar sont les mieux équipés pour obtenir des pièces et fournir un service afin de s'assurer que votre véhicule est corrigé le plus rapidement possible. TOUTEFOIS, si vous apprenez votre véhicule chez votre concessionnaire à la date prévue et que cette condition n'est pas corrigée à cette date ou dans les cinq jours ; veuillez communiquer avec le service à la clientèle de Newmar Corporation au 1-800-731-8300.

Si vous avez fait effectuer la réparation avant de recevoir cette lettre, vous pourriez être admissible à recevoir un remboursement pour le coût de l'obtention d'un recours préalable à la notification. Pour de plus amples renseignements, veuillez communiquer avec Newmar Corporation à l'adresse suivante :

**Département des services**  
Newmar Corporation  
355 N Delaware St  
Nappanee, IN 46550-0030

Si vous n'êtes plus propriétaire de ce véhicule, veuillez nous fournir le nom complet, le numéro de téléphone, le courriel et l'adresse physique de la personne ou du concessionnaire à qui vous avez vendu ou échangé votre véhicule. Je vous remercie de votre coopération.

Votre sécurité et votre satisfaction à l'égard de votre produit Newmar sont importantes pour nous et nous regrettons tout inconfort pour vous.

Cordialement,

Newmar Corporation



## **IMPORTANT SAFETY RECALL**

**NHTSA RECALL NO. 23E098**

**DATE: 1.10.24**

**To: Newmar Corporation**

**Subject: Villa seating recall notification**

This letter was sent in accordance with the National Traffic and Motor Vehicle Safety Act. Villa International has determined that certain Newmar motor-homes equipped with Villa passenger seating fail to conform to Federal Motor Vehicle Safety Standard no. 207, "seating systems".

The safety defect involves the pedestal used on Villa ABTS driver and passenger seating where the seat assembly is attached to the pedestal and serves as an anchorage to the vehicle. On certain seat pedestals the can may be improperly welded to the mounting plate. The pedestal in the affected seat assemblies could fail in the event of a vehicular collision.

The Villa seats affected by the recall were fabricated and delivered to Newmar Corporation from April 19, 2022 through July 19, 2022. These seats were installed in Newmar, Dutch Star, Mountain Aire, London Aire, and Essex.

### **The Repair**

Inspection of the seats in the vehicles listed above is necessary in order to identify if a repair is required on Villa driver and passenger seats. Attached with this notification is a drawing to help identify the defective pedestal.

**If the vehicle inspection reveals that the pedestal does have the improper weld, then the pedestal is required to be replaced for that seat.**

Please contact Villa International at 1-888-707-7272 for information as well as replacement parts for the repair. The parts are available by faxing your part requirements to 1-562-404-7785. If there are additional questions concerning this repair please contact James Mariel at 1-574-389-8383.



### **Manufacturer Responsibility**

All the unsold new vehicles in the possession of the manufacturer and subject to this recall must be inspected as well as repaired according to the Villa repair procedure before dealers or owners can take possession of the affected vehicle.

Dealers should also receive notification of this recall and are to repair the affected vehicles of this recall at no charge to the owners regardless of mileage, vehicle age, or ownership from this time forward.

Owners of the affected vehicles recently sold from a dealer inventory in which the dealer received the recall notification are to be contacted by the dealer in order to make arrangements for the repair to be completed.

This will be done by mailing the owner's notification letter accompanying the dealer and this notification.

The vehicle owners will also be instructed to contact the Newmar customer service if their dealer does not complete the repair within seven (7) days of the mutually agreed upon service date. The owners are also instructed to contact the National Highway Traffic Safety Administration if the repair does not occur within the reasonable amount of time.

In conclusion, please ensure that the Newmar vehicles affected by this recall in your inventory have been inspected and properly repaired before selling or releasing the vehicle to dealers or owners.


We at Villa International regret to have caused this inconvenience at this time.

We have taken this action to ensure the safety of your customers and the continued satisfaction of our seating products.

Sincerely,

J.G. Mariel

Villa International



| Prod#            | VIN Num   | Year | Brand | Type | Floor | Chassis | Date In   | Date Off  |
|------------------|-----------|------|-------|------|-------|---------|-----------|-----------|
| <b>USA Units</b> |           |      |       |      |       |         |           |           |
| 501249           | 4UZFTBG6  | 2016 | LA    | DP   | 4503  | FL      | 3/17/2015 | 3/25/2015 |
| 501928           | 4VZVU1R1  | 2022 | LA    | DP   | 4579  | S       | 6/15/2022 | 6/22/2022 |
| 501938           | 4VZVU1R1  | 2022 | LA    | DP   | 4533  | S       | 6/29/2022 | 7/15/2022 |
| 502010           | 4VZVU1R1  | 2022 | LA    | DP   | 4551  | S       | 4/27/2022 | 5/4/2022  |
| 502012           | 4VZVU1R1  | 2022 | LA    | DP   | 4551  | S       | 4/21/2022 | 4/28/2022 |
| 502017           | 4VZVU1R1  | 2022 | LA    | DP   | 4551  | S       | 4/28/2022 | 5/5/2022  |
| 502021           | 4VZVU1R1  | 2022 | LA    | DP   | 4551  | S       | 5/9/2022  | 5/17/2022 |
| 502022           | 4VZVU1R1  | 2022 | LA    | DP   | 4551  | S       | 6/2/2022  | 6/14/2022 |
| 502023           | 4VZVU1R1  | 2022 | LA    | DP   | 4533  | S       | 5/31/2022 | 6/9/2022  |
| 502024           | 4VZVU1R1  | 2022 | LA    | DP   | 4535  | S       | 6/14/2022 | 6/21/2022 |
| 502025           | 4VZVU1R1  | 2023 | LA    | DP   | 4569  | S       | 6/20/2022 | 6/30/2022 |
| 609639           | 4UZFCHFE7 | 2022 | DS    | DP   | 4369  | FL      | 5/5/2022  | 5/17/2022 |
| 609675           | 4UZFCHFE9 | 2022 | DS    | DP   | 4369  | FL      | 6/16/2022 | 6/28/2022 |
| 609679           | 4UZFCHFE4 | 2022 | DS    | DP   | 4326  | FL      | 6/1/2022  | 6/10/2022 |
| 609682           | 4UZFCHFE4 | 2022 | DS    | DP   | 4369  | FL      | 6/15/2022 | 6/22/2022 |
| 609694           | 4UZFCHFE8 | 2022 | DS    | DP   | 4369  | FL      | 5/5/2022  | 5/17/2022 |
| 609700           | 4UZFCHFE5 | 2022 | DS    | DP   | 4310  | FL      | 5/17/2022 | 5/24/2022 |
| 609703           | 4VZAU1D1  | 2022 | DS    | DP   | 4369  | S       | 6/1/2022  | 6/9/2022  |
| 609715           | 4UZFCHFE1 | 2022 | DS    | DP   | 4310  | FL      | 5/24/2022 | 6/3/2022  |
| 609719           | 4UZFCHFE0 | 2022 | DS    | DP   | 4081  | FL      | 5/17/2022 | 5/24/2022 |
| 609725           | 4VZAU1D1  | 2022 | DS    | DP   | 4369  | S       | 6/7/2022  | 6/16/2022 |
| 609727           | 4VZAU1D1  | 2022 | DS    | DP   | 4369  | S       | 6/7/2022  | 6/15/2022 |
| 609730           | 4VZAU1D1  | 2022 | DS    | DP   | 4081  | S       | 5/5/2022  | 5/13/2022 |
| 609731           | 4VZAU1D1  | 2022 | DS    | DP   | 4081  | S       | 7/13/2022 | 7/21/2022 |
| 609743           | 4VZAU1D1  | 2022 | DS    | DP   | 4369  | S       | 6/14/2022 | 6/21/2022 |
| 609744           | 4VZAU1D1  | 2022 | DS    | DP   | 4369  | S       | 6/1/2022  | 6/9/2022  |
| 609748           | 4VZAU1D1  | 2022 | DS    | DP   | 4369  | S       | 5/2/2022  | 5/11/2022 |
| 609752           | 4VZAU1D1  | 2022 | DS    | DP   | 4081  | S       | 5/31/2022 | 6/9/2022  |
| 609791           | 4VZAU1D1  | 2022 | DS    | DP   | 4369  | S       | 5/2/2022  | 5/10/2022 |
| 609803           | 4UZFCHFE4 | 2022 | DS    | DP   | 4081  | FL      | 7/12/2022 | 7/19/2022 |
| 609858           | 4UZFCHFE5 | 2022 | DS    | DP   | 4369  | FL      | 6/28/2022 | 7/14/2022 |
| 609875           | 4VZAU1D1  | 2022 | DS    | DP   | 4369  | S       | 7/12/2022 | 7/19/2022 |
| 609885           | 4UZFCHFE3 | 2022 | DS    | DP   | 4369  | FL      | 5/20/2022 | 6/2/2022  |
| 609917           | 4VZAU1D1  | 2022 | DS    | DP   | 4369  | S       | 6/3/2022  | 6/15/2022 |
| 609922           | 4VZAU1D1  | 2022 | DS    | DP   | 4081  | S       | 7/12/2022 | 7/20/2022 |
| 609923           | 4VZAU1D1  | 2022 | DS    | DP   | 4081  | S       | 4/29/2022 | 5/10/2022 |
| 609924           | 4UZFCHFE2 | 2022 | DS    | DP   | 4081  | FL      | 5/13/2022 | 5/24/2022 |
| 609926           | 4VZAU1D1  | 2022 | DS    | DP   | 4081  | S       | 5/4/2022  | 5/13/2022 |
| 609927           | 4UZFCHFE3 | 2022 | DS    | DP   | 4328  | FL      | 6/10/2022 | 6/21/2022 |
| 609966           | 4VZAU1D1  | 2022 | DS    | DP   | 4081  | S       | 5/13/2022 | 5/23/2022 |
| 610017           | 4UZFCHFE2 | 2022 | DS    | DP   | 4081  | FL      | 6/10/2022 | 6/20/2022 |
| 610025           | 4UZFCHFE4 | 2022 | DS    | DP   | 4020  | FL      | 4/27/2022 | 5/4/2022  |
| 610030           | 4UZFCHFE8 | 2022 | DS    | DP   | 4081  | FL      | 4/26/2022 | 5/4/2022  |
| 610032           | 4UZFCHFE0 | 2022 | DS    | DP   | 4081  | FL      | 4/26/2022 | 5/4/2022  |

| Prod#  | VIN Num   | Year | Brand | Type | Floor | Chassis | Date In   | Date Off  |
|--------|-----------|------|-------|------|-------|---------|-----------|-----------|
| 610033 | 4UZFCHFE0 | 2022 | DS    | DP   | 4081  | FL      | 6/22/2022 | 7/12/2022 |
| 610035 | 4UZFCHFE0 | 2022 | DS    | DP   | 4369  | FL      | 5/31/2022 | 6/8/2022  |
| 610037 | 4UZFCHFE0 | 2022 | DS    | DP   | 4081  | FL      | 6/22/2022 | 7/12/2022 |
| 610056 | 4UZFCHFE2 | 2022 | DS    | DP   | 4081  | FL      | 5/12/2022 | 5/20/2022 |
| 610057 | 4VZAU1D1  | 2022 | DS    | DP   | 4081  | S       | 5/3/2022  | 5/12/2022 |
| 610062 | 4VZAU1D1  | 2022 | DS    | DP   | 4020  | S       | 6/9/2022  | 6/20/2022 |
| 610091 | 4UZFCHFE2 | 2022 | DS    | DP   | 4081  | FL      | 5/3/2022  | 5/12/2022 |
| 610093 | 4UZFCHFE7 | 2022 | DS    | DP   | 4081  | FL      | 5/12/2022 | 5/20/2022 |
| 610097 | 4VZAU1D1  | 2022 | DS    | DP   | 4369  | S       | 5/31/2022 | 6/8/2022  |
| 610105 | 4VZAU1D1  | 2022 | DS    | DP   | 4369  | S       | 4/11/2022 | 4/22/2022 |
| 610115 | 4VZAU1D1  | 2022 | DS    | DP   | 4081  | S       | 5/4/2022  | 5/12/2022 |
| 610129 | 4UZACHFE1 | 2022 | DS    | DP   | 3709  | FL      | 6/10/2022 | 6/20/2022 |
| 610147 | 4UZFCHFE0 | 2022 | DS    | DP   | 4369  | FL      | 6/22/2022 | 7/12/2022 |
| 610148 | 4UZFCHFE0 | 2022 | DS    | DP   | 4369  | FL      | 7/14/2022 | 7/21/2022 |
| 610149 | 4UZFCHFE> | 2022 | DS    | DP   | 4081  | FL      | 4/27/2022 | 5/5/2022  |
| 610150 | 4UZFCHFE9 | 2022 | DS    | DP   | 4081  | FL      | 5/20/2022 | 6/1/2022  |
| 610155 | 4UZFCHFE> | 2022 | DS    | DP   | 4369  | FL      | 7/14/2022 | 7/25/2022 |
| 610176 | 4UZFCHFE> | 2022 | DS    | DP   | 4081  | FL      | 6/10/2022 | 6/20/2022 |
| 610181 | 4UZFCHFE2 | 2022 | DS    | DP   | 4081  | FL      | 4/29/2022 | 5/9/2022  |
| 610182 | 4UZFCHFE9 | 2022 | DS    | DP   | 4081  | FL      | 4/27/2022 | 5/4/2022  |
| 610184 | 4UZFCHFE0 | 2022 | DS    | DP   | 4369  | FL      | 4/29/2022 | 5/9/2022  |
| 610188 | 4UZFCHFE9 | 2022 | DS    | DP   | 4081  | FL      | 5/19/2022 | 6/1/2022  |
| 610202 | 4VZAU1D1  | 2022 | DS    | DP   | 4081  | S       | 5/18/2022 | 5/31/2022 |
| 610214 | 4UZFCHFE0 | 2022 | DS    | DP   | 4369  | FL      | 5/19/2022 | 5/31/2022 |
| 610215 | 4UZFCHFE> | 2022 | DS    | DP   | 4369  | FL      | 6/9/2022  | 6/17/2022 |
| 610219 | 4VZAU1D1  | 2022 | DS    | DP   | 4081  | S       | 5/11/2022 | 5/20/2022 |
| 610222 | 4VZAU1D1  | 2022 | DS    | DP   | 4081  | S       | 5/11/2022 | 5/19/2022 |
| 610225 | 4UZFCHFE7 | 2022 | DS    | DP   | 4081  | FL      | 5/18/2022 | 5/25/2022 |
| 610227 | 4UZACHFE1 | 2022 | DS    | DP   | 3736  | FL      | 5/11/2022 | 5/20/2022 |
| 610229 | 4UZFCHFE6 | 2022 | DS    | DP   | 4081  | FL      | 4/26/2022 | 5/3/2022  |
| 610231 | 4UZFCHFE6 | 2022 | DS    | DP   | 4369  | FL      | 6/2/2022  | 6/14/2022 |
| 610235 | 4VZAU1D1  | 2022 | DS    | DP   | 4369  | S       | 4/25/2022 | 5/3/2022  |
| 610237 | 4VZAU1D1  | 2022 | DS    | DP   | 4081  | S       | 5/3/2022  | 5/12/2022 |
| 610238 | 4VZAU1D1  | 2022 | DS    | DP   | 4081  | S       | 7/14/2022 | 7/21/2022 |
| 610239 | 4UZFCHFE5 | 2022 | DS    | DP   | 4081  | FL      | 6/29/2022 | 7/15/2022 |
| 610240 | 4UZFCHFE3 | 2022 | DS    | DP   | 4081  | FL      | 6/8/2022  | 6/17/2022 |
| 610241 | 4UZFCHFE5 | 2022 | DS    | DP   | 4081  | FL      | 4/19/2022 | 4/27/2022 |
| 610247 | 4VZAU1D1  | 2022 | DS    | DP   | 4369  | S       | 4/25/2022 | 5/3/2022  |
| 610248 | 4VZAU1D1  | 2022 | DS    | DP   | 4369  | S       | 5/11/2022 | 5/19/2022 |
| 610255 | 4UZFCHFE6 | 2022 | DS    | DP   | 4369  | FL      | 6/16/2022 | 6/23/2022 |
| 610286 | 4UZFCHFE2 | 2022 | DS    | DP   | 4020  | FL      | 4/25/2022 | 5/2/2022  |
| 610299 | 4VZAU1D1  | 2022 | DS    | DP   | 4369  | S       | 6/8/2022  | 6/17/2022 |
| 610300 | 4VZAU1D1  | 2022 | DS    | DP   | 4369  | S       | 5/10/2022 | 5/19/2022 |
| 610304 | 4VZAU1D1  | 2022 | DS    | DP   | 4369  | S       | 5/10/2022 | 5/18/2022 |
| 610316 | 4UZFCHFE4 | 2022 | DS    | DP   | 4369  | FL      | 6/21/2022 | 7/12/2022 |



| Prod#  | VIN Num   | Year | Brand | Type | Floor | Chassis | Date In   | Date Off  |
|--------|-----------|------|-------|------|-------|---------|-----------|-----------|
| 610324 | 4VZAU1D1  | 2022 | DS    | DP   | 4328  | S       | 6/8/2022  | 6/16/2022 |
| 610328 | 4VZAU1D1  | 2022 | DS    | DP   | 4369  | S       | 6/2/2022  | 6/10/2022 |
| 610346 | 4UZFCHFE2 | 2022 | DS    | DP   | 4369  | FL      | 6/15/2022 | 6/22/2022 |
| 610353 | 4UZFCHFE2 | 2022 | DS    | DP   | 4369  | FL      | 6/28/2022 | 7/15/2022 |
| 610355 | 4UZFCHFE9 | 2022 | DS    | DP   | 4081  | FL      | 5/3/2022  | 5/12/2022 |
| 610375 | 4UZFCHFE1 | 2022 | DS    | DP   | 4081  | FL      | 7/18/2022 | 7/26/2022 |
| 610376 | 4VZAU1D1  | 2022 | DS    | DP   | 4081  | S       | 7/15/2022 | 7/25/2022 |
| 610377 | 4UZFCHFE1 | 2022 | DS    | DP   | 4081  | FL      | 7/13/2022 | 7/20/2022 |
| 610525 | 4UZFCHFE6 | 2022 | DS    | DP   | 4369  | FL      | 4/28/2022 | 5/9/2022  |
| 610550 | 4UZFCHFE7 | 2022 | DS    | DP   | 4369  | FL      | 4/28/2022 | 5/5/2022  |
| 610563 | 4VZAU1D1  | 2022 | DS    | DP   | 4081  | S       | 5/9/2022  | 5/17/2022 |
| 610564 | 4VZAU1D1  | 2022 | DS    | DP   | 4081  | S       | 7/12/2022 | 7/20/2022 |
| 610565 | 4UZFCHFE4 | 2022 | DS    | DP   | 4081  | FL      | 6/21/2022 | 6/30/2022 |
| 610566 | 4UZFCHFE9 | 2022 | DS    | DP   | 4081  | FL      | 6/20/2022 | 6/29/2022 |
| 610567 | 4VZAU1D1  | 2022 | DS    | DP   | 4081  | S       | 5/17/2022 | 5/25/2022 |
| 610568 | 4UZFCHFE2 | 2022 | DS    | DP   | 4081  | FL      | 6/28/2022 | 7/14/2022 |
| 610592 | 4UZFCHFE9 | 2022 | DS    | DP   | 4326  | FL      | 5/12/2022 | 5/23/2022 |
| 610596 | 4UZFCHFE0 | 2022 | DS    | DP   | 4081  | FL      | 5/9/2022  | 5/17/2022 |
| 610598 | 4UZFCHFE9 | 2022 | DS    | DP   | 4369  | FL      | 5/13/2022 | 5/23/2022 |
| 610605 | 4UZACHFE1 | 2022 | DS    | DP   | 3736  | FL      | 5/20/2022 | 6/1/2022  |
| 610606 | 4UZFCHFE1 | 2022 | DS    | DP   | 4369  | FL      | 5/2/2022  | 5/11/2022 |
| 610608 | 4VZAU1D1  | 2022 | DS    | DP   | 4369  | S       | 5/17/2022 | 5/24/2022 |
| 610611 | 4VZAU1D1  | 2022 | DS    | DP   | 4081  | S       | 5/25/2022 | 6/7/2022  |
| 610613 | 4VZAU1D1  | 2022 | DS    | DP   | 4081  | S       | 5/24/2022 | 6/7/2022  |
| 610614 | 4VZAU1D1  | 2022 | DS    | DP   | 4081  | S       | 5/24/2022 | 6/3/2022  |
| 610615 | 4VZAU1D1  | 2022 | DS    | DP   | 4081  | S       | 6/2/2022  | 6/10/2022 |
| 610616 | 4VZAU1D1  | 2022 | DS    | DP   | 4081  | S       | 5/24/2022 | 6/3/2022  |
| 610617 | 4VZAU1D1  | 2022 | DS    | DP   | 4081  | S       | 5/23/2022 | 6/3/2022  |
| 610618 | 4VZAU1D1  | 2022 | DS    | DP   | 4081  | S       | 6/1/2022  | 6/10/2022 |
| 610619 | 4VZAU1D1  | 2022 | DS    | DP   | 4081  | S       | 5/23/2022 | 6/2/2022  |
| 610620 | 4VZAU1D1  | 2022 | DS    | DP   | 4081  | S       | 5/23/2022 | 6/2/2022  |
| 610621 | 4VZAU1D1  | 2022 | DS    | DP   | 4081  | S       | 5/23/2022 | 6/2/2022  |
| 610622 | 4VZAU1D1  | 2022 | DS    | DP   | 4081  | S       | 6/3/2022  | 6/15/2022 |
| 610623 | 4UZFCHFE4 | 2022 | DS    | DP   | 4326  | FL      | 5/20/2022 | 6/2/2022  |
| 610624 | 4VZAU1D1  | 2022 | DS    | DP   | 4081  | S       | 5/12/2022 | 5/23/2022 |
| 610625 | 4UZFCHFE6 | 2022 | DS    | DP   | 4081  | FL      | 7/12/2022 | 7/19/2022 |
| 610626 | 4UZFCHFE0 | 2022 | DS    | DP   | 4081  | FL      | 6/3/2022  | 6/14/2022 |
| 610628 | 4VZAU1D1  | 2022 | DS    | DP   | 4081  | S       | 6/8/2022  | 6/16/2022 |
| 610630 | 4UZACHFE0 | 2022 | DS    | DP   | 3709  | FL      | 6/7/2022  | 6/15/2022 |
| 610631 | 4VZAU1D1  | 2022 | DS    | DP   | 4081  | S       | 7/15/2022 | 7/26/2022 |
| 610632 | 4VZAU1D1  | 2022 | DS    | DP   | 4369  | S       | 6/20/2022 | 6/29/2022 |
| 610633 | 4VZAU1D1  | 2022 | DS    | DP   | 4081  | S       | 6/10/2022 | 6/21/2022 |
| 610634 | 4VZAU1D1  | 2022 | DS    | DP   | 4369  | S       | 6/30/2022 | 7/19/2022 |
| 610635 | 4VZAU1D1  | 2023 | DS    | DP   | 4328  | S       | 6/17/2022 | 6/29/2022 |
| 610636 | 4VZAU1D1  | 2023 | DS    | DP   | 4369  | S       | 6/17/2022 | 6/28/2022 |

| Prod#  | VIN Num   | Year | Brand | Type | Floor | Chassis | Date In   | Date Off  |
|--------|-----------|------|-------|------|-------|---------|-----------|-----------|
| 610637 | 4VZAU1D1  | 2023 | DS    | DP   | 4081  | S       | 7/15/2022 | 7/26/2022 |
| 610638 | 4UZFCHFE6 | 2022 | DS    | DP   | 4326  | FL      | 6/22/2022 | 7/13/2022 |
| 801466 | 4VZVU1R1  | 2022 | EX    | DP   | 4569  | S       | 6/16/2022 | 6/23/2022 |
| 801494 | 4VZVU1R1  | 2022 | EX    | DP   | 4551  | S       | 4/25/2022 | 5/2/2022  |
| 801512 | 4VZVU1R1  | 2022 | EX    | DP   | 4551  | S       | 4/29/2022 | 5/9/2022  |
| 801513 | 4VZVU1R1  | 2022 | EX    | DP   | 4551  | S       | 6/22/2022 | 7/12/2022 |
| 801514 | 4VZVU1R1  | 2022 | EX    | DP   | 4569  | S       | 5/19/2022 | 5/31/2022 |
| 801516 | 4VZVU1R1  | 2022 | EX    | DP   | 4551  | S       | 5/13/2022 | 5/24/2022 |
| 801519 | 4VZVU1R1  | 2022 | EX    | DP   | 4551  | S       | 5/11/2022 | 5/20/2022 |
| 801521 | 4VZVU1R1  | 2022 | EX    | DP   | 4551  | S       | 5/4/2022  | 5/12/2022 |
| 801525 | 4VZVU1R1  | 2022 | EX    | DP   | 4551  | S       | 5/25/2022 | 6/7/2022  |
| 801526 | 4VZVU1R1  | 2022 | EX    | DP   | 4551  | S       | 6/3/2022  | 6/14/2022 |
| 801527 | 4VZVU1R1  | 2022 | EX    | DP   | 4569  | S       | 6/10/2022 | 6/21/2022 |
| 801530 | 4VZVU1R1  | 2023 | EX    | DP   | 4595  | S       | 7/13/2022 | 7/20/2022 |
| 801552 | 4VZVU1R1  | 2023 | EX    | DP   | 4595  | S       | 7/19/2022 | 7/27/2022 |
| 904928 | 4VZVU1E1  | 2022 | MA    | DP   | 4118  | S       | 6/20/2022 | 6/29/2022 |
| 904985 | 4VZVU1E1  | 2022 | MA    | DP   | 4118  | S       | 6/30/2022 | 7/19/2022 |
| 905014 | 4VZVU1E1  | 2022 | MA    | DP   | 4118  | S       | 5/2/2022  | 5/10/2022 |
| 905018 | 4VZVU1E9  | 2022 | MA    | DP   | 4543  | S       | 4/25/2022 | 5/2/2022  |
| 905020 | 4VZVU1E1  | 2022 | MA    | DP   | 4118  | S       | 5/5/2022  | 5/13/2022 |
| 905023 | 4VZVU1E1  | 2022 | MA    | DP   | 4118  | S       | 5/24/2022 | 6/3/2022  |
| 905024 | 4VZAU1D1  | 2022 | MA    | DP   | 4118  | S       | 5/25/2022 | 6/8/2022  |
| 905025 | 4VZVU1E1  | 2022 | MA    | DP   | 4118  | S       | 6/1/2022  | 6/10/2022 |
| 905026 | 4VZVU1E9  | 2022 | MA    | DP   | 4551  | S       | 6/7/2022  | 6/16/2022 |
| 905027 | 4VZVU1E1  | 2022 | MA    | DP   | 4551  | S       | 6/23/2022 | 7/13/2022 |
| 905028 | 4VZVU1E1  | 2023 | MA    | DP   | 4118  | S       | 6/21/2022 | 6/30/2022 |

| Prod#          | VIN Num   | Year | Brand | Type | Floor | Chassis | Date In   | Date Off  |
|----------------|-----------|------|-------|------|-------|---------|-----------|-----------|
| CANADIAN UNITS |           |      |       |      |       |         |           |           |
| 501899         | 4VZVU1R1  | 2022 | LA    | DP   | 4551  | S       | 5/2/2022  | 5/11/2022 |
| 501920         | 4VZVU1R1  | 2022 | LA    | DP   | 4551  | S       | 6/30/2022 | 7/18/2022 |
| 609925         | 4UZFCHFE9 | 2022 | DS    | DP   | 4081  | FL      | 5/12/2022 | 5/20/2022 |
| 610302         | 4VZAU1D1  | 2022 | DS    | DP   | 4369  | S       | 5/10/2022 | 5/19/2022 |
| 610310         | 4VZAU1D1  | 2022 | DS    | DP   | 4369  | S       | 6/15/2022 | 6/23/2022 |
| 610361         | 4VZAU1D1  | 2022 | DS    | DP   | 4081  | S       | 5/9/2022  | 5/18/2022 |
| 610364         | 4UZFCHFE5 | 2022 | DS    | DP   | 4081  | FL      | 5/3/2022  | 5/11/2022 |
| 610365         | 4UZFCHFE0 | 2022 | DS    | DP   | 4081  | FL      | 5/25/2022 | 6/7/2022  |
| 610603         | 4UZACHFE0 | 2022 | DS    | DP   | 3717  | FL      | 6/3/2022  | 6/14/2022 |
| 610629         | 4VZAU1D1  | 2022 | DS    | DP   | 4081  | S       | 6/7/2022  | 6/16/2022 |