

72185 COUNTY ROAD 3
NAPPANEE IN 46550

NEWMAR CORPORATION WARRANTY DEPARTMENT

FAX. 800.858.4924
219.773.2007

TECHNICAL SERVICE BULLETIN

Date Issued
09/26/00

Model Year(s) Affected
2000-2001

Model(s) Affected
Motorized

TSB #
206

Brand				Type		
ALL <input type="radio"/>	American Star <input type="radio"/>	Kountry Star <input checked="" type="radio"/>	Dutch Star <input checked="" type="radio"/>	All <input type="radio"/>	TT <input type="radio"/>	FW <input type="radio"/>
	Mountain Aire <input checked="" type="radio"/>	Kountry Aire <input checked="" type="radio"/>	London Aire <input checked="" type="radio"/>	CA <input checked="" type="radio"/>	DP <input checked="" type="radio"/>	DB <input checked="" type="radio"/>

- ☐ Air Conditioning & Heating
- ☒ Appliances & Accessories
- ☐ Cabinets & Furniture
- ☐ Chassis Components
- ☐ Construction Components

- ☐ Electrical Components
- ☐ Exterior Components
- ☐ Interior Components
- ☐ Plumbing & Bath Components
- ☐ Windows, Awnings, Vents & Doors

Description of Problem

Inspection of HWH pump mounting bracket. 2000-2001 models built from July, 1999 through September, 2000.

Recommended Solution

Inspect the weld point of the mounting bracket to the frame for possible cracking. If cracking is present, contact a Newmar dealer representative for an authorization number and then add a gusset brace to the bottom of the bracket.

If you have any questions regarding this T.S.B., please contact a Warranty Service Representative at Newmar Corporation.

TSB.09019