

# NEWMAR CORPORATION

## WARRANTY DEPARTMENT

### TECHNICAL SERVICE BULLETIN

Date Issued  
01/26/01

Model Year(s) Affected  
2000-2001

Model(s) Affected  
Diesel Pushers

TSB #  
208

B r a n d				T y p e		
ALL <input type="radio"/>	American Star <input type="radio"/>	Kountry Star <input checked="" type="radio"/>	Dutch Star <input checked="" type="radio"/>	All <input type="radio"/>	T T <input type="radio"/>	F W <input type="radio"/>
	Mountain Aire <input checked="" type="radio"/>	Kountry Aire <input checked="" type="radio"/>	London Aire <input checked="" type="radio"/>	C A <input type="radio"/>	D P <input checked="" type="radio"/>	D B <input type="radio"/>

- |   |   |
|---|---|
| <input checked="" type="radio"/> Air Conditioning & Heating | <input type="radio"/> Electrical Components           |
| <input type="radio"/> Appliances & Accessories              | <input type="radio"/> Exterior Components             |
| <input type="radio"/> Cabinets & Furniture                  | <input type="radio"/> Interior Components             |
| <input checked="" type="radio"/> Chassis Components         | <input type="radio"/> Plumbing & Bath Components      |
| <input type="radio"/> Construction Components               | <input type="radio"/> Windows, Awnings, Vents & Doors |

#### Description of Problem

Possible incorrect heater hose installation on units manufactured between February 20, 2000 - August 24, 2000. Please inspect all diesel pushers built in this time frame.

#### Recommended Solution

Inspect all heater hoses. If they are labeled heater hose no change is necessary. However, if the hose is labeled farm tank hose it must be replaced. Please contact the Newmar Service Department to obtain authorization. Inspection time allowed is .2 and the labor flate rate code is 01830326.

The correct hose may be ordered from the Newmar Parts Department or a local parts supply store. When ordering from Newmar, please refer to part #10446.