

NEWMAR CORPORATION WARRANTY DEPARTMENT

TECHNICAL SERVICE BULLETIN							
DATE ISSUED		MODEL YEAR(S) AFFECTED		MODEL(S) AFFECTED		TSB #	
6/19/06		2005-2006		As Noted		260	
BRAND						TYPE	
All	■	American Star	<input type="checkbox"/>	Mountain Aire	<input type="checkbox"/>	All	<input type="checkbox"/>
		Dutch Star	<input type="checkbox"/>	Kountry Aire	<input type="checkbox"/>	FW	<input type="checkbox"/>
		Kountry Star	<input type="checkbox"/>	Essex	<input type="checkbox"/>	DP	<input type="checkbox"/>
Scottsdale	■	Northern Star	<input type="checkbox"/>	London Aire	<input type="checkbox"/>	CA	■
						DB	<input type="checkbox"/>
<div style="display: flex; justify-content: space-between;"> <div> <input type="checkbox"/> Air Conditioning & Heating <input type="checkbox"/> Appliances & Accessories <input type="checkbox"/> Cabinets & Furniture <input checked="" type="checkbox"/> Chassis Components <input type="checkbox"/> Construction Components </div> <div> <input type="checkbox"/> Electrical Components <input type="checkbox"/> Exterior Components <input type="checkbox"/> Interior Components <input type="checkbox"/> Plumbing & Bath Components <input type="checkbox"/> Windows, Awnings, Vents, & Doors </div> </div>							
DESCRIPTION OF PROBLEM							
<p>Workhorse Custom Chassis has determined there may be a mismatch condition regarding the steering shaft on the 2005 – 2006 class A motorhome chassis.</p>							
RECOMMENDED SOLUTION							
<p>Inspect and repair per Workhorses' attached bulletin. See attached information for procedures and times.</p>							