

# NEWMAR CORPORATION WARRANTY DEPARTMENT

TECHNICAL SERVICE BULLETIN							
DATE ISSUED		MODEL YEAR(S) AFFECTED		MODEL(S) AFFECTED		TSB #	
6/22/06		7/25/03 – 3/19/04		Spartan Chassis K2 Models		275	
BRAND						TYPE	
All	<input type="checkbox"/>	American Star	<input type="checkbox"/>	Mountain Aire	<input type="checkbox"/>	All	<input type="checkbox"/>
		Dutch Star	<input type="checkbox"/>	Kountry Aire	<input type="checkbox"/>	T T	<input type="checkbox"/>
		Kountry Star	<input type="checkbox"/>	Essex	<input checked="" type="checkbox"/>	F W	<input type="checkbox"/>
Scottsdale	<input type="checkbox"/>	Northern Star	<input type="checkbox"/>	London Aire	<input type="checkbox"/>	C A	<input type="checkbox"/>
						D P	<input checked="" type="checkbox"/>
						D B	<input checked="" type="checkbox"/>
<input type="checkbox"/> Air Conditioning & Heating				<input type="checkbox"/> Electrical Components			
<input type="checkbox"/> Appliances & Accessories				<input type="checkbox"/> Exterior Components			
<input type="checkbox"/> Cabinets & Furniture				<input type="checkbox"/> Interior Components			
<input checked="" type="checkbox"/> Chassis Components				<input type="checkbox"/> Plumbing & Bath Components			
<input type="checkbox"/> Construction Components				<input type="checkbox"/> Windows, Awnings, Vents, & Doors			
DESCRIPTION OF PROBLEM							
<p>Air Cleaner and CAC Plumbing:</p> <p>Potential exists for contact between the air cleaner tubing and a CAC hose where a chafing condition could occur.</p>							
RECOMMENDED SOLUTION							
<p>Reposition CAC hose. If component damage is found, contact Spartan Chassis, Inc. for further direction. See Manufacturers attached repair directions. Contact manufacturer directly for additional information or instructions.</p>							