

NEWMAR CORPORATION

WARRANTY DEPARTMENT

TECHNICAL SERVICE BULLETIN							
DATE ISSUED		MODEL YEAR(S) AFFECTED		MODEL(S) AFFECTED		TSB #	
01/29/2010		2009 - Present		ALL		365	
BRAND						TYPE	
All	<input checked="" type="checkbox"/>	American Star	<input type="checkbox"/>	Mountain Aire	<input type="checkbox"/>	All	<input checked="" type="checkbox"/>
		Dutch Star	<input type="checkbox"/>	Kountry Aire	<input type="checkbox"/>	F W	<input type="checkbox"/>
		Kountry Star	<input type="checkbox"/>	Essex	<input type="checkbox"/>	D P	<input type="checkbox"/>
Scottsdale	<input type="checkbox"/>	Northern Star	<input type="checkbox"/>	London Aire	<input type="checkbox"/>		
<div style="display: flex; justify-content: space-between;"> <div> <input type="checkbox"/> Air Conditioning & Heating <input type="checkbox"/> Appliances & Accessories <input type="checkbox"/> Cabinets & Furniture <input type="checkbox"/> Chassis Components <input type="checkbox"/> Construction Components </div> <div> <input type="checkbox"/> Electrical Components <input checked="" type="checkbox"/> Exterior Components <input type="checkbox"/> Interior Components <input type="checkbox"/> Plumbing & Bath Components <input type="checkbox"/> Windows, Awnings, Vents, & Doors </div> </div>							
DESCRIPTION OF PROBLEM							
12" black rubber AM/FM radio antenna masts are being broke off at the base of the antenna mount.							
RECOMMENDED SOLUTION							
<p>When replacing a 12" AM/FM rubber radio antenna mast, Newmar Corporation recommends that the tip of the mast be pointed back towards the rear of the coach and positioned at approximately a 60 degree angle. This process is currently being performed during the production stage at Newmar on all current units.</p> <ul style="list-style-type: none"> The Newmar part number for the radio antenna mast is # 34782A. Warranty flat rate time allowed is .10 Flat rate code to be used is 0650 							

If you have any questions regarding this T.S.B., please contact a Warranty Service Representative at Newmar Corporation.

NEWMAR CORPORATION WARRANTY DEPARTMENT



Figure 1 - This shows the roof mounting of a 12" black AM/FM radio antenna.



Figure 2 - Upon replacement of the 12" black rubber AM/FM antenna mast, please make sure that the tip of the mast is pointed to the rear of the coach and is in approximately a 60 degree angle.

If you have any questions regarding this T.S.B., please contact a Warranty Service Representative at Newmar Corporation.