



Newmar Corporation Warranty Department

Technical Service Bulletin

Date Issued	Model Year(s) Affected	Model(s) Affected	TSB #
09/24/2010	2008-2011	Motorized	374
Brand			Type
All <input type="checkbox"/>	American Star <input type="checkbox"/>	Mountain Aire <input checked="" type="checkbox"/>	All <input type="checkbox"/> T T <input type="checkbox"/>
Cypress <input type="checkbox"/>	Dutch Star <input checked="" type="checkbox"/>	Kountry Aire <input type="checkbox"/>	FW <input type="checkbox"/> C A <input type="checkbox"/>
Northern Star <input type="checkbox"/>	Kountry Star	Essex	DP <input checked="" type="checkbox"/> DB <input type="checkbox"/>
Scottsdale <input type="checkbox"/>	King Aire	London Aire <input type="checkbox"/>	
All Star ME <input type="checkbox"/>	Ventana <input checked="" type="checkbox"/>	Bay Star <input type="checkbox"/>	
<div style="display: flex; justify-content: space-between;"> <div style="width: 48%;"> <input type="checkbox"/> Air Conditioning & Heating <input type="checkbox"/> Appliances & Accessories <input type="checkbox"/> Cabinets & Furniture <input type="checkbox"/> Chassis Components <input type="checkbox"/> Construction Components </div> <div style="width: 48%;"> <input type="checkbox"/> Electrical Components <input checked="" type="checkbox"/> Exterior Components <input type="checkbox"/> Interior Components <input type="checkbox"/> Plumbing & Bath Components <input type="checkbox"/> Windows, Awnings, Vents, & Doors </div> </div>			
Description of Problem			
<p>There is a limited quantity of units with Dometic awnings 198" or over that were installed with 1 anti billow stud. Due to potential risk of damage while in transit, an upgrade kit is requested to be installed.</p>			
Recommended Solution			
<p>Please add a secondary anti billowing spacer kit to Dometic awnings 198" and over that are missing. Please refer to Campaign Notification letter attached.</p>			
<p><u>Picture of anti billow kit.</u></p> 		<p><u>Picture showing kit installed</u></p> 	
<p><u>Parts needed:</u> Vender # 3109252.001 Newmar # 011953</p>		<p><u>Flat rate pays:</u> 0.4 hours</p>	

If you have any questions regarding this T.S.B., please contact a Warranty Service Representative at Newmar Corporation.