

NEWMAR CORPORATION WARRANTY DEPARTMENT

TECHNICAL SERVICE BULLETIN							
DATE ISSUED	MODEL YEAR(S) AFFECTED	MODEL(S) AFFECTED	TSB #				
7/25/91	1990-1991	ALL	44				
BRAND		TYPE					
All <input checked="" type="checkbox"/>	American Star <input type="checkbox"/>	Kountry Star <input type="checkbox"/>	Dutch Star <input type="checkbox"/>	All <input checked="" type="checkbox"/>	T T <input type="checkbox"/>	F W <input type="checkbox"/>	
NewAire <input type="checkbox"/>	Mountain Aire <input type="checkbox"/>	Kountry Aire <input type="checkbox"/>	London Aire <input type="checkbox"/>	C A <input type="checkbox"/>	D P <input type="checkbox"/>	D B <input type="checkbox"/>	
<input type="checkbox"/> Air Conditioning & Heating				<input type="checkbox"/> Electrical Components			
<input checked="" type="checkbox"/> Appliances & Accessories				<input type="checkbox"/> Exterior Components			
<input type="checkbox"/> Cabinets & Furniture				<input type="checkbox"/> Interior Components			
<input type="checkbox"/> Chassis Components				<input type="checkbox"/> Plumbing & Bath Components			
<input type="checkbox"/> Construction Components				<input type="checkbox"/> Windows, Awnings, Vents, & Doors			
DESCRIPTION OF PROBLEM							
Water leaks on water heater connections on Suburban drain plugs.							
RECOMMENDED SOLUTION							
Refer to the Suburban service bulletin.							

If you have any questions regarding this T.S.B., please contact a Warranty Service Representative at Newmar Corporation.

NEWMAR CORPORATION WARRANTY DEPARTMENT



Dayton, Tennessee • Elkhart, Indiana

Technical Services Information

WATER HEATER
NEW DRAIN PLUG

All Models

TSI: RV91-343

Date: 07/05/91

SERVICE BULLETIN

TO: All Service Centers
RV Distributors
OEM Accounts

FROM: Neal Stultz

SUBJECT: NEW WATER HEATER DRAIN PLUG

Effective immediately, all Suburban water heaters now incorporate a 3/8" diameter steel drain plug, replacing the brass petcock valve #160927.

This change has greatly reduced troublesome water leaks around the threaded connection, and allows for faster tank draining. For easy removal of this plug, use a 3/8" diameter 8-point socket.

If you have any questions or need additional information, please contact the Factory Service Department at 615-775-2131.

Neal Stultz
National Service Manager

NS:gd