TECHNICAL SERVICE BULLETIN													
DATE ISSUED	MODEL Y	MODEL YEAR(S) AFFECTED		MODEL(S) AFFECTE		TSB #							
7/21/94 1994				A11		101							
	AND		Түре										
All 🛛 American Star 🗖 Kountry Star 🗖				ch Star	Star ■ All □ TT□ FW								
NewAire 🛛 Mount	Kountry Aire	Lon	don Aire	$CA \blacksquare DP \blacksquare DB \square$									
Air Conditioning a			Electrical Components										
Appliances & Accessories				Exterior Components									
Cabinets & Furniture				Interior Components									
Chassis Components				Plumbing & Bath Components									
Construction Components				Windows, Awnings, Vents, & Doors									
DESCRIPTION OF PROBLEM													
Charle attached chart to	soo if it has	RECOMMENDED			won have any o	vestions plasse							
Check attached chart to contact your service rep		the right weight tag to	mat	ch chassis. It	you have any qu	lestions, please							

If you have any questions regarding this T.S.B., please contact a Warranty Service Representative at Newmar Corporation.

Dear Dealer

Newmar has discovered that a few 1994 Motorhomes have left here with incorrect information typed on the Federal Certification Label. The error is in the stated GVWR of the motorhome. Please check any units you may have against the enclosed chart for errors. If an error is found, call the warranty department and notify us with the serial number of the unit and we will send you a corrected Federal Certification Label

Thank you,

Dave Garl

Warranty Manager

Chassis	Model	Dutch Star	Kountry Star	Mountain Aire	Kountry Aire	London Aire
Chevy	27 WCB	16,000				
Ford	27 WCB	17,000				
Chevy	29 WCB			16,000		
Ford	29 WCB		17,000	17,000	17,000	
Chevy	31 WCB	16,000				
Ford	31 WCB	17,000				
Ford	32 CBD		17,000	17,000	17,000	
Ford	32 WCB	17,000				
Spartan	34 CB		26,000			
Chevy	34 CBD		18,500	18,500	18,500	
Ford	34 CBD		20,000	20,000	20,000	
Ford	34 CBD2	17,000				
Chevy	34 CBDS		18,500	18,500	18,500	
Ford	34 CBDS		20,000	20,000	20,000	
Spartan	34 CBS	20,000				
Chevy	34 CBWS		18,500	18,500	18,500	
Ford	34 CBWS		20,000	20,000	20,000	
Chevy	34 SACB	16,000				
Ford	34 SACB	17,000				
Ford	34 WBS		20,000	20,000	20.000	
Spartan	34 WBS2	20,000				
Spartan	34 WBSS	and the second sec	26,000			
Chevy	34 WCB		18,500	18,500		
Ford	34 WCB		20,000	20,000		
Chevy	34 WCB1	16,000				
Ford	34 WCB1	17,000				
Ford	34 WCB2	17,000				
Ford	34 WCBD				20,000	
Chevy	34 WCDS		18,500	18,500	18,500	
Ford	34 WCDS		20,000	20,000	20,000	
Spartan	38 CBSA		26,000			26.000
Spartan	38 WDSK		26,000			26,000
Spartan	38 WDSL		26,000			26,000
Spartan	40 CBSA		26,000			26,000
Spartan	40 SKWD		26,000			20,000
Spartan	40 WDSK		26,000			

If you have any questions regarding this T.S.B., please contact a Warranty Service Representative at Newmar Corporation.