

# NEWMAR CORPORATION WARRANTY DEPARTMENT

TECHNICAL SERVICE BULLETIN						
DATE ISSUED	MODEL YEAR(S) AFFECTED	MODEL(S) AFFECTED	TSB #			
1/9/95	1994-1995	ALL	108			
BRAND		TYPE				
All <input type="checkbox"/>	American Star <input type="checkbox"/>	Kountry Star <input type="checkbox"/>	Dutch Star <input type="checkbox"/>	All <input type="checkbox"/>	T T <input checked="" type="checkbox"/>	F W <input checked="" type="checkbox"/>
NewAire <input type="checkbox"/>	Mountain Aire <input type="checkbox"/>	Kountry Aire <input checked="" type="checkbox"/>	London Aire <input checked="" type="checkbox"/>	C A <input type="checkbox"/>	D P <input type="checkbox"/>	D B <input type="checkbox"/>
<input type="checkbox"/> Air Conditioning & Heating				<input type="checkbox"/> Electrical Components		
<input type="checkbox"/> Appliances & Accessories				<input type="checkbox"/> Exterior Components		
<input type="checkbox"/> Cabinets & Furniture				<input type="checkbox"/> Interior Components		
<input type="checkbox"/> Chassis Components				<input type="checkbox"/> Plumbing & Bath Components		
<input checked="" type="checkbox"/> Construction Components				<input type="checkbox"/> Windows, Awnings, Vents, & Doors		
DESCRIPTION OF PROBLEM						
Over greasing of Dexter EZ lube hubs.						
RECOMMENDED SOLUTION						
Some customers believe the grease fitting in the EZ lube hub is for periodically adding grease to the hub. It is not for that purpose. The fitting is there so bearings can be packed upon initial installation of the hub. It is not necessary to add grease between the initial installation and the next time the hub is removed. When the hub is removed, it is recommended the grease seal be replaced and the bearing refilled at that time.						

□

If you have any questions regarding this T.S.B., please contact a Warranty Service Representative at Newmar Corporation.