
TECHNICAL SERVICE BULLETIN											
DATE ISSUED		MODEL YEAR(S) AFFECTED				MODEL(S)	AFFECTED		TSB #		
5/24/95		1994-1995				36 R	LDS		111		
Brand								Түре			
All 🗖] Kountry Sta	Kountry Star 🛛 Dutch Star 🛛			All 🗖 TT 🗖 FW 🗖						
NewAire 🗖 Mountain Aire 🗖 Kountry Aire					Lon	don Aire					
 Air Conditioning & Heating 						Electrical Components					
Appliances & Accessories						Exterior Components					
Cabinets & Furniture						☐ Interior Components					
Chassis Components						Plumbing &	g & Bath Components				
Construction Components						Windows, Awnings, Vents, & Doors					
DESCRIPTION OF PROBLEM											
RECOMMENDED SOLUTION											
Change out LP lines with new LP line. Add spring onto LP line per attached print. Make sure there is 1.5" clearance on arm at location of spring.											
Note: Parts can be purchased from Newmar. Newmar will pay 1 hour to change out LP lines per drawing.											

If you have any questions regarding this T.S.B., please contact a Warranty Service Representative at Newmar Corporation.

NEWMAR CORPORATION WARRANTY DEPARTMENT



If you have any questions regarding this T.S.B., please contact a Warranty Service Representative at Newmar Corporation.