TECHNICAL SERVICE BULLETIN								
DATE ISSUED MODEL		(EAR(S) AFFECTED		MODEL(S) AFFECTED		TSB #		
10/16/95	ALL			ALL		119		
Brand					Түре			
All Americ	can Star 🛛	Kountry Star 🛛 I	Dut	ch Star 🛛	All 🗖 T	ТП	FW 🗖	
NewAire 🗖 Mounta	ain Aire 🛛	Kountry Aire 🛛 I	Lon	don Aire 🗖	C A 🗖 D	РП	DB 🗖	
Air Conditioning & Heating Electrical Components								
Appliances & Accessories				Exterior Components				
□ Cabinets & Furniture				Interior Components				
□ Chassis Components				Plumbing & Bath Components				
Construction Components				Windows, Awnings, Vents, & Doors				
DESCRIPTION OF PROBLEM Installing rollers and caster wheels on the bottom of frame or hitch on the rear end. This could cause frame or								
Recommended Solution Remove rollers or caster wheels.								
	t wheels.							

If you have any questions regarding this T.S.B., please contact a Warranty Service Representative at Newmar Corporation.