TECHNICAL SERVICE BULLETIN								
DATE ISSUED	MODEL YEAR(S) AFFECTED			MODEL(S)	AFFECTED	TSB #		
10/16/95	1	995-1996	A		L	120		
BRAND					Түре			
All Americ	can Star 🛛	Kountry Star 🛛	Dut	ch Star 🛛	All T	Т 🗖	FW 🗖	
NewAire 🛛 Mountain Aire 🗖 Kountry Aire 🗖			Lon	don Aire□				
Air Conditioning & Heating				Electrical Components				
Appliances & Accessories				Exterior Components				
□ Cabinets & Furniture				Interior Components				
□ Chassis Components				Plumbing &	oing & Bath Components			
Construction Components				Windows, Awnings, Vents, & Doors				
DESCRIPTION OF PROBLEM Interior front of water heater cracking on Suburban water heaters, models SW-8 or SW-10. Check for cracks in								
RECOMMENDED SOLUTION								
If front of water heater replacement. 2X2 block Newmar service represe	ks must be ad	lded to both sides of	wate	r heater. Any	questions, pleas			

If you have any questions regarding this T.S.B., please contact a Warranty Service Representative at Newmar Corporation.