TECHNICAL SERVICE BULLETIN								
DATE ISSUED MODEL Y		'EAR(S) AFFECTED		MODEL(S) AFFECTE		TSB #		
10/19/95	1995-1996			ALL		121		
Brand					Түре			
All 🗖 Americ	can Star 🛛	Kountry Star	Dut	ch Star 🗖	All 🗖 🗇	TT 🗖	FW 🗖	
NewAire □ Mountain Aire ■ Kountry Aire ■			Lon	don Aire□	C A I	⊃ P 🗖	DB 🗖	
□ Air Conditioning & Heating				Electrical Components				
Appliances & Accessories				Exterior Components				
□ Cabinets & Furniture				□ Interior Components				
Chassis Components				Plumbing & Bath Components				
Construction Components				☐ Windows, Awnings, Vents, & Doors				
DESCRIPTION OF PROBLEM								
RECOMMENDED SOLUTION								
The P30 Chevy chassis in The F53 Ford chassis in removed to reach the ho the work. This should h	odule hook- ook-up. This	up is located on the dr information is for aut	iver hor	side of the en ized Ford and	igine. The eng Chevy service	ne cove centers	er must be for perform	

If you have any questions regarding this T.S.B., please contact a Warranty Service Representative at Newmar Corporation.