TECHNICAL SERVICE BULLETIN								
DATE ISSUED MODEL YI		EAR(S) AFFECTED		MODEL(S) AFFECTED		TSB #		
9/18/96	1997			ALL		134		
BRAND					Түре			
All Americ	can Star 🛛	Kountry Star 🛛	Dut	ch Star 🛛	All 🗖 T	Т	FW	
NewAire 🛛 Mountain Aire 🗖 Kountry Aire 🗖				don Aire 🗖	C A 🗖 D	P□	DB 🗖	
□ Air Conditioning & Heating [Electrical Components				
Appliances & Accessories				Exterior Components				
□ Cabinets & Furniture				Interior Components				
□ Chassis Components				Plumbing & Bath Components				
Construction Components				Windows, A	indows, Awnings, Vents, & Doors			
DESCRIPTION OF PROBLEM Location of the monitor panel probes on the bottom underbelly metal.								
Recommended Solution Label has been attached to show location.								
Laber has been attached		40011.						

If you have any questions regarding this T.S.B., please contact a Warranty Service Representative at Newmar Corporation.