

# NEWMAR CORPORATION WARRANTY DEPARTMENT

| TECHNICAL SERVICE BULLETIN   |  |                                       |                                      |   |                              |                              |  |
|--|--|---------------------------------------|--------------------------------------|---|------------------------------|------------------------------|--|
| DATE ISSUED  | MODEL YEAR(S) AFFECTED                 | MODEL(S) AFFECTED                     | TSB #                                |   |                              |                              |  |
| 10/24/96   | 1996-1997                              | ALL                                   | 135                                  |   |                              |                              |  |
| BRAND  |  | TYPE                                  |                                      |   |                              |                              |  |
| All <input checked="" type="checkbox"/>  | American Star <input type="checkbox"/> | Kountry Star <input type="checkbox"/> | Dutch Star <input type="checkbox"/>  | All <input checked="" type="checkbox"/>                   | T T <input type="checkbox"/> | F W <input type="checkbox"/> |  |
| NewAire <input type="checkbox"/>   | Mountain Aire <input type="checkbox"/> | Kountry Aire <input type="checkbox"/> | London Aire <input type="checkbox"/> | C A <input type="checkbox"/>                              | D P <input type="checkbox"/> | D B <input type="checkbox"/> |  |
| <input type="checkbox"/> Air Conditioning & Heating  |  |                                       |                                      | <input type="checkbox"/> Electrical Components            |                              |                              |  |
| <input type="checkbox"/> Appliances & Accessories  |  |                                       |                                      | <input checked="" type="checkbox"/> Exterior Components   |                              |                              |  |
| <input type="checkbox"/> Cabinets & Furniture  |  |                                       |                                      | <input type="checkbox"/> Interior Components              |                              |                              |  |
| <input type="checkbox"/> Chassis Components  |  |                                       |                                      | <input type="checkbox"/> Plumbing & Bath Components       |                              |                              |  |
| <input type="checkbox"/> Construction Components   |  |                                       |                                      | <input type="checkbox"/> Windows, Awnings, Vents, & Doors |                              |                              |  |
| DESCRIPTION OF PROBLEM   |  |                                       |                                      |   |                              |                              |  |
| The bottom trim on units built with Filon or fiberglass sides are not sealed on the bottom side of the trim.   |  |                                       |                                      |   |                              |                              |  |
| RECOMMENDED SOLUTION   |  |                                       |                                      |   |                              |                              |  |
| All units built with Filon or fiberglass sides must have trim sealed on the bottom with silicone or sikaflex. This will seal off the wood backer that is being used on the Filon and fiberglass. This will take .5 hour to seal off. |  |                                       |                                      |   |                              |                              |  |

□

If you have any questions regarding this T.S.B., please contact a Warranty Service Representative at Newmar Corporation.