

# NEWMAR CORPORATION WARRANTY DEPARTMENT

TECHNICAL SERVICE BULLETIN									
DATE ISSUED		MODEL YEAR(S) AFFECTED			MODEL(S) AFFECTED			TSB #	
3/18/97		1996-1997			ALL			138	
BRAND					TYPE				
All	<input type="checkbox"/>	American Star	<input type="checkbox"/>	Kountry Star	<input checked="" type="checkbox"/>	Dutch Star	<input type="checkbox"/>	All	<input type="checkbox"/>
NewAire	<input type="checkbox"/>	Mountain Aire	<input checked="" type="checkbox"/>	Kountry Aire	<input checked="" type="checkbox"/>	London Aire	<input checked="" type="checkbox"/>	T T	<input checked="" type="checkbox"/>
								F W	<input checked="" type="checkbox"/>
								C A	<input checked="" type="checkbox"/>
								D P	<input checked="" type="checkbox"/>
								D B	<input type="checkbox"/>
<input type="checkbox"/>	Air Conditioning & Heating				<input checked="" type="checkbox"/>	Electrical Components			
<input type="checkbox"/>	Appliances & Accessories				<input type="checkbox"/>	Exterior Components			
<input type="checkbox"/>	Cabinets & Furniture				<input type="checkbox"/>	Interior Components			
<input type="checkbox"/>	Chassis Components				<input type="checkbox"/>	Plumbing & Bath Components			
<input type="checkbox"/>	Construction Components				<input type="checkbox"/>	Windows, Awnings, Vents, & Doors			
DESCRIPTION OF PROBLEM									
Indoor halogen spotlight lens turning yellow from heat build-up.									
RECOMMENDED SOLUTION									
Change the light lens to a new type that is vented on the inside. The light lens can be removed by turning the lens.									

□

If you have any questions regarding this T.S.B., please contact a Warranty Service Representative at Newmar Corporation.