

NEWMAR CORPORATION WARRANTY DEPARTMENT

TECHNICAL SERVICE BULLETIN													
DATE ISSUED		MODEL YEAR(S) AFFECTED			MODEL(S) AFFECTED			TSB #					
8/18/97		1998			ALL			144					
BRAND					TYPE								
All	<input type="checkbox"/>	American Star	<input type="checkbox"/>	Kountry Star	<input checked="" type="checkbox"/>	Dutch Star	<input checked="" type="checkbox"/>	All	<input type="checkbox"/>	T T	<input type="checkbox"/>	F W	<input type="checkbox"/>
NewAire	<input type="checkbox"/>	Mountain Aire	<input checked="" type="checkbox"/>	Kountry Aire	<input checked="" type="checkbox"/>	London Aire	<input checked="" type="checkbox"/>	C A	<input checked="" type="checkbox"/>	D P	<input checked="" type="checkbox"/>	D B	<input type="checkbox"/>
<input type="checkbox"/> Air Conditioning & Heating					<input type="checkbox"/> Electrical Components								
<input type="checkbox"/> Appliances & Accessories					<input checked="" type="checkbox"/> Exterior Components								
<input type="checkbox"/> Cabinets & Furniture					<input type="checkbox"/> Interior Components								
<input type="checkbox"/> Chassis Components					<input type="checkbox"/> Plumbing & Bath Components								
<input type="checkbox"/> Construction Components					<input type="checkbox"/> Windows, Awnings, Vents, & Doors								
DESCRIPTION OF PROBLEM													
Plastic installed on front of unit for shipment.													
RECOMMENDED SOLUTION													
Please be sure to remove the plastic shipment covering within 24 hours of receipt of unit. This request comes from Newmar's paint provider. Leaving the covering on for extended time may cause harmful effects to the paint.													

□

If you have any questions regarding this T.S.B., please contact a Warranty Service Representative at Newmar Corporation.