TECHNICAL SERVICE BULLETIN								
DATE ISSUED	Model Year(s) Affecter			Model(s) Affected		-	TSB #	
10/01/97	1998			Ford Chassis			145	
Brand					Түре			
All 🗖 Americ	American Star 🗖 Kountry Star 🔳			Dutch Star 📕 All 🗖 TT 🗖 F W 🗖				
NewAire D Mount	ain Aire 🗖	Kountry Aire	Lon	don Aire 🗖	CA	D P 🗖	DB 🗖	
 Air Conditioning & Heating Electrical Components 								
Appliances & Accessories				Exterior Components				
Cabinets & Furniture				Interior Components				
Chassis Components				Plumbing &	& Bath Components			
Construction Components				Windows, A	s, Awnings, Vents, & Doors			
DESCRIPTION OF PROBLEM Tow vehicle wiring from seven-way trailer plug on the Ford chassis only.								
RECOMMENDED SOLUTION								
The Ford Chassis is equ the tow vehicle through the "ON" position to a call your service represe	the seven-wa ctivate the Fo	ay Bargman plug for	the m	arker lights b	e sure the mo	torhome	gnition is in	

If you have any questions regarding this T.S.B., please contact a Warranty Service Representative at Newmar Corporation.