800.858.4924 Fax 219.773.2007

NEWMAR CORPORATION WARRANTY DEPARTMENT

TECHNICAL SERVICE BULLETIN					
DATE ISSUED	MODEL YEAR(S) AFFECTED	Model(s)	AFFECTED	TSB#	
11/12/97	1998	ALL		147	
BRAND			Түре		
All American Star		Outch Star	All ■ TT□ FW□		
NewAire □ Mount	ain Aire 🗆 Kountry Aire 🗖 I	London Aire□	C A □ D	PD DBD	
☐ Air Conditioning & Heating ☐ Electrical Components					
☐ Appliances & Acc	☐ Exterior Components				
☐ Cabinets & Furnit	☐ Interior Components				
☐ Chassis Compone	☐ Plumbing & Bath Components				
☐ Construction Com	Windows, Awnings, Vents, & Doors				
DESCRIPTION OF PROBLEM					
RECOMMENDED SOLUTION					
Thermoil has increased the number of plates per cell to 13 for the 24 dc and 15 for the 27 dc. This process resulted in more reserve capacity for your customers, but a longer recharge time especially if the battery is completely depleted. Batteries may be "trickle discharged" below 11 volts. Some converters may associate this low voltage to a dead cell and refuse to charge the battery system. Please be sure to charge the batteries with a conventional battery charger before replacing them. To receive warranty coverage on Thermoil batteries, please be sure to adhere to the following: 1. Call Thermoil's customer assistance at 800-697-9505. 2. The RV battery number will be required so be sure to either document the number or remove the tag. 3. Include the retail purchase date of the RV. 4. If a replacement battery has been purchased, a copy of the receipt showing the purchase will be required.					