TECHNICAL SERVICE BULLETIN					
DATE ISSUED	ATE ISSUED MODEL YEAR(S) AFFECTED MODEL(S		AFFECTED	TSB #	
7/14/98	1998-1999	Units Mfg. after 1/97.		159	
BRAND			Түре		
All 🗖 Ameri	can Star 🛛 Kountry Star 🗖	Dutch Star	All 🗖 T	Т П Г W П	
NewAire 🗖 Mountain Aire 🗖 Kountry Aire 🗖		London Aire 🗖	C A 🗖 D	P■ DB□	
 Air Conditioning & Heating Electrical Components 					
Appliances & Accessories			Exterior Components		
Cabinets & Furnit	□ Interior Con	Interior Components			
Chassis Compone	Plumbing & Bath Components				
Construction Con	☐ Windows, Awnings, Vents, & Doors				
DESCRIPTION OF PROBLEM					
RECOMMENDED SOLUTION					
	to the front bottom edge of the gen IS BP-82. Allow .3 hour for install		art can be obtair	ned from Newmar	

If you have any questions regarding this T.S.B., please contact a Warranty Service Representative at Newmar Corporation.